



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPONDER 91.413)	KSAT		MTH 10-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK					A/R			
055002	ACCOMPLISH OVERSPEED CHECK					A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK					A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK	KSAT		MTH 04-Jun-2013 HRS 1144.5 LDG 964		A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK	KSAT		MTH 04-Jun-2013 HRS 1144.5 LDG 964		A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK					A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK					A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK					A/R			
5-12-01 051201	INSPECTION DOCUMENT 01 KSAT			MTH 27-Jun-2023 HRS 2592.4 LDG 2386		450		3042.4	289.3
5-12-02 051202	INSPECTION DOCUMENT 02 KSAT			MTH 06-Dec-2023 HRS 2641.3 LDG 2437		900		3541.3	788.2
5-12-03 051203	INSPECTION DOCUMENT 03 KSAT			MTH 06-Dec-2023 HRS 2641.3 LDG 2437		1350		3991.3	1238.2
5-12-04 051204	INSPECTION DOCUMENT 04 ICT			MTH 15-Dec-2015 HRS 1810.7 LDG 1581		1800		3610.7	857.6
5-12-05 051205	INSPECTION DOCUMENT 05 *CF			MTH 13-Oct-2009 HRS 0		3150		3150	396.9
5-12-06 051206	INSPECTION DOCUMENT 06 KSAT			MTH 21-Feb-2024 HRS 2664.4 LDG 2460		12		28-Feb-2025	2 m 8 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)	KSAT	C352TS G-97925127	MTH 21-Feb-2024 HRS 2664.4 LDG 2460		12		28-Feb-2025	2 m 8 d
5-12-07 051207	INSPECTION DOCUMENT 07 KSAT			MTH 21-Feb-2024 HRS 2664.4 LDG 2460		24		28-Feb-2026	14 m 8 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSAT		MTH 23-Jan-2020 HRS 2224.2 LDG 2026		60			



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004 051210 : FB	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)	KSAT		30401102-2 61544B1	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		60		31-Jul-2029	55 m 11 d
Hydro Check Date: 31-Jul-2024										
5-12-11 051211	INSPECTION DOCUMENT 11	KSAT			MTH 11-Nov-2021 HRS 2441.9 LDG 2242		72		30-Nov-2027	35 m 10 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)	KSAT		C352TS G-97925127	MTH 11-Nov-2021 HRS 2441.9 LDG 2242		72		30-Nov-2027	35 m 10 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSAT		C352TS G-97925127	MTH 11-Nov-2021 HRS 2441.9 LDG 2242		144			
B262101 051212	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)	KSAT		C352TS G-97925127	MTH 11-Nov-2021		144		30-Nov-2033	107 m 10 d
Hydro Check Date: 11-Nov-2021										
5-12-13 051213	INSPECTION DOCUMENT 13	KSAT			MTH 10-Apr-2024 HRS 2681 LDG 2477		12 450		30-Apr-2025 3131	4 m 10 d 377.9
5-12-14 051214	INSPECTION DOCUMENT 14	KSAT			MTH 04-Dec-2024 HRS 2751.8 LDG 2547		12 900		31-Dec-2025 3651.8	12 m 11 d 898.7
5-12-15 051215	INSPECTION DOCUMENT 15	KSAT			MTH 21-Feb-2024 HRS 2664.4 LDG 2460		24 1350		28-Feb-2026 4014.4	14 m 8 d 1261.3
5-12-16 051216	INSPECTION DOCUMENT 16	KSAT			MTH 11-Apr-2022 HRS 2487.6 LDG 2282		36 1350		30-Apr-2025 3837.6	4 m 10 d 1084.5
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK			29-10-00-720 HM50C-3 308B	MTH HRS		36 1350		30-Apr-2025 3837.6	4 m 10 d 1084.5
5-12-17 051217	INSPECTION DOCUMENT 17	KSAT			MTH 11-Apr-2022 HRS 2487.6 LDG 2282		36 1800		30-Apr-2025 4287.6	4 m 10 d 1534.5
5-12-18 051218	INSPECTION DOCUMENT 18	KSAT			MTH 11-Apr-2022 HRS 2487.6 LDG 2282		36 2250		30-Apr-2025 4737.6	4 m 10 d 1984.5
5-12-20 051220	INSPECTION DOCUMENT 20	KSAT			MTH 16-Feb-2022 HRS 2474.2 LDG 2268		48 2700		28-Feb-2026 5174.2	14 m 8 d 2421.1
5-12-21 051221	INSPECTION DOCUMENT 21	KSAT			MTH 21-Feb-2024 HRS 2664.4 LDG 2460		12		28-Feb-2025	2 m 8 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSAT			MTH 10-Apr-2024 HRS 2681 LDG 2477		24			
B341001 AIRSPEED 051222 : A/S	CALIBRATION TEST INDICATOR 14 CFR PART 91.411	KSAT		261440-1143 285592A	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										
B341001 NO. 1 051222 : ADC	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KSAT		011-01110-00 43805659	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 2 051222 : ADC#2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KSAT		011-01110-00 43805650	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										
B341001 STANDBY 051222 : STDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	KSAT		162350-1161 178742C	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	KSAT			MTH 07-Apr-2024		24		30-Apr-2026	16 m 10 d
B345000 LEFT 051222 : XPDR1	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KSAT		011-00779-21 84805671	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										
B345000 RIGHT 051222 : XPDR2	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KSAT		011-00779-21 84805407	MTH 07-Apr-2024 HRS 2681 LDG 2477		24		30-Apr-2026	16 m 10 d
Calibration Date: 07-Apr-2024										
5-12-23 051223	INSPECTION DOCUMENT 23 (NOT USED)	KSAT			MTH 24-Oct-2012 HRS 984 LDG 809		N/R			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KSAT		3-1640 0675	MTH 16-Feb-2022 HRS 2474.2 LDG 2268		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	KSAT		3-1642 0316	MTH 07-Nov-2023 HRS 2630.1 LDG 2430		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KSAT		3-1640 0685	MTH 16-Feb-2022 HRS 2474.2 LDG 2268		A/R			
5-12-30 051230	INSPECTION DOCUMENT 30	KSAT			MTH 11-Apr-2022 HRS 2487.6 LDG 2282		48 1800		30-Apr-2026 4287.6	16 m 10 d 1534.5
5-12-31 051231	INSPECTION DOCUMENT 31	KSAT			MTH 27-Jun-2023 HRS 2592.4 LDG 2386		450		3042.4	289.3
5-12-32 051232	INSPECTION DOCUMENT 32	KSAT			MTH 11-Nov-2021 HRS 2441.9 LDG 2242		72 1800		30-Nov-2027 4042	35 m 10 d 1493
5-12-35	INSPECTION DOCUMENT 35	KSAT			MTH 23-Sep-2024 HRS 2729.6 LDG 2525		6		31-Mar-2025	3 m 11 d
5-12-37	INSPECTION DOCUMENT 37				MTH 13-Oct-2009 HRS 0		7200		9315.1	6562
5-12-38	INSPECTION DOCUMENT 38	KSAT			MTH 11-Dec-2024 HRS 2751.8 LDG 2547		12			
B243000 051224B	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK)	KSAT		RG-390E/30 41405595	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		12		31-Dec-2025	12 m 11 d



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MA <i>0512MA</i>	INSPECTION DOCUMENT MA	KSAT		MTH HRS LDG	04-Feb-2021 2334 2150		500		2834	80.9
5-12-MB <i>0512MB</i>	INSPECTION DOCUMENT MB	KSAT		MTH HRS LDG	26-Jul-2016 1862.5 1638		950		2812.5	59.4
5-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC	*CF		MTH HRS	13-Oct-2009 0		4000		4000	1246.9
5-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD	KSAT		MTH HRS LDG	21-Feb-2024 2664.4 2460		12		28-Feb-2025	2 m 8 d
5-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME	KSAT		MTH HRS LDG	01-Feb-2022 2466.7 2264		36 1400		28-Feb-2025 3866.7	2 m 8 d 1113.6
5-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF	*CF		MTH HRS	13-Oct-2009 0		12000		12000	9246.9
5-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG	*CF		MTH HRS	13-Oct-2009 0		5000		5000	2246.9
5-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH	*CF		MTH HRS	13-Oct-2009 0		8250		8250	5496.9
5-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI	*CF		MTH HRS	13-Oct-2009 0		12000		12000	9246.9
5-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ	*CF		MTH HRS	13-Oct-2009 0		10600		10600	7846.9
5-12-MK <i>0512MK</i>	INSPECTION DOCUMENT MK	*CF		MTH HRS	13-Oct-2009 0		10400		10400	7646.9
057102A E1	INSPECT ENGINE FRESH WATER RINSE	KSAT		MTH HRS	23-Oct-2013 1323.7		O/C			
057102A E2	INSPECT ENGINE FRESH WATER RINSE	KSAT		MTH HRS LDG	23-Oct-2013 1463.8 1232		O/C			
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE	KSAT		MTH HRS LDG	23-May-2016 1851.1 1629		A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	13-Oct-2009		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS	13-Oct-2009		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS	13-Oct-2009		A/R			
0521009	ENVIRO SYSTEMS 500 HOUR INSPECTION	KSAT		MTH HRS LDG ACH	04-Jul-2020 2265.9 2082 0		500		500	218.2
0521009A	ENVIRO SYSTEMS 12 MONTH INSPECTION	KSAT		MTH HRS LDG	11-Dec-2024 2751.8 2547		12		31-Dec-2025	12 m 11 d
262003A LEFT <i>262003 : L</i>	REPLACE FIRE EXT CARTRIDGE	KSAT	13083-5 01/2024	MTH HRS LDG	11-Dec-2024 2751.8 2547		72	11	31-Jan-2030	61 m 11 d
262003A RIGHT <i>262003 : R</i>	REPLACE FIRE EXT CARTRIDGE	KSAT	13083-5 01/2024	MTH HRS LDG	11-Dec-2024 2751.8 2547		72	11	31-Jan-2030	61 m 11 d



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)	KSAT			MTH 11-Dec-2024 HRS 2751.8 LDG 2547		3		31-Mar-2025	3 m 11 d
32-30-40-960 051208 : LG	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KSAT		40005369-2 10243	MTH 30-Jun-2024 HRS 2706.4 LDG 2505		36		30-Jun-2027	30 m 10 d
Hydro Check Date: 30-Jun-2024										
32-40-00-960 051208 : EB	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KSAT		40005399-1 6084	MTH 16-Oct-2024 HRS 2733.5 LDG 2531		36		30-Jun-2027	30 m 10 d
Hydro Check Date: 30-Jun-2024										
35-00-00-960 051210 : OXY	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	KSAT		4441073-040 0438-073	MTH 14-Jun-2023		60		30-Jun-2028	42 m 10 d
Hydro Check Date: 14-Jun-2023										
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KSAT			MTH 04-Dec-2024 HRS 2751.8 LDG 2547		12 450		31-Dec-2025 (3153.1)3201.8	12 m 11 d 448.7
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KSAT			MTH 04-Dec-2024 HRS 2751.8 LDG 2547		12 450		31-Dec-2025 (3063.1)3201.8	12 m 11 d 448.7
710010 E1	COMPRESSOR DESALINATION WASH	SAT			MTH 23-Mar-2011 HRS 496.4 LDG 413		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010 E2	COMPRESSOR DESALINATION WASH	SAT			MTH 23-Mar-2011 HRS 586.4 LDG 483		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010A E1	DESALINATION WASH / RINSE	KSAT			MTH 04-Feb-2021 HRS 2334 LDG 2150		A/R			
710010A E2	DESALINATION WASH / RINSE	KSAT			MTH 04-Feb-2021 HRS 2334 LDG 2150		A/R			
72-00-00-620-804-01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 13-Oct-2009		A/R			
72-00-00-620-804-01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 13-Oct-2009		A/R			
72-00-00-620-804-02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 13-Oct-2009		A/R			
72-00-00-620-804-02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 13-Oct-2009		A/R			
72-00-00-620-804-03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 13-Oct-2009		A/R			
72-00-00-620-804-03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 13-Oct-2009		A/R			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-620-805-01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-805-01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-805-02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-805-02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-806-01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	13-Oct-2009		A/R			
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	13-Oct-2009		A/R			
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	13-Oct-2009		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	13-Oct-2009		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	13-Oct-2009		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	13-Oct-2009		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	13-Oct-2009		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	13-Oct-2009		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	13-Oct-2009		A/R			
720000 E1	PERFORM ENGINE OVERHAUL		MTH	13-Oct-2009	HRS 48.7	3500		(3500)3548.7	795.6
720000 E2	PERFORM ENGINE OVERHAUL		MTH	13-Oct-2009	HRS 138.7	3500		(3500)3638.7	885.6
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION ICT		MTH	14-Dec-2015	HRS 1810.7 LDG 1581	1750		(3504.5)3560.7	807.6
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION ICT		MTH	14-Dec-2015	HRS 1879.4 LDG 1654	1750		(3490.7)3629.4	876.3



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720003 E1	INSPECT LOW UTILIZATION ENGINE KSAT			MTH HRS LDG	06-Dec-2023 2641.3 2437		24		31-Dec-2025	12 m 11 d
720003 E2	INSPECT LOW UTILIZATION ENGINE KSAT			MTH HRS LDG	06-Dec-2023 2641.3 2437		24		31-Dec-2025	12 m 11 d
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER ICT			MTH HRS LDG	14-Dec-2015 1810.7 1581		1750		(3504.5)3560.7	807.6
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER KSAT			MTH HRS LDG	03-Jan-2017 1937.6 1708		1750		(3552.5)3687.6	934.5
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT KSAT			MTH HRS LDG	04-Dec-2024 2751.8 2547		12 900		31-Dec-2025 (3603.1)3651.8	12 m 11 d 898.7
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT KSAT			MTH HRS LDG	04-Dec-2024 2751.8 2547		12 900		31-Dec-2025 (3513.1)3651.8	12 m 11 d 898.7
731055 E1	REPLACE FUEL MANIFOLD UNK			35C6160-01 DEAAAA26328 MTH HRS LDG	14-Dec-2015 1810.7 1581		1750		(3504.5)3560.7	807.6
731055 E2	REPLACE FUEL MANIFOLD UNK			35C6160-01 SN-UNKNOWN MTH HRS LDG	30-May-2016 1851.1 1629		1750		(3492.8)3601.1	848
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH ICT			PN SN-UNKNOWN MTH HRS LDG	14-Dec-2015 1810.7 1581		1750		(3504.5)3560.7	807.6
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH ICT			35C3388-01 WDA103969 MTH HRS LDG	30-May-2016 1881.5 1655		1750	2.1	(3490.7)3629.4	876.3
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY ICT			PN SN-UNKNOWN MTH HRS LDG	14-Dec-2015 1810.7 1581		1750		(3504.5)3560.7	807.6
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY ICT			PN SN-UNKNOWN MTH HRS LDG	14-Dec-2015 1879.4 1654		1750		(3490.7)3629.4	876.3
790015 E1	REPLACE OIL FILTER ELEMENT KSAT			MTH HRS LDG	10-Nov-2021 2441.9 2242		900		(3293.2)3341.9	588.8
790015 E2	REPLACE OIL FILTER ELEMENT KSAT			MTH HRS LDG	10-Nov-2021 2441.9 2242		900		(3203.2)3341.9	588.8
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS KSAT			PN SN-UNKNOWN MTH HRS LDG	04-Dec-2024 2751.8 2547		6 100		30-Jun-2025 (2803.1)2851.8	6 m 10 d 98.7
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS KSAT			35C0412-01 AB0601 MTH HRS LDG	04-Dec-2024 2751.8 2547		6 100		30-Jun-2025 (2713.1)2851.8	6 m 10 d 98.7



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY. *CF			0113-12 1745	MTH 13-Oct-2009		O/C			
213001	KAPS II CONTROLLER KSAT			52811-1102 / 9912661-MTH 12 867A	30-Jan-2019 HRS 2125.5 LDG 1920		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 1234	MTH 13-Oct-2009		O/C			
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 1241	MTH 13-Oct-2009		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14 KSAT			1133610-4 171	MTH 04-Jul-2020 HRS 2265.9 LDG 2082		O/C	0 0 0		
215002	CONDENSOR ASSEMBLY 9912660-3 *CF			1134620-5 407	MTH 13-Oct-2009		O/C			
215003	RECEIVER DRYER ASSY 9912660-18 *CF			1134275-13 2423	MTH 13-Oct-2009		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 634	MTH 13-Oct-2009		O/C			
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 633	MTH 13-Oct-2009		O/C			
215005	VANE AXIAL BLOWER ASSY. KSAT			1250435-10 613	MTH 20-Jul-2014 HRS 1487.5 LDG 1270		O/C			
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD KSAT			1133610-4 171	MTH 04-Jul-2020 HRS 2265.9 LDG 2082 ACH 0			0 0 0	800	518.2
221001 AILERON	GSA 80 TORQUE SERVO KSAT			11-00877-00 66305605	MTH 11-Sep-2022 HRS 2536 LDG 2325		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO *CF			011-00877-00 66306364	MTH 13-Oct-2009		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO *CF			011-00878-10 71307089	MTH 13-Oct-2009		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO *CF			011-00878-10 71307071	MTH 13-Oct-2009		O/C			
221003 AILERON	GSM 85A SERVO MOUNT KSAT			011-0146-A2 10900102	MTH 21-Apr-2020 HRS 2249.8 LDG 2052		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT *CF			011-01436-A0 11205211	MTH 13-Oct-2009		O/C			
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT *CF			011-01436-A1 11305210	MTH 13-Oct-2009		O/C			
221003 RUDDER	GSM 85 SERVO MOUNT *CF			011-01436-A3 11005206	MTH 13-Oct-2009		O/C			
221004	GMC 710 AFCS CONTROLLER KSAT			011-01020-10 22006404	MTH 21-Nov-2017 HRS 1950 LDG 1719		O/C	0 0 0		
231002 NO. 1	GMA 1347D AUDIO PANEL *CF			011-01257-00 48405264	MTH 13-Oct-2009		O/C			
231002 NO. 2	GMA 1347D AUDIO PANEL *CF			011-01257-00 48405370	MTH 13-Oct-2009		O/C			
231003 NO. 1	VHF COMM ANTENNA *CF			VHF10-829 0613	MTH 13-Oct-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231003 NO. 2	VHF COMM ANTENNA *CF	VHF10-829 0617	MTH 13-Oct-2009		O/C			
231011	SAT PHONE ANTENNA *CF	S67-1575-109 N/A	MTH 13-Oct-2009		O/C			
231101	HIGH FREQUENCY CONTROLLER S3100-470 *CF	071-01605-0201 N/A	MTH 13-Oct-2009		O/C			
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449 *CF	064-01073-0102 N/A	MTH 13-Oct-2009		O/C			
231103	HIGH FREQUENCY ANTENNA *CF	16390 N/A	MTH 13-Oct-2009		O/C			
231104	HIGH FREQUENCY POWER AMPLIFIER *CF	064-01072-0101 N/A	MTH 13-Oct-2009		O/C			
243001 LEFT	DIGITAL GCU 9912682-3	KOPF GCSG550-5 09118836	MTH 28-Dec-2013 HRS 1361.2 LDG 1141		O/C	1361.2 1141		
243001 RIGHT	DIGITAL GCU 9912682-3	KOPF GCSG550-5 09118863	MTH 28-Dec-2013 HRS 1361.2 LDG 1141		O/C	1361.2 1141		
243002	EMER INST BATTERY KSAT	CBS24 00919	MTH 10-Apr-2024 HRS 2681 LDG 2477		O/C			
243007	MAIN SHIP BATTERY CONCORDE (LEAD ACID)	KSAT RG-390E/30 41405595	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY S3155-1 *CF	A-931F CR-39170	MTH 13-Oct-2009		O/C			
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 0653	MTH 13-Oct-2009		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 0655	MTH 13-Oct-2009		O/C			
245003	FLAP CONTROL MODULE *CF	7018916-9 0414	MTH 13-Oct-2009		O/C			
245005 LEFT	ICE PROTECTION CONTROL *CF	7018917-9 0331	MTH 13-Oct-2009		O/C			
245005 RIGHT	ICE PROTECTION CONTROL *CF	7018918-13 0374	MTH 13-Oct-2009		O/C			
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF	7018919-13 0509	MTH 13-Oct-2009		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF	7018919-13 0499	MTH 13-Oct-2009		O/C			
245008	DOOR MONITOR- *CF	7018921-8 0324	MTH 13-Oct-2009		O/C			
245009	LANDING GEAR MONITOR- *CF	7018923-12 0341	MTH 13-Oct-2009		O/C			
245010 LEFT	START CONTROL *CF	7018924-5 0668	MTH 13-Oct-2009		O/C			
245010 RIGHT	START CONTROL *CF	7018924-5 0675	MTH 13-Oct-2009		O/C			
245011	FLAP MONITOR- *CF	7018925-11 0371	MTH 13-Oct-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245012 LEFT	SPEEDBRAKE ASSY	*CF		7018926-1 0683	MTH 13-Oct-2009		O/C			
245012 RIGHT	SPEEDBRAKE ASSY	*CF		7018926-1 0655	MTH 13-Oct-2009		O/C			
245013	DIAGNOSTIC UNIT	*CF		7018927-7 0389	MTH 13-Oct-2009		O/C			
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	*CF		85-230-2 0830-926M2	MTH 13-Oct-2009		O/C			
245015	MASTER INTERIOR SSR UNIT UZ100	*CF		10747P03E25 08125237	MTH 13-Oct-2009		O/C			
245016 RIGHT	AVN BUS #1 SENSOR UZ102	*CF		10747P03E25 09025427	MTH 13-Oct-2009		O/C			
245017 LEFT	AVN SENSOR UZ103	*CF		10747P03E25 08125232	MTH 13-Oct-2009		O/C			
245018 RIGHT	AVN BUS #2 SENSOR UZ104	*CF		10747P03E25 09025423	MTH 13-Oct-2009		O/C			
245019 LEFT	IGN #1 SENSOR UZ105	*CF		10747P03E10 09025408	MTH 13-Oct-2009		O/C			
245019 RIGHT	IGN #1 SENSOR UZ106	*CF		10747P03E10 09015398	MTH 13-Oct-2009		O/C			
245020 LEFT	IGN #2 SENSOR UZ107	*CF		10747P03E10 09015396	MTH 13-Oct-2009		O/C			
245020 RIGHT	IGN #2 SENSOR UZ108	*CF		10747P03E10 09025403	MTH 13-Oct-2009		O/C			
245021	COCKPIT FAN SENSOR UZ109	*CF		10747P03E25 08125236	MTH 13-Oct-2009		O/C			
245022	CABIN FAN SENSOR UZ110	*CF		10747P03E25 09025428	MTH 13-Oct-2009		O/C			
245023 LEFT	LH BOOST PUMP SENSOR UZ114	*CF		10747P03E25 09025429	MTH 13-Oct-2009		O/C			
245023 RIGHT	RH BOOST PUMP SENSOR UZ111	*CF		10747P03E25 08125234	MTH 13-Oct-2009		O/C			
245024	CONDENSER FAN SENSOR UZ112	*CF		10747P03E25 09025431	MTH 13-Oct-2009		O/C			
245025	DC-DC CONVERTER UZ116	*CF		10747P03E10 09015395	MTH 13-Oct-2009		O/C			
245026	AVN EMERG SENSOR UZ200	*CF		10747P03E25 09025460	MTH 13-Oct-2009		O/C			
245201 LEFT	CABIN ALTITUDE MODULE	*CF		7018119-1 547	MTH 13-Oct-2009		O/C			
245201 RIGHT	CABIN ALTITUDE MODULE	*CF		7018119-1 548	MTH 13-Oct-2009		O/C			
251001	GLARESHIELD ASSEMBLY	*CF		4319027-17 132959-13	MTH 13-Oct-2009		O/C			
256001 NO. 1	LIFE VEST	KSAT		P01074-207 18081520082	MTH 02-Jan-2019 HRS 2115.1 LDG 1910		120 O/C	5	31-Aug-2028	44 m 11 d
256001 NO. 2	LIFE VEST	KSAT		P01074-207 18081520083	MTH 02-Jan-2019 HRS 2115.1 LDG 1910		120 O/C	5	31-Aug-2028	44 m 11 d
256001 NO. 3	LIFE VEST	KSAT		P01074-207 17112100104	MTH 15-May-2018 HRS 2075.8 LDG 1858		120 O/C	6	30-Nov-2027	35 m 10 d
256001 NO. 4	LIFE VEST	KSAT		P01074-207 17112100105	MTH 15-May-2018 HRS 2075.8 LDG 1858		120 O/C	6	30-Nov-2027	35 m 10 d



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256001 NO. 5	LIFE VEST	KSAT		P01074-207 22120420172	MTH 05-Jan-2023 HRS 2556.8 LDG 2338		120 O/C	1	31-Dec-2032	96 m 11 d
256001 NO. 6	LIFE VEST	KSAT		P01074-207 19041150062	MTH 25-Jun-2019 HRS 2158.7 LDG 1963		120 O/C	0	30-Jun-2029	54 m 10 d
256002	ELT BATTERY	KSAT		452-0133 399355-018	MTH 27-Jun-2023 HRS 2592.4 LDG 2386		60	3 0 0	31-Mar-2028	39 m 11 d
256003A	FIRST AID KIT --	KSAT		932-1528-61 NSN	MTH 23-Sep-2024 HRS 2729.6 LDG 2525		12	0 0 0	30-Sep-2025	9 m 10 d
256004	ELT ANTENNA	*CF		110-340 273149	MTH 13-Oct-2009		O/C			
256007 256001	ELT PROCESSOR C406N	*CF		453-5060 07400	MTH 13-Oct-2009		O/C			
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 210237	MTH 13-Oct-2009		O/C			
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 210251	MTH 13-Oct-2009		O/C			
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KSAT		30401102-2 61544B1	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		O/C	5		
262003 LEFT	FIRE EXT CARTRIDGE	KSAT		13083-5 01/2024	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		72		31-Jan-2030	61 m 11 d
Manufacture Date: 31-Jan-2024										
262003 RIGHT	FIRE EXT CARTRIDGE	KSAT		13083-5 01/2024	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		72		31-Jan-2030	61 m 11 d
Manufacture Date: 31-Jan-2024										
262004	PORTABLE FIRE EXTINGUISHER	KSAT		C352TS G-97925127	MTH 10-Nov-2021 HRS 2441.9 LDG 2242		O/C	0 0 0		
271001 LEFT	CONTROL WHEEL ASSY	*CF		4319065-1 1553	MTH 13-Oct-2009		O/C			
271001 RIGHT	CONTROL WHEEL ASSY	*CF		4319065-2 1566	MTH 13-Oct-2009		O/C			
271002 --	ELEVATOR TRIM TAB ACTUATOR			PN SN-UNKNOWN	MTH 13-Oct-2009		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 431	MTH 13-Oct-2009		O/C			
273002	AILERON TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 389	MTH 13-Oct-2009		O/C			
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1	*CF		MP50Y-1 286	MTH 13-Oct-2009		O/C			
275002 LEFT	FLAP ACTUATOR	*CF		41013930-105 677	MTH 13-Oct-2009		O/C			
275002 RIGHT	FLAP ACTUATOR	*CF		41013930-106 711	MTH 13-Oct-2009		O/C			
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-59	KSAT		140527-5900 1022	MTH 11-Apr-2022 HRS 2487.6 LDG 2282		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344.59	140527-5900 1023	MTH 11-Apr-2022 HRS 2487.6 LDG 2282		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-3	41014070-106 0488	MTH 21-Apr-2016 HRS 1851.1 LDG 1629		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-2	41014070-103 0488	MTH 13-Oct-2009		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5	LR45300A C1762	MTH 13-Oct-2009		O/C			
282001 RIGHT	PRIMARY EJECTOR 9912190-5	LR45300A C1811	MTH 13-Oct-2009		O/C			
282002	TRANSFER VALVE 9914103-6	ZSV57 08-12155	MTH 13-Oct-2009		O/C			
282003 LEFT	DC FUEL PUMP 9912553-1	1C7-23 2BE58	MTH 13-Oct-2009		O/C			
282003 RIGHT	DC FUEL PUMP 9912553-1	1C7-23 2BE88	MTH 13-Oct-2009		O/C			
282004 L1	SCAVENGE EJECTOR 9912190-2	RG45310 C1957	MTH 13-Oct-2009		O/C			
282004 L2	SCAVENGE EJECTOR 9912190-2	RG45310 C1975	MTH 13-Oct-2009		O/C			
282004 R1	SCAVENGE EJECTOR 9912190-2	RG45310 C1962	MTH 13-Oct-2009		O/C			
282004 R2	SCAVENGE EJECTOR 9912190-2	RG45310 C1982	MTH 13-Oct-2009		O/C			
282005 LEFT	VALVE-FUEL MOTOR 9912014-3	AV24B1507 193072	MTH 13-Oct-2009		O/C			
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3	AV24B1507 184078	MTH 13-Oct-2009		O/C			
284001 L1	FUEL PROBE 9912664-1	020-251-001 728	MTH 13-Oct-2009		O/C			
284001 L2	FUEL PROBE 9912664-2	020-251-002 545	MTH 13-Oct-2009		O/C			
284001 L3	FUEL PROBE 9912664-3	020-251-003 0550	MTH 23-May-2010 HRS 285 LDG 204		O/C			
284001 L4	FUEL PROBE 9912664-4	020-251-004 437	MTH 13-Oct-2009		O/C			
284001 L5	FUEL PROBE 9912664-5	020-251-005 360	MTH 13-Oct-2009		O/C			
284001 R1	FUEL PROBE 9912664-1	020-251-001 749	MTH 13-Oct-2009		O/C			
284001 R2	FUEL PROBE 9912664-2	020-251-002 532	MTH 13-Oct-2009		O/C			
284001 R3	FUEL PROBE 9912664-3	020-251-003 576	MTH 23-May-2010 HRS 285 LDG 204		O/C			
284001 R4	FUEL PROBE 9912664-4	020-251-004 436	MTH 13-Oct-2009		O/C			
284001 R5	FUEL PROBE 9912664-5	020-251-005 317	MTH 13-Oct-2009		O/C			
284002	SIGNAL CONDITIONER 9912664-6	367-350-001 1168	MTH 14-Aug-2010 HRS 342.4 LDG 250		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2 *CF	HM50C-3 308B	MTH 13-Oct-2009		O/C			
291002	HYDRAULIC CHECK VALVE *CF	4001-20 5498A	MTH 13-Oct-2009		O/C			
291003	HYDRAULIC SYS PRESSURE GAUGE *CF	19940933-1 030160	MTH 13-Oct-2009		O/C			
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4 *CF	80665 0293	MTH 13-Oct-2009		O/C			
291007	HYDRAULIC MANIFOLD 9912657-14 *CF	8257-3 0285	MTH 13-Oct-2009		O/C			
291008	HYDRAULIC RELIEF VALVE 9912657-2 *CF	2672 0287	MTH 13-Oct-2009		O/C			
291009	BRAKE PRESSURE SWITCH KSAT	9912657-3 0536	MTH 19-Mar-2021 HRS 2349.6 LDG 2163		O/C	0 0 0		
291010	HYD SOLENOID CONTROL VALVE 9912657-5 *CF	4251 283	MTH 13-Oct-2009		O/C			
291010	HYD SOLENOID CONTROL VALVE 9912657-7 *CF	4252 0283	MTH 13-Oct-2009		O/C			
291011	HYDRAULIC DUMP VALVE 9912657-15 *CF	9625-1 0288	MTH 13-Oct-2009		O/C			
291012	HYDRAULIC RESERVOIR ASSEMBLY *CF	7017005-28 AS79031	MTH 13-Oct-2009		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2 *CF	7550-2 0646	MTH 13-Oct-2009		O/C			
301001	WING DE-ICE BOOT LEFT 9912662-17	P35-4D5317-17 NCR9270	MTH 15-Dec-2015 HRS 1810.7 LDG 1581		O/C	0 0 0		
301001	WING DE-ICE BOOT RIGHT 9912662-18	P35-4D5317-18 NCS1800	MTH 15-Dec-2015 HRS 1810.7 LDG 1581		O/C	0 0 0		
301003	HORIZONTAL STAB DE-ICE BOOT LEFT KSAT	9912662-3 NDW4120	MTH 13-Sep-2017 HRS 1950 LDG 1719		O/C	0 0 0		
301003	HORIZONTAL STAB DE-ICE BOOT RIGHT KSAT	9912662-4 NDW4150	MTH 13-Sep-2017 HRS 1950 LDG 1719		O/C	0 0 0		
301004	DE-ICE PRESSURE SWITCH L1 *CF	1106P55-1 7325A	MTH 13-Oct-2009		O/C			
301004	DE-ICE PRESSURE SWITCH L2 *CF	1106P55-1 7385A	MTH 13-Oct-2009		O/C			
301004	DE-ICE PRESSURE SWITCH L3 *CF	1106P55-1 7017A	MTH 13-Oct-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R1 *CF	1106P55-1 7612A	MTH 13-Oct-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R2 *CF	1106P55-1 7365A	MTH 13-Oct-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R3 *CF	1106P55-1 7224A	MTH 13-Oct-2009		O/C			
301004	VERT DE-ICE BOOT 9912662-13	P29S4D5317-13 NEC4300	MTH 18-Sep-2017 HRS 1950 LDG 1719		O/C	0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY KSAT			5285-00-3 2235	MTH 10-Feb-2013 HRS 1071.8 LDG 897		O/C	1071.8 897		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY KSAT			5285-00-3 2261	MTH 10-Feb-2013 HRS 1071.8 LDG 897		O/C	1071.8 897		
302002 LEFT	TEMP SWITCH	*CF		1173T0759 5406	MTH 13-Oct-2009		O/C			
302002 RIGHT	TEMP SWITCH	*CF		1173T0759 5191	MTH 13-Oct-2009		O/C			
304001 L1	DE-ICE VALVE	*CF		3D2353-06 N085829	MTH 13-Oct-2009		O/C			
304001 L2	DE-ICE VALVE	*CF		3D2353-06 N084745	MTH 13-Oct-2009		O/C			
304002 LEFT	WINDSHIELD CONTROLLER KSAT			7018108-30 03058	MTH 11-Jun-2017 HRS 1987.5 LDG 1765		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER KSAT			7018108-30 0307	MTH 11-Jun-2017 HRS 1987.5 LDG 1765		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF			7041020-5 250	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF			7041020-6 251	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
321001	NOSE LANDING GEAR TRUNNION *CF			7042020-1 246	MTH 13-Oct-2009		O/C			
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY *CF			7041050-4 355	MTH 13-Oct-2009 LDG 0		12000	0	12000	9451
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY *CF			7041050-4 347	MTH 13-Oct-2009 LDG 0		12000	0	12000	9451
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF			7041030-1 253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF			7041030-2 253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK *CF			6327504-6 2705	MTH 13-Oct-2009		O/C			
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK *CF			6327504-6 2700	MTH 13-Oct-2009		O/C			
322002	NOSE GEAR FORK & PISTON ASSEMBLY *CF			7042040-1 254	MTH 13-Oct-2009		O/C			
322003 NOSE GEAR	UPLOCK ACTUATOR *CF			6327504-7 1055	MTH 13-Oct-2009		O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1	*CF		FA100036-001 FA100036-1-0314	MTH 13-Oct-2009 LDG 0		12000	0	12000	9451
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-5	KSAT		FA100104-001 FA100104-1-0281	MTH 10-Nov-2021 HRS 2441.9 LDG 2242		12000	2222	12020	9471

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains			
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains	
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR				MTH	13-Oct-2009					
RIGHT	9912653-6	*CF		FA100105-001 FA100105-1-0102	LDG	0	1	12000	0	12001	9452
322011	NOSE LANDING GEAR ACTUATOR				MTH	13-Oct-2009					
	9912654-2	*CF		FA100087-001 FA100087-1-0294	LDG	0		12000	0	12000	9451
322202	SHIMMY DAMPER	*CF		7042030-2 TSKC-0001	MTH	13-Oct-2009		O/C			
322205	LANDING GEAR STRUT ASSEMBLY				MTH	13-Oct-2009					
NOSE		*CF		7042010-4 249	LDG	0		20000	0	20000	17451
322206	LANDING GEAR DRAG BRACE ASSY				MTH	13-Oct-2009					
NOSE	CHP 4	*CF		7042120-5 3	LDG	0		20000	0	20000	17451
323001	LANDING GEAR ASSEMBLY				MTH	13-Oct-2009		O/C			
LEFT		*CF		7041010-5 NSN							
323001	LANDING GEAR ASSEMBLY				MTH	13-Oct-2009		O/C			
RIGHT		*CF		7041010-6 NSN							
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE				MTH	24-Jul-2024		288	1	30-Jun-2048	282 m 10 d
	9914678-3	KSAT		40005369-2 10243	HRS	2706.4					
					LDG	2505					
Manufacture Date: 30-Jun-2024											
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE				MTH	16-Oct-2024		288	4	31-Mar-2032	87 m 11 d
	9914678-4	KSAT		40005399-1 6084	HRS	2733.5					
					LDG	2531					
Manufacture Date: 31-Mar-2008											
323003	EMER BLOW DOWN BTL PRESSURE GAUGE				MTH	13-Oct-2009		O/C			
		*CF		19940931-1 029784							
324001	MAIN LANDING GEAR TIRE				MTH	07-Nov-2023		O/C	0		
LEFT	9912646-1	KSAT		021-523-0 3054T00464	HRS	2630.1			0		
					LDG	2430			0		
324001	MAIN LANDING GEAR TIRE				MTH	07-Nov-2023		O/C	0		
RIGHT	9912646-1	KSAT		021-523-0 3056T00454	HRS	2630.1			0		
					LDG	2430			0		
324002	NOSE LANDING GEAR TIRE				MTH	07-Nov-2023		O/C			
	9912649-1	KSAT		079-606-0 1205T00200	HRS	2630.1					
					LDG	2430					
324003	MAIN LANDING GEAR WHEEL				MTH	16-Feb-2022		O/C			
LEFT	9912645-1	KSAT		3-1640 0675	HRS	2474.2					
					LDG	2268					
324003	MAIN LANDING GEAR WHEEL				MTH	16-Feb-2022		O/C			
RIGHT	9912645-1	KSAT		3-1640 0685	HRS	2474.2					
					LDG	2268					
324004	NOSE LANDING GEAR WHEEL				MTH	07-Nov-2023		O/C			
NOSE	9912648-1	KSAT		3-1642 0316	HRS	2630.1					
					LDG	2430			2430		
324005	MAIN LANDING GEAR BRAKE ASSY				MTH	03-Mar-2020		O/C	0		
LEFT	9912645-3	KSAT		2-1706-1 0710A	HRS	2242.5			0		
					LDG	2041			0		
324005	MAIN LANDING GEAR BRAKE ASSY				MTH	02-Aug-2019		O/C			
RIGHT	9912645-3	KSAT		2-1706-1 0478A	HRS	2170.7					
					LDG	1974					
324006	SHUTTLE VALVE	*CF			MTH	13-Oct-2009		O/C			
LEFT	9914689-4			5145-1 0343							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324006 RIGHT	SHUTTLE VALVE 9914689-4	*CF 5145-1 0357	MTH 13-Oct-2009		O/C			
324007	BRAKE METERING VALVE 9912650-9	*CF 84-75 0289	MTH 13-Oct-2009		O/C			
324101 LEFT	WHEEL SPEED SENSOR 9912650-5	*CF 466-23-1 0601	MTH 13-Oct-2009		O/C			
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5	*CF 466-23-1 0605	MTH 13-Oct-2009		O/C			
324101	PARKING BRAKE VALVE 9912388-10	*CF 98433-1 0281	MTH 13-Oct-2009		O/C			
324102	ANTISKID CONTROL UNIT 9912650-1	*CF 556-3 302829384	MTH 13-Oct-2009		O/C			
324103	ANTISKID CONTROL VALVE 9912650-6	*CF 211-134-1 0280	MTH 13-Oct-2009		O/C			
324104	EMERGENCY BRAKE VALVE 9912651-1	ICT 72298 0311	MTH 03-May-2010 HRS 271.5 LDG 192		O/C	0 0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE *CF	19940931-1 029791	MTH 13-Oct-2009		O/C			
325001	BUNGE ASSEMBLY	*CF 7042072-9 NSN	MTH 13-Oct-2009		O/C			
334001 LEFT	POWER SUPPLY 9912677-3	KSAT 82004-1 000647	MTH 19-Nov-2013 HRS 1344.1 LDG 1126		O/C	1344.1 1126		
334001 RIGHT	POWER SUPPLY 9912677-3	KSAT 82004-1 000627	MTH 19-Nov-2013 HRS 1344.1 LDG 1126		O/C	1344.1 1126		
334002	GROUND RECOGNITION LIGHT 9912679-4	KSAT 84003-3 001126	MTH 09-Sep-2019 HRS 2182.4 LDG 1985		O/C	0 0 0		
334003 LEFT	ANTI-COLLISION LIGHT KSAT	9912679-7 000228	MTH 04-Jun-2013 HRS 1144.5 LDG 964		O/C	0 0		
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2	KSAT 84005-2 000257	MTH 04-Jun-2013 HRS 1144.5 LDG 964		8000	0 0	9144.5	6391.4
335169 R/H	LANDING/TAXI LIGHT ASSEMBLY KSAT	9912677-2 000854	MTH 24-May-2021 HRS 2369.2 LDG 2184		O/C	0 0 0		
341001	SWAAT UNIT 9912689-1	*CF 0863B2 330	MTH 13-Oct-2009		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM KSAT	011-01110-00 43805659	MTH 28-Sep-2011 HRS 576.4 LDG 456		O/C	9 0		
341002 NO. 2	GDC 74B AIRDATA SYSTEM *CF	011-01110-00 43805650	MTH 13-Oct-2009		O/C			
341003 NO. 1	GTP 59 OAT PROBE SYSTEM *CF	011-00978-00 47913196	MTH 13-Oct-2009		O/C			
341003 NO. 2	GTP 59 OAT PROBE SYSTEM *CF	011-00978-00 47913208	MTH 13-Oct-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
341004 LEFT	PITOT PROBE 9912678-1	0851LN 247200	MTH 02-Aug-2011 HRS 555.6 LDG 432		O/C	0 0 0		
341004 RIGHT	PITOT PROBE 9912678-1	0851LN 279845	MTH 02-Aug-2011 HRS 555.6 LDG 432		O/C	0 0 0		
342001 STANDBY	ALTIMETER S3100-465	162350-1161 178742C	MTH 13-Oct-2009		O/C			
342002 AIRSPEED	INDICATOR	261440-1143 285592A	MTH 24-Aug-2011 HRS 571.3 LDG 448		O/C	0 0 0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE KSAT	011-00831-00 46724862	MTH 09-Dec-2018 HRS 2113.9 LDG 1908		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE KSAT 1,2,3	011-00831-00 46710602	MTH 27-Nov-2018 HRS 2111.1 LDG 1904		O/C			
342003	MAGNETIC COMPASS *CF	S2800-821 NSN	MTH 13-Oct-2009		O/C			
342004 NO. 1	NO. 1 GDU 1050A DISPLAY KSAT	011-03470-10 494106038	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
342004 NO. 2	NO. 2 GDU 1050A DISPLAY KSAT	011-03470-10 494106029	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	011-00868-10 42012380	MTH 04-Oct-2011 HRS 588.7 LDG 465		O/C	588.7 465		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	011-00868-10 42012362	MTH 04-Oct-2011 HRS 588.7 LDG 465		O/C	588.7 465		
342006 NO. 1	GMU 44 MAGNETOMETER KSAT	011-00870-00 47521183	MTH 03-Mar-2020 HRS 2242.5 LDG 2041		O/C			
342006 NO. 2	GMU 44 MAGNETOMETER *CF	011-00870-00 47513786	MTH 13-Oct-2009		O/C			
342007	GDU 1550 MFD UNIT KSAT	011-03472-00 496001845	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513 *CF	4200-21 G09-10171	MTH 13-Oct-2009		O/C			
3420SD	FLIGHT STREAM 510 SD CARD KSAT	011-03595-00 402013385	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR KSAT	011-00883-20 47203138	MTH 07-Dec-2011 HRS 645.7 LDG 515		O/C	1 0		



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344002	GARMIN GDL-69A DATA LINK *CF			011-00987-00 47762035	MTH 13-Oct-2009		O/C			
345001	GPS/WAAS/XM ANTENNA KSAT			013-00245-00 27783	MTH 17-Dec-2024 HRS 2753.1 LDG 2549		O/C	0 0		
345002 RIGHT	TRANSPONDER KSAT			011-00779-21 84805407	MTH 23-Jan-2023 HRS 2560.8 LDG 2344		O/C			
345003 LEFT	TRANSPONDER KSAT			011-00779-21 84805671	MTH 19-Mar-2021 HRS 2349.6 LDG 2163		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KSAT			011-04475-00 48V000628	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
345005	ADF RECEIVER *CF			013-00166-00 N/A	MTH 13-Oct-2009		O/C			
345006	ADF ANTENNA *CF			013-00165-00 N/A	MTH 13-Oct-2009		O/C			
345007	MARKER BEACON ANTENNA *CF			MB10-754-2 272	MTH 13-Oct-2009		O/C			
345008	GLIDE SLOPE ANTENNA *CF			RGS10-48 14335	MTH 13-Oct-2009		O/C			
345009 LEFT	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 2323	MTH 13-Oct-2009		O/C			
345009 RIGHT	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 2327	MTH 13-Oct-2009		O/C			
345009 UPPER	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 2324	MTH 13-Oct-2009		O/C			
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA *CF			L10-611-14 2514	MTH 13-Oct-2009		O/C			
345010	VOR/LOC ANTENNA *CF			VT10-767-3 0893	MTH 13-Oct-2009		O/C			
345011	KN63 DME TRANSCEIVER *CF			066-01070-0001 33290	MTH 13-Oct-2009		O/C			
345013	RMI CONVERTER *CF			013-00167-00 N/A	MTH 13-Oct-2009		O/C			
345014	GPS/WAAS/ ANTENNA *CF			013-00244-00 6476	MTH 13-Oct-2009		O/C			
345015	DME ANTENNA *CF			L10-611-14 2320	MTH 13-Oct-2009		O/C			
346010	TAS PROCESSOR KSAT			066-01152-0101 KTA810-3995	MTH 02-Nov-2016 HRS 1923.4 LDG 1693		O/C			
346011 BOTTOM	TAS ANTENNA *CF			L10-611-14 2331	MTH 13-Oct-2009		O/C			
346011 TOP	TAS ANTENNA *CF			071-01599-0100 21956	MTH 13-Oct-2009		O/C			
346012	CONFIGURATION MODULE *CF			071-00112-0200 14804	MTH 13-Oct-2009		O/C			
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT *CF			011-01105-01 15W009538	MTH 13-Oct-2009		O/C			
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT KSAT			011-01105-01 15W011411	MTH 03-Apr-2023 HRS 2578.1		O/C	1 0		



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description		Part Number		C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
350001	OXYGEN BOTTLE	KSAT		4441073-040 0438-073	MTH 27-Jun-2023 HRS 2592.4 LDG 2386		180		31-Jul-2033	103 m 11 d
Manufacture Date: 01-Jul-2018										
350002	OXYGEN PRESSURE GAUGE C668512-0101	*CF		MD97-1 G09-10445	MTH 13-Oct-2009		O/C			
351001 LEFT	CREW OXYGEN MASK	KSAT		MC10-16-101 - 9914067-41 98346	MTH 16-Sep-2020 HRS 2282.5 LDG 2100		72	1	31-Aug-2026	20 m 11 d
351001 RIGHT	CREW OXYGEN MASK	KSAT		MC10-16-101 / 9914067-41 15467	MTH 23-Oct-2024 HRS 2734.7 LDG 2533		72	1	30-Sep-2030	69 m 10 d
361001 LEFT	PRECOOLER	KSAT		9914402-7 HX-02227	MTH 06-Dec-2023 HRS 2641.3 LDG 2437		O/C	0 0 0		
361001 RIGHT	PRECOOLER	KSAT		9914402-7 HX-02178	MTH 06-Dec-2023 HRS 2641.3 LDG 2437		O/C	0 0 0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY	KSAT		2601-34 0544A	MTH 17-Jul-2012 HRS 847.4 LDG 727		O/C	0 0 0		
361002 RIGHT	VARIABLE VENTURI VALVE ASSY	KSAT		2601-34 0543A	MTH 17-Jul-2012 HRS 847.4 LDG 727		O/C	0 0 0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2	*CF		1H75-23 1BD23	MTH 13-Oct-2009		O/C			
361004 LEFT	B/A SHUTOFF VALVE	KSAT		5253-00-3 1197	MTH 25-Jul-2012 HRS 856.2 LDG 735		O/C	2 0 0		
361004 RIGHT	B/A SHUTOFF VALVE	KSAT		5253-00-3 2717	MTH 17-Jul-2012 HRS 847.4 LDG 727		O/C	0 0 0		
361101 R1	DE-ICE VALVE	*CF		3D2353-06 N092714	MTH 13-Oct-2009		O/C			
361101 R2	DE-ICE VALVE	*CF		3D2353-06 N092721	MTH 13-Oct-2009		O/C			
522001	CABIN DOOR SEAL 9912674-3	*CF		S-22560-3 269	MTH 13-Oct-2009		O/C			
522002	ESCAPE HATCH SEAL 9912675-1	*CF		S-22561 355	MTH 13-Oct-2009		O/C			
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-3 0253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-4 0253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-11 0253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-10 0253	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
534101 FWD	ENGINE BEAM	*CF		7012061-3 00245	MTH 13-Oct-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
535005	RADOME	KSAT		7013010-802-1 450	MTH 04-Jun-2013 HRS 1144.5 LDG 964		O/C	0 0 0		
552001 LEFT	ELEVATOR ASSEMBLY *CF			7034001-11 172	MTH 13-Oct-2009		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY *CF			7034001-12 170	MTH 13-Oct-2009		O/C			
553001	VERTICAL STABILIZER ASSY *CF			7031001-1 221	MTH 13-Oct-2009		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) KSAT			9912745-13 20350H0740	MTH 04-Feb-2021 HRS 2334 LDG 2150		O/C	0 0 0		
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-10 *CF			NP-188601-2 09090H5650	MTH 13-Oct-2009		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1 *CF			93310-1 1585	MTH 13-Oct-2009		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2 *CF			93310-2 1606	MTH 13-Oct-2009		O/C			
562003 L1	CABIN WINDOW 9912747-10 *CF			93320-10 2464	MTH 13-Oct-2009		O/C			
562003 L2	CABIN WINDOW 9912747-10 *CF			93320-10 2498	MTH 13-Oct-2009		O/C			
562003 L3	CABIN WINDOW 9912747-10 *CF			93320-10 2734	MTH 13-Oct-2009		O/C			
562003 R1	CABIN WINDOW 9912747-10 *CF			93320-10 2518	MTH 13-Oct-2009		O/C			
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10 *CF			93320-10 2634	MTH 13-Oct-2009		O/C			
562003 R3	CABIN WINDOW 9912747-10 *CF			93320-10 2750	MTH 13-Oct-2009		O/C			
572001 LEFT WING	FWD SPAR *CF			7022022-1 72848	MTH 13-Oct-2009		O/C			
572001 RIGHT WING	FWD SPAR *CF			7022022-2 72853	MTH 13-Oct-2009		O/C			
572002 LEFT WING	REAR SPAR *CF			7022032-3 72866	MTH 13-Oct-2009		O/C			
572002 RIGHT WING	REAR SPAR *CF			7022032-4 72862	MTH 13-Oct-2009		O/C			
572003 LEFT WING	MAIN SPAR *CF			7022027-1 69792	MTH 13-Oct-2009		O/C			
572003 RIGHT WING	MAIN SPAR *CF			7022027-2 36016	MTH 13-Oct-2009		O/C			
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-5 244	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-6 245	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-9 241	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-10 236	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-5 261	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-6 257	MTH 13-Oct-2009 LDG 0		20000	0	20000	17451
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1 *CF			7051001-1 233	MTH 13-Oct-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 0992	MTH 13-Oct-2009 HRS 0		4000	0	4000	1246.9
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 0986	MTH 13-Oct-2009 HRS 0		4000	0	4000	1246.9
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF	7051001-2 299	MTH 13-Oct-2009		O/C			
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1211	MTH 13-Oct-2009 HRS 0		4000	0	4000	1246.9
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1097	MTH 13-Oct-2009 HRS 0		4000	0	4000	1246.9
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3 *CF	LM-471-SA4 LK2244	MTH 13-Oct-2009 HRS 0		8000	0	8000	5246.9
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3 *CF	LM-471-SA4 LK2190	MTH 13-Oct-2009 HRS 0		8000	0	8000	5246.9
712003 AFT	ENGINE BEAM *CF	7012066-2 00253	MTH 13-Oct-2009		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL *CF	7051001-3 251	MTH 13-Oct-2009		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL *CF	7051001-4 259	MTH 13-Oct-2009		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	35C0510-01 PCE-LB0527	MTH 15-Jan-2013 HRS 1049.4 LDG 872		E/C	1341.9		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	35C0510-01 PCE-LB0526	MTH 08-Jun-2016 HRS 1881.5 LDG 1651		E/C	1742.8		
720010 E1	FAN ROTOR *CF	35C1940-01 FRAEPKNA96	MTH 13-Oct-2009 LDG 73 ACCC YC	1	10500	0	(10500)10573	8024 8024
720010 E2	FAN ROTOR *CF	35C1940-01 FRAEPKNA91	MTH 13-Oct-2009 LDG 143 ACCC YC	1	10500	0	(10500)10643	8094 8094
721010 E1	HP TURBINE DISK *CF	35C2311-01 CRAZADMB129	MTH 13-Oct-2009 LDG 73 ACCC YC	1	5250	0	(5250)5323	2774 2774
721010 E2	HP TURBINE DISK *CF	35C2311-01 CRAZADMB116	MTH 13-Oct-2009 LDG 143 ACCC YC	1	5250	0	(5250)5393	2844 2844
721020 E1	LP TURBINE DISK *CF	35C2372-01 CRAZADLQ029	MTH 13-Oct-2009 LDG 73 ACCC YC	1	10500	0	(10500)10573	8024 8024
721020 E2	LP TURBINE DISK *CF	35C2372-01 CRAZADLQ023	MTH 13-Oct-2009 LDG 143 ACCC YC	1	10500	0	(10500)10643	8094 8094
723010 E1	IMPELLER AND SHAFT ASSEMBLY *CF	35C4888-01 AAPPIAGV2114	MTH 13-Oct-2009 LDG 73 ACCC YC	1	10500	0	(10500)10573	8024 8024
723010 E2	IMPELLER AND SHAFT ASSEMBLY *CF	35C4888-01 AAPPIAGV2113	MTH 13-Oct-2009 LDG 143 ACCC YC	1	10500	0	(10500)10643	8094 8094



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
725010 E1	HP COMPRESSOR ROTOR *CF	35C3661-01 TXA1C0307	MTH 13-Oct-2009 LDG 73 ACCC YC	1	10500	0	(10500)10573	8024 8024
725010 E2	HP COMPRESSOR ROTOR *CF	35C3661-01 FRAEPKHH152	MTH 13-Oct-2009 LDG 143 ACCC YC	1	10500	0	(10500)10643	8094 8094
726010 E1	AGB STARTER MAGNETIC SEAL ICT	35C1022-01 SN-UNKNOWN	MTH 14-Dec-2015 HRS 1810.7 LDG 1581		1750	0 0	(3504.5)3560.7	807.6
726010 E2	AGB STARTER MAGNETIC SEAL KSAT	35C1022-01 NSN	MTH 17-Jan-2017 HRS 1939.9 LDG 1712		1750	0	(3554.8)3689.9	936.8
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF	1103P0448 9047	MTH 13-Oct-2009		O/C			
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF	1103P0448 9010	MTH 13-Oct-2009		O/C			
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 *CF	TFF1573-4 0908-013	MTH 13-Oct-2009		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1 *CF	TFF1573-4 0909-022	MTH 13-Oct-2009		O/C			
731050 E1	FUEL MANIFOLD UNK	35C6160-01 DEAAAA26328	MTH 14-Dec-2015 HRS 1810.7 LDG 1581		O/C	0 0 0		
731050 E2	FUEL MANIFOLD UNK	35C6160-01 SN-UNKNOWN	MTH 30-May-2016 HRS 1851.1 LDG 1629		O/C	0 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.) *CF	35C0794-04 16565812	MTH 13-Oct-2009		H/T H/T			
732101 E2	FUEL METERING UNIT (F.M.U.) *CF	35C0794-04 16584742	MTH 13-Oct-2009		H/T H/T			
733010 E2	FUEL FILTER IMPENDING BYPASS SWITCH UNK	35C3388-01 WDA103969	MTH 30-May-2016 HRS 1851.1 LDG 1629		O/C			
741001 E1	IGNITION EXCITER *CF	35C5472-01 WDA1089889	MTH 13-Oct-2009		O/C			
741001 E2	IGNITION EXCITER KSAT	35C2353-02 WDA145272	MTH 06-Dec-2023 HRS 2641.3 LDG 2437		O/C	0 0 0		
741002 E1 LEFT	IGNITER CABLE *CF	35C0844-01 NSN	MTH 13-Oct-2009		O/C			
741002 E2 LEFT	IGNITER CABLE *CF	35C0844-01 NSN	MTH 13-Oct-2009		O/C			
741003 E1 RIGHT	IGNITER CABLE *CF	35C0799-01 NSN	MTH 13-Oct-2009		O/C			
741003 E2 RIGHT	IGNITER CABLE *CF	35C0799-01 NSN	MTH 13-Oct-2009		O/C			
741004 E1 INBOARD	SPARK IGNITER KSAT	35C2353-02 WDA147027	MTH 06-Dec-2023 HRS 2641.3 LDG 2437		O/C	0 0 0		
741004 E2 INBOARD	SPARK IGNITER KSAT	35C2353-02 WDA145064	MTH 06-Dec-2023 HRS 2641.3 LDG 2437		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
741005 E1 OUTBOARD	SPARK IGNITER	ICT	35C2353-01 WDA108358	MTH HRS LDG	02-May-2010 320.2 265	O/C	0 0		
741005 E2 OUTBOARD	SPARK IGNITER	KSAT	35C2353-02 N/A	MTH HRS LDG	02-Jan-2019 2115.1 1910	O/C	0 0 0		
751003 E1	BLEED VALVE ACTUATOR	*CF	35C2851-02 16613654	MTH	13-Oct-2009	H/T H/T			
751003 E2	BLEED VALVE ACTUATOR	*CF	35C2851-02 16602011	MTH	13-Oct-2009	H/T H/T			
761001 E1	FADEC	KSAT	01R35C4035-04 09-693	MTH HRS LDG	24-Oct-2012 1032.7 882	O/C			
761001 E2	FADEC	KSAT	35C4035-04 09-706	MTH HRS LDG	08-Jun-2016 1881.5 1651	O/C	1742.8 1512		
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)	ICT	35C3778-03 SN-UNKNOWN	MTH HRS LDG	06-Feb-2010 232.3 205	H/T H/T H/T			
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)	UNK	10340H WA36505	MTH HRS LDG	30-May-2016 1851.1 1629	H/T H/T H/T	1742.8		
793001 E1	OIL TEMP SENSOR	*CF	102-00083 07329	MTH	13-Oct-2009	O/C			
793001 E2	OIL TEMP SENSOR	*CF	102-00083 07362	MTH	13-Oct-2009	O/C			
793002 E1	OIL PRESSURE TRANSMITTER	KSAT	APTE-598-1000-250G 9080-7-815	MTH HRS LDG	11-Dec-2024 2751.8 2547	O/C	0 0 0		
793002 E2	OIL PRESSURE TRANSMITTER	KSAT	APTE-598-1000-250G 9080-7-821	MTH HRS LDG	11-Dec-2024 2751.8 2547	O/C	0 0 0		
793010 E1	CHIP COLLECTOR		PN SN-UNKNOWN	MTH	13-Oct-2009	O/C	0		
793010 E2	CHIP COLLECTOR	UNK	35C0412-01 AB0601	MTH HRS LDG	30-May-2016 1851.1 1629	O/C			
793050 E2	OIL FILTER IMPENDING BYPASS INDICATOR	UNK	35C4333-01 WDA9513	MTH HRS LDG	30-May-2016 1851.1 1629	O/C			
801000 LEFT	STARTER GENERATOR	KSAT	9912676-1 597D	MTH HRS LDG	30-Jul-2019 2169.6 1972	1500	0	3669.6	916.5
801000 RIGHT	STARTER GENERATOR	KSAT	9912676-1 798D	MTH HRS LDG	30-Jul-2019 2169.6 1972	1500	0	3669.6	916.5



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC :									
	NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0061 THRU -0181.									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT	KSAT		RECOMMENDED	MTH 13-Aug-2019 HRS 2170.7 LDG 1974		-			N/A
	MOC : NOT APPLICABLE - VERIFIED SL510-21-04 DOES NOT AFFECT CURRENT CABIN PRESSURIZATION CONTROLLER INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.									
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT			OPTIONAL			A/R			
	MOC :									
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION			MANDATORY			A/R			
	MOC :									
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION	SAT		MANDATORY	MTH 19-Oct-2010 HRS 379.4 LDG 282		A/R			Complete
	MOC : COMPLIED WITH - C/W SL510-24-10 JUL 29/2010.									
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION			MANDATORY	MTH		A/R			Complete
	MOC : COMPLIED WITH - PREVIOUSLY PER COMPLIANCE WITH EARLIER ISSUE									
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)	SAT		MANDATORY	MTH 19-Oct-2010 HRS 379.4 LDG 282		A/R			N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1									
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION	SAT		MANDATORY	MTH 19-Oct-2010 HRS 379.4 LDG 282		A/R			Complete
	MOC : COMPLIED WITH - C/W SL510-24-12 JUL 29/2010.									
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION	KSAT		MANDATORY	MTH 07-Dec-2011 HRS 645.7 LDG 515		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-24-13 ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION SERVICE LETTER DATED JUNE 30, 2011									
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION	KSAT		MANDATORY	DAYS 11-Jun-2017 HRS 1987.5 LDG 1765		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL510-24-14 - PRINTED CIRCUIT BOARD VERIFICATION, REVISION 1, DATED SEPTEMBER 28, 2016									
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)			MANDATORY	DAYS		-			
	MOC :									
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER			DISCRETIONARY			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS OPTIONAL						-			
	MOC :									
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION SAT			MANDATORY	DAYS 19-Oct-2010 HRS 379.4 LDG 282		A/R			Complete
	MOC :									
	COMPLIED WITH - C/W SL510-25-02 MAY 12/2010.									
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION SAT			RECOMMENDED	MTH 08-May-2013 HRS 1144.5 LDG 964		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-27-02 DATED FEB. 27, 2013.									
SB 510-28-02 28SB-02	LOCKING FUEL CAP INSTALLATION ICT			OPTIONAL	MTH 02-May-2010 HRS 271.5		A/R			
	MOC :									
	- OPEN LOCKING FUEL CAP INSTALLATION, NEEDS TO BE LISTED ON CESCOM AS NOT ACCOMPLISHED									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL						-			
	MOC :									
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT DISCRETIONARY						-			
	MOC :									
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01) DISCRETIONARY						-			
	MOC :									
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT KSAT			DISCRETIONARY	MTH 07-Dec-2011 HRS 645.7 LDG 515		A/R			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB510-30-03 R1 ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT SERVICE BULLETIN									
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01) DISCRETIONARY						A/R			
	MOC :									
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT MANDATORY				MTH		A/R			Complete
	MOC :									
	COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.									
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION KSAT			MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION SERVICE BULLETIN 510 30-05.									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT KSAT			RECOMMENDED	MTH 11-Jun-2017 HRS 1987.5 LDG 1765		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-30-06 - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT, REVISION 1, DATED AUGUST 3, 2016									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01) RECOMMENDED				MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
	INFORMATIONAL									
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)									
	INFORMATIONAL									
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
	INFORMATIONAL									
	MOC :									
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION									
			MANDATORY	MTH			A/R		N/A	
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
	INFORMATIONAL									
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
	INFORMATIONAL									
	MOC :									
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION									
	SAT	RECOMMENDED	MTH	08-May-2013			-		Complete	
			HRS	1144.5						
			LDG	964						
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL510-32-05 DATED APRIL 20, 2012.									
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION									
	KSAT	MANDATORY	DAYS	18-May-2017			-		Complete	
			HRS	1950						
			LDG	1719						
	MOC : COMPLIED WITH - COMPLEID WITH SERVICE LETTER 510-32-07 MAIN LANDING GEAR BRAKE VERIFICATION, DATED FEBRUARY 17, 2017.									
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY									
	KSAT	MANDATORY	DAYS	15-May-2018			-		Complete	
			HRS	2075.8						
			LDG	1858						
	MOC : COMPLIED WITH - COMPLIED WITH SL510-32-08, INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS IAW GOODRICH SERVICE BULLETIN 2-1706-1-32-1. VERIFIED CORRECT WEAR PINS ARE INTALLED. NO FURTHER ACTION REQUIRED.									
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT									
	OPTIONAL									
	MOC :									
SB 510-34-10 34SB-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION									
	*CF	OPTIONAL	MTH				A/R			
	MOC :									
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE									
	KSAT	MANDATORY	MTH	07-Dec-2011			A/R		Complete	
			HRS	645.7						
			LDG	515						
	MOC : COMPLIED WITH - COMPLIED WITH SB510-34-11 R1 NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE SERVICE BULLETIN									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01)	KSAT	MANDATORY	MTH 24-May-2011 HRS 493 LDG 380			A/R			Complete
MOC : COMPLIED WITH - C/W SB510-34-11 GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE.										
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	KSAT	MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH GARMIN DISPLAY IMPROVEMENT SERVICE BULLETIN 510-34-12 REVISION 1.DATED FEB 13, 2012.										
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)		MANDATORY	MTH			-			
MOC :										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	KSAT	MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE SERVICE BULLETIN 510-34-14.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE	KSAT	MANDATORY	MTH 02-Nov-2016 HRS 1923.4 LDG 1693			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB 510-34-17 R1 GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE DATED SEPTEMBER 28, 2016.										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)	KSAT	OPTIONAL	MTH 02-Nov-2016 HRS 1923.4 LDG 1693			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB 510-34-17 R1 GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE DATED SEPTEMBER 28, 2016.										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)		OPTIONAL				-			
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE		OPTIONAL				-			
MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE	KSAT	RECOMMENDED	MTH 04-Feb-2021 HRS 2334 LDG 2150			-			N/A
MOC : NOT APPLICABLE - GARMIN G1000 NXI INSTALLED.										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE		INFORMATIONAL				-			
MOC :										
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A		INFORMATIONAL				A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	KSAT		RECOMMENDED	MTH 07-Dec-2011 HRS 645.7 LDG 515		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-34-15: TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX68 WEATHER RADAR MOD 1.									
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL			-			
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL			-			
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	KSAT		RECOMMENDED	MTH 15-May-2018 HRS 2075.8 LDG 1858		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH GARMIN DATABASE CARD REPLACEMENT IAW SL510-34-23. OPERATIONAL CHECK SATISFACTORY.									
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL			-			
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL			-			
	MOC :									
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG			INFORMATIONAL			-			
	MOC :									
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KSAT		MANDATORY	MTH 20-Jan-2016 DAYS 1812.8 HRS 1582 LDG		-			N/A
MOC : NOT APPLICABLE - THIS SIL IS NOT APPLICABLE DUE TO NOT HAVING MANUFACTURED ITEMS INSTALLED.										
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)			MANDATORY			-			
MOC :										
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	KSAT		MANDATORY	MTH 07-Dec-2011 HRS 645.7 LDG 515		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-35-01 OXYGEN INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY SERVICE BULLETIN. PN MC10-16-101, SN SE27523, PN MXH 15-22, NO BATCH #, MFG DATE 0807S. PN MC10-16-101, SN SE27900, PN MXH 15-22, NO BATCH #, MFG DATE 0809S.										
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W AT PRODUCTION ON -0095 AND ON.										
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	KSAT		MANDATORY	DAYS 29-Jan-2020 HRS 2224.2 LDG 2026		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT IAW MSB510-52-06. NO FURTHER ACTION REQUIRED.										
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION			MANDATORY	MTH		A/R			Complete
MOC : COMPLIED WITH - PARTIALLY AT MFG THIS SL IS COMPLIED WITH IN PRODUCTION ON SERIAL NUMBERS -0200 AND ON.										
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
MOC :										
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT	KSAT		MANDATORY	DAYS 18-Dec-2019 HRS 2210.2 LDG 2016		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH INNER ESCAPE HATCH HANDLE BOLT AND NUT INSPECTION AND TORQUE IAW SL510-52-06. NO FURTHER ACTION REQUIRED.										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS	KSAT		DISCRETIONARY	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PYLON SKIN IMPROVEMENT ON RIGHT PYLON ONLY IAW SERVICE BULLETIN 510-54-01 REV 01.										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)			MANDATORY			A/R			
MOC :										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)	SAT		MANDATORY	DAYS 23-Mar-2011 HRS 447.7 LDG 340		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-55-02: HORIZONTAL STABILIZER SEALANT INSPECTION.										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS	*CF		CATEGORY 5	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS	*CF		CATEGORY 5	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE	*CF		CATEGORY 9	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE	*CF		CATEGORY 9	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING	*CF		CATEGORY 5	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING	*CF		CATEGORY 5	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE	*CF		CATEGORY 9	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE	*CF		CATEGORY 9	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)	*CF		CATEGORY 6	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)	*CF		CATEGORY 6	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)	*CF		CATEGORY 9	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)	*CF		CATEGORY 9	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY	*CF		CATEGORY 9	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY	*CF		CATEGORY 9	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)	*CF		CATEGORY 5	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)	*CF		CATEGORY 5	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63043 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)	*CF		CATEGORY 6	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)	*CF		CATEGORY 6	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6				-			
	MOC :							
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) *CF	CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) *CF	CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7				A/R			
	MOC :							
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7				A/R			
	MOC :							
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) *CF	CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) *CF	CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7				-			
	MOC :							
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7				-			
	MOC :							
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) *CF	CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) *CF	CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER *CF	CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER *CF	CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST CATEGORY 9				-			
	MOC :							
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST CATEGORY 9				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	*CF		CATEGORY 6	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	*CF		CATEGORY 6	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)	*CF		CATEGORY 6	MTH 20-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)	*CF		CATEGORY 6	MTH 17-Aug-2009		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH		A/R			
	MOC :									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH		A/R			
	MOC :									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTc LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
	MOC :									
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
	MOC :									
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5						A/R			
	MOC :									
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5						A/R			
	MOC :									
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01) CATEGORY 5						A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTc LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01) CATEGORY 5				A/R			
MOC :								
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7				-			
MOC :								
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7				-			
MOC :								
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63087 R01 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02) KSAT CATEGORY 3		MTH 24-Oct-2012 HRS 1032.7 LDG 882		-			Complete
MOC : COMPLIED WITH - SB510-76-01 REV 1 SUPERSEDED BY SB510-76-01 REV 2.								
SB PW600-72-63087 R01 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02) KSAT CATEGORY 3		MTH 24-Oct-2012 HRS 1122.7 LDG 952		-			Complete
MOC : COMPLIED WITH - SB510-76-01 REV 1 SUPERSEDED BY SB510-76-01 REV 2.								



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KSAT		CATEGORY 3	MTH 24-Oct-2012 HRS 1032.7 LDG 882		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 REV 2 TRANSMITTAL OF P&W SB PW600-72-63087. OPS CHECK GOOD, FLIGHT MANUAL UPDATED.										
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KSAT		CATEGORY 3	MTH 24-Oct-2012 HRS 1122.7 LDG 952		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 REV 2 TRANSMITTAL OF P&W SB PW600-72-63087. OPS CHECK GOOD, FLIGHT MANUAL UPDATED.										
SB PW600-72-63087 E1	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)	KSAT		CATEGORY 3	MTH 24-Oct-2012 HRS 1032.7 LDG 882		-			Complete
MOC : COMPLIED WITH - SB510-76-01 SUPERSEDED BY SB510-76-01R2.										
SB PW600-72-63087 E2	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)	KSAT		CATEGORY 3	MTH 24-Oct-2012 HRS 1122.7 LDG 952		-			Complete
MOC : COMPLIED WITH - SB510-76-01 SUPERSEDED BY SB510-76-01 REV 2.										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
MOC :										
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
MOC :										
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
MOC :										
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			
	MOC :									
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			
	MOC :									
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6						-			
	MOC :									
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6						-			
	MOC :									
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6						-			
	MOC :									
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6						-			
	MOC :									
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
	MOC :									
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
	MOC :									
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		RECOMMENDED	MTH 14-Dec-2015 HRS 1810.7 LDG 1581		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		RECOMMENDED	MTH 14-Dec-2015 HRS 1879.4 LDG 1654		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL	UNK		RECOMMENDED	MTH 14-Dec-2015 HRS 1810.7 LDG 1581		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL	UNK		RECOMMENDED	MTH 14-Dec-2015 HRS 1879.4 LDG 1654		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5						-			
MOC :										
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5						-			
MOC :										
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5						-			
MOC :										
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5						-			
MOC :										
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3				MTH		-			
MOC :										
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3				MTH		-			
MOC :										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL KSAT CATEGORY 3				MTH 10-Nov-2021 HRS 2441.9 LDG 2242		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW600-72-63112 INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL IAW PRATT AND WHITNEY SERVICE BULLETIN ACCOMPLISHMENT INSRTUCTIONS DATED 03/2021.										
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL KSAT CATEGORY 3				MTH 10-Nov-2021 HRS 2441.9 LDG 2242		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW600-72-63112 INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL IAW PRATT AND WHITNEY SERVICE BULLETIN ACCOMPLISHMENT INSRTUCTIONS DATED 03/2021.										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 7						-			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 7						-			
MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 5						-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 5						-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7						-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
MOC :										
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
MOC :										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
MOC :										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
MOC :										
ASL 510-73-01 LEFT 73ASL01 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MANDATORY	HRS	-25	A/R			
ASL510-73-01 IS BEING SUPERCEDED BY ASL510-73-02. PLEASE DO NOT DO ASL510-73-01 DUE TO PENDING RELEASE OF ASL510-73-03.										
MOC :										
ASL 510-73-01 RIGHT 73ASL01 : R	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MANDATORY	HRS	175	-			
ASL510-73-01 IS BEING SUPERCEDED BY ASL510-73-02. PLEASE DO NOT DO ASL510-73-01 DUE TO PENDING RELEASE OF ASL510-73-03.										
MOC :										
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT		MANDATORY	MTH 06-Feb-2010 HRS 183.6 LDG 132		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED ASL510-73-02 "TRANSMITTAL OF P&WC SB600-72-A63071 ON 2/6/2010										
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT		MANDATORY	MTH 06-Feb-2010 HRS 183.6 LDG 132		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED ASL510-73-02 "TRANSMITTAL OF P&WC SB600-72-A63071" ON 2/6/2010										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY	UNK		CATEGORY 7	MTH 14-Dec-2015 HRS 1810.7 LDG 1581		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY	UNK		CATEGORY 7	MTH 14-Dec-2015 HRS 1879.4 LDG 1654		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
SB PW600-72-63082 E2	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTc LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3			A/R			
MOC :										
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.										
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.										
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	*CF		CATEGORY 3	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	*CF		CATEGORY 3	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63069 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	ICT		CATEGORY 3	MTH 07-Dec-2009 HRS 161.7		-			Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63069 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	ICT		CATEGORY 3	MTH 07-Dec-2009 HRS 251.7		-			Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63071 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01)	ICT		CATEGORY 3	MTH 06-Feb-2010 HRS 232.3 LDG 205		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED PRATT & WHITNEY SB PW600-72-A63071, FUEL OIL HEATER EXCHANGER FUEL-FLITER BYPASS VALVE REPLACEMENT. OPERATION AND LEAK CHECKS GOOD.										
ASB PW600-72-A63071 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01)	ICT		CATEGORY 3	MTH 06-Feb-2010 HRS 322.3 LDG 275		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED PRATT & WHITNEY SB PW600-72-A63071, FUEL OIL HEATER EXCHANGER FUEL-FLITER BYPASS VALVE REPLACEMENT. OPERATION AND LEAK CHECKS GOOD.										
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN	*CF		CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN	*CF		CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 8	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 8	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) *CF			CATEGORY 8	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) *CF			CATEGORY 8	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS *CF			CATEGORY 6	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS *CF			CATEGORY 6	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
MOC : COMPLIED WITH										
SB 510-76-01 REV 01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 (SUPERSEDED BY 510-76-01 REV 02) KSAT			MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809		-			Complete
MOC : COMPLIED WITH - SB510-76-01 REV 1 SUPERSEDED BY SB510-76-01 REV 2.										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 KSAT			MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 REV 2 TRANSMITTAL OF P&W SB PW600-72-63087. OPS CHECK GOOD, FLIGHT MANUAL UPDATED.										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-76-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETINPW600-72-63087 (SUPERSEDED BY 510-76-01 REV 01)	KSAT		MANDATORY	MTH 24-Oct-2012 HRS 984 LDG 809		-			Complete
	MOC : COMPLIED WITH - SB510-76-01 SUPERSEDED BY SB510-76-01R2.									
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS	*CF		CATEGORY 8	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS	*CF		CATEGORY 8	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT	KSAT		OPTIONAL	MTH 11-Dec-2024 HRS 2751.8 LDG 2547		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH OIL PRESSURE TRANSDUCER REPLACEMENT IAW SB 510-79-03. LEAK AND OPERATIONAL CHECK SATISFACTORY.									
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION	KSAT		MANDATORY	DAYS 24-May-2011 HRS 493 LDG 380		A/R			Complete
	MOC : COMPLIED WITH - C/W SL510-79-02 OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION.									
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB PW600-72- 63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72- 63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72- 63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-72- 63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-79- 63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01) *CF				MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01) *CF				MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79- 63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER *CF			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79- 63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH *CF			CATEGORY 7	MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH *CF			CATEGORY 7	MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01) *CF				MTH 20-Aug-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79- 63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01) *CF				MTH 17-Aug-2009		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM	KSAT	RECOMMENDED	MTH 30-Jul-2019 HRS 2169.6 LDG 1972			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-80-02, IAW SERVICE LETTERS ACCOMPLISHMENT INSTRCUTIONS, DATED MARCH 5, 2019.										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS		CANCELLED				-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS		CANCELLED				-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)		CANCELLED				-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW		CANCELLED				-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS		INFORMATIONAL				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KSAT		MANDATORY	MTH 16-Jul-2015 HRS 1718.6 LDG 1498		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THE PARTS REFERRED TO NOT INSTALLED.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KSAT		MANDATORY	MTH 16-Jul-2015 HRS 1718.6 LDG 1498		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THE PARTS REFERRED TO NOT INSTALLED.										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KSAT		MANDATORY	MTH 16-Jul-2015 HRS 1718.6 LDG 1498		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THE PARTS REFERRED TO NOT INSTALLED.										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KSAT		MANDATORY	MTH 16-Jul-2015 HRS 1718.6 LDG 1498		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THE PARTS REFERRED TO NOT INSTALLED.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KSAT			MTH 14-Nov-2018 HRS 2106.2 LDG 1900		-			N/A
MOC : NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KSAT		MANDATORY	MTH 14-Nov-2018 HRS 2106.2 LDG 1900		-			N/A
MOC : NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KSAT		MANDATORY	MTH 14-Nov-2018 HRS 2106.2 LDG 1900		-			N/A
MOC : NOT APPLICABLE - FAA AD 2017-16-01 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT MANDATORY									
MOC :										
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI WITH SERVICABLE UNIT									
	ICT			MANDATORY	DAYS 03-May-2010		A/R			N/A
					HRS 271.5					
					LDG 192					
MOC : NOT APPLICABLE										
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER									
	ICT			MANDATORY	DAYS 03-May-2010		A/R			N/A
					HRS 271.5					
					LDG 192					
MOC : NOT APPLICABLE										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI									
	ICT			MANDATORY	MTH 03-May-2010		A/R			N/A
					HRS 271.5					
					LDG 192					
MOC : NOT APPLICABLE - ACCOMPLISHED AD2010-04-16, EFFECTIVE DATE MARCH/8/2010, SICLI HALON 1211 PORTABLE FIRE EXTINGUISHERS. AIRCRAFT CURRENTLY HAS AMEREX MODEL C352 FIRE EXTINGUISHERS INSTALLED. NOACTION REQUIRED.										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS MANDATORY									
MOC :										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH									
	KSAT			MANDATORY	DAYS 15-May-2018		-			Complete
					HRS 2075.8					
					LDG 1858					
MOC : COMPLIED WITH - COMPLIED WITH AD 2018-07-13, INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS IAW GOODRICH SERVICE BULLETIN 2-1706-1-32-1. VERIFIED CORRECT WEAR PINS ARE INTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION									
	ICT			MANDATORY	MTH 15-Dec-2015		-			N/A
					HRS 1810.7					
					LDG 1581					
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2014-18-01 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION, EFFECTIVE DATE OCTOBER 14, 2014. THIS AD DOES NOT APPLY TO THISAIRCRAFT DUE TO AFFECTED EQUIPMENT IS NOT INSTALLED.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.									
	ICT			MANDATORY	MTH 15-Dec-2015		-			N/A
					HRS 1810.7					
					LDG 1581					
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-51-E AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) - INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS, EFFECTIVE DATE JULY 1,2015. THIS AD DOES NOT APPLY TO THIS AIRCRAFT DUE AFFECTED EQUIPMENT IS NOT INSTALLED.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS									
	ICT			MANDATORY	MTH 15-Dec-2015		-			N/A
					HRS 1810.7					
					LDG 1581					
MOC : NOT APPLICABLE - ACCOMPLISHED FAA AD 2015-10-51 AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) - INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS, EFFECTIVE DATE JULY 1, 2015.THIS AD DOES NOT APPLY TO THIS AIRCRAFT DUE AFFECTED EQUIPMENT IS NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011							
	KSAT	MANDATORY	MTH 29-Jun-2015 HRS 1696.4 LDG 1483		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO NOT HAVING THE EQUIPMENT OUTLINED IN AD 2015-08-07 INSTALLED.								
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES							
	KSAT	MANDATORY	MTH 29-Jun-2015 HRS 1696.4 LDG 1483		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO NOT HAVING THE EQUIPMENT OUTLINED IN AD 2015-08-07 INSTALLED.								
FAA 2015-08-07	APLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES							
	KSAT	MANDATORY	MTH 29-Jun-2015 HRS 1696.4 LDG 1483		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO NOT HAVING THE EQUIPMENT OUTLINED IN AD 2015-08-07 INSTALLED.								
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING THE MANUFACTURED ITEMS INSTALLED.								
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING MANUFACTURED ITEMS INSTALLED.								
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING MANUFACTURED ITEMS INSTALLED.								
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING MANUFACTURED ITEMS INSTALLED.								
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING MANUFACTURED ITEMS INSTALLED.								
FAA 2015-23-09	APLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS							
	KSAT	MANDATORY	MTH 20-Jan-2016 HRS 1812.8 LDG 1582		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE DUE TO NOT HAVING THE MANUFACTURED ITEMS INSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 07-Jul-2016 HRS 1881.5 LDG 1651		-			N/A
	MOC : NOT APPLICABLE - THE MANUFACTURER OF PBE EQUIPMENT OUTLINED IN THIS AD IS NOT INSTALLED. AD 2016-11-26 IS NOT APPLICABLE.							
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY			-			
	MOC :							
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 07-Jul-2016 HRS 1881.5 LDG 1651		-			N/A
	MOC : NOT APPLICABLE							
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY			-			
	MOC :							
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY	MTH 22-Jan-2018 HRS 1950 LDG 1719		-			N/A
	MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2017-18-12 IS NOT APPLICABLE TO THIS AIRPLANE. AFFECTED PBE IS NOT INSTALLED.							
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY	MTH 22-Jan-2018 HRS 1950 LDG 1719		-			N/A
	MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2017-18-12 IS NOT APPLICABLE TO THIS AIRPLANE. AFFECTED PBE IS NOT INSTALLED.							
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	MANDATORY	MTH 22-Jan-2018 HRS 1950 LDG 1719		-			N/A
	MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2017-18-12 IS NOT APPLICABLE TO THIS AIRPLANE. AFFECTED PBE IS NOT INSTALLED.							
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	MANDATORY	MTH 22-Jan-2018 HRS 1950 LDG 1719		-			N/A
	MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2017-18-12 IS NOT APPLICABLE TO THIS AIRPLANE. AFFECTED PBE IS NOT INSTALLED.							
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR	MANDATORY	MTH 06-Feb-2010 HRS 232.3 LDG 205		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED TRANSPORT CANADA AIRWORTHINESS DIRECTIVE CF-2010-03, FUEL OIL HEATER EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR, EFFECTIVE DATE 25/JANUARY/2010. P&WC ALERTSERVICE BULLETIN PW600-72-A63071, DATED DEC/9/2009 HAS BEEN ACCOMPLISHED ON THIS ENGINE. NO ADDITIONAL ACTION REQUIRED.							



CESCOM 10 - Aircraft Status Report

Owner: **LMTC LEASING, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0253**
Unit: **0253** Reg No: **N54CF**
Airworthiness: **13-Oct-2009**
Print Date: **20-Dec-2024 3:10PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2753.1	2549	17-Dec-2024	.3
ENG 1	2704.4	2476	17-Dec-2024	.3
ENG 2	2614.4	2406	17-Dec-2024	.3
AIR COND	281.8		17-Dec-2024	.25

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
TCCA CF-2010-03 E2	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR	UNK	MANDATORY	MTH 30-May-2016 HRS 1851.1 LDG 1629		-				Complete
MOC : COMPLIED WITH										
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	KSAT	MANDATORY	MTH 19-Oct-2010 HRS 428.1 LDG 355		-				Complete
MOC : COMPLIED WITH - AD2010-17-06 REPLACEMENT OF FUEL OIL HEAT EXCHANGER FUEL FILTER BYPASS VALVE REPLACEMENT PREVIOUSLY COMPLIED WITH BY WICHITA SERVICE CENTER APPLICATION OF P&WC SB600-72-A63071 6/FEB/2010. REFERENCE PAR (F) OF AD2010-17-06.										
FAA 2010-17-06 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	KSAT	MANDATORY	MTH 19-Oct-2010 HRS 518.1 LDG 425		-				Complete
MOC : COMPLIED WITH - PREVIOUSLY AD2010-17-06 REPLACEMENT OF FUEL OIL HEAT EXCHANGER FUEL FILTER BYPASS VALVE REPLACEMENT PREVIOUSLY COMPLIED WITH BY WICHITA SERVICE CENTER APPLICATION OF P&WC SB600-72-A63071 6/FEB/2010. REFERENCE PAR (F) OF AD2010-17-06.										