



DueList Report

PHENOM 300

S/N 50500042 N479MA

OWNER: HOWARD AIR, LLC
ADDRESS: 5783 AH MAY TAH RD
OSHKOSH WI 54901

OPERATOR: MAXAIR INC.
ADDRESS: 1257 W 20TH AVE
OSHKOSH WI 54902

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: OBUM ONWUDIWE
EMAIL: OONWUDIWE@CAMPSYSTEMS.COM

(514)448-1163 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 12 MOS. to 13-NOV-2025

AIRCRAFT	SERIAL / REGNO: 50500042/N479MA			MODEL:	PHENOM 300		MANUFACTURER: EMBRAER	
CERTIFICATION DATE: 15-SEP-2010				LAST ACTUALS:			PROJECTED:	
				3793.5	A/C HRS	as of 13-NOV-2024	4993.50	
				2782	AFL	as of 13-NOV-2024	3442	
				98	CDMHRS	as of 10-OCT-2024	110	
ENGINE NO. 1	SERIAL / PART: PCE-DG0072/A3072913-01			MODEL:	PW535E		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 25-NOV-2010				LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0 A/C HRS		3793.5	ENG. HRS	as of 13-NOV-2024	4993.50	
0	ENC			2785	ENC	as of 13-NOV-2024	3025	
ENGINE NO. 2	SERIAL / PART: PCE-DG0069/A3072913-01			MODEL:	PW535E		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 25-NOV-2010				LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0 A/C HRS		3793.5	ENG. HRS	as of 13-NOV-2024	4993.50	
0	ENC			2785	ENC	as of 13-NOV-2024	3025	



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
35-11-00-001		OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	12 (+30d/-30d)	08-Nov-23	Adj:2d	10-Nov-24	10-Dec-24	TOL (+27 d)	13-Nov-2024(2)	12.2
	HRS	800 (+30/-30)	3248.1		4048.1	4078.1	254.6 (+30)		545.4
	AFL		2378						404
Disposition: AIRWORTHINESS			REF: AMM 35-11-02						
00-CUS-001 ^U		30 DAY/MONTHLY CHECKLIST							Service ATA:00
	DAYS	30 (+5)	18-Oct-24		17-Nov-24	22-Nov-24	4 d (+5)	17-Nov-2024(13)	26 d
	HRS		3763.8						29.7
	AFL		2756						26
			REF:						
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:7450LS-00	MOS	12	28-Nov-23		28-Nov-24		15 d	28-Nov-2024	11.5
SN:005366	HRS		3287.2						506.3
	AFL		2408						374
			REF: AMM 33-52-01						
25-00-00-001 ^U		DISCARD ORION SKYBLAZER II RED AERIAL SIGNAL FLARES KIT (4EA)							Service ATA:25
	MOS	DUE	01-Oct-21		31-Jan-25 (M)		79 d	31-Jan-2025	37.4
	HRS		1870.8						1922.7
	AFL		1430						1352
			REF:						
24-36-01-003		DISCARD AFT MAIN BATTERY							Service ATA:24
PN:7638-48P	MOS	24 (+1m/-1m)	24-Oct-23		24-Oct-25	24-Nov-25	345 d (+31)	23-Feb-2025	12.6
SN:G03195018	HRS		3236.7						556.8
	AFL	600 (+30/-30)	2367		2967	2997	185 (+30)		415
Disposition: LIFE LIMIT			REF: AMM 24-36-01						
24-36-01-003		DISCARD FORWARD MAIN BATTERY							Service ATA:24
PN:7639-34	MOS	24 (+1m/-1m)	24-Oct-23		24-Oct-25	24-Nov-25	345 d (+31)	23-Feb-2025	12.6
SN:G03193089	HRS		3236.7						556.8
	AFL	600 (+30/-30)	2367		2967	2997	185 (+30)		415
Disposition: LIFE LIMIT			REF: AMM 24-36-01						
71-00-00-760-823		NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	12 (+30d)	20-May-24		20-May-25	19-Jun-25	188 d (+30)	05-Mar-2025(2)	5.8
	HRS	630 (+10%)	3534.3		(4164.3)4164.3	4227.3	370.8 (+63)		259.2
	ENC		2574						211
			REF: MM 71-00-00						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
71-00-00-760-823		NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	12 (+30d)	20-May-24		20-May-25	19-Jun-25	188 d (+30)	05-Mar-2025(2)	5.8
	HRS	630 (+10%)	3534.3		(4164.3)4164.3	4227.3	370.8 (+63)		259.2
	ENC		2574						211
REF: MM 71-00-00									
72-00-02-810-801		NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	12 (+30d)	20-May-24		20-May-25	19-Jun-25	188 d (+30)	05-Mar-2025(2)	5.8
	HRS	630 (+10%)	3534.3		(4164.3)4164.3	4227.3	370.8 (+63)		259.2
	ENC		2574						211
REF: MM 72-00-02									
72-00-02-810-801		NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	12 (+30d)	20-May-24		20-May-25	19-Jun-25	188 d (+30)	05-Mar-2025(2)	5.8
	HRS	630 (+10%)	3534.3		(4164.3)4164.3	4227.3	370.8 (+63)		259.2
	ENC		2574						211
REF: MM 72-00-02									
73-10-05-212-801		NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12 (+30d)	15-Mar-24		15-Mar-25	14-Apr-25	122 d (+30)	15-Mar-2025	7.9
	HRS		3481						312.5
	ENC		2530						255
REF: MM 73-10-05									
73-10-05-212-801		NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12 (+30d)	15-Mar-24		15-Mar-25	14-Apr-25	122 d (+30)	15-Mar-2025	7.9
	HRS		3481						312.5
	ENC		2530						255
REF: MM 73-10-05									
05-30-01		800 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS		15-Mar-24					07-Apr-2025	7.9
	HRS	800 (+30/-30)	3481	Adj:-10.2	4270.8	4300.8	477.3 (+30)		312.5
	AFL		2527						255
REF: SMR 05-30-01									
79-20-01-960-801		NO. 1 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
PN:3052590-01	MOS		15-Mar-24					07-Apr-2025	7.9
SN:UNKNOWN	HRS	800 (+10%)	3481	Adj:-10.2	(4270.8)4270.8	4350.8	477.3 (+80)		312.5
	ENC		2530						255
Disposition: DISCARD REF: MM 79-20-01									



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
79-20-01-960-801		NO. 2 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
PN:3052590-01	MOS		15-Mar-24					07-Apr-2025	7.9
SN:UNKNOWN	HRS	800 (+10%)	3481	Adj:-10.2	(4270.8)4270.8	4350.8	477.3 (+80)		312.5
	ENC		2530						255
Disposition: DISCARD		REF: MM 79-20-01							
73-10-05-960-801		NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
PN:PN-UNKNOWN	MOS		15-Mar-24					10-Apr-2025	7.9
SN:UNKNOWN	HRS	800 (+10%)	3481		(4281)4281	4361	487.5 (+80)		312.5
	ENC		2530						255
		REF: MM 73-10-05							
73-10-05-960-801		NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
PN:PN-UNKNOWN	MOS		15-Mar-24					10-Apr-2025	7.9
SN:UNKNOWN	HRS	800 (+10%)	3481		(4281)4281	4361	487.5 (+80)		312.5
	ENC		2530						255
		REF: MM 73-10-05							
24-36-01-005		FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7638-48P	MOS	6 (+1m/-1m)	23-Oct-24	Adj:1d	24-Apr-25	24-May-25	162 d (+30)	24-Apr-2025(2)	.7
SN:G03195018	HRS		3763.8						29.7
	AFL		2757						25
		REF: AMM 24-36-01							
24-36-01-005		FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7639-34	MOS	6 (+1m/-1m)	23-Oct-24	Adj:1d	24-Apr-25	24-May-25	162 d (+30)	24-Apr-2025(2)	.7
SN:G03193089	HRS		3763.8						29.7
	AFL		2757						25
		REF: AMM 24-36-01							
05-30-10		1600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS		30-Sep-22					13-May-2025	25.5
	HRS	1600 (+30/-30)	2770.4	Adj:19.7	4390.1	4420.1	596.6 (+30)		1023.1
	AFL		2024						758
		REF: SMR 05-30-10							
28-21-07-001		OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS		24-Jul-24					16-May-2025	3.6
	HRS	800 (+30/-30)	3638.6	Adj:-37.7	4400.9	4430.9	607.4 (+30)		154.9
	AFL		2650						132
Disposition: AIRWORTHINESS		REF: AMM 28-21-07							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
28-21-07-001		OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS		24-Jul-24					16-May-2025	3.6
	HRS	800 (+30/-30)	3638.6	Adj:-37.7	4400.9	4430.9	607.4 (+30)		154.9
	AFL		2650						132
Disposition: AIRWORTHINESS			REF: AMM 28-21-07						
32-43-11-001		OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE							Service ATA:32
	MOS		24-Jul-24					16-May-2025	3.6
	HRS	800 (+30/-30)	3638.6	Adj:-37.7	4400.9	4430.9	607.4 (+30)		154.9
	AFL		2650						132
Disposition: AIRWORTHINESS			REF: AMM 32-43-11						
77-20-02-750-801		NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	36 (+30d)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	16-May-2025	24.1
	HRS	1600 (+100)	2800.9		(4400.9)4400.9	4500.9	607.4 (+100)		992.6
	ENC		2045						740
			REF: MM 77-20-02						
77-20-02-750-801		NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	36 (+30d)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	16-May-2025	24.1
	HRS	1600 (+100)	2800.9		(4400.9)4400.9	4500.9	607.4 (+100)		992.6
	ENC		2045						740
			REF: MM 77-20-02						
05-30-42		3200 FH/60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	60 (+1m/-1m)	29-Sep-20	Adj:-14d	15-Sep-25	15-Oct-25	306 d (+30)	30-May-2025	49.5
	HRS	3200 (+30/-30)	1244.6		4444.6	4474.6	651.1 (+30)		2548.9
	AFL		1012						1770
			REF: SMR 05-30-42						
27-11-02-001		FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION							Service ATA:27
	MOS	60 (+1m/-1m)	29-Sep-20		29-Sep-25	29-Oct-25	320 d (+30)	30-May-2025	49.5
	HRS	3200 (+30/-30)	1244.6		4444.6	4474.6	651.1 (+30)		2548.9
	AFL		1012						1770
			REF: AMM 27-11-02						
27-21-02-001		FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION							Service ATA:27
	MOS	60 (+1m/-1m)	29-Sep-20		29-Sep-25	29-Oct-25	320 d (+30)	30-May-2025	49.5
	HRS	3200 (+30/-30)	1244.6		4444.6	4474.6	651.1 (+30)		2548.9
	AFL		1012						1770
			REF: AMM 27-21-02						



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
27-31-02-001		FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION							Service ATA:27
	MOS	60 (+1m/-1m)	29-Sep-20		29-Sep-25	29-Oct-25	320 d (+30)	30-May-2025	49.5
	HRS	3200 (+30/-30)	1244.6		4444.6	4474.6	651.1 (+30)		2548.9
	AFL		1012						1770
REF: AMM 27-31-02									
24-31-01-001		NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q	MOS		09-Aug-24					05-Jun-2025	3.1
SN:S01035XL	HRS	800 (+30/-30)	3665.5		4465.5	4495.5	672 (+30)		128
	AFL		2674						108
REF: AMM 24-31-01									
051254		NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	12 (+30d)	20-Aug-24	Adj:-23d	28-Jul-25	27-Aug-25	257 d (+30)	12-Jun-2025	2.8
	HRS	800 (+10%)	3687.9		(4487.9)4487.9	4567.9	694.4 (+80)		105.6
	ENC		2693						92
REF: MM 05-20-00									
051254		NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	12 (+30d)	20-Aug-24	Adj:-23d	28-Jul-25	27-Aug-25	257 d (+30)	12-Jun-2025	2.8
	HRS	800 (+10%)	3687.9		(4487.9)4487.9	4567.9	694.4 (+80)		105.6
	ENC		2693						92
REF: MM 05-20-00									
24-31-01-001		NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q-4	MOS		26-Aug-24					15-Jun-2025	2.6
SN:S00807XL	HRS	800 (+30/-30)	3699.2		4499.2	4529.2	705.7 (+30)		94.3
	AFL		2704						78
REF: AMM 24-31-01									
71-22-01-01-901		DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL							Service ATA:71
	MOS		15-Sep-10					15-Jun-2025	169.9
	HRS	T:4500	0		4500		706.5		3793.5
	AFL	T:3600	0		3600		818		2782
Disposition: AIRWORTHINESS REF: NDT PART 5 71-22-00									
05-30-20		2400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS		08-Apr-22					15-Sep-2025	31.2
	HRS	2400 (+30/-30)	2408.5	Adj:-8.5	4800	4830	1006.5 (+30)		1385
	AFL		1795						987
REF: SMR 05-30-20									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
26-21-01-001		FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL							Service ATA:26
	MOS		08-Apr-22					15-Sep-2025	31.2
	HRS	2400 (+30/-30)	2408.5	Adj:-8.5	4800	4830	1006.5 (+30)		1385
	AFL		1795						987
Disposition: AIRWORTHINESS		REF: AMM 26-21-00							
25-61-00-001		OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM							Service ATA:25
PN:S1821502-02	MOS	12	18-Sep-24		18-Sep-25		309 d	18-Sep-2025	1.8
SN:2622421-0005	HRS		3709.9						83.6
	AFL		2712						70
		REF: AMM 25-61-00							
26-24-01-001		WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	12	18-Sep-24		18-Sep-25		309 d	18-Sep-2025	1.8
SN:D58317506	HRS		3709.9						83.6
	AFL		2712						70
		REF: AMM 26-24-01							
26-24-01-001		WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	12	18-Sep-24		18-Sep-25		309 d	18-Sep-2025	1.8
SN:D58317504	HRS		3709.9						83.6
	AFL		2712						70
		REF: AMM 26-24-01							
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:640-13595-00	MOS	12	18-Sep-24		18-Sep-25		309 d	18-Sep-2025	1.8
SN:005453	HRS		3709.9						83.6
	AFL		2712						70
		REF: AMM 33-52-01							
25-61-00-002		GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:S1821502-02	MOS	12	27-Sep-24		27-Sep-25		318 d	27-Sep-2025	1.5
SN:2622421-0005	HRS		3731.7						61.8
	AFL		2727						55
		REF: AMM 25-61-00							
05-30-80		12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	12 (+1m/-1m)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
	HRS		3731.7						61.8
	AFL		2727						55
		REF: SMR 05-30-80							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-30-84		60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	60 (+1m/-1m)	29-Sep-20		29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
REF: SMR 05-30-84									
05-30-90		120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	60 (+1m/-1m)	29-Sep-20		29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
REF: SMR 05-30-90									
22-11-00-001		FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
SN:1GK005566	HRS		3731.7						61.8
	AFL		2727						55
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
22-11-00-001		FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
SN:1GK005571	HRS		3731.7						61.8
	AFL		2727						55
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
22-11-00-001		FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
SN:1GK006390	HRS		3731.7						61.8
	AFL		2727						55
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
22-11-00-001		FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO							Service ATA:22
PN:011-01904-00	MOS	12 (+30d/-30d)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
SN:1GK005594	HRS		3731.7						61.8
	AFL		2727						55
Disposition: AIRWORTHINESS		REF: AMM 22-11-00							
32-11-00-003		LUBRICATION OF MAIN LANDING GEAR							Service ATA:32
	MOS	12 (+1m/-1m)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
	HRS		3731.7						61.8
	AFL	650 (+30/-30)	2727		3377	3407	595 (+30)		55
REF: AMM 12-21-00									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
32-11-03-004		SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	12 (+1m/-1m)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
	HRS		3731.7						61.8
	AFL	650 (+30/-30)	2727		3377	3407	595 (+30)		55
		REF: AMM 12-14-02							
32-21-00-003		LUBRICATION OF NOSE LANDING GEAR							Service ATA:32
	MOS	12 (+1m/-1m)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
	HRS		3731.7						61.8
	AFL	650 (+30/-30)	2727		3377	3407	595 (+30)		55
		REF: AMM 12-21-00							
32-21-05-004		SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	12 (+1m/-1m)	27-Sep-24	Adj:2d	29-Sep-25	29-Oct-25	320 d (+30)	29-Sep-2025	1.5
	HRS		3731.7						61.8
	AFL	650 (+30/-30)	2727		3377	3407	595 (+30)		55
		REF: AMM 12-14-03							
55-20-04-001		INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	60	29-Sep-20		29-Sep-25		320 d	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
Disposition: ALI		REF: NDT PART 5 55-20-00							
55-20-04-002		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS							Service ATA:55
	MOS	60	29-Sep-20		29-Sep-25		320 d	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
Disposition: ALI		REF: NDT PART 5 55-20-00							
55-40-04-002		INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	60	29-Sep-20		29-Sep-25		320 d	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
Disposition: ALI		REF: NDT PART 5 55-40-00							
55-40-04-003		SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	60	29-Sep-20		29-Sep-25		320 d	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
Disposition: ALI		REF: NDT PART 5 55-40-00							



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
57-60-00-001		EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON							Service ATA:57
	MOS	60	29-Sep-20		29-Sep-25		320 d	29-Sep-2025	49.5
	HRS		1244.6						2548.9
	AFL		1012						1770
Disposition: ALI		REF: NDT PART 5 57-60-00							
FAA 2023-21-06		INSTALLATION OF STRUCTURAL REINFORCEMENT ON MONUMENTS AND REPLACEMENT OF FASTENERS ON THE FLOOR SUPPORT							AD ATA:25
	MOS	-	EFF		29-Sep-25 * (M)		320 d	29-Sep-2025	
	HRS								
	AFL								
Disposition: MANDATORY		REF: AD							
SB 505-00-0026		GENERAL - W201 HARNESS ROUTING IMPROVEMENT, SERVICE BULLETIN							Bulletin ATA:00
	MOS	T:60			29-Sep-25 (M)		320 d	29-Sep-2025	
	HRS								
	AFL								
Disposition: CATEGORY 02 - RECOMMENDED		REF: BULLETINS							
SB 505-25-0046 REV 03 PART I		ACCOMPLISH EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION, SERVICE BULLETIN RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION							Bulletin ATA:25
	MOS	-			29-Sep-25 (M)		320 d	29-Sep-2025	
	HRS								
	AFL								
Disposition: CATEGORY 01 - MANDATORY		REF: BULLETINS							
SB 505-55-0004		STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT, SERVICE BULLETIN							Bulletin ATA:55
	MOS	-	01-Oct-21		29-Sep-25 (M)		320 d	29-Sep-2025	37.4
	HRS		1870.8						1922.7
	AFL		1430						1352
Disposition: RECOMMENDED		REF: BULLETINS							
72-60-01-212-801		NO. 1 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES							Service ATA:72
	MOS		17-Oct-24					03-Nov-2025	.9
	HRS	1200 (+100)	3763.8		(4963.8)4963.8	5063.8	1170.3 (+100)		29.7
	ENC		2759						26
		REF: GENERIC NO REF							
72-60-01-212-801		NO. 2 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES							Service ATA:72
	MOS		17-Oct-24					03-Nov-2025	.9
	HRS	1200 (+100)	3763.8		(4963.8)4963.8	5063.8	1170.3 (+100)		29.7
	ENC		2759						26
		REF: GENERIC NO REF							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500042 RegNo: N479MA HRS: 3793.5 AFL: 2782 As
Of: 13-Nov-2024 Operator: MAXAIR INC.

Report Date: 13-Nov-2024

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
720060		NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS		06-May-22					08-Nov-2025	30.2
	HRS	2500 (+50)	2479.1		(4979.1)4979.1	5029.1	1185.6 (+50)		1314.4
	ENC		1841						944
		REF: MM 72-00-00							
720060		NO. 2 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS		06-May-22					08-Nov-2025	30.2
	HRS	2500 (+50)	2479.1		(4979.1)4979.1	5029.1	1185.6 (+50)		1314.4
	ENC		1841						944
		REF: MM 72-00-00							
05-30-82		36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	36 (+1m/-1m)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	10-Nov-2025	24.1
	HRS		2800.9						992.6
	AFL		2043						739
		REF: SMR 05-30-82							
35-00-00-001		FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	36 (+30d/-30d)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	10-Nov-2025	24.1
	HRS	2400 (+30/-30)	2800.9		5200.9	5230.9	1407.4 (+30)		992.6
	AFL		2043						739
Disposition: AIRWORTHINESS		REF: AMM 35-00-00							
35-21-00-001		FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE							Service ATA:35
	MOS	36 (+30d/-30d)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	10-Nov-2025	24.1
	HRS	2400 (+30/-30)	2800.9		5200.9	5230.9	1407.4 (+30)		992.6
	AFL		2043						739
Disposition: AIRWORTHINESS		REF: AMM 35-21-00							
35-21-00-002		OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE							Service ATA:35
	MOS	36 (+30d/-30d)	10-Nov-22		10-Nov-25	10-Dec-25	362 d (+30)	10-Nov-2025	24.1
	HRS	2400 (+30/-30)	2800.9		5200.9	5230.9	1407.4 (+30)		992.6
	AFL		2043						739
Disposition: AIRWORTHINESS		REF: AMM 35-21-00							
FAA 2023-22-11		REPLACEMENT OF THE AILERON AUTOPILOT SERVO MOUNT CLUTCH RETAINING BOLT AND WASHER							AD ATA:22
	MOS	36	10-Nov-22		10-Nov-25		362 d	10-Nov-2025	24.1
	HRS								
	AFL								
Disposition: MANDATORY		REF: AD							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time