



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPNDR 91.413)	UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		24		30-Jun-2026	14 m 13 d
055004	ACCOMPLISH LIGHTNING STRIKE CHECK	KCHS			MTH 11-Aug-2012 HRS 502 LDG 333		A/R			
5-12-01	INSPECTION DOCUMENT 01	KGSO			MTH 11-Oct-2023 HRS 3027.2 LDG 1966		450		3477.2	110.4
5-12-02	INSPECTION DOCUMENT 02	GSO			MTH 05-May-2022 HRS 2662.2 LDG 1735		900		3562.2	195.4
5-12-03	INSPECTION DOCUMENT 03	GSO			MTH 05-May-2022 HRS 2662.2 LDG 1735		1350		4012.2	645.4
5-12-04	INSPECTION DOCUMENT 04	KICT			MTH 06-Sep-2018 HRS 1752.5 LDG 1255		1800		3552.5	185.7
5-12-05	INSPECTION DOCUMENT 05	UNK			MTH 24-Apr-2024 HRS 3107 LDG 2019		3150		6257	2890.2
5-12-06	INSPECTION DOCUMENT 06	UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12		30-Jun-2025	2 m 13 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)	UNK		C352TS G-97924666	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12		30-Jun-2025	2 m 13 d
5-12-07	INSPECTION DOCUMENT 07	UNK			MTH 24-Apr-2024 HRS 3107 LDG 2019		24		30-Apr-2026	12 m 13 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSTP			MTH 02-Oct-2020 HRS 1973.5 LDG 1411		60			
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)	KSTP		30401102-2 60931B1	MTH 05-Aug-2020		60		31-Aug-2025	4 m 14 d
Hydro Check Date: 05-Aug-2020										
5-12-11	INSPECTION DOCUMENT 11	GSO			MTH 05-May-2022 HRS 2662.2 LDG 1735		72		31-May-2028	37 m 14 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)	GSO		C352TS G-97924666	MTH 05-May-2022 HRS 2662.5 LDG 1735		72		31-May-2028	37 m 14 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSTP			MTH 16-May-2016 HRS 1423.4 LDG 998		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)	GSO		C352TS G-97924666	MTH 01-Jan-2021		144		31-Jan-2033	93 m 14 d
Hydro Check Date: 01-Jan-2021										
5-12-13	INSPECTION DOCUMENT 13	UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12		30-Jun-2025	2 m 13 d
							450		3634.6	267.8



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-14	INSPECTION DOCUMENT 14	UNK			MTH 13-Jun-2024		12		30-Jun-2025	2 m 13 d
					HRS 3184.6		900		4084.6	717.8
					LDG 2035					
5-12-15	INSPECTION DOCUMENT 15	UNK			MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
					HRS 3184.6		1350		4534.6	1167.8
					LDG 2035					
5-12-16	INSPECTION DOCUMENT 16	GSO			MTH 05-May-2022		36		31-May-2025	1 m 14 d
					HRS 2662.2		1350		4012.2	645.4
					LDG 1735					
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK			29-10-00-720						
				HM50C-3	MTH		36		31-May-2025	1 m 14 d
				359B	HRS		1350		4012.2	645.4
5-12-17	INSPECTION DOCUMENT 17	GSO			MTH 05-May-2022		36		31-May-2025	1 m 14 d
					HRS 2662.2		1800		4462.2	1095.4
					LDG 1735					
5-12-18	INSPECTION DOCUMENT 18	GSO			MTH 05-May-2022		36		31-May-2025	1 m 14 d
					HRS 2662.2		2250		4912.2	1545.4
					LDG 1735					
5-12-20	INSPECTION DOCUMENT 20	KGSO			MTH 29-Jul-2022		48		31-Jul-2026	15 m 14 d
					HRS 2734.1		2700		5434.1	2067.3
					LDG 1246					
5-12-21	INSPECTION DOCUMENT 21				MTH 07-Apr-2025		12		30-Apr-2026	12 m 13 d
					HRS 3366.8					
					LDG 2154					
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK			MTH 13-Jun-2024		24			
					HRS 3184.6					
					LDG 2035					
B341001	CALIBRATION TEST INDICATOR 14 CFR PART 91.411				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
AIRSPEED		UNK		261440-1143						
				295476A						
Calibration Date: 13-Jun-2024										
B341001	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
NO. 1		UNK		011-01110-00						
				43805809						
Calibration Date: 13-Jun-2024										
B341001	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
NO. 2		UNK		011-01110-00						
				43805815						
Calibration Date: 13-Jun-2024										
B341001	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
STANDBY		UNK		162350-1161						
				179668C						
Calibration Date: 13-Jun-2024										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	UNK			MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
B345000	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
LEFT		UNK		011-00779-21						
				84805791						
Calibration Date: 13-Jun-2024										
B345000	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413				MTH 13-Jun-2024		24		30-Jun-2026	14 m 13 d
RIGHT		UNK		011-04334-00						
				51Y001502						
Calibration Date: 13-Jun-2024										
5-12-23	INSPECTION DOCUMENT 23 (NOT USED)	KSAT			MTH 26-Oct-2012		N/R			
					HRS 540.5					
					LDG 352					



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-28	INSPECTION DOCUMENT 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSTP			MTH 31-Oct-2019 HRS 1891.1 LDG 1353		A/R			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	GSO		3-1640 0756	MTH 05-May-2022 HRS 2662.2 LDG 1735		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	GSO		3-1642 0410	MTH 05-May-2022 HRS 2662.2 LDG 1735		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	GSO		3-1640 0754	MTH 05-May-2022 HRS 2662.2 LDG 1735		A/R			
5-12-30	INSPECTION DOCUMENT 30	KGSO			MTH 29-Jul-2022 HRS 2734.1 LDG 1246		48 1800		31-Jul-2026 4534.1	15 m 14 d 1167.3
5-12-31	INSPECTION DOCUMENT 31	KGSO			MTH 11-Oct-2023 HRS 3027.2 LDG 1966		450		3477.2	110.4
5-12-32	INSPECTION DOCUMENT 32	GSO			MTH 05-May-2022 HRS 2662.2 LDG 1735		72 1800		31-May-2028 3535	37 m 14 d 1381
5-12-34	INSPECTION DOCUMENT 34	UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12 900			
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK)	UNK		7639-30 G03202499	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12 900		30-Jun-2025 4084.6	2 m 13 d 717.8
5-12-35	INSPECTION DOCUMENT 35				MTH 07-Apr-2025 HRS 3366.8 LDG 2154	22	6		31-Oct-2025	6 m 14 d
5-12-37	INSPECTION DOCUMENT 37				MTH 08-Apr-2010 HRS 0		7200		8602.3	5235.5
5-12-MA	INSPECTION DOCUMENT MA	UNK			MTH 10-Jan-2025 HRS 3317.6	-3.5	500		3814.1	447.3
5-12-MB	INSPECTION DOCUMENT MB	KGSO			MTH 18-Nov-2022 HRS 2814.1 LDG 1298		950		3764.1	397.3
5-12-MC	INSPECTION DOCUMENT MC				MTH 08-Apr-2010 HRS 0		4000		4000	633.2
5-12-MD	INSPECTION DOCUMENT MD				MTH 07-Apr-2025 HRS 3366.8 LDG 2154		12		30-Apr-2026	12 m 13 d
5-12-ME	INSPECTION DOCUMENT ME	GSO			MTH 05-May-2022 HRS 2662.2 LDG 1735		36 1400		31-May-2025 4062.2	1 m 14 d 695.4
5-12-MF	INSPECTION DOCUMENT MF				MTH 08-Apr-2010 HRS 0		12000		12000	8633.2
5-12-MG	INSPECTION DOCUMENT MG				MTH 08-Apr-2010 HRS 0		5000		5000	1633.2
5-12-MH	INSPECTION DOCUMENT MH				MTH 08-Apr-2010 HRS 0		8250		8250	4883.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-MI	INSPECTION DOCUMENT MI			MTH	08-Apr-2010					
				HRS	0		12000		12000	8633.2
5-12-MJ	INSPECTION DOCUMENT MJ			MTH	08-Apr-2010					
				HRS	0		10600		10600	7233.2
5-12-MK	INSPECTION DOCUMENT MK			MTH	08-Apr-2010					
				HRS	0		10400		10400	7033.2
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE			MTH	13-Jun-2024		36		30-Jun-2027	26 m 13 d
	UNK			HRS	3184.6					
				LDG	2035					
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	21-Aug-2020		A/R			
	KSTP			HRS	1957.3					
				LDG	1403					
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS	02-Oct-2020		A/R			
	KSTP			HRS	1973.5					
				LDG	1411					
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS	24-Jun-2020		A/R			
	KSTP			HRS	1949.5					
				LDG	1382					
0521009	ENVIRO SYSTEMS 500 HOUR INSPECTION			MTH	16-Sep-2021					
	KSTP			HRS	2391.3					
				LDG	1573					
				ACH	0		500		500	500
262003A	REPLACE FIRE EXT CARTRIDGE	13083-5		MTH	02-Oct-2020		72	8	28-Feb-2026	10 m 11 d
LEFT	KSTP	ESD20B788-001								
262003A	REPLACE FIRE EXT CARTRIDGE	13083-5		MTH	02-Oct-2020		72	8	28-Feb-2026	10 m 11 d
RIGHT	KSTP	ESD20B788-001								
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH	29-Jul-2022		A/R			
	KGSO			HRS	2734.1					
				LDG	1246					
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH	23-Sep-2021		A/R			
	UNK			HRS	2391.3					
				LDG	1573					
32-30-40-960	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)			MTH	13-Jul-2022		36		31-Jul-2025	3 m 14 d
	KGSO	40005369-2								
		3990								
Hydro Check Date: 13-Jul-2022										
32-40-00-960	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)			MTH	30-Apr-2024		36		30-Apr-2027	24 m 13 d
	UNK	40005399-1								
		6821								
Hydro Check Date: 30-Apr-2024										
35-00-00-960	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST			MTH	31-Mar-2024		60		31-Mar-2029	47 m 14 d
	UNK	4441073-040								
		0715-173								
Hydro Check Date: 31-Mar-2024										
052001	ENGINE 450 HOUR/ 12 MONTH INSPECTION			MTH	13-Jun-2024		12		30-Jun-2025	2 m 13 d
E1	UNK			HRS	3184.6		450		(3634.6)3634.6	267.8
				LDG	2035					
052001	ENGINE 450 HOUR/ 12 MONTH INSPECTION			MTH	13-Jun-2024		12		30-Jun-2025	2 m 13 d
E2	UNK			HRS	3184.6		450		(3634.6)3634.6	267.8
				LDG	2035					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
710010 E1	COMPRESSOR DESALINATION WASH	KCHS			MTH 12-Apr-2013 HRS 633.3		A/R			
710010 E2	COMPRESSOR DESALINATION WASH	KCHS			MTH 12-Apr-2013 HRS 633.3		A/R			
710010A E1	DESALINATION WASH / FRESH WATER RINSE	GSO			MTH 05-May-2022 HRS 2662.5 LDG 1735		A/R			
710010A E2	DESALINATION WASH / FRESH WATER RINSE	GSO			MTH 05-May-2022 HRS 2662.5 LDG 1732		A/R			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 08-Apr-2010		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 08-Apr-2010		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 08-Apr-2010		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 08-Apr-2010		A/R			
72-00-00-620-805- 01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-805- 01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-805- 02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-805- 02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-806- 01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-806- 01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH 08-Apr-2010		A/R			
72-00-00-620-806- 02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH 08-Apr-2010		A/R			
72-00-00-620-806- 02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH 08-Apr-2010		A/R			
72-00-00-630-804- 01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 08-Apr-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH 08-Apr-2010		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 08-Apr-2010		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH 08-Apr-2010		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 08-Apr-2010		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH 08-Apr-2010		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 08-Apr-2010		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY			MTH 08-Apr-2010		A/R			
720000 E1	PERFORM ENGINE OVERHAUL			MTH 08-Apr-2010 HRS 0		3500		(3500)3500	133.2
720000 E2	PERFORM ENGINE OVERHAUL			MTH 08-Apr-2010 HRS 0		3500		(3500)3500	133.2
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION KICT			MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION KICT			MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
720003 E1	INSPECT LOW UTILIZATION ENGINE UNK			MTH 24-Apr-2024 HRS 3107 LDG 2019		24		30-Apr-2026	12 m 13 d
720003 E2	INSPECT LOW UTILIZATION ENGINE UNK			MTH 24-Apr-2024 HRS 3107 LDG 2019		24		30-Apr-2026	12 m 13 d
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS		1750		(3502.2)3502.2	New Req
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS		1750		(3502.2)3502.2	New Req
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER KICT			MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER KICT			MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12 900		30-Jun-2025 (4084.6)4084.6	2 m 13 d 717.8
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT UNK			MTH 13-Jun-2024 HRS 3184.6 LDG 2035		12 900		30-Jun-2025 (4084.6)4084.6	2 m 13 d 717.8
731055 E1	REPLACE FUEL MANIFOLD KICT		35C6160-01 DEAAAA41301	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731055 E2	REPLACE FUEL MANIFOLD KICT			35C6160-01 DEAAAA40143	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH KICT			PN SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH KICT			PN SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY KICT			PN SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY KICT			PN SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
790015 E1	REPLACE OIL FILTER ELEMENT GSO				MTH 05-May-2022 HRS 2662.2 LDG 1735		900		(3562.2)3562.2	195.4
790015 E2	REPLACE OIL FILTER ELEMENT GSO				MTH 05-May-2022 HRS 2662.2 LDG 1732		900		(3562.2)3562.2	195.4
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL KICT				MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL KICT				MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750		(3502.2)3502.2	135.4



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY.	0113-12 1794	MTH 08-Apr-2010		O/C	0		
213001	KAPS II CONTROLLER 9912661-6	52811-102 1270	MTH 08-Apr-2010		O/C	0		
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7	52812-102 1382	MTH 08-Apr-2010		O/C	0		
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7	52812-102 1372	MTH 08-Apr-2010		O/C	0		
215001	AIR CONDITIONING COMPRESSOR MODULE UNK	1133130-7 945	MTH 26-Aug-2022 HRS 2748.4		O/C	0 0		
215002	CONDENSOR ASSEMBLY 9912660-3 KSTP	1134620-5 907	MTH 05-Nov-2020 HRS 1993.3 LDG 1425		O/C	1 0		
215003	RECEIVER DRYER ASSY KSTP	9912660-18 N/A	MTH 30-Dec-2020 HRS 2168.7		O/C	0 0		
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7	1133300-1 750	MTH 08-Apr-2010		O/C	0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7	1133300-1 754	MTH 08-Apr-2010		O/C	0		
215005	VANE AXIAL BLOWER ASSY.	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
215006A	COMPRESSOR DRIVE BELT UNK	5MR535-25 N/A	MTH 09-Sep-2022 HRS 2763.3		O/C	2 0		
215007	FREON A/C COMPRESSOR DRIVE MOTOR UNK	1134146-6 1523A	MTH 09-Sep-2022 HRS 2763.3		O/C	1 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD	PN SN-UNKNOWN	MTH 26-Aug-2022 HRS 2748.4 ACH 0			0 0 0	800	800
216000 LH	THERMAL ACTUATOR UNK	74S235H6F255 SN-UNKNOWN	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		O/C	0 0 0		
216000 RH	THERMAL ACTUATOR	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
221001 AILERON	GSA 80 TORQUE SERVO	011-00877-00 66306651	MTH 08-Apr-2010		O/C	0		
221001 RUDDER	GSA 80 TORQUE SERVO FAT	011-00877-00 66306375	MTH 15-Sep-2010 HRS 145.2 LDG 105		O/C	0 0 0		
221002 ELEVATOR	GSA 81 TORQUE SERVO	011-00878-10 71307433	MTH 08-Apr-2010		O/C	0		
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO	011-00878-10 71307462	MTH 08-Apr-2010		O/C	0		
221003 AILERON	GSM 85A SERVO MOUNT	011-01436-A2 10905263	MTH 08-Apr-2010		O/C	0		
221003 ELEVATOR	GSM 85A SERVO MOUNT	011-01436-A0 11205271	MTH 08-Apr-2010		O/C	0		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT	011-01436-A1 11305262	MTH 08-Apr-2010		O/C	0		
221003 RUDDER	GSM 85 SERVO MOUNT	011-01436-A3 11005259	MTH 08-Apr-2010		O/C	0		
221004	GMC 710 AFCS CONTROLLER	011-01020-10 22005564	MTH 08-Apr-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231002 NO. 1	GMA 1347D AUDIO PANEL	011-01257-00 48405471	MTH 08-Apr-2010		O/C	0		
231002 NO. 2	GMA 1347D AUDIO PANEL	011-01257-00 48405472	MTH 08-Apr-2010		O/C	0		
231003 NO. 1	VHF COMM ANTENNA	VHF10-829 729	MTH 08-Apr-2010		O/C	0		
231003 NO. 2	VHF COMM ANTENNA	VHF10-829 0756	MTH 08-Apr-2010		O/C	0		
231011	SAT PHONE ANTENNA	S67-1575-109 10389	MTH 08-Apr-2010		O/C	0		
231101	HIGH FREQUENCY CONTROLLER S3100-470	071-01605-0201 NSN	MTH 08-Apr-2010		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449	064-01073-0102 NSN	MTH 08-Apr-2010		O/C	0		
231103	HIGH FREQUENCY ANTENNA	16390 NSN	MTH 08-Apr-2010		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFIER	064-01072-0101 NSN	MTH 08-Apr-2010		O/C	0		
233001	GRT10 XM REMOTE RECEIVER	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
233002	GRC10 XM REMOTE CONTROL KICT	011-01558-00 14R002409	MTH 25-Oct-2013 HRS 781.2 LDG 515		O/C	0 0 0		
233003	ADAPTER MODULE	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
237002 CO-PILOT	USB CHARGE PORT- DOUBLE -- GSO	6430202-1 L21-11159	MTH 05-May-2022 HRS 2662.5 LDG 1735		O/C	0 0 0		
237002 PILOT	USB CHARGE PORT- DOUBLE -- GSO	6430202-1 M21-10659	MTH 05-May-2022 HRS 2662.5 LDG 1735		O/C	0 0 0		
243001 LEFT	DIGITAL GCU 9912682-3	GCSG550-5 09118941	MTH 08-Apr-2010		O/C	0		
243001 RIGHT	DIGITAL GCU 9912682-3	GCSG550-5 09118943	MTH 08-Apr-2010		O/C	0		
243002	EMER INST BATTERY UNK	CBS24 01135	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		O/C			
243007	MAIN SHIP BATTERY UNK	7639-30 G03202499	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY S3155-1	A-931F CR-55748	MTH 08-Apr-2010		O/C	0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	7018920-5 0782	MTH 08-Apr-2010		O/C	0		
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	7018920-5 0785	MTH 08-Apr-2010		O/C	0		
245003	FLAP CONTROL MODULE	7018916-9 0477	MTH 08-Apr-2010		O/C	0		
245005 LEFT	ICE PROTECTION CONTROL	7018917-9 0414	MTH 08-Apr-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245005 RIGHT	ICE PROTECTION CONTROL	7018918-13 0440	MTH 08-Apr-2010		O/C	0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL	7018919-13 0619	MTH 08-Apr-2010		O/C	0		
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL	7018919-13 0594	MTH 08-Apr-2010		O/C	0		
245008	DOOR MONITOR-	7018921-8 0376	MTH 08-Apr-2010		O/C	0		
245009	LANDING GEAR MONITOR-	7018923-12 0400	MTH 08-Apr-2010		O/C	0		
245010 LEFT	START CONTROL	7018924-5 0800	MTH 08-Apr-2010		O/C	0		
245010 RIGHT	START CONTROL	7018924-5 0799	MTH 08-Apr-2010		O/C	0		
245011	FLAP MONITOR-	7018925-11 0422	MTH 08-Apr-2010		O/C	0		
245012 LEFT	SPEEDBRAKE ASSY	7018926-1 0829	MTH 08-Apr-2010		O/C	0		
245012 RIGHT	SPEEDBRAKE ASSY	7018926-1 0828	MTH 08-Apr-2010		O/C	0		
245013	DIAGNOSTIC UNIT	7018927-7 0440	MTH 08-Apr-2010		O/C	0		
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	85-230-2 0830-963M2	MTH 08-Apr-2010		O/C	0		
245015	MASTER INTERIOR SSR UNIT UZ100	10747P03E25 09116577	MTH 08-Apr-2010		O/C	0		
245016 RIGHT	AVN BUS #1 SENSOR UZ102	10747P03E25 09086142	MTH 08-Apr-2010		O/C	0		
245017 LEFT	AVN SENSOR UZ103	10747P03E25 09076089	MTH 08-Apr-2010		O/C	0		
245018 RIGHT	AVN BUS #2 SENSOR UZ104	10747P03E25 09116586	MTH 08-Apr-2010		O/C	0		
245019 LEFT	IGN #1 SENSOR UZ105	10747P03E10 08034010	MTH 08-Apr-2010		O/C	0		
245019 RIGHT	IGN #1 SENSOR UZ106	10747P03E10 09116453	MTH 08-Apr-2010		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107	10747P03E10 09116461	MTH 08-Apr-2010		O/C	0		
245020 RIGHT	IGN #2 SENSOR UZ108	10747P03E10 08074528	MTH 08-Apr-2010		O/C	0		
245021	COCKPIT FAN SENSOR UZ109	10747P03E25 09116556	MTH 08-Apr-2010		O/C	0		
245022	CABIN FAN SENSOR UZ110	10747P03E25 09116578	MTH 08-Apr-2010		O/C	0		
245023 LEFT	LH BOOST PUMP SENSOR UZ114	10747P03E25 09116558	MTH 08-Apr-2010		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR UZ111	10747P03E25 09086138	MTH 08-Apr-2010		O/C	0		
245024	CONDENSER FAN SENSOR UZ112	10747P03E25 09116569	MTH 08-Apr-2010		O/C	0		
245025	DC-DC CONVERTER UZ116	10747P03E10 09116456	MTH 08-Apr-2010		O/C	0		
245026	AVN EMERG SENSOR UZ200	10747P03E25 09086132	MTH 08-Apr-2010		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE	7018119-1 684	MTH 08-Apr-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245201 RIGHT	CABIN ALTITUDE MODULE			7018119-1 685	MTH 08-Apr-2010		O/C	0		
251001	GLARESHIELD ASSEMBLY			4319027-17 142361-3	MTH 08-Apr-2010		O/C	0		
256001 NO. 1	LIFE VEST	KSTP		P01074-207 200900130026	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120 -	0	31-Oct-2030	66 m 14 d
256001 NO. 2	LIFE VEST	KSTP		P01074-207 200900130048	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120 -	0	31-Oct-2030	66 m 14 d
256001 NO. 3	LIFE VEST	KSTP		P01074-207 200900130025	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120 -	0	31-Oct-2030	66 m 14 d
256001 NO. 4	LIFE VEST	KSTP		P01074-207 200900130020	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120 -	0	31-Oct-2030	66 m 14 d
256001 NO. 5	LIFE VEST	KSTP		P01074-207 200900130059	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120 -	0	31-Oct-2030	66 m 14 d
256001 NO. 6	LIFE VEST	KSTP		P01074-207 200900130017	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		120	0	31-Oct-2030	66 m 14 d
256002	ELT BATTERY	UNK		452-0133 1008977-020	MTH 24-Apr-2024 HRS 3107 LDG 2019	4	60	0 0 0	31-Aug-2029	52 m 14 d
256004	ELT ANTENNA			110-340 249540	MTH 08-Apr-2010		O/C	0		
256007	ELT PROCESSOR C406N			453-5060 08786	MTH 08-Apr-2010		O/C	0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 210877	MTH 08-Apr-2010		O/C	0		
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 210873	MTH 08-Apr-2010		O/C	0		
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KSTP		30401102-2 60931B1	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		O/C	2 0		
262003 LEFT	FIRE EXT CARTRIDGE	KSTP		13083-5 ESD20B788-001	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		72		28-Feb-2026	10 m 11 d
Manufacture Date: 27-Feb-2020										
262003 RIGHT	FIRE EXT CARTRIDGE	KSTP		13083-5 ESD20B788-001	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		72		28-Feb-2026	10 m 11 d
Manufacture Date: 27-Feb-2020										
262004	PORTABLE FIRE EXTINGUISHER GSO			C352TS G-97924666	MTH 05-May-2022 HRS 2662.5 LDG 1735		O/C	16 0 0		
271001 LEFT	CONTROL WHEEL ASSY			4319065-1 1705	MTH 08-Apr-2010		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY			4319065-2 1632	MTH 08-Apr-2010		O/C	0		
271002 --	ELEVATOR TRIM TAB ACTUATOR			PN SN-UNKNOWN	DAYS 08-Apr-2010		H/T H/T	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
273001	RUDDER TRIM ACTUATOR 9912639-2			SYLC-53361-1 453	MTH 08-Apr-2010		O/C	0		
273002	AILERON TRIM ACTUATOR 9912639-2			SYLC-53361-1 0483	MTH 08-Apr-2010		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1			MP50Y-1 335	MTH 08-Apr-2010		O/C	0		
275002 LEFT	FLAP ACTUATOR 9912640-1	KCHS		41013930-105 0246	MTH 07-Sep-2012 HRS 514.6 LDG 340		O/C			
275002 RIGHT	FLAP ACTUATOR 9912640-2	KCHS		41013930-108 0104	MTH 07-Sep-2012 HRS 514.6 LDG 340		O/C	0 0 0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-59	KCHS		140527-5900 0391	MTH 07-Sep-2012 HRS 514.6 LDG 340		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344.59	KCHS		140527-5900 0396	MTH 07-Sep-2012 HRS 514.6 LDG 340		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-1	KCHS		41014070-104 0201	MTH 28-Feb-2011 HRS 237.1 LDG 168		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-1	KCHS		41014070-104 0703	MTH 28-Feb-2011 HRS 237.1 LDG 168		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5			LR45300A C1899	MTH 08-Apr-2010		O/C	0		
282001 RIGHT	PRIMARY EJECTOR 9912190-5			LR45300A C1897	MTH 08-Apr-2010		O/C	0		
282002	TRANSFER VALVE 9914103-6			ZSV57 09-090823	MTH 08-Apr-2010		O/C	0		
282003 LEFT	DC FUEL PUMP 9912553-1			1C7-23 1BF19	MTH 08-Apr-2010		O/C	0		
282003 RIGHT	DC FUEL PUMP 9912553-1			1C7-23 1BF25	MTH 08-Apr-2010		O/C	0		
282004 L1	SCAVENGE EJECTOR 9912190-2			RG45310 C2190	MTH 08-Apr-2010		O/C	0		
282004 L2	SCAVENGE EJECTOR 9912190-2			RG45310 C2199	MTH 08-Apr-2010		O/C	0		
282004 R1	SCAVENGE EJECTOR 9912190-2			RG45310 C2210	MTH 08-Apr-2010		O/C	0		
282004 R2	SCAVENGE EJECTOR 9912190-2			RG45310 C2215	MTH 08-Apr-2010		O/C	0		
282005 LEFT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 211322	MTH 08-Apr-2010		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 217394	MTH 08-Apr-2010		O/C	0		
284001 L1	FUEL PROBE 9912664-1			020-251-001 786	MTH 08-Apr-2010		O/C	0		
284001 L2	FUEL PROBE 9912664-2			020-251-002 722	MTH 08-Apr-2010		O/C	0		
284001 L3	FUEL PROBE 9912664-3			020-251-003 781	MTH 08-Apr-2010		O/C	0		
284001 L4	FUEL PROBE 9912664-4			020-251-004 714	MTH 08-Apr-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284001 L5	FUEL PROBE 9912664-5			020-251-005 716	MTH 08-Apr-2010		O/C	0		
284001 R1	FUEL PROBE 9912664-1			020-251-001 780	MTH 08-Apr-2010		O/C	0		
284001 R2	FUEL PROBE 9912664-2			020-251-002 771	MTH 08-Apr-2010		O/C	0		
284001 R3	FUEL PROBE 9912664-3			020-251-003 783	MTH 08-Apr-2010		O/C	0		
284001 R4	FUEL PROBE 9912664-4			020-251-004 706	MTH 08-Apr-2010		O/C	0		
284001 R5	FUEL PROBE 9912664-5			020-251-005 723	MTH 08-Apr-2010		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6			367-350-001 1329	MTH 08-Apr-2010		O/C	0		
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2			HM50C-3 359B	MTH 08-Apr-2010		O/C	0		
291002	HYDRAULIC CHECK VALVE			4001-20 5399A	MTH 08-Apr-2010		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE			19940933-1 031500	MTH 08-Apr-2010		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4			80665 0343	MTH 08-Apr-2010		O/C	0		
291007	HYDRAULIC MANIFOLD 9912657-14			8257-3 0322	MTH 08-Apr-2010		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2			2672 0305	MTH 08-Apr-2010		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3			80664 0345	MTH 08-Apr-2010		O/C	0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5			4251 0320	MTH 08-Apr-2010		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7			4252 0319	MTH 08-Apr-2010		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15			9625-1 0304	MTH 08-Apr-2010		O/C	0		
291012	HYDRAULIC RESERVOIR ASSEMBLY			7017005-28 21137248	MTH 08-Apr-2010		O/C	0		
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2			7550-2 0727	MTH 08-Apr-2010		O/C	0		
301001 LEFT	WING DE-ICE BOOT 9912662-17	GSO		P35-4D5317-17 NGB1550	MTH 05-May-2022 HRS 2662.5 LDG 1735		O/C	0 0 0		
301001 RIGHT	WING DE-ICE BOOT 9912662-18	KSTP		P35-4D5317-18 NDT1060	MTH 28-Jul-2017 HRS 1600.5 LDG 1120		O/C	0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3	KSTP		P29S4D5317-05 NFI1070	MTH 30-Dec-2020 HRS 2168.7		O/C	0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4	KSTP		P29S4D5317-06 NFR8890	MTH 30-Dec-2020 HRS 2168.7		O/C	0 0		
301004 L1	DE-ICE PRESSURE SWITCH			1106P55-1 8002A	MTH 08-Apr-2010		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH			1106P55-1 8032A	MTH 08-Apr-2010		O/C	0		
301004 L3	DE-ICE PRESSURE SWITCH			1106P55-1 8083A	MTH 08-Apr-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301004 R1	DE-ICE PRESSURE SWITCH			1106P55-1 8109A	MTH 08-Apr-2010		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH	KSTP		1106P55-1 10848A	MTH 23-Sep-2016 HRS 1506.1 LDG 1058		O/C	0 0		
301004 R3	DE-ICE PRESSURE SWITCH	KSTP		1106P55-1 11035A	MTH 23-Sep-2016 HRS 1506.1 LDG 1058		O/C	0 0		
301004	VERT DE-ICE BOOT	KSTP		9912662-13 NFO2990	MTH 30-Dec-2020 HRS 2168.7		O/C	0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2337	MTH 08-Apr-2010		O/C	0		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2425	MTH 08-Apr-2010		O/C	0		
302002 LEFT	TEMP SWITCH			1173T0759 5845	MTH 08-Apr-2010		O/C	0		
302002 RIGHT	TEMP SWITCH			1173T0759 5988	MTH 08-Apr-2010		O/C	0		
304001 L1	DE-ICE VALVE			3D2353-06 N093613	MTH 08-Apr-2010		O/C	0		
304001 L2	DE-ICE VALVE			3D2353-06 N093600	MTH 08-Apr-2010		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER	KSTP		7098108-1 0758A	MTH 03-Sep-2014 HRS 917.9 LDG 591		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER	KSAT		7098108-1 0847A	MTH 26-Oct-2012 HRS 540.5 LDG 352		O/C			
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY			7041020-5 304	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY			7041020-6 305	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
321001	NOSE LANDING GEAR TRUNNION			7042020-1 314	MTH 08-Apr-2010		O/C	0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY	KSTP		7041050-4 480	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		12000	998	12018	9864
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY	KSTP		7041050-4 481	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		12000	998	12018	9864
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	GSO		7041030-3 307M	MTH 05-May-2022 HRS 2662.5 LDG 1735		20000	1735	20000	17846
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	GSO		7041030-4 307M	MTH 05-May-2022 HRS 2662.5 LDG 1735		20000	1735	20000	17846
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK			6327504-6 2822	MTH 08-Apr-2010		O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK			6327504-6 2782	MTH 08-Apr-2010		O/C	0		
322002	NOSE GEAR FORK & PISTON ASSEMBLY			7042040-1 307	MTH 08-Apr-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
322003	UPLOCK ACTUATOR	6327504-7	MTH 08-Apr-2010		O/C	0		
NOSE GEAR		1448						
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR	FA100036-001	MTH 08-Apr-2010			0		
	9912655-1	FA100036-1-0346	LDG 0		12000	0	12000	9846
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR	FA100104-001	MTH 08-Apr-2010			0		
LEFT	9912653-5	FA100104-1-0307	LDG 0		12000	0	12000	9846
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR	FA100105-001	MTH 08-Apr-2010			0		
RIGHT	9912653-6	FA100105-1-0312	LDG 0		12000	0	12000	9846
322011	NOSE LANDING GEAR ACTUATOR	FA100087-001	MTH 08-Apr-2010			0		
	9912654-2	FA100087-1-0321	LDG 0		12000	0	12000	9846
322202	SHIMMY DAMPER	7042030-2	MTH 02-Nov-2016		O/C	0		
		AT198	HRS 1535.2			0		
			LDG 1084			0		
322205	LANDING GEAR STRUT ASSEMBLY	7042010-4	MTH 02-Nov-2016			1448.4		
NOSE	KSTP	302	HRS 1535.2			1018	20066	17912
			LDG 1084		20000			
322206	LANDING GEAR DRAG BRACE ASSY	7042120-5	MTH 08-Apr-2010			0		
NOSE	CHP 4	56	LDG 0		20000	0	20000	17846
323001	LANDING GEAR ASSEMBLY	7041010-5	MTH 08-Apr-2010		O/C	0		
LEFT		NSN						
323001	LANDING GEAR ASSEMBLY	7041010-6	MTH 08-Apr-2010		O/C	0		
RIGHT		NSN						
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE	40005369-2	MTH 29-Jul-2022		288	0	31-Dec-2027	32 m 14 d
	9914678-3	KGSO	HRS 2734.1			0		
		3990	LDG 1246			0		
Manufacture Date: 01-Dec-2003								
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE	40005399-1	MTH 13-Jun-2024		288	182	30-Apr-2033	96 m 13 d
	9914678-4	UNK	HRS 3184.6			0		
		6821	LDG 2035			0		
Manufacture Date: 30-Apr-2009								
323003	EMER BLOW DOWN BTL PRESSURE GAUGE	19940931-1	MTH 08-Apr-2010		O/C	0		
		030997						
324001	MAIN LANDING GEAR TIRE	021-523-0	MTH 05-Mar-2025		O/C			
LEFT	9912646-1	2351T00377	HRS 3343.7					
			LDG 2139					
324001	MAIN LANDING GEAR TIRE	021-523-0	MTH 05-Mar-2025		O/C			
RIGHT	9912646-1	2351T00374	HRS 3343.7					
			LDG 2139					
324002	NOSE LANDING GEAR TIRE	079-606-0	MTH 05-Mar-2025		O/C			
	9912649-1	3117T00162	HRS 3343.7					
			LDG 2139					
324003	MAIN LANDING GEAR WHEEL	3-1640	MTH 05-May-2022		O/C	0		
LEFT	9912645-1	GSO 0756	HRS 2662.2			0		
			LDG 1735			0		
324003	MAIN LANDING GEAR WHEEL	3-1640	MTH 05-May-2022		O/C	0		
RIGHT	9912645-1	GSO 0754	HRS 2662.2			0		
			LDG 1735			0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324004 NOSE	NOSE LANDING GEAR WHEEL 9912648-1	GSO		3-1642 0410	MTH 05-May-2022 HRS 2662.2 LDG 1735		O/C	0 0 0		
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KGSO		2-1706-1 1143	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KGSO		2-1706-1 0365A	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE 9914689-4			5145-1 0268	MTH 08-Apr-2010		O/C	0		
324006 RIGHT	SHUTTLE VALVE 9914689-4			5145-1 0634	MTH 08-Apr-2010		O/C	0		
324007	BRAKE METERING VALVE 9912650-9			84-75 0330	MTH 08-Apr-2010		O/C	0		
324101 LEFT	WHEEL SPEED SENSOR 9912650-5	GSO		466-23-1 1067	MTH 05-May-2022 HRS 2662.2 LDG 1735		O/C	0 0 0		
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0681	MTH 08-Apr-2010		O/C	0		
324101	PARKING BRAKE VALVE 9912388-10			98433-1 0323	MTH 08-Apr-2010		O/C	0		
324102	ANTISKID CONTROL UNIT 9912650-1			556-3 302829429	MTH 08-Apr-2010		O/C	0		
324103	ANTISKID CONTROL VALVE 9912650-6			211-134-1 0346	MTH 08-Apr-2010		O/C	0		
324104	EMERGENCY BRAKE VALVE 9912651-1			72298 0358	MTH 08-Apr-2010		O/C	0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE			19940931-1 031519	MTH 08-Apr-2010		O/C	0		
325001	BUNGE ASSEMBLY			7042072-9 NSN	MTH 08-Apr-2010		O/C	0		
334001 LEFT	POWER SUPPLY 9912677-3			82004-1 000743	MTH 08-Apr-2010		O/C	0		
334001 RIGHT	POWER SUPPLY 9912677-3			82004-1 000744	MTH 08-Apr-2010		O/C	0		
334002	GROUND RECOGNITION LIGHT 9912679-3			84003-2 000471	MTH 08-Apr-2010		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1			84005-1 000596	MTH 08-Apr-2010 HRS 0		8000	0	8000	4633.2
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2			84005-2 000562	MTH 08-Apr-2010 HRS 0		8000	0	8000	4633.2
341001	SWAAT UNIT 9912689-1			0863B2 385	MTH 08-Apr-2010		O/C	0		
341002 NO. 1	GDC 74B AIRDATA SYSTEM			011-01110-00 43805809	MTH 08-Apr-2010		O/C	0		
341002 NO. 2	GDC 74B AIRDATA SYSTEM			011-01110-00 43805815	MTH 08-Apr-2010		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM			011-00978-00 47913997	MTH 08-Apr-2010		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM			011-00978-00 47914037	MTH 08-Apr-2010		O/C	0		
341004 LEFT	PITOT PROBE 9912678-1			0851LN 270678	MTH 08-Apr-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341004 RIGHT	PITOT PROBE 9912678-1			0851LN 270675	MTH 08-Apr-2010		O/C	0		
342001 STANDBY	ALTIMETER S3100-465			162350-1161 179668C	MTH 08-Apr-2010		O/C	0		
342002 AIRSPEED	INDICATOR			261440-1143 295476A	MTH 08-Apr-2010		O/C	0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE KGSO			011-00831-00 46709052	MTH 06-Jun-2023 HRS 2942.5 LDG 1922		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE KGSO			011-00831-00 46711240	MTH 06-Jun-2023 HRS 2942.5 LDG 1922		O/C	2942.5 1922		
342003	MAGNETIC COMPASS			S2800-821 NSN	MTH 08-Apr-2010		O/C	0		
342004 NO. 1	NO. 1 GDU 1050A DISPLAY KGSO			11-03470-10 494107126	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
342004 NO. 2	NO. 2 GDU 1050A DISPLAY KGSO			11-03470-10 494107142	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	KSTP		011-00868-10 42013488	MTH 30-Jan-2015 HRS 1087.9 LDG 740		O/C	57 1087.9 740		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	KSTP		011-00868-10 42013487	MTH 30-Jan-2015 HRS 1087.9 LDG 740		O/C	57 1087.9 740		
342006 NO. 1	GMU 44 MAGNETOMETER			011-00870-00 47515139	MTH 08-Apr-2010		O/C	0		
342006 NO. 2	GMU 44 MAGNETOMETER			011-00870-00 47515111	MTH 08-Apr-2010		O/C	0		
342007	GDU 1550 MFD UNIT KGSO			11-03472-00 496002081	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513			4200-21 C09-10767	MTH 08-Apr-2010		O/C	0		
3420SD	FLIGHT STREAM 510 SOFTWARE SD CARD KGSO			011-03595-05 59Q003880	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR GSO			011-00883-20 47203075	MTH 12-Apr-2011 HRS 245 LDG 173		O/C			
344002	GARMIN GDL-69A DATA LINK			011-00987-00 47762571	MTH 08-Apr-2010		O/C	0		
345001	GPS/WAAS/XM ANTENNA			013-00245-00 6949	MTH 08-Apr-2010		O/C	0		
345002 RIGHT	TRANSPONDER KGSO			011-04334-00 51Y001502	MTH 18-Nov-2022 HRS 2814.1 LDG 1298		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345003 LEFT	TRANSPONDER KICT	011-00779-21 84805791	MTH 06-Sep-2018 HRS 1752.5 LDG 1255		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KGSO	11-04475-00 48V001418	MTH 29-Jul-2022 HRS 2734.1 LDG 1246		O/C	0 0 0		
345005	ADF RECEIVER	013-00166-00 NSN	MTH 08-Apr-2010		O/C	0		
345006	ADF ANTENNA	013-00165-00 NSN	MTH 08-Apr-2010		O/C	0		
345007	MARKER BEACON ANTENNA	MB10-754-2 353	MTH 08-Apr-2010		O/C	0		
345008	GLIDE SLOPE ANTENNA	RGS10-48 14742	MTH 08-Apr-2010		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA	L10-611-14 2778	MTH 08-Apr-2010		O/C	0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA	L10-611-14 2794	MTH 08-Apr-2010		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA	L10-611-14 2783	MTH 08-Apr-2010		O/C	0		
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA	L10-611-14 2787	MTH 08-Apr-2010		O/C	0		
345010 LEFT	NAV ANTENNA	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
345010 RIGHT	NAV ANTENNA	PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
345010	VOR/LOC ANTENNA CHS	VT10-767-3 1311	MTH 05-Aug-2012 HRS 502 LDG 333		O/C	0 0 0		
345011	KN63 DME TRANSCEIVER	066-01070-0001 33344	MTH 08-Apr-2010		O/C	0		
345013	RMI CONVERTER	013-00167-00 NSN	MTH 08-Apr-2010		O/C	0		
345014	GPS/WAAS/ ANTENNA	013-00244-00 6505	MTH 08-Apr-2010		O/C	0		
345015	DME ANTENNA	L10-611-14 2780	MTH 08-Apr-2010		O/C	0		
346010	TAS PROCESSOR	066-01152-0101 2597	MTH 08-Apr-2010		O/C	0		
346011 BOTTOM	TAS ANTENNA	L10-611-14 2802	MTH 08-Apr-2010		O/C	0		
346011 TOP	TAS ANTENNA	071-01599-0100 21109	MTH 08-Apr-2010		O/C	0		
346012	CONFIGURATION MODULE	071-00112-0200 15652	MTH 08-Apr-2010		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT	011-01105-01 15W010118	MTH 08-Apr-2010		O/C	0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT	011-01105-01 15W011015	MTH 08-Apr-2010		O/C	0		
350001	OXYGEN BOTTLE UNK	4441073-040 0715-173	MTH 13-Jun-2024 HRS 3184.6 LDG 2035		180	9	30-Sep-2038	161 m 13 d
Manufacture Date: 01-Sep-2023								
350002	OXYGEN PRESSURE GAUGE C668512-0101	MD97-1 M09-10487	MTH 08-Apr-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
351001 LEFT	CREW OXYGEN MASK 9914067-41	KSTP MC10-16-101 B151570	MTH 25-Sep-2019 HRS 1869.5 LDG 1341		72	0	25-Sep-2025	5 m 8 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41	KSDL MC10-15-109 53629	MTH 26-May-2021 HRS 2334.7 LDG 1535		72	0	31-May-2027	25 m 14 d
361001 LEFT	PRECOOLER	UNK 9914402-7 HX-02860	MTH 24-Apr-2024 HRS 3107 LDG 2019		O/C	0 0 0		
361001 RIGHT	PRECOOLER	UNK 9914402-7 HX-02476	MTH 24-Apr-2024 HRS 3107 LDG 2019		O/C	0 0 0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY ICT	2601-34 0279A	MTH 04-Aug-2010 HRS 126.1 LDG 80		O/C			
361002 RIGHT	VARIABLE VENTURI VALVE ASSY	2601-34 0625A	MTH 08-Apr-2010		O/C	0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2	1H75-23 6BE24	MTH 08-Apr-2010		O/C	0		
361004 LEFT	B/A SHUTOFF VALVE	5253-00-3 2897	MTH 08-Apr-2010		O/C	0		
361004 RIGHT	B/A SHUTOFF VALVE	5253-00-3 2687	MTH 08-Apr-2010		O/C	0		
361101 R1	DE-ICE VALVE	3D2353-06 N100301	MTH 08-Apr-2010		O/C	0		
361101 R2	DE-ICE VALVE	3D2353-06 N100304	MTH 08-Apr-2010		O/C	0		
522001	CABIN DOOR SEAL 9912674-3	S-22560-3 394	MTH 08-Apr-2010		O/C	0		
522002	ESCAPE HATCH SEAL 9912675-1	S-22561 488	MTH 08-Apr-2010		O/C	0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY	7013022-3 307	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY	7013022-16 TSW0044	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	7013022-11 307	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	7013022-10 307	MTH 08-Apr-2010 LDG 0		20000	0 0	20000	17846
534101 FWD	ENGINE BEAM	7012061-3 310	MTH 08-Apr-2010		O/C	0		
552001 LEFT	ELEVATOR ASSEMBLY KCHS	7034001-9 0000012	MTH 16-Nov-2012 HRS 561.6 LDG 365		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY ICT	7034001-10 0000006	MTH 12-Sep-2010 HRS 131.7 LDG 95		O/C			
553001	VERTICAL STABILIZER ASSY	7031001-1 278	MTH 08-Apr-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561001 LEFT	WINDSHIELD ASSY, (LH)	KGSO		9912745-13	MTH 11-Oct-2023		O/C	0		
				23096H1612	HRS 3027.2			0		
					LDG 1966			0		
561001 RIGHT	WINDSHIELD ASSY, (RH)			NP-188601-2	MTH 08-Apr-2010		O/C	0		
	9912745-10			08204H3973						
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW			93310-1	MTH 08-Apr-2010		O/C	0		
	9912746-1			1715						
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW			93310-2	MTH 08-Apr-2010		O/C	0		
	9912746-2			1702						
562003 L1	CABIN WINDOW			93320-10	MTH 08-Apr-2010		O/C	0		
	9912747-10			2991						
562003 L2	CABIN WINDOW			93320-10	MTH 08-Apr-2010		O/C	0		
	9912747-10			2868						
562003 L3	CABIN WINDOW	UNK		93320-10	MTH 18-Aug-2010		O/C	0		
	9912747-10			2841	HRS 129.7			0		
					LDG 90			0		
562003 R1	CABIN WINDOW			93320-10	MTH 08-Apr-2010		O/C	0		
	9912747-10			2952						
562003 R2	CABIN (ESCAPE HATCH) WINDOW			93320-10	MTH 08-Apr-2010		O/C	0		
	9912747-10			2822						
562003 R3	CABIN WINDOW			93320-10	MTH 08-Apr-2010		O/C	0		
	9912747-10			2900						
572001 LEFT WING	FWD SPAR			7022022-1	MTH 08-Apr-2010		O/C	0		
				87850						
572001 RIGHT WING	FWD SPAR			7022022-2	MTH 08-Apr-2010		O/C	0		
				87851						
572002 LEFT WING	REAR SPAR			7022032-3	MTH 08-Apr-2010		O/C	0		
				87973						
572002 RIGHT WING	REAR SPAR			7022032-4	MTH 08-Apr-2010		O/C	0		
				87974						
572003 LEFT WING	MAIN SPAR			7022027-1	MTH 08-Apr-2010		O/C	0		
				87912						
572003 RIGHT WING	MAIN SPAR			7022027-2	MTH 08-Apr-2010		O/C	0		
				87913						
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-5	MTH 08-Apr-2010			0		
				298	LDG 0		20000	0	20000	17846
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-6	MTH 08-Apr-2010			0		
				301	LDG 0		20000	0	20000	17846
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-9	MTH 08-Apr-2010			0		
				306	LDG 0		20000	0	20000	17846
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-10	MTH 08-Apr-2010			0		
				307	LDG 0		20000	0	20000	17846
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-5	MTH 08-Apr-2010			0		
				331	LDG 0		20000	0	20000	17846
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-6	MTH 08-Apr-2010			0		
				319	LDG 0		20000	0	20000	17846
712001 LEFT	ENG CHANNEL-FWD MOUNT			7051001-1	MTH 08-Apr-2010		O/C	0		
	7051001-1			297						
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12	MTH 08-Apr-2010			0		
	9912647-1			1596	HRS 0		4000	0	4000	633.2
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12	MTH 08-Apr-2010			0		
	9912647-1			1224	HRS 0		4000	0	4000	633.2
712001 RIGHT	ENG CHANNEL-FWD MOUNT			7051001-2	MTH 08-Apr-2010		O/C	0		
				270						
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12	MTH 08-Apr-2010			0		
	9912647-1			1431	HRS 0		4000	0	4000	633.2



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	LM-471-SA12 1460	MTH 08-Apr-2010 HRS 0		4000	0	4000	633.2
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	LM-471-SA4 LK2360	MTH 08-Apr-2010 HRS 0		8000	0	8000	4633.2
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	LM-471-SA4 LK2306	MTH 08-Apr-2010 HRS 0		8000	0	8000	4633.2
712003 AFT	ENGINE BEAM 307	7012066-2	MTH 08-Apr-2010		O/C	0		
712003 LEFT	AFT ENGINE MOUNT CHANNEL 333	7051001-3	MTH 08-Apr-2010		O/C	0		
712003 RIGHT	AFT ENGINE MOUNT CHANNEL 357	7051001-4	MTH 08-Apr-2010		O/C	0		
71EN1 NO. 1	ENGINE PCE-LB0577	35C0510-01			E/C			
71EN2 NO. 2	ENGINE PCE-LB0586	35C0510-01			E/C			
720010 E1	FAN ROTOR	35C1940-01 FRAEPKUT61	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
720010 E2	FAN ROTOR	35C1940-01 TXA1B5786	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
721010 E1	HP TURBINE DISK	35C2311-01 FRAEPKPU77	MTH 08-Apr-2010 LDG 0 ACCC YC		5250	0 0	(5250)5250	3096 3096
721010 E2	HP TURBINE DISK	35C2311-01 FRAEPKPU54	MTH 08-Apr-2010 LDG 0 ACCC YC		5250	0 0	(5250)5250	3096 3096
721020 E1	LP TURBINE DISK	35C2372-01 FRAEPKPM17	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
721020 E2	LP TURBINE DISK	35C2372-01 FRAEPKWB32	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
723010 E1	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 AAPPIAGV2165	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
723010 E2	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 AAPPIAGV2138	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
725010 E1	HP COMPRESSOR ROTOR	35C3661-01 FRAEPKPB119	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
725010 E2	HP COMPRESSOR ROTOR	35C3661-01 FRAEPKPB178	MTH 08-Apr-2010 LDG 0 ACCC YC		10500	0 0	(10500)10500	8346 8346
726010 E1	AGB STARTER MAGNETIC SEAL KICT	35C1022-01 SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750	0 0	(3502.2)3502.2	135.4
726010 E2	AGB STARTER MAGNETIC SEAL KICT	35C1022-01 SN-UNKNOWN	MTH 06-Sep-2018 HRS 1752.2 LDG 1255		1750	0 0	(3502.2)3502.2	135.4

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2			1103P0448 9236	MTH 08-Apr-2010		O/C	0		
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2			1103P0448 9262	MTH 08-Apr-2010		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1			TFF1573-4 AAA1040	MTH 08-Apr-2010		O/C	0		
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1	KSTP		TFF1573-4 1738	MTH 23-Sep-2016 HRS 1506.1 LDG 1058		O/C	0		
731050 E1	FUEL MANIFOLD	BTV		35C6160-01 DEAAAAA41301	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		O/C	1 0 0		
731050 E2	FUEL MANIFOLD	BTV		35C6160-01 DEAAAAA40143	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		O/C	1 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.)			35C0794-04 16690141	MTH 08-Apr-2010		H/T H/T	0		
732101 E2	FUEL METERING UNIT (F.M.U.)			35C0794-04 16738260	MTH 08-Apr-2010		H/T H/T	0		
741001 E1	IGNITION EXCITER			35C5472-01 WDA109542	MTH 08-Apr-2010		O/C	0		
741001 E2	IGNITION EXCITER			35C5472-01 WDA109790	MTH 08-Apr-2010		O/C	0		
741002 E1 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 08-Apr-2010		O/C	0		
741002 E2 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 08-Apr-2010		O/C	0		
741003 E1 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 08-Apr-2010		O/C	0		
741003 E2 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 08-Apr-2010		O/C	0		
741004 E1 INBOARD	SPARK IGNITER	KSTP		35C2353-01 N/A	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		O/C	0 0 0		
741004 E2 INBOARD	SPARK IGNITER	KSTP		35C2653-02 N/A	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		O/C	0 0 0		
741005 E1 OUTBOARD	SPARK IGNITER	KSTP		35C2353-01 N/A	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		O/C	0 0		
741005 E2 OUTBOARD	SPARK IGNITER	KSTP		35C2353-02 N/A	MTH 02-Oct-2020 HRS 1973.5 LDG 1411		O/C	0 0		
751003 E1	BLEED VALVE ACTUATOR			35C2851-02 16704950	MTH 08-Apr-2010		H/T H/T	0		
751003 E2	BLEED VALVE ACTUATOR			35C2851-02 16728235	MTH 08-Apr-2010		H/T H/T	0		
761001 E1	FADEC	KGSO		35C5731-01 08-452	MTH 11-Oct-2023 HRS 3027.2 LDG 1966		O/C			
761001 E2	FADEC 9912637-2			35C4035-04 09-773	MTH 08-Apr-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-02 WA37848	MTH 08-Apr-2010		H/T H/T	0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-02 WA37850	MTH 08-Apr-2010		H/T H/T	0		
793001 E1	OIL TEMP SENSOR			102-00083 07531	MTH 08-Apr-2010		O/C	0		
793001 E2	OIL TEMP SENSOR			102-00083 07518	MTH 08-Apr-2010		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER KSTP			APTE-304A-250G 7723-5-532	MTH 07-Aug-2017 HRS 1619.7 LDG 1146		O/C			
793002 E2	OIL PRESSURE TRANSMITER KSTP			APTE-304A-250G 7711-10-363	MTH 07-Aug-2017 HRS 1619.7 LDG 1146		O/C			
793010 E1	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
793010 E2	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 08-Apr-2010		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1			MG94E-1 734D	MTH 24-Feb-2021 HRS 2235.5 LDG 1376		1500	5 0 0	3735.5	368.7
801000 RIGHT	STARTER GENERATOR 9912676-1	KGSO		MG94E-1 494D	MTH 06-Jun-2023 HRS 2942.5 LDG 1922		1500	0	4442.5	1075.7



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 510-99-02 REV 01	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 02)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 510-99-02	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 510-05-01 REV 01	TIME LIMITS/MAINTENANCE CHECKS - LANDING GEAR LIFE LIMIT EXEMPTION			INFORMATIONAL			A/R			
	MOC :									
SL 510-11-03	PLACARDS AND MARKINGS - BRAKE ACCUMULATOR PLACARD INSPECTION	GSO		RECOMMENDED	MTH 18-Apr-2012 HRS 436.9 LDG 293		A/R			Complete
	MOC :				COMPLIED WITH - C/W SL510-11-03, BRAKE ACCUMULATOR PLACARD INSPECTION					
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02)									
				INFORMATIONAL			-			
MOC :										
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03)									
				INFORMATIONAL			A/R			
MOC :										
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04)									
				INFORMATIONAL			A/R			
MOC :										
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)									
				INFORMATIONAL			A/R			
MOC :										
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01)									
				INFORMATIONAL			-			
MOC :										
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									
				INFORMATIONAL			-			
MOC :										
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			N/A
MOC : NOT APPLICABLE - SL510-21-02 R1 DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER; PLEASE UPDATE CESCOM										
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT									
				RECOMMENDED	MTH		-			
MOC :										
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT									
				OPTIONAL			-			
MOC :										
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT									
				OPTIONAL			A/R			
MOC :										
SL 510-23-01	LIGHTNING RELATED ANOMALIES OF THE GARMIN GMA 1347[D] AUDIO PANEL									
				INFORMATIONAL			A/R			
MOC :										
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			N/A
MOC : NOT APPLICABLE - SL510-24-08 R1 DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER;										
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION									
				MANDATORY	MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.										
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION									
				MANDATORY	MTH		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE -										
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)									
				MANDATORY			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION ICT			MANDATORY	MTH 13-Sep-2010 HRS 133.1 LDG 97		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-12, CONTROL COLUMN TIE STRAP INSPECTION.										
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION ICT			MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-13;ELECTRICAL POWER-THROTTLE QUADRANT WIRE BUNDLE INSPECTION, DATED JUNE 30, 2011.										
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION KSTP			MANDATORY	DAYS 13-Apr-2017 HRS 1589.9 LDG 1104		-			Complete
MOC : COMPLIED WITH - COMPLETED SERVICE LETTER SL510-24-14 R1 BY INSPECTION OF PRINTED CIRCUIT BOARDS FOR DATE CODES IAW ACCOMPLISHMENT INSTRUCTIONS. FOUND NOT APPLICABLE BY DATE CODE. DATE CODE WAS 10650K926 ON BOTH BOARDS.										
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01) MANDATORY			DAYS			-			
MOC :										
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT OPTIONAL						A/R			
MOC :										
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER DISCRETIONARY						A/R			
MOC :										
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS OPTIONAL						-			
MOC :										
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION MANDATORY				DAYS		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE -INCORPORATED ON PRODUCTION AIRCRAFT -0278 AND ON										
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION GSO			RECOMMENDED	MTH 05-May-2013 HRS 651.9 LDG 426		-			Complete
MOC : COMPLIED WITH - C/W SB510-27-02 COMPLETED ALL INSTRUCTIONS INCLUDING THE INTENT THERIN.SPEED BRAKE MECHANICAL SWITCH CONVERSION.										
SB 510-28-02	LOCKING FUEL CAP INSTALLATION OPTIONAL						A/R			
MOC :										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL						-			
MOC :										
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT DISCRETIONARY						-			
MOC :										
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01) KSAT			DISCRETIONARY	MTH 26-Oct-2012 HRS 540.5 LDG 352		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT SERVICE BULLETIN 510-30-02.										
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT DISCRETIONARY						A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01) DISCRETIONARY A/R									
	MOC :									
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT MANDATORY MTH A/R Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.									
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION GSO MANDATORY MTH 18-Apr-2012 HRS 436.9 LDG 293 Complete									
	MOC : COMPLIED WITH - C/W SB510-30-05, WINDSHIELD TEMP CONTROL UNIT MODIFICATION									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT RECOMMENDED MTH 25-Jan-2017 -									
	MOC : DEFERRED									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01) RECOMMENDED MTH -									
	MOC :									
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES INFORMATIONAL -									
	MOC :									
SL CIL-30-01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY CIL-30-01 REV 01) INFORMATIONAL -									
	MOC :									
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02) INFORMATIONAL A/R									
	MOC :									
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03) INFORMATIONAL A/R									
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04) INFORMATIONAL A/R									
	MOC :									
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01) INFORMATIONAL A/R									
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL -									
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL -									
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION INFORMATIONAL -									
	MOC :									
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION GSO RECOMMENDED MTH 05-May-2013 HRS 651.9 LDG 426 Complete									
	MOC : COMPLIED WITH - C/W SL510-32-05 COMPLETED ALL INSTRUCTIONS INCLUDING THE INTENT THERIN.NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION.									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	KSTP		MANDATORY	DAYS 13-Apr-2017 HRS 1589.9 LDG 1104		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL510-32-07 BY VISUAL INSPECTION OF S/N OF BRAKE(S) INSTALLED. FOUND NOT APPLICABLE BY S/N'S INSTALLED. LEFT S/N -750 RIGHT S/N 0728.										
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	KSTP		MANDATORY	DAYS 28-Jul-2017 HRS 1600.5 LDG 1120		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-32-08 BY MEASURING BRAKE WEAR PINS IAW UTC AEROSPACE SYSTEMS SERVICE BULLETIN 2-1706-1-32-1. LENGTH FOUND GOOD. APPLIED YELLOW PAINT TO BRAKE PIN ENDS PER SERVICE BULLETIN.										
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL			-			
MOC :										
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-34-11 R1; NAVIGATION-GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE, DATED JULY 13, 2011.										
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	GSO		MANDATORY	MTH 18-Apr-2012 HRS 436.9 LDG 293		-			Complete
MOC : COMPLIED WITH - C/W SB510-34-12R1, GARMIN DISPLAY IMPROVEMENT										
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)			MANDATORY	MTH		-			
MOC :										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	KSAT		MANDATORY	MTH 26-Oct-2012 HRS 540.5 LDG 352		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE SERVICE BULLETIN 510-34-14.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE	KICT		MANDATORY	MTH 06-Sep-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-34-16 R1; GARMIN GRS-77 AHRS SOFTWARE UPDATE, DATED SEPTEMBER 30, 2016.										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)	KICT		OPTIONAL	MTH 06-Sep-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-34-17 R02 GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE, REV.02 DATED 4/26/2017.										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL			-			
	MOC :									
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE			RECOMMENDED MTH			-			
	MOC :									
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
	MOC :									
SL 510-34-01	TRANSMITTAL OF GARMIN SERVICE ALERT 070424-00			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-05	GARMIN G1000 TRANSPONDER OPERATION CHANGE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-06	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0811, G1000 SERIES FLIGHT PLAN SEQUENCING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-07	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 0825 LPV AND LNAV/VNAV APPROACHES WITH THREE-CHARACTER AIRPORT IDENTIFIERS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-08	GPS/WAAS LOSS OF RECEPTION IN ALASKA, NORTHWEST CANADA, AND EASTERN RUSSIA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-10	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0915 REVISION A, G1000 SERIES NAVIGATION SUSPENDING DURING NON-PRECISION APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A			INFORMATIONAL MTH			A/R			
	MOC :									
SL 510-34-12	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0933 REVISION A, SYSTEM MAY SELECT NAV 2 AS A NAVIGATION SOURCE DURING APPROACH			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-13	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0922 REVISION A, VOR OR LOC/ILS APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-14	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0941 REV A. ERRONEOUS GWX SERVICE MESSAGE MAY BE DISPLAYED			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	GSO		RECOMMENDED MTH 12-Apr-2011			A/R			Complete
				HRS 245						
				LDG 173						
	MOC : COMPLIED WITH - C/W SL510-34-15, GARMIN SB 1017, GWX 68 WX RADAR MOD 1									
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSSUE INFORMATIONAL									
	MOC :									
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA INFORMATIONAL									
	MOC :									
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS INFORMATIONAL									
	MOC :									
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS INFORMATIONAL									
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION INFORMATIONAL									
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL INFORMATIONAL									
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT RECOMMENDED MTH									
	MOC :									
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS INFORMATIONAL									
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM) INFORMATIONAL									
	MOC :									
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG INFORMATIONAL									
	MOC :									
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS) INFORMATIONAL									
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001									
	KSTP	MANDATORY	MTH	24-Feb-2016			-		N/A	
				DAYS	1370.6					
				HRS	961					
				LDG						
	MOC : NOT APPLICABLE - INSPECTED MASKS AND FOUND SERVICE LETTER IS NOT APPLICABLE TO THE P/N AND S/N OF THE MASKS INSTALLED AT THIS TIME/DATE.									
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02) MANDATORY									
	MOC :									
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 MANDATORY									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-35-01; OXYGEN-TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, DATED SEPTEMBER										
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W AT PRODUCTION ON -0095 AND ON.										
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	KSTP		MANDATORY	DAYS 21-Jan-2020 HRS 1923.8 LDG 1376		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-52-06 BY REPLACING HANDLE SCREW AND NUT WITH CLEVIS PIN AND WASHER IAW ACCOMPLISHMENT INSTRUCTIONS										
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
MOC :										
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT				DAYS		-			
MOC :										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS	GSO		DISCRETIONARY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			Complete
MOC : COMPLIED WITH - C/W SB510-54-01 REV 1, PYLON SKIN IMPROVEMENT ON RH PYLON ONLY.										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)			MANDATORY			A/R			
MOC :										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)	ICT		MANDATORY	DAYS 27-Oct-2011 HRS 325.4 LDG 224		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-55-02 R2; STABILIZER - HORIZONTAL STABILIZER SEALANT INSPECTION, DATED AUGUST 31, 2011										
SL 510-57-02	WINGS - FLAP ACTUATOR BOLT REPLACEMENT			MANDATORY			-			
MOC :										
SB PW600-72-63000 R01 E1	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS			CATEGORY 11			-			
MOC :										
SB PW600-72-63000 R01 E2	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS			CATEGORY 11			-			
MOC :										
SB PW600-72-63001 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
MOC :										
SB PW600-72-63001 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)			CATEGORY 6	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
MOC :										
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
MOC :										
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63021 E1	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING			CATEGORY 6			-			
MOC :										
SB PW600-72-63021 E2	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING			CATEGORY 6			-			
MOC :										
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
MOC :										
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
MOC :										
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 8			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8				-			
MOC :								
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5				-			
MOC :								
SB PW600-72-63028 R01 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5				-			
MOC :								
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 R01 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63037 R01 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63043 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) CATEGORY 6						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63043 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02)	CATEGORY 6			-			
	MOC :							
SB PW600-72-63043 R02 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER	CATEGORY 6			-			
	MOC :							
SB PW600-72-63043 R02 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER	CATEGORY 6			-			
	MOC :							
SB PW600-72-63043 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)	CATEGORY 6	MTH 23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)	CATEGORY 6	MTH 30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY UNK	CATEGORY 6	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY UNK	CATEGORY 6	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY				-			
	MOC :							
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY				-			
	MOC :							
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)	CATEGORY 7	MTH 23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)	CATEGORY 7	MTH 30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63051 R01 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	CATEGORY 7			-			
	MOC :							
SB PW600-72-63051 R01 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	CATEGORY 7			-			
	MOC :							
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES	CATEGORY 6			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6				-			
MOC :								
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) CATEGORY 7	MTH 23-Jan-2010		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) CATEGORY 7	MTH 30-Nov-2009		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7			A/R				
MOC :								
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7			A/R				
MOC :								
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) CATEGORY 7	MTH 23-Jan-2010		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) CATEGORY 7	MTH 30-Nov-2009		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7			-				
MOC :								
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7			-				
MOC :								
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) CATEGORY 7	MTH 23-Jan-2010		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) CATEGORY 7	MTH 30-Nov-2009		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER CATEGORY 7	MTH 23-Jan-2010		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER CATEGORY 7	MTH 30-Nov-2009		-				Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST CATEGORY 9			-				
MOC :								
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST CATEGORY 9			-				
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 23-Jan-2010		-			Complete
	MOC :									
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 30-Nov-2009		-			Complete
	MOC :									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 23-Jan-2010		-			Complete
	MOC :									
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 30-Nov-2009		-			Complete
	MOC :									
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 23-Jan-2010		-			Complete
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
MOC :										
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 23-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 30-Nov-2009		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	UNK		CATEGORY 7	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	UNK		CATEGORY 7	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	UNK		CATEGORY 7	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		A/R			Complete
MOC : COMPLIED WITH										
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			-			
MOC :										
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			-			
MOC :										
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
MOC :										
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5				A/R			
MOC :								
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5				A/R			
MOC :								
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01) CATEGORY 5				A/R			
MOC :								
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01) CATEGORY 5				A/R			
MOC :								
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7				-			
MOC :								
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7				-			
MOC :								
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7				A/R			
MOC :								
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7				-			
MOC :								
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7				A/R			
MOC :								
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7				A/R			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KCHS		CATEGORY 3	MTH 05-Jun-2013 HRS 651.9 LDG 426		-			Complete
MOC : COMPLIED WITH - CW PWC SB 63087 OF LH FADEC PAR NO. 35C4035-04 SERIAL NO. 09-768. ALL MAINT DONE I.A.W. PWC SB 63087 AND CE510 SB510-76-01. OPS CHECKS GOOD.										
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KCHS		CATEGORY 3	MTH 05-Jun-2013 HRS 651.9 LDG 426		-			Complete
MOC : COMPLIED WITH - /W PWC SB 63087 R2 TO THE RH FADEC PART NO. 35C4035-04 SERIAL NO. 09-773. ALL MANIT I.A.W. PWC SB 63087 R2 AND CE510 SB510-76-01. OPS CHECKS GOOD.										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
MOC :										
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF	UNK		CATEGORY 6	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
MOC :										
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
MOC :										
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS	CATEGORY 6	(SUPERSEDED BY PW600-72-63091 R02)		-			
	MOC :							
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS UNK	CATEGORY 6	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS UNK	CATEGORY 6	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)	CATEGORY 6			-			
	MOC :							
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)	CATEGORY 6			-			
	MOC :							
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7				-			
	MOC :							
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7				-			
	MOC :							
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6				A/R			
	MOC :							
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6				A/R			
	MOC :							
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7				-			
	MOC :							
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			CATEGORY 5			-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		RECOMMENDED	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC :									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		RECOMMENDED	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
	MOC :									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
	MOC :									
SB PW600-72-63102 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63102 R01)			RECOMMENDED	MTH		-			
	MOC :									
SB PW600-72-63102 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63102 R01)			RECOMMENDED	MTH		-			
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE	UNK		CATEGORY 5	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE	UNK		CATEGORY 5	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE	UNK		CATEGORY 5	MTH 19-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE	BTV		CATEGORY 5	MTH 10-Aug-2018 HRS 1752.5 LDG 1255		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING			CATEGORY 3	MTH		-			
MOC :										
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING			CATEGORY 3	MTH		-			
MOC :										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KSTP		CATEGORY 3	MTH 11-Nov-2021 HRS 2399.9 LDG 1575		-			N/A
MOC : NOT APPLICABLE - FOUND NOT APPLICABLE DUE TO INSTALLATION DATE OF AFFECTED SEAL.										
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KSTP		CATEGORY 3	MTH 11-Nov-2021 HRS 2399.9 LDG 1575		-			N/A
MOC : NOT APPLICABLE - FOUND NOT APPLICABLE DUE TO INSTALLATION DATE OF AFFECTED SEAL.										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7				-			
MOC :								
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) ICT CATEGORY 3	MTH 08-Sep-2010 HRS 129.7 LDG 90			A/R			Complete
MOC : COMPLIED WITH - PREVIOUSLY ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 12/10/2009. REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.								
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) ICT CATEGORY 3	MTH 08-Sep-2010 HRS 129.7 LDG 90			A/R			Complete
MOC : COMPLIED WITH - PREVIOUSLY ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 1/14/2010. REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.								
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3				-			
MOC :								
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3				-			
MOC :								
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				A/R			
MOC :								
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				A/R			
MOC :								
ASL 510-73-01 LEFT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE ICT MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224			A/R			Complete
MOC : COMPLIED WITH - ASL510-73-01 HAS BEEN SUPERSEDED BY ASL510-73-02								
ASL 510-73-01 RIGHT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE ICT MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224			-			Complete
MOC : COMPLIED WITH - ASL510-73-01 HAS BEEN SUPERSEDED BY ASL510-73-02. REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL - FILTER BYPASS VALVE. REFERENCE MTR I.D. #1673536 DATED 08-SEP-2010, ITEM NAME P&WC SB NO. A63071 FOR COMPLETION OF ASL								
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE ICT MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224			A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED ASL510-73-02, LH ENGINE TRANSMITTAL OF P&WC SB A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL - FILTER BYPASS VALVE. REFERENCE MTR I.D. #1673529 DATED 08-SEP-2010, ITEM NAME P&WC SB NO. A63071 FOR COMPLETION OF ASL.								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED ASL510-73-02,R/H ENGINE TRANSMITTAL OF P&WC SB A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL - FILTER BYPASS VALVE. REFERENCE MTR I.D. #1673536 DATED 08-SEP-2010, ITEM NAME P&WC SB NO. A63071 FOR COMPLETION OF ASL.										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8				MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8				MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7				MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7				MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6						A/R			
MOC :										
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6				MTH 30-Nov-2009		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7						A/R			
MOC :										
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7						A/R			
MOC :										
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6						A/R			
MOC :										
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6						A/R			
MOC :										
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)	CATEGORY 6			A/R			
MOC :								
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)	CATEGORY 3			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.								
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)	CATEGORY 3			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.								
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	CATEGORY 3	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	CATEGORY 3	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
ASB PW600-72-A63069 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63069 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63069 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63069 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63069 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	CATEGORY 3			A/R			
MOC :								
ASB PW600-72-A63069 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01)	CATEGORY 3			A/R			
MOC :								
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN	CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN	CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8				-			
MOC :								
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8				-			
MOC :								
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7	MTH	30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7	MTH	23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7	MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7	MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7	MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7	MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7	MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63050 E1	LIMITED INCORPORATION OF FUEL MANIFOLD PINS CATEGORY 10				-			
	MOC :							
SB PW600-73-63050 E2	LIMITED INCORPORATION OF FUEL MANIFOLD PINS CATEGORY 10				-			
	MOC :							
SB PW600-73-63115 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7	MTH			-			
	MOC :							
SB PW600-73-63115 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7	MTH			-			
	MOC :							
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7				-			
	MOC :							
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7				-			
	MOC :							
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER CATEGORY 7	MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER CATEGORY 7	MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6	MTH	23-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6	MTH	30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7			-			
MOC :										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7			-			
MOC :										
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01)			CATEGORY 7	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01)			CATEGORY 7	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087	KCHS		MANDATORY	MTH 05-Jun-2013 HRS 670.3 LDG 439		-			Complete
MOC : COMPLIED WITH - C/W SB510-76-01 R2 FOR BOTH LH FADEC PART NO:35C4035-04 SERIAL NO. 09-768 AND RH FADEC PART NO. 35C4035-04 SERIAL NO. 09-773 I.A.W. SB510-76-01 R2 INSTRUCTIONS. REF PW600-72-63087SERVICE BULLETINE. OPS CHECKS GOOD.										
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT			RECOMMENDED	MTH		-			New Req
MOC :										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH 23-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH 30-Nov-2009		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL			-			
MOC :										
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION	GSO		MANDATORY	DAYS 12-Apr-2011 HRS 245 LDG 173		A/R			Complete
MOC : COMPLIED WITH - C/W SL510-79-02, OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION										
SL 510-79-03 REV 01	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT			MANDATORY			-			
MOC :										
SL 510-79-03	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT (SUPERSEDED BY SL510-79-03 REV 01)			MANDATORY	MTH		-			
MOC :										
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
MOC :										
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB PW600-72- 63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 23-Jan-2010		-			Complete
	MOC :									
SB PW600-72- 63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 30-Nov-2009		-			Complete
	MOC :									
SB PW600-72- 63068 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)			CATEGORY 6	MTH 23-Jan-2010		A/R			Complete
	MOC :									
SB PW600-72- 63068 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)			CATEGORY 6	MTH 30-Nov-2009		A/R			Complete
	MOC :									
SB PW600-72- 63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72- 63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-79- 63008 R01 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)			CATEGORY 5			-			
	MOC :									
SB PW600-79- 63008 R01 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)			CATEGORY 5			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63008 R02 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5				-			
MOC :								
SB PW600-79-63008 R02 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5				-			
MOC :								
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01) MTH 23-Jan-2010				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01) MTH 30-Nov-2009				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH 23-Jan-2010			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH 30-Nov-2009			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				-			
MOC :								
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				-			
MOC :								
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7	MTH 23-Jan-2010			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7	MTH 30-Nov-2009			-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-79-63047 R01 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02) CATEGORY 3				-			
MOC :								
SB PW600-79-63047 R01 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02) CATEGORY 3				-			
MOC :								
SB PW600-79-63047 R03 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS CATEGORY 3				-			
MOC :								
SB PW600-79-63047 R03 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS CATEGORY 3				-			
MOC :								
SB PW600-79-63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01) MTH 23-Jan-2010				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)				MTH 30-Nov-2009		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SL 510-80-01	ENGINE STARTING			INFORMATIONAL			-			
	MOC :									
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM			RECOMMENDED	MTH		-			
	MOC :									
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
	MOC :									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
	MOC :									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KSTP		MANDATORY	MTH 31-Jul-2015 HRS 1221.2 LDG 849		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT. AFFECTED SEATS ARE NOT INSTALLED IN THIS AIRCRAFT AT THIS TIME/DATE.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KSTP		MANDATORY	MTH 31-Jul-2015 HRS 1221.2 LDG 849		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT. AFFECTED SEATS ARE NOT INSTALLED IN THIS AIRCRAFT AT THIS TIME/DATE.										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KSTP		MANDATORY	MTH 31-Jul-2015 HRS 1221.2 LDG 849		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT. AFFECTED SEATS ARE NOT INSTALLED IN THIS AIRCRAFT AT THIS TIME/DATE.										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KSTP		MANDATORY	MTH 31-Jul-2015 HRS 1221.2 LDG 849		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT. AFFECTED SEATS ARE NOT INSTALLED IN THIS AIRCRAFT AT THIS TIME/DATE.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KSTP			MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KSTP		MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KSTP		MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE.										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	GSO		MANDATORY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			N/A
MOC : NOT APPLICABLE - FAA 2021-07-13 APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT DOES NOT APPLY. P/N BUCKLE NOT INSTALLED ON AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	GSO		MANDATORY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			N/A
MOC : NOT APPLICABLE - FAA 2021-07-13 APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT DOES NOT APPLY. P/N BUCKLE NOT INSTALLED ON AIRCRAFT.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	GSO		MANDATORY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			N/A
MOC : NOT APPLICABLE - FAA 2021-07-13 APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT DOES NOT APPLY. P/N BUCKLE NOT INSTALLED ON AIRCRAFT.										
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	GSO		MANDATORY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			N/A
MOC : NOT APPLICABLE - FAA 2021-07-13 APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT DOES NOT APPLY. P/N BUCKLE NOT INSTALLED ON AIRCRAFT.										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
MOC :										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
EASA 2009-0251-E	APPLIANCE/EMERGENCY AD - FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION /REPLACEMENT	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPPED WITH AMEREX FIRE BOTTLES, THIS AD IS NOT APPLICABLE.										
EASA 2009-0262	APPLIANCE AD - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT (SUPERSEDED BY 2009-0262 R01)			SUPERSEDED			A/R			
MOC :										
EASA 2009-0278	APPLIANCE AD - FIRE PROTECTION - PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPPED WITH AMEREX FIRE BOTTLES, THIS AD IS NOT APPLICABLE.										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPPED WITH AMEREX FIRE BOTTLES, THIS AD IS NOT APPLICABLE.										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	ICT		MANDATORY	MTH 27-Oct-2011 HRS 325.4 LDG 224		A/R			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPPED WITH AMEREX FIRE BOTTLES, THIS AD IS NOT APPLICABLE.										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	GSO		MANDATORY	MTH 05-May-2022 HRS 2662.5 LDG 1732		-			Complete
MOC : COMPLIED WITH - C/W FAA 2021-23-12 APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS.										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	KSTP		MANDATORY	DAYS 04-May-2018 HRS 1722.6		-			Complete
MOC : COMPLIED WITH - FOUND AIRWORTHINESS DIRECTIVE 2018-07-13 IS APPLICABLE DUE TO SERIAL NUMBERS OF BRAKES INSTALLED. BRAKE SERIAL NUMBERS LISTED IN TABLE 1 OF SERVICE BULLETIN 2-1706-1-32-1. LEFT SERIAL NUMBER: 07250. RIGHT SERIAL NUMBER: 0728. HOWEVER, SERVICE BULLETIN 2-1706-1-32-1 REVISION 1, DATED JULY 18, 2017 HAS PREVIOUSLY BEEN COMPLIED WITH. BRAKE WEAR PINS MEASURE LESS THAN 1.65" AND HAVE ALREADY BEEN PAINTED YELLOW.										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KSTP		MANDATORY	MTH 31-Jul-2015 HRS 1221.2 LDG 849		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT. AVIDYNE INTEGRATED FLIGHT DISPLAY IS NOT INSTALLED IN THIS AIRCRAFT AT THIS TIME/DATE.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
MOC :										
FAA 2009-21-10	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE (SUPERSEDED BY 2009-21-10 R1)			SUPERSEDED			A/R			
MOC :										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KSTP		MANDATORY	MTH 29-May-2015 HRS 1168 LDG 807		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES	KSTP		MANDATORY	MTH 29-May-2015 HRS 1168 LDG 807		-			Complete
MOC : COMPLIED WITH										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES	KSTP		MANDATORY	MTH 29-May-2015 HRS 1168 LDG 807		-			Complete
MOC : COMPLIED WITH										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KSTP		MANDATORY	MTH 24-Feb-2016 DAYS 1370.6 HRS 961 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KSTP		MANDATORY	MTH 24-Feb-2016 DAYS 1370.6 HRS 961 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KSTP		MANDATORY	MTH 24-Feb-2016 DAYS 1370.6 HRS 961 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KSTP		MANDATORY	MTH 24-Feb-2016 DAYS 1370.6 HRS 961 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KSTP		MANDATORY	MTH 24-Feb-2016 HRS 1370.6 LDG 961		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KSTP		MANDATORY	MTH 24-Feb-2016 HRS 1370.6 LDG 961		-			N/A
MOC : NOT APPLICABLE - INSPECTED O2 MASKS IAW ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001. FOUND AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY P/N AND S/N OF THE INSTALLED MASKS AT THIS TIME/DATE.										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THERE ARE NO PBE'S INSTALLED AT THIS TIME/DATE.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THERE ARE NO PBE'S INSTALLED AT THIS TIME/DATE.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THERE ARE NO PBE'S INSTALLED AT THIS TIME/DATE.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 30-Jun-2016 HRS 1448.9 LDG 1016		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THERE ARE NO PBE'S INSTALLED AT THIS TIME/DATE.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.			MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES			MANDATORY	MTH 06-Dec-2017 HRS 1678.3 LDG 1190		-			N/A
		KSTP								
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE. THE AFFECT EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT AT THIS TIME/DATE										



CESCOM 10 - Aircraft Status Report

Owner: **198GB, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0307**
Unit: **307** Reg No: **N872G**
Airworthiness: **08-Apr-2010**
Print Date: **17-Apr-2025 8:29PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3366.8	2154	07-Apr-2025	.68
ENG 1	3366.8	2154	07-Apr-2025	.68
ENG 2	3366.8	2154	07-Apr-2025	.68

Airworthiness Directives

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E1		ICT		MANDATORY	MTH 08-Sep-2010		-			Complete
					HRS 129.7					
					LDG 90					

MOC : COMPLIED WITH - PREVIOUSLY ACCOMPLISHED AD2010-17-06, PW615F-A FOHE FUEL FILTER BYPASS VALVE POPPET, EFFECTIVE DATE SEPT/27/2010. ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 12/10/2009. REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.

FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E2		ICT	MANDATORY	MTH 08-Sep-2010			-			Complete
				HRS 129.7						
				LDG 90						

MOC : COMPLIED WITH - PREVIOUSLY ACCOMPLISHED AD2010-17-06, PW615F-A FOHE FUEL FILTER BYPASS VALVE POPPET, EFFECTIVE DATE SEPT/27/2010. ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 01/14/2010. REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.