



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
4-12-MA	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MA KEXX			MTH HRS LDG	11-Jul-2016 1196 760		1200		2396	222.3
4-12-MB	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MB			MTH HRS	01-Jun-2011 0		2500		2500	326.3
4-12-MC	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MC			MTH HRS	01-Jun-2011 0		4000		4000	1826.3
4-12-MD	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MD			MTH HRS	01-Jun-2011 0		5000		5000	2826.3
4-12-ME	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT ME			MTH HRS	01-Jun-2011 0		5500		5500	3326.3
4-12-MF	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MF			MTH HRS	01-Jun-2011 0		8600		8600	6426.3
4-12-MG	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MG			MTH HRS	01-Jun-2011 0		12000		12000	9826.3
4-12-MH	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MH			MTH HRS	01-Jun-2011 0		12000		12000	9826.3
4-12-MI	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MI KBCB			MTH HRS LDG	21-Aug-2019 1575.4 1117		800		2375.4	201.7
4-12-MK	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MK KSIF			MTH HRS LDG	27-Dec-2022 1946.4 1480		400		2346.4	172.7
4-12-ML	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT ML			MTH HRS	01-Jun-2011 0		12000		12000	9826.3
4-12-MM	AIRWORTHINESS LIMITATIONS INSPECTION DOCUMENT MM KSIF			MTH HRS LDG	25-Jun-2024 2108.1 1636		12 330		30-Jun-2025 2438.1	5 m 6 d 264.4
050000	SAMPLE OIL SOAP	KEXX		MTH HRS LDG	19-Aug-2015 990.2 603		-			
052514	REGISTRATION AIRCRAFT KSIF			MTH HRS LDG	02-Jul-2020 1657.8 1208		A/R			
053401 #1	REPLACE ADC INTERNAL BATTERY KGYH			MTH HRS LDG	18-Jul-2023 2006.2 1524		144		31-Jul-2035	126 m 7 d
053401 #2	REPLACE ADC INTERNAL BATTERY KGYH			MTH HRS LDG	18-Jul-2023 2006.2 1524		144		31-Jul-2035	126 m 7 d
053402	REPLACE MDC INTERNAL BATTERY KSIF			MTH HRS LDG	12-Feb-2021 1719.6 1265		84		29-Feb-2028	37 m 5 d
053404 #1	REPLACE FMC INTERNAL BATTERY			MTH	01-Oct-2020		60		31-Oct-2025	9 m 7 d
053404 #2	REPLACE FMC INTERNAL BATTERY			MTH	01-Oct-2020		60		31-Oct-2025	9 m 7 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK		MTH	01-Jun-2011		A/R			
055002	ACCOMPLISH OVERSPEED CHECK		MTH	01-Jun-2011		A/R			
055003	ACCOMPLISH SEVERE AIR TURBULENCE CHECK		MTH	01-Jun-2011		A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK KEXX		MTH HRS LDG	22-Jul-2015 967.7 575		A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK		MTH	01-Jun-2011		A/R			
055006	ACCOMPLISH TOWING WITH A LARGE FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK		MTH	01-Jun-2011		A/R			
055007	ACCOMPLISH TOWS MORE THAN THE MECHANICAL LIMITS WITH RUDDER GUST LOCK ENGAGED		MTH	01-Jun-2011		A/R			
057103 L/H	WASH DESALINIZATION		MTH	01-Jun-2011		A/R			
057103 R/H	WASH DESALINIZATION		MTH	01-Jun-2011		A/R			
5-12-01	NON-MSG-3 INSPECTION DOCUMENT 01		MTH HRS LDG	28-Dec-2024 2170 1698		12		31-Dec-2025	11 m 7 d
5-12-02	NON-MSG-3 INSPECTION DOCUMENT 02 KBCB		MTH HRS LDG	15-Jun-2023 1994.3 1512		24		30-Jun-2025	5 m 6 d
5-12-03	NON-MSG-3 INSPECTION DOCUMENT 03 KBCB		MTH HRS LDG	15-Jun-2023 1994.3 1512		48		30-Jun-2027	29 m 6 d
5-12-05	NON-MSG-3 INSPECTION DOCUMENT 05 KICT		MTH HRS LDG	19-Jun-2017 1375.2 897		96		30-Jun-2025	5 m 6 d
5-12-06	NON-MSG-3 INSPECTION DOCUMENT 06 KBCB		MTH HRS LDG	15-Jun-2023 1994.3 1512		144		30-Jun-2035	125 m 6 d
5-12-07	NON-MSG-3 INSPECTION DOCUMENT 07 KSIF		MTH HRS LDG	25-Jun-2024 2108.1 1636		12 400		30-Jun-2025 2508.1	5 m 6 d 334.4
5-12-08	NON-MSG-3 INSPECTION DOCUMENT 08 KBCB		MTH HRS LDG	15-Jun-2023 1994.3 1512		24 1600		30-Jun-2025 3594.3	5 m 6 d 1420.6
5-12-09	NON-MSG-3 INSPECTION DOCUMENT 09 KBCB		MTH HRS LDG	15-Jun-2023 1994.3 1512		48 1600		30-Jun-2027 3594.3	29 m 6 d 1420.6
B237101	OPERATIONAL CHECK COCKPIT VOICE RECORDER COCKPIT VOICE RECORDER SYSTEM KGYH		2100-1020-02 000688211 MTH HRS LDG	18-Jul-2023 2006.2 1524		48 1600		31-Jul-2027 3606.2	30 m 7 d 1432.5
B237103	FUNCTIONAL CHECK COCKPIT VOICE RECORDER COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON KGYH		2100-1020-02 000688211 MTH HRS LDG	18-Jul-2023 2006.2 1524		48 1600		31-Jul-2027 3606.2	30 m 7 d 1432.5



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B313103	FLIGHT DATA RECORDER LOCATOR BEACON FUNCTIONAL CHECK	KGYH		DK120 NSN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		31-Jul-2027 3606.2	30 m 7 d 1432.5
5-12-11	NON-MSG-3 INSPECTION DOCUMENT 11	KSIF			MTH 27-Dec-2022 HRS 1946.4 LDG 1480		400		2346.4	172.7
5-12-12	NON-MSG-3 INSPECTION DOCUMENT 12				MTH 28-Dec-2024 HRS 2170 LDG 1698		4 200			
B243115	LEAD-ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) TASK 24-31-10-722			S3597-4 41353649	MTH 28-Dec-2024 HRS 2170 LDG 1698		4 200		30-Apr-2025 2370	3 m 6 d 196.3
5-12-13	NON-MSG-3 INSPECTION DOCUMENT 13	KBCB			MTH 21-Aug-2019 HRS 1575.4 LDG 1117		800		2375.4	201.7
5-12-17	NON-MSG-3 INSPECTION DOCUMENT 17 (NOT CURRENTLY USED)				MTH 01-Jun-2011		144			
5-12-18	NON-MSG-3 INSPECTION DOCUMENT 18 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 01-Jun-2011 HRS 0 LDG 0		T/C			
A324109 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR WHEEL ASSEMBLY (NDI) SPECIAL DETAILED INSPECTION	KEXX		90006036 MAR15-0497	MTH 30-Oct-2015 HRS 1040.9 LDG 647		T/C			
A324109 NOSE LANDING GEAR	NOSE LANDING GEAR WHEEL ASSEMBLY (NDI) SPECIAL DETAILED INSPECTION			90006044 OCT100068	MTH 01-Jun-2011		T/C			
A324109 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY (NDI) SPECIAL DETAILED INSPECTION	GSO		90006036 OCT10-0131	MTH		T/C			
5-12-21	NON-MSG-3 INSPECTION DOCUMENT 21				MTH 01-Jun-2011 HRS 0		12000		12000	9826.3
B221111	OPERATIONAL CHECK FLIGHT GUIDANCE PANEL COLLINS FGP-3000			822-1107-136 3VHXY	MTH 01-Jun-2011 HRS 0		12000		12000	9826.3
B323101	MAIN LANDING GEAR CONTROL VALVE FUNCTIONAL CHECK			4270-1 0051	MTH 01-Jun-2011 HRS 0		12000		12000	9826.3
5-12-22	NON-MSG-3 INSPECTION DOCUMENT 22	KSIF			MTH 22-May-2022 HRS 1853 LDG 1390		1850		3703	1529.3
5-12-23	NON-MSG-3 INSPECTION DOCUMENT 23	KICT			MTH 19-Jun-2017 HRS 1375.2 LDG 897		1400		2775.2	601.5
5-12-24	NON-MSG-3 INSPECTION DOCUMENT 24				MTH 01-Jun-2011 HRS 0		2850		2850	676.3
5-12-25	NON-MSG-3 INSPECTION DOCUMENT 25	KSIF			MTH 27-Apr-2021 HRS 1737.9 LDG 1285		900		2637.9	464.2
5-12-26	NON-MSG-3 INSPECTION DOCUMENT 26	KSIF			MTH 22-May-2022 HRS 1853 LDG 1390		625		2478	304.3



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-28	NON-MSG-3 INSPECTION DOCUMENT 28			MTH HRS	01-Jun-2011 0		2800		2800	626.3
5-12-29	NON-MSG-3 INSPECTION DOCUMENT 29 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	01-Jun-2011 0 0		12 100			
5-12-31	NON-MSG-3 INSPECTION DOCUMENT 31 KSIF			MTH HRS LDG	25-Jun-2024 2108.1 1636		24 300		30-Jun-2026 2408.1	17 m 6 d 234.4
5-12-32	NON-MSG-3 INSPECTION DOCUMENT 32			MTH HRS LDG	28-Dec-2024 2170 1698		6		30-Jun-2025	5 m 6 d
5-12-33	NON-MSG-3 INSPECTION DOCUMENT 33 (NOT CURRENTLY USED)			MTH	01-Jun-2011		N/A			
5-12-34	NON-MSG-3 INSPECTION DOCUMENT 34			MTH HRS LDG	14-Jul-2020 1660.2 1212		7200		8860.2	6686.5
35-31-00-2100	PROTECTIVE BREATHING EQUIPMENT GENERAL VISUAL INSPECTION PN SN-UNKNOWN			MTH	01-Jun-2011		N/A			
05-50-00-870-803-01 E1	POLISH FAN ROTOR			MTH	01-Jun-2011		A/R			
05-50-00-870-803-01 E2	POLISH FAN ROTOR			MTH	01-Jun-2011		A/R			
052001 E1	FJ44 CHECK 1	KBCB		MTH HRS LDG	17-Aug-2023 2023.8 1543		300		(2308.6)2323.8	150.1
052001 E2	FJ44 CHECK 1	KBCB		MTH HRS LDG	17-Aug-2023 2023.8 1543		300		(2323.8)2323.8	150.1
052002 E1	FJ44 CHECK 2	GYH		MTH HRS LDG	16-Mar-2021 1731.2 1278		600		(2316)2331.2	157.5
052002 E2	FJ44 CHECK 2	GYH		MTH HRS LDG	16-Mar-2021 1732.2 1278		600		(2332.2)2332.2	158.5
052003 E1	FJ44 CHECK 3			MTH HRS	01-Jun-2011 15.2	-12500	15000		(2500)2515.2	341.5
052003 E2	FJ44 CHECK 3			MTH HRS	01-Jun-2011 0	-12500	15000		(2500)2500	326.3
052004 E1	FJ44 CHECK 4			MTH HRS	01-Jun-2011 15.2	-10000	15000		(5000)5015.2	2841.5
052004 E2	FJ44 CHECK 4			MTH HRS	01-Jun-2011 0	-10000	15000		(5000)5000	2826.3
052005 E1	FJ44 CHECK 5			MTH HRS	01-Jun-2011 15.2	-7500	15000		(7500)7515.2	5341.5
052005 E2	FJ44 CHECK 5			MTH HRS	01-Jun-2011 0	-7500	15000		(7500)7500	5326.3
052006 E1	FJ44 CHECK 6			MTH HRS	01-Jun-2011 15.2	-5000	15000		(10000)10015.2	7841.5
052006 E2	FJ44 CHECK 6			MTH HRS	01-Jun-2011 0	-5000	15000		(10000)10000	7826.3
052007 E1	FJ44 CHECK 7			MTH HRS	01-Jun-2011 15.2	-2500	15000		(12500)12515.2	10341.5
052007 E2	FJ44 CHECK 7			MTH HRS	01-Jun-2011 0	-2500	15000		(12500)12500	10326.3

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052008 E1	FJ44 CHECK 8			MTH HRS	01-Jun-2011 15.2		15000		(15000)15015.2	12841.5
052008 E2	FJ44 CHECK 8			MTH HRS	01-Jun-2011 0		15000		(15000)15000	12826.3
052009 E1	FJ44 CHECK 9			MTH HRS	01-Jun-2011 15.2		17500		(17500)17515.2	15341.5
052009 E2	FJ44 CHECK 9			MTH HRS	01-Jun-2011 0		17500		(17500)17500	15326.3
052010 E1	FJ44 CHECK 10			MTH HRS	01-Jun-2011 15.2		20000		(20000)20015.2	17841.5
052010 E2	FJ44 CHECK 10			MTH HRS	01-Jun-2011 0		20000		(20000)20000	17826.3
052011 E1	FJ44 CHECK 11			MTH HRS	01-Jun-2011 15.2		22500		(22500)22515.2	20341.5
052011 E2	FJ44 CHECK 11			MTH HRS	01-Jun-2011 0		22500		(22500)22500	20326.3
052012 E1	FJ44 CHECK 12			MTH HRS	01-Jun-2011 15.2		25000		(25000)25015.2	22841.5
052012 E2	FJ44 CHECK 12			MTH HRS	01-Jun-2011 0		25000		(25000)25000	22826.3
052013 E1	FJ44 CHECK 13			MTH HRS	01-Jun-2011 15.2		27500		(27500)27515.2	25341.5
052013 E2	FJ44 CHECK 13			MTH HRS	01-Jun-2011 0		27500		(27500)27500	25326.3
052014 E1	FJ44 CHECK 14			MTH HRS	01-Jun-2011 15.2		30000		(30000)30015.2	27841.5
052014 E2	FJ44 CHECK 14			MTH HRS	01-Jun-2011 0		30000		(30000)30000	27826.3
23-71-00-960	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD			DK120/90 AT181058	MTH HRS LDG				01-Aug-2029	54 m 8 d
							DUE DUE DUE DUE			
24-31-10-960	A123 LITHIUM-ION BATTERY PACK DISCARD			S3597-4 41353649	MTH		N/A			
25-61-00-220	EMERGENCY LOCATOR TRANSMITTER DETAILED INSPECTION	KSIF		453-5060 10476	MTH HRS LDG		12		30-Jun-2025	5 m 6 d
25-61-00-720	EMERGENCY LOCATOR TRANSMITTER FUNCTIONAL CHECK	KSIF		453-5060 10476	MTH HRS LDG	-8	12		30-Jun-2025	5 m 6 d
25-61-00-960	EMERGENCY LOCATOR BEACON BATTERY DISCARD			452-0133 391747-036	MTH HRS LDG				01-Oct-2026	20 m 7 d
							DUE DUE DUE DUE			
26-21-10-780	ENGINE FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION			FX02200-1 0024	MTH		60		31-Mar-2026	14 m 7 d
26-21-15-960.1 NO. 1	NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (SQUIB) DISCARD - SERVICE LIFE			PN SN-UNKNOWN	MTH		144		30-Apr-2033	99 m 6 d
26-21-15-960.1 NO. 2	NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (SQUIB) DISCARD - SERVICE LIFE			PN SN-UNKNOWN	MTH		144		30-Apr-2033	99 m 6 d



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
26-23-00-720 CABIN	CABIN HALON PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK) FUNCTIONAL CHECK	KGSO		C352TS E-68635450	MTH 27-Dec-2024 HRS 2170 LDG 1698		12		31-Dec-2025	11 m 7 d
Weight Check Date: 27-Dec-2024										
26-23-00-720 COCKPIT	COCKPIT HALON PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK) FUNCTIONAL CHECK	KGSO		C352TS E-68635451	MTH 27-Dec-2024 HRS 2170 LDG 1698		12		31-Dec-2025	11 m 7 d
Weight Check Date: 27-Dec-2024										
26-23-00-780 CABIN	CABIN HALON PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK			C352TS E-68635450	MTH 26-Apr-2018		144		30-Apr-2030	63 m 6 d
26-23-00-780 COCKPIT	COCKPIT HALON PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK			C352TS E-68635451	MTH 26-Apr-2018		144		30-Apr-2030	63 m 6 d
26-23-00-960 CABIN	CABIN HALON PORTABLE FIRE EXTINGUISHER RESTORATION	KSIF		C352TS E-68635450	MTH 13-May-2024 HRS 2099.8 LDG 1621		72		31-May-2030	64 m 7 d
26-23-00-960 COCKPIT	COCKPIT HALON PORTABLE FIRE EXTINGUISHER RESTORATION	KSIF		C352TS E-68635451	MTH 13-May-2024 HRS 2099.8 LDG 1621		72		31-May-2030	64 m 7 d
B262303 CABIN	RESTORATION PORTABLE FIRE EXTINGUISHER	KBCB			MTH 26-Apr-2018		144		30-Apr-2030	63 m 6 d
Hydro Check Date: 26-Apr-2018										
B262303 COCKPIT	RESTORATION PORTABLE FIRE EXTINGUISHER	KBCB			MTH 26-Apr-2018		144		30-Apr-2030	63 m 6 d
Hydro Check Date: 26-Apr-2018										
27-65-10-9600	GROUND SPOILER ACTUATOR RESTORATION				MTH 01-Jun-2011 HRS 0		12000		12000	9826.3
29-11-00-9600 BYPASS	HYDRAULIC BYPASS FILTER ELEMENT - DISCARD			9914672-5 SN-UNKNOWN	MTH		N/A			
29-11-00-9600 RETURN	HYDRAULIC RETURN FILTER ELEMENT - DISCARD			9914672-3 SN-UNKNOWN	MTH		N/A			
29-11-00-960 BYPASS	HYDRAULIC BYPASS FILTER ELEMENT - DISCARD	KGYH		9914672-5 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		18-Jul-2027 3606.2	29 m 24 d 1432.5
29-11-00-960 LEFT	LEFT NON-BYPASS HYDRAULIC FILTER ELEMENT - DISCARD	KGYH		9914465-10 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		18-Jul-2027 3606.2	29 m 24 d 1432.5
29-11-00-960 LINE	HYDRAULIC LINE FILTER ELEMENT - DISCARD	KGYH		9912579-2 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		31-Jul-2027 3606.2	30 m 7 d 1432.5
29-11-00-960 RETURN	HYDRAULIC RETURN FILTER ELEMENT - DISCARD	KGYH		9914672-3 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		18-Jul-2027 3606.2	29 m 24 d 1432.5
29-11-00-960 RIGHT	RIGHT NON-BYPASS HYDRAULIC FILTER - DISCARD	KGYH		9914465-10 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		18-Jul-2027 3606.2	29 m 24 d 1432.5



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
32-11-00-9600	LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD									
LEFT MAIN LANDING GEAR				7194005-13 41	MTH 01-Jun-2011 LDG 0		20000		20000	18299
32-11-00-9600	RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD									
RIGHT MAIN LANDING GEAR				7194005-14 40	MTH 01-Jun-2011 LDG 0		20000		20000	18299
32-11-00-9601	LEFT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD									
LEFT MAIN LANDING GEAR				7141030-3 41	MTH 01-Jun-2011 LDG 0		43300		43300	41599
32-11-00-9601	RIGHT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD									
RIGHT MAIN LANDING GEAR				7141030-4 41	MTH 01-Jun-2011 LDG 0		43300		43300	41599
32-11-00-9602	LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD									
LEFT MAIN LANDING GEAR				7141050-3 52	MTH 05-Nov-2011 HRS 101.6 LDG 49		23300		23349	21648
32-11-00-9602	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD									
RIGHT MAIN LANDING GEAR				7141050-3 06	MTH 26-May-2011 LDG 0		23300		23300	21599
32-11-00-9603	LEFT MAIN LANDING GEAR HYDRAULIC ACTUATOR DISCARD									
LEFT MAIN LANDING GEAR				FA100114-002 0098	MTH 01-Jun-2011 LDG 0		15000		15000	13299
32-11-00-9603	RIGHT MAIN LANDING GEAR HYDRAULIC ACTUATOR DISCARD									
RIGHT MAIN LANDING GEAR				FA100114-002 0101	MTH 01-Jun-2011 LDG 0		15000		15000	13299
32-21-00-9600	NOSE LANDING GEAR ASSEMBLY DISCARD									
NOSE				7142010-7 NSN	MTH 01-Jun-2011 LDG 0		26000		26000	24299
32-21-00-9601	NOSE LANDING GEAR HYDRAULIC ACTUATOR DISCARD									
NOSE LANDING GEAR				FA100115-002 0052	MTH 01-Jun-2011 LDG 0		15000		15000	13299
32-37-10-780	EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST) RESTORATION									
				40005414-1 7283	MTH 31-Mar-2022		36		31-Mar-2025	2 m 7 d
Hydro Check Date: 31-Mar-2022										
32-37-10-960	EMERGENCY PNEUMATIC BOTTLE DISCARD									
				40005414-1 7283	MTH 22-May-2022 HRS 1853 LDG 1390		288		30-Jun-2034	113 m 6 d
32-43-50-960	BRAKE SYSTEM FILTER ELEMENT DISCARD									
	KG YH			037913-04-53 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		48 1600		31-Jul-2027 3606.2	30 m 7 d 1432.5
B323711	EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST) RESTORATION									
	KSIF				MTH 31-Mar-2022		36		31-Mar-2025	2 m 7 d
Hydro Check Date: 31-Mar-2022										
33-51-00-961	AFT EMERGENCY LIGHTING BATTERY PACK RESTORATION									
AFT	KGSO			CBS28-1 2314M	MTH 27-Dec-2024 HRS 2170 LDG 1698		48		31-Dec-2028	47 m 7 d
33-51-00-961	FORWARD EMERGENCY LIGHTING BATTERY PACK RESTORATION									
FORWARD	KGSO			CBS28-1 2480M	MTH 27-Dec-2024 HRS 2170 LDG 1698		48		31-Dec-2028	47 m 7 d
33-51-00-961	MAIN EMERGENCY LIGHTING BATTERY PACK RESTORATION									
MAIN	KGSO			CBS28-1 2551M	MTH 27-Dec-2024 HRS 2170 LDG 1698		48		31-Dec-2028	47 m 7 d
34-13-00-720	NO. 1 AIR DATA COMPUTER PITOT-STATIC SYSTEM FUNCTIONAL CHECK									
NO. 1	KG YH			822-1109-128 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		24		31-Jul-2025	6 m 7 d



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
34-13-00-720 NO. 2	NO. 2 AIR DATA COMPUTER PITOT-STATIC SYSTEM FUNCTIONAL CHECK	KGYH		822-1109-128 3WJ7T	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		24		31-Jul-2025	6 m 7 d
34-13-00-720 STANDBY	STANDBY AIR DATA COMPUTER PITOT-STATIC SYSTEM FUNCTIONAL CHECK	KGYH		9200-30000-206 5065	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		24		31-Jul-2025	6 m 7 d
34-51-00-720 NO. 1	NO. 1 TRANSPONDER SYSTEM FUNCTIONAL CHECK	KGYH		622-9210-501 45CYW	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		24		31-Jul-2025	6 m 7 d
34-51-00-720	NO. 2 TRANSPONDER SYSTEM FUNCTIONAL CHECK	KGYH		822-2132-001 4P84H	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		24		31-Jul-2025	6 m 7 d
B345101 NO. 1	NO. 1 TRANSPONDER (CALIBRATE) FUNCTIONAL CHECK	KGYH		622-9210-501 45CYW	MTH 17-Jul-2023		24		31-Jul-2025	6 m 7 d
Calibration Date: 17-Jul-2023										
B345101	TSS W/TRANSPONDER COMPUTER FUNCTIONAL CHECK	KGYH		822-2132-001 4P84H	MTH 17-Jul-2023	-1	24		31-Jul-2025	6 m 7 d
Calibration Date: 17-Jul-2023										
35-11-10-780	OXYGEN BOTTLE ASSEMBLY RESTORATION (HYDROSTATIC TEST)	GSO		4441073-050 450907601	MTH 01-Sep-2021		60		01-Sep-2026	19 m 8 d
Hydro Check Date: 01-Sep-2021										
35-11-10-960	OXYGEN BOTTLE ASSEMBLY - DISCARD			4441073-050 450907601	MTH		180		01-Jun-2026	16 m 8 d
35-11-40-960 COPILOT	CO-PILOT CREW OXYGEN MASK RESTORATION (OVERHAUL)			MC10-16-150 B156959	MTH 01-Jan-2021 HRS 1713.1 LDG 1261		72		31-Jan-2027	24 m 7 d
35-11-40-960 PILOT	PILOT CREW OXYGEN MASK RESTORATION (OVERHAUL)			MC10-16-150 B112315	MTH 09-Aug-2022 HRS 1897.8 LDG 1435		72		31-Aug-2028	43 m 7 d
53-00-00-9600 LEFT	LEFT NOSE LANDING GEAR ATTACH FITTING ASSEMBLY DISCARD			7113052-9 NSN	MTH 01-Jun-2011 LDG 0		26000		26000	24299
53-00-00-9600 RIGHT	NOSE LANDING GEAR TRUNNION SUPPORT FITTING			7113052-10 NSN	MTH 01-Jun-2011 LDG 0		26000		26000	24299
53-00-00-9601	NOSE LANDING GEAR HYDRAULIC ACTUATOR FITTING ASSEMBLY DISCARD			7111091-8 NSN	MTH 01-Jun-2011 LDG 0		26000		26000	24299
57-00-00-9600 LEFT MAIN GEAR	LEFT FORWARD MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY DISCARD			7141155-1 48	MTH 01-Jun-2011 LDG 0		43300		43300	41599
57-00-00-9600 RIGHT MAIN GEAR	RIGHT FORWARD MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY DISCARD			7141155-2 41	MTH 01-Jun-2011 LDG 0		43300		43300	41599
57-00-00-9601 LEFT MAIN GEAR	LEFT AFT MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY DISCARD			7141165-1 NSN	MTH 01-Jun-2011 LDG 0		43300		43300	41599
57-00-00-9601 RIGHT MAIN GEAR	RIGHT AFT MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY DISCARD			7141165-2 NSN	MTH 01-Jun-2011 LDG 0		43300		43300	41599
57-00-00-9602 LEFT MAIN GEAR	LEFT SIDE MAIN LANDING GEAR BRACE ACTUATOR ATTACH FITTING ASSEMBLY DISCARD			7141175-1 39	MTH 01-Jun-2011 LDG 0		43300		43300	41599

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
57-00-00-9602 RIGHT MAIN GEAR	RIGHT SIDE MAIN LANDING GEAR BRACE ACTUATOR ATTACH FITTING ASSEMBLY DISCARD			7141175-2 37	MTH 01-Jun-2011 LDG 0		43300		43300	41599
71-21-00-9600 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA3 LK0166	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
71-21-00-9600 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA3 LK0190	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
71-21-00-9600 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA3 LK0196	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
71-21-00-9600 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA3 LK0186	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
71-21-00-9601 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA2 LK0091	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
71-21-00-9601 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT ASSEMBLY DISCARD			LM-610-SA2 LK0082	MTH 01-Jun-2011 HRS 0		11000		11000	8826.3
710015 E1	COMPRESSOR CLEANING				MTH 01-Jun-2011		A/R			
710015 E2	COMPRESSOR CLEANING				MTH 01-Jun-2011		A/R			
731025 E1	REPLACE FUEL FILTER	GYH			MTH 16-Mar-2021 HRS 1731.2 LDG 1278		1200		(2916)2931.2	757.5
731025 E2	REPLACE FUEL FILTER	GYH			MTH 16-Mar-2021 HRS 1732.2 LDG 1278		1200		(2932.2)2932.2	758.5
80-11-10-960 LEFT	LEFT STARTER-GENERATOR RESTORATION (OVERHAUL)			MG94D-3 0295	MTH 22-Dec-2017 HRS 1408.7 LDG 939		1000		2408.7	235
80-11-10-960 RIGHT	RIGHT STARTER-GENERATOR RESTORATION (OVERHAUL)	KSIF		MG94D-3 0728B	MTH 27-Feb-2023 HRS 1963.7 LDG 1492		1000		2963.7	790



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
210001 AFT	TEMP SENSOR ASSEMBLY	7115070-10 0152	MTH 01-Jun-2011		O/C	0		
210001 FORWARD	TEMP SENSOR ASSEMBLY	7115070-10 0153	MTH 01-Jun-2011		O/C	0		
210001 LEFT	PRECOOLER 9912624-2	8363-1 T0109	MTH 01-Jun-2011		O/C	0		
210001 RIGHT	PRECOOLER 9912624-2	8363-1 T0107	MTH 01-Jun-2011		O/C	0		
210002 LEFT	OVERTEMPERATURE SENSOR 9914519-2	1E51-1 12BF239	MTH 01-Jun-2011		O/C	0		
210002 RIGHT	OVERTEMPERATURE SENSOR 9914519-2	1E51-1 12BF241	MTH 01-Jun-2011		O/C	0		
210003 LEFT	CABIN DUCT TEMPERATURE SENSOR	MS28034-3 162091	MTH 01-Jun-2011		O/C	0		
210003 RIGHT	CABIN DUCT TEMPERATURE SENSOR	MS28034-3 163090	MTH 01-Jun-2011		O/C	0		
210005 CABIN	PNEUMATIC SHUTOFF VALVE KIWA	2601-48 0204	MTH 16-Aug-2012 HRS 321 LDG 124		O/C	0 0 0		
210005 CKPT	PNEUMATIC SHUTOFF VALVE *CF	2601-48 0015	MTH 26-May-2011		O/C	0		
211001 LEFT	PRESS REGULATOR SHUTOFF VALVE 9912704-4	1422-4 0271	MTH 01-Jun-2011		O/C	0		
211001 RIGHT	PRESS REGULATOR SHUTOFF VALVE 9912704-4	1422-4 0284	MTH 01-Jun-2011		O/C	0		
211005	PNEUMATIC SHUTOFF VALVE 9912422-3	2601-43 0020	MTH 01-Jun-2011		O/C	0		
211006	A/C CHECK VALVE	1310150-2 NSN	MTH 01-Jun-2011		O/C	0		
212001	UNDERFLOOR INLET AIR BLOWER	0113-12 1954	MTH 01-Jun-2011		O/C	0		
212100 CABIN	AIR DISTRIBUTION SOLENOID VALVE	5303-25 188	MTH 01-Jun-2011		O/C	0		
212100 COCKPIT	AIR DISTRIBUTION SOLENOID VALVE	5303-25 187	MTH 01-Jun-2011		O/C	0		
213003	PRESSURE CONTROLLER 9912661-5	52811-103 1153	MTH 01-Jun-2011		O/C	0		
213004 LEFT	RAM AIR MODULATING VALVE 9912703-2	27241287-27 1BG7	MTH 01-Jun-2011		O/C	0		
213004 RIGHT	RAM AIR MODULATING VALVE 9912703-2	27241287-27 1BG8	MTH 01-Jun-2011		O/C	0		
213005 LEFT	OUTBOUND OUTFLOW VALVE 9912661-3	52812-103 863	MTH 01-Jun-2011		O/C	0		
213005 RIGHT	INBOUND OUTFLOW VALVE 9912661-3	52812-103 896	MTH 01-Jun-2011		O/C	0		
215001 LEFT FORWARD	EVAPORATOR MODULE 9912660-13	004-0257-1 K52023	MTH 01-Jun-2011		O/C	0		
215001 RIGHT FORWARD	EVAPORATOR MODULE 9912660-13 KGSO	004-0257-1 P027210-1	MTH 07-Nov-2023 HRS 2048.6 LDG 1570		O/C			
215002 AFT	EVAPORATOR MODULE 9912660-13	004-0257-1 K51764	MTH 01-Jun-2011		O/C	0		
215004	EVAPORATOR FAN KGSO	004-0255-2 P02466-1	MTH 07-Nov-2023 HRS 2048.6 LDG 1570		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215005	CONDENSER ASSEMBLY 9912660-11			004-0350-1 K51754	MTH 01-Jun-2011		O/C	0		
215008	RECEIVER DRYER MODULE 9912660-16	KBCB		004-0850-1 T-A267379-10	MTH 21-Aug-2019 HRS 1575.4 LDG 1117		O/C	0 0		
215010	COMPRESSOR/BLOWER MODULE GSO			JBS222-1 T-C54125-01	MTH 14-Sep-2019 HRS 1578.8 LDG 1125		O/C	0 0 0		
215011	RECEIVER/DRYER PRESS TRANSDUCER 9912660-17			APTE-519-625-500A 762412300	MTH 01-Jun-2011		O/C	0		
215012	AIR CONDITIONER DRIVE BELT KBCB			ES20040-10 NSN	MTH 21-Aug-2019 HRS 1575.4 LDG 1117		O/C	0 0		
215014	MOTOR COMPRESSOR GSO			98-0906-1 T-C54126-02	MTH 14-Sep-2019 HRS 1578.8 LDG 1125		O/C	0 0 0		
216101	SOLAR SENSOR ASSEMBLY			7115070-9 0116	MTH 01-Jun-2011		O/C	0		
221002 AILERON	SERVO MOUNT SMT-65			622-5735-021 45MCK	MTH 01-Jun-2011		O/C	0		
221002 ELEVATOR	SERVO MOUNT			622-5735-020 45M2L	MTH 01-Jun-2011		O/C	0		
221002 RUDDER	SERVO MOUNT SMT-65			622-5735-519 45M4F	MTH 01-Jun-2011		O/C	0		
221003 AILERON	SERVO SVO-3000	KBCB		822-1168-022 44V6X	MTH 03-Jun-2018 HRS 1458.1 LDG 992		O/C			
221003 ELEVATOR	SERVO SVO-3000			822-1168-021 45MTV	MTH 01-Jun-2011		O/C	0		
221003 RUDDER	SERVO SVO-3000			822-1168-023 45MMW	MTH 01-Jun-2011		O/C	0		
221005	FLIGHT GUIDANCE PANEL FGP-3000			822-1107-136 3VHXY	MTH 01-Jun-2011		O/C	0		
231006 NO.1	VHF COMMUNICATION TRANSCEIVER			822-1468-110 45W6X	MTH 01-Jun-2011		O/C	0		
231006 NO.2	VHF COMMUNICATION TRANSCEIVER			822-1468-110 45W5M	MTH 01-Jun-2011		O/C	0		
231006 NO.3	VHF COMMUNICATION TRANSCEIVER			822-1468-310 45WFD	MTH 01-Jun-2011		O/C	0		
231007 NO.1	COMMUNICATION ANTENNA			VHF10-829 0974	MTH 01-Jun-2011		O/C	0		
231007 NO.2	COMMUNICATION ANTENNA			VHF10-829 0980	MTH 01-Jun-2011		O/C	0		
231007 NO.3	COMMUNICATION ANTENNA			VHF10-829 1013	MTH 01-Jun-2011		O/C	0		
232003	TELEPHONE TRANSCEIVER			P12023 1202312032	MTH 01-Jun-2011		O/C	0		
232006	AIRCELL ROUTER	IWA		P12083 1208372385	MTH 06-Apr-2013 HRS 379.4 LDG 151		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232007 CABIN	AIRCELL FLITEFONE HANDSET	KGSO		P12192-002 1219236619	MTH 23-May-2015 HRS 922 LDG 538		O/C			
232007 COCKPIT	AIRCELL FLITEFONE HANDSET	KEXX		P12192-002 1219236340	MTH 26-Jun-2013 HRS 432.3 LDG 192		O/C	0 0 0		
232008	AIRCELL COMPUTER	IWA		P13989 138912202	MTH 06-Apr-2013 HRS 379.4 LDG 151		O/C	0 0 0		
232009	AIRCELL CONFIG MODULE	IWA		P14126 1412612175	MTH 06-Apr-2013 HRS 379.4 LDG 151		O/C	0 0 0		
232020 FWD	BROADBAND AIRCELL ANTENNA	IWA		P12949 410939	MTH 06-Apr-2013 HRS 379.4 LDG 151		O/C	0 0 0		
232022 AFT	BROADBAND AIRCELL ANTENNA	IWA		P12949 411534	MTH 06-Apr-2013 HRS 379.4 LDG 151		O/C	0 0 0		
235005	RADIO INTERFACE UNIT			822-1864-024 3XFJC	MTH 01-Jun-2011		O/C	0		
235006	RIU W/DATALINK & SELCAL UNIT RIU-4010			822-1863-074 3XFLM	MTH 01-Jun-2011		O/C	0		
237000	COCKPIT VOICE RECORDER LOCATOR BEACON			DK120 SC84963	MTH 01-Jun-2011		O/C	0		
237001	COCKPIT VOICE RECORDER			2100-1020-02 000688211	MTH 01-Jun-2011		O/C	0		
237002	COCKPIT VOICE RECORDER CONTROLLER			S251-1120-00 000567588	MTH 01-Jun-2011		O/C	0		
237003	COCKPIT VOICE RECORDER MICROPHONE			S055-0067-00 000591719	MTH 01-Jun-2011		O/C	0		
237005 237000A	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY	KSIF		DK120/90 AT181058	MTH 07-Sep-2022 HRS 1905.5 LDG 1442		H/T H/T H/T	0 0 0		
240000 LEFT	POWER CONTROL UNIT			94496-1 0140	MTH 06-Jan-2025 HRS 2173.7 LDG 1701		O/C	0 0 0		
240000 RIGHT	POWER CONTROL UNIT			94496-1 0133	MTH 28-Dec-2024 HRS 2170 LDG 1698		O/C			
243001	BATTERY TEMP SENSOR	GSO		S3597-9 40006922	MTH 11-Aug-2018 HRS 1468.2 LDG 1003		O/C	0 0		
243002 LEFT	AC ALTERNATOR			94495-1 095	MTH 01-Jun-2011		O/C	0		
243002 RIGHT	AC ALTERNATOR			94495-1 094	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
243003 LEFT	GENERATOR CONTROL UNIT	51525-001F P5309	MTH 01-Jun-2011		O/C	0		
243003 RIGHT	GENERATOR CONTROL UNIT	51525-001F P5312	MTH 01-Jun-2011		O/C	0		
243007	BATTERY	S3597-4 41353649	MTH 06-Feb-2024 HRS 2074.6 LDG 1593		O/C	0 0 0		
243008	BATTERY RELAY	A931F CR81574	MTH 01-Jun-2011		O/C	0		
243101 LEFT	GROUND FAULT TRANSFORMER	76779-1 9108	MTH 01-Jun-2011		O/C	0		
243101 RIGHT	GROUND FAULT TRANSFORMER	76779-1 9099	MTH 01-Jun-2011		O/C	0		
243102	TRANSFORMER RECTIFIER UNIT	TRU1-125-1 136	MTH 01-Jun-2011		O/C	0		
245001 LEFT	DIMMING CONTROL PCB	8718991-14 0174	MTH 01-Jun-2011		O/C	0		
245001 RIGHT	DIMMING CONTROL PCB	8718991-14 0175	MTH 01-Jun-2011		O/C	0		
245002 LEFT	BLEED AIR CONTROL PCB KBCB	8718999-17 0728	MTH 01-Jul-2019 HRS 1562.8 LDG 1103		O/C	0 0		
245002 RIGHT	BLEED AIR CONTROL PCB	8718999-17 0172	MTH 01-Jun-2011		O/C	0		
245003 LEFT	BLEED AIR MONITOR PCB	8718981-11 0174	MTH 01-Jun-2011		O/C	0		
245003 RIGHT	BLEED AIR MONITOR PCB	8718981-11 0175	MTH 01-Jun-2011		O/C	0		
245004 LEFT	ARINC DECODER PCB	8718997-25 0171	MTH 01-Jun-2011		O/C	0		
245004 RIGHT	ARINC DECODER PCB	8718997-25 0172	MTH 01-Jun-2011		O/C	0		
245005 NO.1	POWER DISTRIBUTION PCB	8718992-17 0175	MTH 01-Jun-2011		O/C	0		
245005 NO.2	POWER DISTRIBUTION PCB	8718992-17 0176	MTH 01-Jun-2011		O/C	0		
245006 LEFT	ENVIRONMENTAL PCB KEXX	8718993-27 0174	MTH 13-Oct-2015 HRS 1030.5 LDG 637		O/C			
245006 RIGHT	ENVIRONMENTAL PCB KEXX	8718993-27 0175	MTH 13-Oct-2015 HRS 1030.5 LDG 637		O/C			
245007	HDAV OUTLET	441-0007-102 NG48T	MTH 01-Jun-2011		O/C	0		
245008 LEFT	CABIN ALT MODULE ASSEMBLY PC BOARD BOX	7018119-1 0874	MTH 01-Jun-2011		O/C	0		
245008 RIGHT	CABIN ALT MODULE ASSEMBLY PC BOARD BOX	7018119-1 0875	MTH 01-Jun-2011		O/C	0		
245009	A/C CONTROLLER 1 IN-4OUT	106282-1 2620111	MTH 01-Jun-2011		O/C	0		
245011	BULKHEAD MONITOR- *CF	441-0005-100 1011500067	MTH 27-Apr-2011		O/C	0		
245012 LEFT	SPEEDBRAKE PCB	8718988-4 0131	MTH 01-Jun-2011		O/C	0		
245012 RIGHT	SPEEDBRAKE PCB	8718988-4 0132	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245013 LEFT	FLAP CONTROL PCB	8718979-21 0179	MTH 01-Jun-2011		O/C	0		
245013 RIGHT	FLAP CONTROL PCB	8718979-21 0180	MTH 01-Jun-2011		O/C	0		
245014	LIGHTING CONTROL ASSEMBLY PCB	8718987-21 0137	MTH 01-Jun-2011		O/C	0		
245015 LEFT	LANDING GEAR CONTROL PCB	8718998-25 0175	MTH 01-Jun-2011		O/C	0		
245015 RIGHT	LANDING GEAR CONTROL PCB	8718998-25 0176	MTH 01-Jun-2011		O/C	0		
245016	TRIM MONITOR PCB	8718976-7 0138	MTH 01-Jun-2011		O/C	0		
245017	SECONDARY TRIM ASSEMBLY PCB	8718975-4 0138	MTH 01-Jun-2011		O/C	0		
245018	DOOR/REV ASSY PCB	8718989-9 0134	MTH 01-Jun-2011		O/C	0		
245019 LEFT	DIAGNOSTICS PCB	8718996-5 0176	MTH 01-Jun-2011		O/C	0		
245019 RIGHT	DIAGNOSTICS PCB	8718996-5 0178	MTH 01-Jun-2011		O/C	0		
245020 LEFT	FUEL CONTROL ASSY PCB	8718994-5 0177	MTH 01-Jun-2011		O/C	0		
245020 RIGHT	FUEL CONTROL ASSY PCB	8718994-5 0178	MTH 01-Jun-2011		O/C	0		
245021 LEFT	5V POWER ASSY PCB	8718980-1 0174	MTH 01-Jun-2011		O/C	0		
245021 RIGHT	5V POWER ASSY PCB	8718980-1 0175	MTH 01-Jun-2011		O/C	0		
245022	AUDIO SWITCHING ASSY PCB	8718982-1 0138	MTH 01-Jun-2011		O/C	0		
245023	AUDIO/REV ASSY PCB	8718995-9 0133	MTH 01-Jun-2011		O/C	0		
245024	PRIMARY TRIM PCB	8718977-7 0136	MTH 01-Jun-2011		O/C	0		
245025	IPOD ECM POD	441-0038-100 NSN	MTH 01-Jun-2011		O/C	0		
245026	PORT CONTROLLER	2052-1 NSN	MTH 01-Jun-2011		O/C	0		
245027	ENTRY SWITCH	*CF 441-0024-100 3YKCB	MTH 27-Apr-2011		O/C	0		
245028	CLIENT SWITCH	KLNN 441-0025-100 3L31P	MTH 29-Jun-2011 HRS 23.7 LDG 17		O/C	0 0 0		
245029	A/V AUXILARY PORT	*CF 441-0026-100 40DDJ	MTH 24-Apr-2011		O/C	0		
245047	MEDIA CENTER DEVICE	441-0008-100 4JG9N	MTH 23-May-2015 HRS 922 LDG 538		O/C	0 0 0		
246099	DC TO DC CONVERTER	IWA RR18 4502	MTH 05-Nov-2011 HRS 101.6 LDG 49		O/C	0 0 0		
25-65-00-9600 CO-PILOT	CO-PILOT LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET							
	KGSO	P01074-207 24091730055	MTH 27-Dec-2024 HRS 2170 LDG 1698		O/C	0 0 0	30-Sep-2034	116 m 6 d



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
25-65-00-9600 COUCH	COUCH LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730074	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 LAVATORY	LAVATORY LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730076	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 3	NO. 3 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730053	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 4	NO.4 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730052	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 5	NO. 5 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730054	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 6	NO. 6 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730077	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 7	NO.7 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730073	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 NO. 8	NO. 8 LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730075	HRS 2170			0		
					LDG 1698			0		
25-65-00-9600 PILOT	PILOT LIFE VEST (AIR RETENTION FUNCTIONAL CHECK AND COMPRESSED AIR CARTRIDGE FUNCTIONAL CHECK) RESTORATION JACKET									
		KGSO		P01074-207	MTH 27-Dec-2024		O/C	0	30-Sep-2034	116 m 6 d
				24091730056	HRS 2170			0		
					LDG 1698			0		
250001 NO.3	LEFT SIDE AFT FACING SEAT			4710008-9 NSN	MTH 01-Jun-2011		O/C	0		
250001 NO.4	RIGHT SIDE AFT FACING SEAT			4710008-10 NSN	MTH 01-Jun-2011		O/C	0		
250001 NO.5	LEFT SIDE FORWARD FACING SEAT			4710008-11 NSN	MTH 01-Jun-2011		O/C	0		
250001 NO.6	RIGHT SIDE FORWARD FACING SEAT			4710008-12 NSN	MTH 01-Jun-2011		O/C	0		
250001 NO.7	LEFT SIDE FORWARD FACING SEAT			4710008-10 NSN	MTH 01-Jun-2011		O/C	0		
250001 NO.8	RIGHT SIDE FORWARD FACING SEAT			4710008-9 NSN	MTH 01-Jun-2011		O/C	0		
251002 LEFT NO. 1	ELECTRONIC CABIN WINDOW SHADE 9919108-4			ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 LEFT NO. 2	ELECTRONIC CABIN WINDOW SHADE 9919108-4			ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
251002 LEFT NO. 3	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 LEFT NO. 4	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 LEFT NO. 5	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 1	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 2	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 3	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 4	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 5	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251002 RIGHT NO. 6	ELECTRONIC CABIN WINDOW SHADE 9919108-4	ATG74F001-A017 NSN	MTH 01-Jun-2011		O/C	0		
251003 CABINET	CABIN MANAGEMENT SYSTEM SWITCH ASSY *CF	441-0010-100 40B5W	MTH 27-Apr-2011		O/C	0		
251003 COUCH	CABIN MANAGEMENT SYSTEM SWITCH ASSEMBLY *CF	441-0010-100 40B8J	MTH 27-Apr-2011		O/C	0		
251003	CABIN MANAGEMENT SYSTEM SWITCH SEAT# 8 ASSY *CF	441-0010-100 40B5C	MTH 27-Apr-2011		O/C	0		
251004	CABIN MANAGEMENT SYSTEM SWITCH SEAT #3 ASSY *CF	441-0010-100 40B5L	MTH 27-Apr-2011		O/C	0		
251005	CABIN MANAGEMENT SYSTEM SWITCH SEAT #4 ASSY *CF	441-0010-100 40B8W	MTH 27-Apr-2011		O/C	0		
251006	CABIN MANAGEMENT SYSTEM SWITCH SEAT #5 ASSY *CF	441-0010-100 40B5X	MTH 27-Apr-2011		O/C	0		
251007	CABIN MANAGEMENT SYSTEM SWITCH SEAT #6 ASSY *CF	441-0010-100 40B4N	MTH 27-Apr-2011		O/C	0		
251008	CABIN MANAGEMENT SYSTEM SWITCH SEAT #7 ASSY *CF	441-0010-100 40B9C	MTH 27-Apr-2011		O/C	0		
252001	PRIMARY PORT CONTROLLER	2052-1-1 3XD4B	MTH 01-Jun-2011		O/C	0		
252002	PA AMPLIFIER	102025-2 5581210	MTH 01-Jun-2011		O/C	0		
254099	TOILET ASSY	KGSO 1700-457 11242257	MTH 27-Dec-2024 HRS 2170 LDG 1698		O/C	0 0 0		
256001	EMERGENCY LOCATOR TRANSMITTER C406N	453-5060 10476	MTH 26-May-2011		O/C	0		
256003	REMOTE SWITCH	453-0022 NSN	MTH 01-Jun-2011		O/C	0		
256004	EMERGENCY LOCATOR TRANSMITTER ANTENNA	110-340 329390	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256030 256002	EMERGENCY LOCATOR BEACON BATTERY	KSIF		452-0133 391747-036	MTH 01-Jul-2021 HRS 1757.5 LDG 1310		H/T H/T H/T H/T	1		
26-21-15-960 NO. 1	NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE			CARTRIDGE (SQUIB) PN SN-UNKNOWN	DISCARD - TOTAL LIFE MTH 12-Apr-2021 HRS 1733.9 LDG 1281		180		28-Feb-2035	121 m 4 d
26-21-15-960 NO. 2	NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE			CARTRIDGE (SQUIB) PN SN-UNKNOWN	DISCARD - TOTAL LIFE MTH 12-Apr-2021 HRS 1733.9 LDG 1281		180		29-Feb-2036	133 m 5 d
261000 AFT	TAILCONE OVERHEAT SENSOR			MS28034-3 163490	MTH 01-Jun-2011		O/C	0		
261001 LEFT ENGINE	FIRE DETECTOR 9912416-1			3001-212-1004/455-9 211488	MTH 01-Jun-2011		O/C	0		
261001 RIGHT ENGINE	FIRE DETECTOR 9912416-1			3001-212-1004/455-9 211514	MTH 01-Jun-2011		O/C	0		
261002 AFT	SMOKE DETECTOR 9912736-1			474716 ABJ4910	MTH 01-Jun-2011		O/C	0		
261002 FORWARD	SMOKE DETECTOR 9912736-1	KEXX		474716 525C	MTH 04-Jun-2015 HRS 934.9 LDG 547		O/C	0 0 0		
261003	LEAK DETECT CONTROLLER KBCB			474715 1966	MTH 01-Jul-2019 HRS 1562.8 LDG 1103		O/C	0 0		
262001	ENGINE FIRE EXTINGUISHER BOTTLE 9912738-1	KSIF		FX02200-1 0024	MTH 12-Apr-2021 HRS 1733.9 LDG 1281		O/C	0 0		
262003 CABIN	PORTABLE FIRE EXTINGUISHER HALON	KBCB		C352TS E-68635450	MTH 03-Jun-2018 HRS 1458.1 LDG 992		O/C	0 0 0		
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER HALON	KBCB		C352TS E-68635451	MTH 03-Jun-2018 HRS 1458.1 LDG 992		O/C	0 0 0		
270001 LEFT	SPEED BRAKE FILTER FITTING			20666-6-250 NSN	MTH 01-Jun-2011		O/C	0		
270001 RIGHT	SPEED BRAKE FILTER FITTING			20666-6-250 NSN	MTH 01-Jun-2011		O/C	0		
270003 LEFT CENTER	GROUND SPOILER PROXIMITY SWITCH KEXX			8-405-04 B80976	MTH 06-Aug-2016 HRS 1209.1 LDG 771		O/C	0 0		
270003 LEFT INBOARD	GROUND SPOILER PROXIMITY SWITCH KEXX			8-405-04 B80986	MTH 06-Aug-2016 HRS 1209.1 LDG 771		O/C	0 0		
270003 LEFT OUTBOARD	GROUND SPOILER PROXIMITY SWITCH KEXX			8-405-04 B80910	MTH 06-Aug-2016 HRS 1209.1 LDG 771		O/C	0 0		
270003 RIGHT CENTER	GROUND SPOILER PROXIMITY SWITCH KEXX			8-405-04 B80979	MTH 06-Aug-2016 HRS 1209.1 LDG 771		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
270003 RIGHT INBOARD	GROUND SPOILER PROXIMITY SWITCH	KEXX		8-405-04 B80980	MTH 06-Aug-2016 HRS 1209.1 LDG 771		O/C	0		
270003 RIGHT OUTBOARD	GROUND SPOILER PROXIMITY SWITCH			8-405-04 B65898	MTH 01-Jun-2011		O/C	0		
270004 LEFT	SPEED BRAKE PROXIMITY SWITCH			8-405-04 B66218	MTH 01-Jun-2011		O/C	0		
270004 RIGHT	SPEED BRAKE PROXIMITY SWITCH			8-405-04 B66441	MTH 01-Jun-2011		O/C	0		
271000 AILERON	ELECTRONIC TRIM ACTUATOR			2A7216C C0057	MTH 01-Jun-2011		O/C	0		
271000 NO.1	ELEVATOR ELECTRONIC TRIM ACTUATOR	KEXX		2A7218F F0219	MTH 09-Oct-2015 HRS 1027.2 LDG 633		O/C			
271000 NO.2	ELEVATOR ELECTRONIC TRIM ACTUATOR	KEXX		2A7218F F0269	MTH 09-Oct-2015 HRS 1027.2 LDG 633		O/C			
271000 RUDDER	ELECTRONIC TRIM ACTUATOR			2A7217D D0053	MTH 01-Jun-2011		O/C	0		
271011	ISOLATION CHECK VALVE			8272-1 0051	MTH 01-Jun-2011		O/C	0		
271021	FLAP CONTROL VALVE			4271-1 0053	MTH 01-Jun-2011		O/C	0		
272001 LEFT	RUDDER BIAS SHUTOFF VALVE			5307-3 1063	MTH 01-Jun-2011		O/C	0		
272001 RIGHT	RUDDER BIAS SHUTOFF VALVE			5307-3 1100	MTH 01-Jun-2011		O/C	0		
273001	SHAKER CONTROL			201 8650	MTH 01-Jun-2011		O/C	0		
275001 LEFT CENTER	2 POSITION ACTUATOR			494800-1003 0297	MTH 01-Jun-2011		O/C	0		
275001 LEFT INBOARD	2 POSITION ACTUATOR			494800-1003 0296	MTH 01-Jun-2011		O/C	0		
275001 LEFT OUTBOARD	2 POSITION ACTUATOR			494800-1003 0304	MTH 01-Jun-2011		O/C	0		
275001 RIGHT CENTER	2 POSITION ACTUATOR			494800-1003 0294	MTH 01-Jun-2011		O/C	0		
275001 RIGHT INBOARD	2 POSITION ACTUATOR			494800-1003 0267	MTH 01-Jun-2011		O/C	0		
275001 RIGHT OUTBOARD	2 POSITION ACTUATOR			494800-1003 0302	MTH 01-Jun-2011		O/C	0		
275002 LEFT	FLAP ACTUATOR			471000-1005 0098	MTH 01-Jun-2011		O/C	0		
275002 RIGHT	FLAP ACTUATOR			471000-1005 0110	MTH 01-Jun-2011		O/C	0		
275003 LEFT	RVDT FLAP POSITION SENSOR			3A1332A B0090	MTH 01-Jun-2011		O/C	0		
275003 RIGHT	RVDT FLAP POSITION SENSOR			3A1332A B0091	MTH 01-Jun-2011		O/C	0		
275004 LEFT	MODULATING ACTUATOR			470700-1005 0127	MTH 01-Jun-2011		O/C	0		
275004 RIGHT	MODULATING ACTUATOR			470700-1005 0128	MTH 01-Jun-2011		O/C	0		
275005 LEFT	RVDT SB POS SENSOR			3A21200096B NSN	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
275006 LEFT	RVDT THROTTLE POSITION SENSOR NSN	3A21200096B	MTH 01-Jun-2011		O/C	0		
275006 RIGHT	RVDT THROTTLE POSITION SENSOR NSN	3A21200096B	MTH 01-Jun-2011		O/C	0		
275007	THROTTLE QUADRANT ASSY RVDT ICT	7165200-11 0062	MTH 13-Jun-2011 HRS 9.5 LDG 7		O/C	0 0 0		
280001 LEFT	MOTOR ACTUATOR 9914423-2	MA20A1029-1 AA256112	MTH 01-Jun-2011		O/C	0		
280001 RIGHT	MOTOR ACTUATOR 9914423-2	MA20A1029-1 AA256113	MTH 01-Jun-2011		O/C	0		
282001 LEFT	FUEL BOOST PUMP 9914688-2	3C7-2 12BF45	MTH 01-Jun-2011		O/C	0		
282001 RIGHT	FUEL BOOST PUMP 9914688-2	3C7-2 12BF52	MTH 01-Jun-2011		O/C	0		
282002 LEFT AFT	EJECTOR FUEL SCAVENGE PUMP 9912190-3	RG45880 B3077	MTH 01-Jun-2011		O/C	0		
282002 LEFT FORWARD	EJECTOR FUEL SCAVENGE PUMP 9912190-3	RG45880 B3075	MTH 01-Jun-2011		O/C	0		
282002 RIGHT AFT	EJECTOR FUEL SCAVENGE PUMP 9912190-3	RG45880 B3068	MTH 01-Jun-2011		O/C	0		
282002 RIGHT FORWARD	EJECTOR FUEL SCAVENGE PUMP 9912190-3	RG45880 B3067	MTH 01-Jun-2011		O/C	0		
282003 LEFT	BALL VALVE 9914423-4	125838AW AA258838	MTH 01-Jun-2011		O/C	0		
282003 RIGHT	BALL VALVE 9914423-4	125838AW AA258840	MTH 01-Jun-2011		O/C	0		
282005 LEFT	EJECTOR FUEL PRIMARY PUMP 9912190-2	RG45310 C2648	MTH 01-Jun-2011		O/C	0		
282005 RIGHT	EJECTOR FUEL PRIMARY PUMP 9912190-2	RG45310 C2632	MTH 01-Jun-2011		O/C	0		
282006 LEFT	FUEL SHUTOFF VALVE 9914107-3	61086 4122	MTH 01-Jun-2011		O/C	0		
282006 RIGHT	FUEL SHUTOFF VALVE 9914107-3	61086 4116	MTH 01-Jun-2011		O/C	0		
282007 LEFT	PILOT HIGH LEV VALVE 9914107-1	61087 5678	MTH 01-Jun-2011		O/C	0		
282007 RIGHT	PILOT HIGH LEV VALVE 9914107-1	61087 5695	MTH 01-Jun-2011		O/C	0		
282008 LEFT	POS/NEG RELIEF FUEL VALVE 9912501-2	840203-105 6110XP	MTH 01-Jun-2011		O/C	0		
282008 RIGHT	POS/NEG RELIEF FUEL VALVE 9912501-2	840203-105 6356XP	MTH 01-Jun-2011		O/C	0		
282009 LEFT	DEFUEL VALVE 2082	61084-2 2082	MTH 01-Jun-2011		O/C	0		
282009 RIGHT	DEFUEL VALVE 1986	61084-2 1986	MTH 01-Jun-2011		O/C	0		
282010	TRANSFER VALVE 9914103-6	ZSV57 100510106	MTH 01-Jun-2011		O/C	0		
282011	HOUSING ASSEMBLY 9914168-2	61088 329	MTH 01-Jun-2011		O/C	0		
282012	PRECHECK VALVE ASSEMBLY	9036-351-2 1786	MTH 01-Jun-2011		O/C	0		
284001 NO. 5 LEFT	FUEL PROBE 9912698-5	020-251-010 0283	MTH 01-Jun-2011		O/C	0		
284001 NO. 5 RIGHT	FUEL PROBE 9912698-5	020-251-010 0284	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
284002	FUEL PROBE	020-251-011	MTH 01-Jun-2011		O/C	0		
NO. 6 LEFT	9912698-6	0281						
284002	FUEL PROBE	020-251-011	MTH 01-Jun-2011		O/C	0		
NO. 6 RIGHT	9912698-6	0285						
284003	FUEL PROBE	020-251-012	MTH 01-Jun-2011		O/C	0		
NO. 7 LEFT	9912698-7	0281						
284003	FUEL PROBE	020-251-012	MTH 01-Jun-2011		O/C	0		
NO. 7 RIGHT	9912698-7	0284						
284004	FUEL PROBE	020-251-008	MTH 01-Jun-2011		O/C	0		
NO. 3 LEFT	9912698-3	0285						
284004	FUEL PROBE	020-251-008	MTH 01-Jun-2011		O/C	0		
NO. 3 RIGHT	9912698-3	0284						
284005	FUEL PROBE	020-251-009	MTH 01-Jun-2011		O/C	0		
NO. 4 LEFT	9912698-4	0285						
284005	FUEL PROBE	020-251-009	MTH 01-Jun-2011		O/C	0		
NO. 4 RIGHT	9912698-4	0280						
284006	FUEL PROBE	020-251-007	MTH 01-Jun-2011		O/C	0		
NO. 2 LEFT	9912698-2	0293						
284006	FUEL PROBE	020-251-007	MTH 01-Jun-2011		O/C	0		
NO. 2 RIGHT	9912698-2	0295						
284007	FUEL PROBE	020-251-006	MTH 01-Jun-2011		O/C	0		
NO. 1 LEFT	9912698-1	0283						
284007	FUEL PROBE	020-251-006	MTH 01-Jun-2011		O/C	0		
NO. 1 RIGHT	9912698-1	0284						
284008	FUEL FLOAT SWITCH	L16H-14	MTH 01-Jun-2011		O/C	0		
LEFT		5678						
284008	FUEL FLOAT SWITCH	L16H-14	MTH 23-May-2015		O/C	0		
RIGHT	KGSO	2259	HRS 922			0		
			LDG 538			0		
284009	VENT FLOAT VALVE	60221-4	MTH 01-Jun-2011		O/C	0		
LEFT	9914268-5	2075						
284009	VENT FLOAT VALVE	60221-4	MTH 01-Jun-2011		O/C	0		
RIGHT	9914268-5	2178						
284010	FUEL QUANTITY SIGNAL CONDITIONER		MTH 01-Jun-2011		O/C	0		
	9912698-8	367-500-001						
		1040						
291000	HYDRAULIC BOOTSTRAP 335 CI RESERVOIR		MTH 01-Jun-2011		O/C	0		
	9912713-1	7569						
		0044						
291002	HYDRAULIC PUMP	51171-02	MTH 01-Jun-2011		O/C	0		
LEFT	9914643-3	K0762						
291002	HYDRAULIC PUMP	51171-02	MTH 01-Jun-2011		O/C	0		
RIGHT	9914643-3	K0760						
291003	NON-BYPASS HYDRAULIC FILTER ELEMENT		MTH 18-Jul-2023		H/T	0		
LEFT	KG YH	9914465-10	HRS 2006.2		H/T	0		
		SN-UNKNOWN	LDG 1524		H/T	0		
					H/T	0		
291003	NON-BYPASS HYDRAULIC FILTER ELEMENT		MTH 18-Jul-2023		H/T	0		
RIGHT	KG YH	9914465-10	HRS 2006.2		H/T	0		
		SN-UNKNOWN	LDG 1524		H/T	0		
					H/T	0		
291004	RET-HYDRAULIC MANIFOLD	AEC45520	MTH 01-Jun-2011		O/C	0		
		0364						
291005	HYDRAULIC LINE FILTER ELEMENT	9912579-2	MTH 18-Jul-2023		H/T	0		
LINE	KG YH	SN-UNKNOWN	HRS 2006.2		H/T	0		
			LDG 1524		H/T	0		
					H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
291006 RETURN	HYDRAULIC RETURN FILTER ELEMENT KG YH	9914672-3 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		H/T H/T H/T H/T	0 0 0 0		
291007 BYPASS	HYDRAULIC BYPASS FILTER ELEMENT KG YH	9914672-5 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		H/T H/T H/T H/T	0 0 0 0		
291010 LEFT	SHUTOFF VALVE 9912400-5	AV24B1388-3 AA256048	MTH 01-Jun-2011		O/C	0		
291010 RIGHT	SHUTOFF VALVE 9912400-5	AV24B1388-3 AA256046	MTH 01-Jun-2011		O/C	0		
291013	CONTROL MANIFOLD ASSEMBLY	8271-3 0060	MTH 01-Jun-2011		O/C	0		
291014	SYSTEM RELIEF VALVE 9912712-2	2685 060	MTH 01-Jun-2011		O/C	0		
291015	CROSS OVER RELIEF VALVE 9912712.00	2684 NSN	MTH 01-Jun-2011		O/C	0		
291016 NO.1	EDP1 PRESSURE TRANSDUCER 9912712-4	80804-1 NSN	MTH 01-Jun-2011		O/C	0		
291016 NO.2	EDP2 PRESSURE TRANSDUCER 9912712-5	80804-2 78251159	MTH 01-Jun-2011		O/C	0		
291017	EDP1 CHECK VALVE 9912712-17	9639-1 NSN	MTH 01-Jun-2011		O/C	0		
291101	REMOTE HYDRAULIC RES INDICATOR 9912713-3	9611-2 0050	MTH 01-Jun-2011		O/C	0		
301001 LEFT	ELEC WNDSHLD ANTI-ICE CONTROLLER 9914411-2	856-1-3 3XBT D	MTH 01-Jun-2011		O/C	0		
301001 RIGHT	ELEC WNDSHLD ANTI-ICE CONTROLLER 9914411-2	856-1-3 3XBT G	MTH 01-Jun-2011		O/C	0		
301002 LEFT BOTTOM	TEMPERATURE TRANSDUCER	1050C K0096	MTH 01-Jun-2011		O/C	0		
301002 LEFT TOP	TEMPERATURE TRANSDUCER	1050C K0513	MTH 01-Jun-2011		O/C	0		
301002 RIGHT BOTTOM	TEMPERATURE TRANSDUCER	1050C H7545	MTH 01-Jun-2011		O/C	0		
301002 RIGHT TOP	TEMPERATURE TRANSDUCER	1050C K0098	MTH 01-Jun-2011		O/C	0		
301003 LEFT	MODULATING VALVE 9912584-2	1H139-2 12BF41	MTH 01-Jun-2011		O/C	0		
301003 RIGHT	MODULATING VALVE 9912584-1	1H139-1 3BD38	MTH 01-Jun-2011		O/C	0		
301004 LEFT	PRECOOL TEMPERATURE SENSOR 9912584-3	27431501-10 12BF56	MTH 01-Jun-2011		O/C	0		
301004 RIGHT	PRECOOL TEMPERATURE SENSOR 9912584-3	27431501-10 12BF58	MTH 01-Jun-2011		O/C	0		
301005 LEFT	PRESSURE REGULATOR SHUTOFF VALVE 9912704-3	5845-00-1 0115	MTH 01-Jun-2011		O/C	0		
301005 RIGHT	PRESSURE REGULATOR SHUTOFF VALVE 9912704-3	5845-00-1 0046A	MTH 01-Jun-2011		O/C	0		
301006 LEFT	HORIZONTAL STABILIZER BOOT	P29S4D5329-03 NHE2880	MTH 26-Jul-2024 HRS 2119.5 LDG 1648		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301006 RIGHT	HORIZONTAL STABILIZER BOOT	KGSO		P29S4D5329-04 NGU8990	MTH 26-Jul-2024 HRS 2119.5 LDG 1648		O/C	0 0 0		
301007	ENGINE BLEED SHUTOFF VALVE 9914552-2			2602-43 0427	MTH 01-Jun-2011		O/C	0		
301008 LEFT	PRESSURE SWITCH			1106P55-1 8866A	MTH 01-Jun-2011		O/C	0		
301008 RIGHT	PRESSURE SWITCH			1106P55-1 8664A	MTH 01-Jun-2011		O/C	0		
301100 LEFT	LEFT WING ANTI-ICE CHECK VALVE 9914774-2			4005-20 197	MTH 01-Jun-2011		O/C	0		
301100 RIGHT	RIGHT WING ANTI-ICE CHECK VALVE 9914774-2			4005-20 199	MTH 01-Jun-2011		O/C	0		
302001 LEFT	PRESSURE REGULATOR VALVE 9914710-6			1420-4 0172	MTH 01-Jun-2011		O/C	0		
302001 RIGHT	PRESSURE REGULATOR VALVE 9914710-6			1420-4 0170	MTH 01-Jun-2011		O/C	0		
303002 LEFT	PITOT TUBE			0851JL1 280482	MTH 01-Jun-2011		O/C	0		
303002 RIGHT	PITOT TUBE			0851JL1 279865	MTH 01-Jun-2011		O/C	0		
303003 STANDBY	PITOT TUBE			0851JL1 279864	MTH 01-Jun-2011		O/C	0		
304011 LEFT	SOLENOID DEICE VALVE			3D2353-06 N102929	MTH 01-Jun-2011		O/C	0		
304011 RIGHT	SOLENOID DEICE VALVE			3D2353-06 N102926	MTH 01-Jun-2011		O/C	0		
313001	FLIGHT HOURMETER			C664503-0104 NSN	MTH 01-Jun-2011		O/C	0		
321000	MANUAL SHUTOFF VALVE 9912693-2			98444-3 0052	MTH 01-Jun-2011		O/C	0		
321001 LEFT	MAIN LANDING GEAR			7141010-7 NSN	MTH 01-Jun-2011		O/C	0		
321001 RIGHT	MAIN LANDING GEAR			7141010-8 NSN	MTH 01-Jun-2011		O/C	0		
321002	BRAKE SYSTEM FILTER ELEMENT KGYH			037913-04-53 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		H/T H/T H/T	0 0 0		
321003 LEFT MAIN LANDING GEAR	TRUNNION ASSEMBLY			7194005-13 41	MTH 01-Jun-2011		H/T H/T	0		
321004 RIGHT MAIN LANDING GEAR	TRUNNION ASSEMBLY			7194005-14 40	MTH 01-Jun-2011		H/T H/T	0		
321005 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	KIWA		7141050-3 52	MTH 05-Nov-2011 HRS 101.6 LDG 49		H/T H/T H/T	0 0 0		
321005 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	*CF		7141050-3 06	MTH 26-May-2011		H/T H/T	0		
321010 LEFT MAIN LANDING GEAR	TRAILING LINK			7141030-3 41	MTH 01-Jun-2011		H/T H/T	0		
321010 RIGHT MAIN LANDING GEAR	TRAILING LINK			7141030-4 41	MTH 01-Jun-2011		H/T H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321011	ANTISKID CONTROL VALVE 9912742-3	39-939 167	MTH 01-Jun-2011		O/C	0		
322001 LEFT	CHECK/PR VALVE	AAVX0510300B NSN	MTH 01-Jun-2011		O/C	0		
322001 RIGHT	CHECK/PR VALVE	AAVX0510300B NSN	MTH 01-Jun-2011		O/C	0		
322002 NOSE	LANDING GEAR ASSEMBLY	7142010-7 NSN	MTH 01-Jun-2011		H/T H/T	0		
322003 NOSE LANDING GEAR	FORK	7142042-2 NSN	MTH 01-Jun-2011		O/C	0		
322004 NOSE LANDING GEAR	FORK AND PISTON ASSEMBLY	7142040-2 NSN	MTH 01-Jun-2011		O/C	0		
322005	RELIEF VALVE	PRFA2812080L NSN	MTH 01-Jun-2011		O/C	0		
322006 NOSE LANDING GEAR	SHIMMY DAMPER	7194009-1 38	MTH 01-Jun-2011		O/C	0		
322007 NOSE LANDING GEAR	TRUNNION ASSEMBLY	7142020-7 37	MTH 01-Jun-2011		O/C	0		
322008	ZERO LEAK CHECK VALVE	CSFA1876005A NSN	MTH 01-Jun-2011		O/C	0		
323000	MAIN LANDING GEAR MODULE ICT	9912750-2 T8329	MTH 27-Nov-2012 HRS 376.9 LDG 149		O/C			
323001 LEFT MAIN LANDING GEAR	HYDRAULIC ACTUATOR 9912705-4	FA100114-002 0098	MTH 01-Jun-2011		H/T H/T	0		
323001 RIGHT MAIN LANDING GEAR	HYDRAULIC ACTUATOR 9912705-4	FA100114-002 0101	MTH 01-Jun-2011		H/T H/T	0		
323002 LEFT MAIN LANDING GEAR	UPLOCK HOOK	7141100-5 NSN	MTH 01-Jun-2011		O/C	0		
323002 RIGHT MAIN LANDING GEAR	UPLOCK HOOK	7141100-6 NSN	MTH 01-Jun-2011		O/C	0		
323003	MAIN LANDING GEAR CONTROL VALVE 9912712-13	4270-1 0051	MTH 01-Jun-2011		O/C	0		
323004 NOSE LANDING GEAR	HYDRAULIC ACTUATOR 9912705-5	FA100115-002 0052	MTH 01-Jun-2011		H/T H/T	0		
323005 LEFT MAIN LANDING GEAR	UPLOCK ACTUATOR	6947010-3 726	MTH 01-Jun-2011		O/C	0		
323005 RIGHT MAIN LANDING GEAR	UPLOCK ACTUATOR	6947010-3 735	MTH 01-Jun-2011		O/C	0		
323005	NOSE LANDING GEAR UPLOCK ACTAUTOR	7147030-9 49	MTH 01-Jun-2011		O/C	0		
323006	HYDRAULIC SHUTTLE VALVE	98312 2024A	MTH 01-Jun-2011		O/C	0		
323007 LEFT	REGEN SHUTTLE VALVE 9914689-1	5128-5 770	MTH 01-Jun-2011		O/C	0		
323007 RIGHT	REGEN SHUTTLE VALVE 9914689-1	5128-5 775	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323008 NOSE LANDING GEAR	UPPER BARREL ASSEMBLY			7142020-3 NSN	MTH 01-Jun-2011		O/C	0		
323021	EMERGENCY GEAR BOTTLE GAUGE			19940931-1 033924	MTH 01-Jun-2011		O/C	0		
323022	BRAKE PRESSURE GAUGE 0-2000 PSI			19940935-1 033592	MTH 01-Jun-2011		O/C	0		
323701	EMERGENCY PNEUMATIC BOTTLE 9914678-5	KSIF		40005414-1 7283	MTH 22-May-2022 HRS 1853 LDG 1390		H/T H/T H/T	143		
324001 LEFT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912702-7			90006036 MAR15-0497	MTH 01-Jun-2011		O/C	0		
324001 RIGHT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912702-7	KSIF		90006036 OCT10-0131	MTH 13-May-2024 HRS 2099.8 LDG 1621		O/C	0 0		
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY 9912648-2			90006044 OCT100068	MTH 01-Jun-2011		O/C	0		
324003 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR TIRE 9912709-1 MICHELIN	KSIF		026-617-1 4040P00075	MTH 23-Apr-2024 HRS 2099.2 LDG 1619		O/C	0 0		
324003 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR TIRE 9912709-1 MICHELIN	KSIF		026-617-1 3060P00147	MTH 01-Aug-2023 HRS 2018 LDG 1537		O/C	0 0		
324004 NOSE LANDING GEAR	TIRE 9912706-1 MICHELIN	KSIF		M19301 9155C200	MTH 15-Dec-2021 HRS 1806.4 LDG 1350		O/C	0 0		
324005 LEFT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912702-2	KSIF		90006022G JAN12-0284	MTH 15-Dec-2021 HRS 1806.4 LDG 1350		O/C	0 0		
324005 RIGHT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912702-2	KSIF		90006022G AUG10-0127	MTH 15-Dec-2021 HRS 1806.4 LDG 1350		O/C	0 0		
324101	BRAKE ANTISKID/METERING VALVE 9912742-2			32-117 138	MTH 01-Jun-2011		O/C	0		
324102 LEFT	ADAPTER TRANSDUCER 9912305-2			40-955 NSN	MTH 01-Jun-2011		O/C	0		
324102 RIGHT	ADAPTER TRANSDUCER 9912305-2			40-955 NSN	MTH 01-Jun-2011		O/C	0		
324103	DIG ANTISKID CONTROL BOX 9912742-5			142-153-1 156	MTH 01-Jun-2011		O/C	0		
324104	BRAKE PRESSURE SWITCH			GPP1250-69 1043430	MTH 01-Jun-2011		O/C	0		
324105	PARKING BRAKE VALVE 9912388-12			98478-1 0041	MTH 01-Jun-2011		O/C	0		
324106	HYDRAULIC PUMP MOTOR			MP50B1 4373	MTH 01-Jun-2011		O/C	0		
324107	BRAKE ANTISKID ACCUMULATOR 9912644-2			7550-2 0876	MTH 01-Jun-2011		O/C	0		
324108	LOW PRESSURE SWITCH			GPP1250-79 1050445	MTH 01-Jun-2011		O/C	0		
324109	BRAKE PRESSURE PUMP 9912364-2			640929 2652	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324110	EMERGENCY BRAKE VALVE 9914478-5 KSIF	98480-2 0100	MTH 10-Jun-2019 HRS 1559.6 LDG 1099		O/C	0		
324111	BRAKE RESERVOIR ASSEMBLY	7117005-11 NSN	MTH 01-Jun-2011		O/C	0		
324113	THERMAL RELIEF VALVE	1785-3 0441	MTH 01-Jun-2011		O/C	0		
324205	HYDRAULIC PACK ASSEMBLY	6517102-23 NSN	MTH 01-Jun-2011		O/C	0		
326001 LEFT MAIN LANDING GEAR	UPLOCK SWITCH	65-430087 NSN	MTH 01-Jun-2011		O/C	0		
326001 RIGHT MAIN LANDING GEAR	UPLOCK SWITCH	65-430087 NSN	MTH 01-Jun-2011		O/C	0		
330001	MAIN LANDING GEAR LED PANEL 9912750-3	92-1060-2 0052	MTH 01-Jun-2011		O/C	0		
331003 LEFT	INDIRECT LIGHTING CONTROL BOX	CLC500-01 500003660	MTH 01-Jun-2011		O/C	0		
331003 RIGHT	INDIRECT LIGHTING CONTROL BOX	CLC500-01 500003652	MTH 01-Jun-2011		O/C	0		
332001	500VA STATIC INVERTER	SS50 NSN	MTH 01-Jun-2011		O/C	0		
334001	GROUND REC LIGHT 9912679-3	84003-2 000588	MTH 01-Jun-2011		O/C	0		
334005 LEFT	COLLISION LIGHT ASSEMBLY	84056-1 0053	MTH 01-Jun-2011		O/C	0		
334005 RIGHT	COLLISION LIGHT ASSEMBLY	84056-2 0052	MTH 01-Jun-2011		O/C	0		
334006 LEFT	TAIL FLOOD LIGHT *CF	TIL100-02 207000336	MTH 26-May-2011		O/C	0		
334006 RIGHT	TAIL FLOOD LIGHT *CF	TIL100-02 207000467	MTH 26-May-2011		O/C	0		
334007 LEFT	WING INSPECTION LIGHT	WIL100-01 205000232	MTH 01-Jun-2011		O/C	0		
334008 LEFT	LANDING LIGHT	LDL100-01 206000384	MTH 01-Jun-2011		O/C	0		
334008 RIGHT	LANDING LIGHT KSIF	LDL100-01 206000339	MTH 11-Oct-2020 HRS 1678.5 LDG 1234		O/C	0		
334009 LEFT	TOUCH SWITCH MODULE	RDG410-01 254000524	MTH 01-Jun-2011		O/C	0		
334009 RIGHT	TOUCH SWITCH MODULE	RDG410-01 254000448	MTH 01-Jun-2011		O/C	0		
335000 AFT	EMERGENCY EXIT BATTERY KGSO	CBS28-1 2314M	MTH 27-Dec-2024 HRS 2170 LDG 1698		H/T H/T H/T	0 0 0		
335000 FORWARD	EMERGENCY EXIT BATTERY KGSO	CBS28-1 2480M	MTH 27-Dec-2024 HRS 2170 LDG 1698		H/T H/T H/T	0 0 0		
335000 MAIN	EMERGENCY EXIT BATTERY KGSO	CBS28-1 2551M	MTH 27-Dec-2024 HRS 2170 LDG 1698		H/T H/T H/T	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
335001 AFT	EMERGENCY OVERWING LIGHT	KGSO		OWL100-03 202400000025144	MTH 27-Dec-2024 HRS 2170 LDG 1698		O/C	0 0 0		
335100 AFT	G-FORCE SWITCH			7212-2-000 956	MTH 01-Jun-2011		O/C	0		
335100 FWD	G-FORCE SWITCH			7212-2-000 858	MTH 01-Jun-2011		O/C	0		
335100 MID	G-FORCE SWITCH			7212-2-000 965	MTH 01-Jun-2011		O/C	0		
340001	MAGNOMETER			501-1826-03 4246	MTH 01-Jun-2011		O/C	0		
340002	CHECKLIST CKL-550			866-1098-001 NSN	MTH 01-Jun-2011		O/C	0		
340003 LEFT	PANEL SWITCH 9912751-2	KICT		80-02472-002 0292	MTH 19-Jun-2017 HRS 1375.2 LDG 897		O/C	0 0		
340004 RIGHT	PANEL SWITCH			80-02500-001 0051	MTH 01-Jun-2011		O/C	0		
340005 FWD	PED PANEL SWITCH 9912753-1			80-02495-001 0050	MTH 01-Jun-2011		O/C	0		
340006 AFT	PED PANEL SWITCH			80-02515-001 0054	MTH 01-Jun-2011		O/C	0		
340007 LEFT	PANEL CONSOLE			92-1056-1 0050	MTH 01-Jun-2011		O/C	0		
340007 RIGHT	PANEL CONSOLE			92-1055-1 0056	MTH 01-Jun-2011		O/C	0		
340008 LEFT	CB PANEL			92-1058-3 0050	MTH 01-Jun-2011		O/C	0		
340008 RIGHT	CB PANEL			92-1057-2 0019	MTH 01-Jun-2011		O/C	0		
340009 CENTER	THROTTLE QUAD LED PANEL			92-1059-3 0050	MTH 01-Jun-2011		O/C	0		
340010 LEFT	REVERSIONARY PANEL			80-02506-001 0048	MTH 01-Jun-2011		O/C	0		
340011 LEFT	POWER SWITCH PANEL 9912761-1			80-02483-001 0053	MTH 01-Jun-2011		O/C	0		
341001 NO. 1	AIR DATA COMPUTER ADC-3000	KGYH		822-1109-128 SN-UNKNOWN	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		O/C	0 0 0		
341001 NO. 2	AIR DATA COMPUTER ADC-3000	KGYH		822-1109-128 3WJ7T	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		O/C	0 0 0		
341001 STANDBY	AIR DATA COMPUTER			9200-30000-206 5065	MTH 01-Jun-2011		O/C	0		
341003	AOA INDEXER			C12463-3 14113701	MTH 01-Jun-2011		O/C	0		
341004	AOA COMPUTER 9912697-1			0863D1 061	MTH 01-Jun-2011		O/C	0		
341010 LEFT	RADIO ALT ANTENNA			S67-2002 54355765	MTH 01-Jun-2011		O/C	0		
341010 RIGHT	RADIO ALT ANTENNA			S67-2002 54355753	MTH 01-Jun-2011		O/C	0		
341034	RADIO ALT TRANSMITTER ALT-4000			822-0615-206 3Y9BJ	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
341103 NO.1	CONFIGURATION CONTROL STRAPPING UNIT CSU-3100	822-1363-002 46G4C	MTH 01-Jun-2011		O/C	0		
341103 NO.2	CONFIGURATION CONTROL STRAPPING UNIT CSU-3100	822-1363-002 46G4D	MTH 01-Jun-2011		O/C	0		
342001	DATA BASE UNIT DBU-5000	822-2215-602 458WG	MTH 01-Jun-2011		O/C	0		
342002 LEFT	AHRS COMPUTER AHC-3000	822-1110-002 455HD	MTH 01-Jun-2011		O/C	0		
342002 RIGHT	AHRS COMPUTER AHC-3000	822-1110-002 46JFH	MTH 01-Jun-2011		O/C	0		
342005 LEFT	FLIGHT GUIDANCE COMPUTER FGC-3000	822-1108-048 46FPJ	MTH 01-Jun-2011		O/C	0		
342005 RIGHT	FLIGHT GUIDANCE COMPUTER FGC-3000	822-1108-048 46FPG	MTH 01-Jun-2011		O/C	0		
342006 LEFT	FLUX DETECTOR FDU-3000	822-1193-001 300267	MTH 01-Jun-2011		O/C	0		
342006 RIGHT	FLUX DETECTOR FDU-3000	822-1193-001 300197	MTH 01-Jun-2011		O/C	0		
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	822-1200-003 455KM	MTH 01-Jun-2011		O/C	0		
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	822-1200-003 455KR	MTH 01-Jun-2011		O/C	0		
342007	EXTERNAL FSU COMPENSATION UNIT ECU-3000-FSU	822-1200-998 46JBN	MTH 01-Jun-2011		O/C	0		
342008 LEFT	IAPS POWER SUPPLY PWR-3000	822-1137-001 45N3H	MTH 01-Jun-2011		O/C	0		
342008 RIGHT	IAPS POWER SUPPLY PWR-3000	822-1137-001 45N3J	MTH 01-Jun-2011		O/C	0		
342009	ENVIRONMENTAL CONTROL	822-1167-001 46FTW	MTH 01-Jun-2011		O/C	0		
342010 LEFT	OPER CONFIG MODULE OCM-3100	822-1484-228 45N2M	MTH 01-Jun-2011		O/C	0		
342010 RIGHT	OPER CONFIG MODULE OCM-3100	822-1484-228 45N2N	MTH 01-Jun-2011		O/C	0		
342011 LEFT	I/O CONCENTRATOR IAPS MODULE IOC-4110	822-2065-001 45LGR	MTH 01-Jun-2011		O/C	0		
342011 RIGHT	I/O CONCENTRATOR IAPS MODULE IOC-4110	822-2065-001 45LPC	MTH 01-Jun-2011		O/C	0		
342012	IAPS-CARD CAGE ICC-3111	822-2191-001 45LFR	MTH 01-Jun-2011		O/C	0		
342013	EXTERNAL AUDIO COMPENSATION UNIT ECU-3000	822-1200-997 46JPG	MTH 01-Jun-2011		O/C	0		
342014	DETACHABLE CONFIG MODULE	501-1803-226 4930	MTH 01-Jun-2011		O/C	0		
342031	STANDBY GYRO POWER SUPPLY PS-855A	501-1712-01 81174	MTH 01-Jun-2011		O/C	0		
342032	SECONDARY FLIGHT DISPLAY	501-1741-3103 27086	MTH 01-Jun-2011		O/C	0		
342033	MAINTENANCE DIAGNOSTIC COMPUTER KSIF	822-1987-008 4L0K4	MTH 12-Feb-2021 HRS 1719.6 LDG 1265		O/C	0 0		
342055 LEFT	DATA CONCENTRATOR UNIT	822-1538-202 3YBCR	MTH 01-Jun-2011		O/C	0		
342056 LEFT	AFD CONTROL DISPLAY PANEL DCP-3320	822-2433-100 461MB	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342056 RIGHT	AFD CONTROL DISPLAY PANEL DCP-3320			822-2433-100 461RM	MTH 01-Jun-2011		O/C	0		
342057 NO.1	CURSOR CONTROL PANEL CCP-3320			822-2434-100 461JT	MTH 01-Jun-2011		O/C	0		
342057 NO.2	CURSOR CONTROL PANEL CCP-3320			822-2434-100 461KW	MTH 01-Jun-2011		O/C	0		
342302 LEFT	ADAPTIVE FLIGHT DISPLAY AFD-3310			822-1993-100 3Y0KJ	MTH 01-Jun-2011		O/C	0		
342302 RIGHT	CURSOR CONTROL PANEL AFD-3310			822-1993-100 3Y0MY	MTH 01-Jun-2011		O/C	0		
342303 LEFT	ADAPTIVE FLIGHT MFD DISPLAY AFD-3320	ICT		822-2349-100 46HGT	MTH 13-Jun-2011 HRS 9.5 LDG 7		O/C	0 0 0		
342303 RIGHT	ADAPTIVE FLIGHT MFD DISPLAY AFD-3320	KSIF		822-2349-100 46HBN	MTH 04-Aug-2020 HRS 1663.4 LDG 1218		O/C	0 0		
343000	MARKER BEACON COUPLER			DMB20-20 3400	MTH 01-Jun-2011		O/C	0		
343001	MARKER BEACON ANTENNA			MB10-754-2 0426	MTH 01-Jun-2011		O/C	0		
343002	DUAL GLIDESLOPE COUPLER			DGSC20-02 6058	MTH 01-Jun-2011		O/C	0		
343003	GLIDESLOPE ASSEMBLY ANTENNA			RGS10-48 15535	MTH 01-Jun-2011		O/C	0		
344001	EGPWS COMPUTER MARK(V111) HONEYWELL			965-1210-026 EMK808065	MTH 01-Jun-2011		O/C	0		
344002	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA KSIF			822-2254-001 3Y2XK	MTH 10-Jun-2019 HRS 1559.6 LDG 1099		O/C	0 0		
344014	XM DATA RECEIVER XMWR-1000	KIWA		822-2031-002 456JX	MTH 09-Sep-2011 HRS 68.7 LDG 35		O/C			
344015 NO. 1	XM RADIO RECEIVER SYSTEM			XMR100-01 801000603	MTH 01-Jun-2011		O/C	0		
344017 NO.1	GPS XM ANTENNA	KIWA		CI428-410 315815	MTH 09-Sep-2011 HRS 68.7 LDG 35		O/C	0 0 0		
344017 NO.2	GPS XM ANTENNA			CI428-410 344012	MTH 01-Jun-2011		O/C	0		
345001 NO.1	DME ANTENNA			L10-611-14 3306	MTH 01-Jun-2011		O/C	0		
345001 NO.2	DME ANTENNA			L10-611-14 3565	MTH 01-Jun-2011		O/C	0		
345002 NO.1	DME TRANSCEIVER DME-4000			822-1466-001 3YDGG	MTH 01-Jun-2011		O/C	0		
345002 NO.2	DME TRANSCEIVER DME-4000			822-1466-001 3YDHB	MTH 01-Jun-2011		O/C	0		
345005 LEFT	VHF NAVIGATION ANTENNA			VT10-767-3 0991	MTH 01-Jun-2011		O/C	0		
345040 NO.1	TRANSPONDER ANTENNA ANT-42			L10-611-14 3467	MTH 01-Jun-2011		O/C	0		
345040 NO.2	TRANSPONDER ANTENNA ANT-42			L10-611-14 3462	MTH 01-Jun-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345041 NO. 1	TRANSPONDER	KICT		622-9210-501 45CYW	MTH 01-Aug-2017 HRS 1376.4 LDG 898		O/C			
345042	TSS W/TRANSPONDER COMPUTER TSS-4100	KICT		822-2132-001 4P84H	MTH 01-Aug-2017 HRS 1376.4 LDG 898		O/C	0 0		
345043 BOTTOM	TSS ANTENNA TSA-4100			866-0016-101 3WBIW	MTH 01-Jun-2011		O/C	0		
345043 TOP	TSS ANTENNA TSA-4100			866-0016-101 455XK	MTH 01-Jun-2011		O/C	0		
345046 NO.1	FMS COMPUTER FMC-3000	KSIF		822-0883-038 426Y4Y	MTH 11-Oct-2020 HRS 1678.5 LDG 1234		O/C	0 0		
345046 NO.2	FMS COMPUTER FMC-3000	KSIF		822-0883-038 45LYJ	MTH 11-Oct-2020 HRS 1678.5 LDG 1234		O/C	0 0		
345047 NO.1	FMS CONTROL DISPLAY UNIT CDU-3000			822-0884-662 467LF	MTH 01-Jun-2011		O/C	0		
345047 NO.2	FMS CONTROL DISPLAY UNIT CDU-3000			822-0884-662 467MT	MTH 01-Jun-2011		O/C	0		
345051	IRIDIUM/GPS ANTENNA			S67-1575-165 4494458	MTH 01-Jun-2011		O/C	0		
345056 NO.1	GPS RECEIVER			822-2189-002 3VLXV	MTH 01-Jun-2011		O/C	0		
345056 NO.2	GPS RECEIVER			822-2189-002 3VLXY	MTH 01-Jun-2011		O/C	0		
345057 NO. 1	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500			822-1579-001 3B3CD	MTH 01-Jun-2011		O/C	0		
345057 NO. 2	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500			822-1579-001 3XFPB	MTH 01-Jun-2011		O/C	0		
345065	TSS COMPENSATION UNIT ECU-3000	KICT		822-1200-803 47NN4L	MTH 01-Aug-2017 HRS 1376.4 LDG 898		O/C	0 0		
345066	FILE SERVER UNIT FSU-5010	KIWA		822-1543-101 2G3VN	MTH 05-Nov-2011 HRS 101.6 LDG 49		O/C	0 0 0		
345068 NO.1	AUDIO CONTROL PANEL RADIO APC-4130	MIA		822-2381-235 4BC5C	MTH 16-Nov-2014 HRS 788 LDG 449		O/C			
345068 NO.2	AUDIO CONTROL PANEL RADIO APC-4130	GSO		822-2381-235 4573V	MTH 19-Jul-2016 HRS 1203.7 LDG 766		O/C			
350007	OXYGEN PRESSURE GAGE			P24140 0054	MTH 01-Jun-2011		O/C	0		
350009	OXYGEN PRESSURE TRANSDUCER IWA			S2800-902 7566-10-259	MTH 29-Dec-2011 HRS 151.8 LDG 65		O/C	0 0 0		
351001	OXYGEN CONTROL VALVE *CF			110081-04 1038	MTH 26-May-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
351101 COPILOT	COPILOT OXYGEN MASK KSIF	MC10-16-150 B156959	MTH 01-Jan-2021 HRS 1713.1 LDG 1261		H/T H/T H/T H/T	0		
351101 PILOT	PILOT OXYGEN MASK KSIF	MC10-16-150 B112315	MTH 09-Aug-2022 HRS 1897.8 LDG 1435		H/T H/T H/T H/T	0 0 0		
351102 350006	OXYGEN BOTTLE ASSEMBLY DOT E-10945 GSO	4441073-050 450907601	DAYS 07-Jan-2022 HRS 1817.3 LDG 1358		H/T H/T H/T H/T	0 0 0		
353102 350008	PROTECTIVE BREATHING EQUIPMENT	PN SN-UNKNOWN	MTH 01-Jun-2011		H/T H/T	0		
361002 LEFT	PRECOOLER ASSEMBLY 9914402-8	8385-1 T0058	MTH 01-Jun-2011		O/C	0		
361002 RIGHT	PRECOOLER ASSEMBLY 9914402-8	8385-1 T0097	MTH 01-Jun-2011		O/C	0		
361004 LEFT	HEAT EXCHANGE FAN AIR EJECTOR VALVE	1407-13 0148	MTH 01-Jun-2011		O/C	0		
361004 RIGHT	HEAT EXCHANGE FAN AIR EJECTOR VALVE	1407-13 0188	MTH 01-Jun-2011		O/C	0		
361005 LEFT	SERVICE AIR CHECK VALVE KGSO	9914171-1 11119	MTH 26-Jul-2024 HRS 2119.5 LDG 1648		O/C			
361005 RIGHT	SERVICE AIR CHECK VALVE 9914171-1	8C210 8996	MTH 01-Jun-2011		O/C	0		
361007	SERVICE AIR REGULATOR 9912510-1	1H75-18 10BF22	MTH 01-Jun-2011		O/C	0		
361300 LEFT	ENG BLEED AIR SOLENOID VALVE	5303-25 0208	MTH 01-Jun-2011		O/C	0		
361300 RIGHT	ENG BLEED AIR VALVE	5303-25 0201	MTH 01-Jun-2011		O/C	0		
450000	ARES RECORDER UNIT ASSEMBLY KSIF	6918231-1 1398	MTH 27-May-2021 HRS 1737.9 LDG 1285		O/C	0 0		
520001	4 CH PROX SENSING CARD	80-187-01 E2596	MTH 01-Jun-2011		O/C	0		
522001	INFLATABLE DOOR SEAL 9911525-5	31M116-5 NSN	MTH 01-Jun-2011		O/C	0		
522003	CABIN DOOR PROXIMITY SWITCH	NBB8-18GM50-E0 NSN	MTH 01-Jun-2011		O/C	0		
522004	ESC HATCH PROXIMITY SWITCH	NBB8-18GM30-E2 NSN	MTH 01-Jun-2011		O/C	0		
530000	RADOME ASSEMBLY KEXX	6313101-47 089	MTH 02-Feb-2015 HRS 843.3 LDG 484		O/C			
531004 LEFT	LEFT NOSE LANDING GEAR ATTACH FITTING ASSEMBLY	7113052-9 NSN	MTH 01-Jun-2011		H/T H/T	0		
531004 RIGHT	RIGHT NOSE LANDING GEAR ATTACH FITTING ASSEMBLY	7113052-10 NSN	MTH 01-Jun-2011		H/T H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
531005	NOSE LANDING GEAR HYDRAULIC ACTUATOR FITTING ASSEMBLY			7111091-8 NSN	MTH 01-Jun-2011		H/T H/T	0		
561001 LEFT	WINDSHIELD ASSY, (LH) 9912699-5			NP-197501-5 10337H9930	MTH 01-Jun-2011		O/C	0		
561001 RIGHT	RIGHT WINDSHIELD ASSY, (RH) 9912699-6			NP-197501-6 10217H5616	MTH 01-Jun-2011		O/C	0		
561002 LEFT NO. 1	CABIN WINDOW			6311323-9 6131	MTH 01-Jun-2011		O/C	0		
561002 LEFT NO. 2	CABIN WINDOW			6311323-9 6098	MTH 01-Jun-2011		O/C	0		
561002 LEFT NO. 3	CABIN WINDOW			6311323-9 6084	MTH 01-Jun-2011		O/C	0		
561002 LEFT NO. 4	CABIN WINDOW			6311323-9 6128	MTH 01-Jun-2011		O/C	0		
561002 LEFT NO. 5	CABIN WINDOW			6311323-9 6068	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 1	CABIN WINDOW			6311323-9 6202	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 2	CABIN WINDOW			6311323-9 6113	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 3	CABIN WINDOW			6311323-9 6109	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 4	CABIN WINDOW			6311323-9 6114	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 5	CABIN WINDOW			6311323-9 6106	MTH 01-Jun-2011		O/C	0		
561002 RIGHT NO. 6	CABIN WINDOW			6311323-9 6103	MTH 01-Jun-2011		O/C	0		
561003 PILOT	SIDE WINDOW 9912700-11	*CF		NP-197502-11 10287H4463	MTH 26-May-2011		O/C	0		
561004 COPILOT	SIDE WINDOW 9912700-12			NP-197502-12 10260H1474	MTH 01-Jun-2011		O/C	0		
571001 LEFT MAIN GEAR	LEFT SIDE MAIN LANDING GEAR BRACE ACTUATOR ATTACH FITTING ASSEMBLY			7141175-1 39	MTH 01-Jun-2011		H/T H/T	0		
571001 RIGHT MAIN GEAR	RIGHT SIDE MAIN LANDING GEAR BRACE ACTUATOR ATTACH FITTING ASSEMBLY			7141175-2 37	MTH 01-Jun-2011		H/T H/T	0		
571002 LEFT MAIN GEAR	LEFT AFT MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY			7141165-1 NSN	MTH 01-Jun-2011		H/T H/T	0		
571002 RIGHT MAIN GEAR	RIGHT AFT MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY			7141165-2 NSN	MTH 01-Jun-2011		H/T H/T	0		
571003 LEFT MAIN GEAR	LEFT FORWARD MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY			7141155-1 48	MTH 01-Jun-2011		H/T H/T	0		
571003 RIGHT MAIN GEAR	RIGHT FORWARD MAIN LANDING GEAR TRUNNION ATTACH FITTING ASSEMBLY			7141155-2 41	MTH 01-Jun-2011		H/T H/T	0		
710002 LEFT	NO.1 ENGINE TEMPERATURE SWITCH			MS28034-3 163496	MTH 01-Jun-2011		O/C	0		
710002 RIGHT	NO. 2 ENGINE TEMPERATURE SWITCH			MS28034-3 163967	MTH 01-Jun-2011		O/C	0		
710003 LEFT	NO.1 ENGINE QUAD MOUNTING PLATE 9914777-4			94518 CES00077	MTH 01-Jun-2011		O/C	0		
710003 RIGHT	NO. 2 ENGINE QUAD MOUNTING PLATE 9914777-4			94518 CES00078	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712002 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT ASSEMBLY 9912711-2			LM-610-SA2 LK0091	MTH 01-Jun-2011		H/T H/T	0		
712002 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT ASSEMBLY 9912711-1			LM-610-SA3 LK0166	MTH 01-Jun-2011		H/T H/T	0		
712002 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT ASSEMBLY 9912711-1			LM-610-SA3 LK0190	MTH 01-Jun-2011		H/T H/T	0		
712002 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT ASSEMBLY 9912711-2			LM-610-SA2 LK0082	MTH 01-Jun-2011		H/T H/T	0		
712002 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT ASSEMBLY 9912711-1			LM-610-SA3 LK0196	MTH 01-Jun-2011		H/T H/T	0		
712002 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT ASSEMBLY 9912711-1			LM-610-SA3 LK0186	MTH 01-Jun-2011		H/T H/T	0		
71EN1 NO. 1	ENGINE 9912710-1 FJ44-4A	GSO		73200-200 211089	MTH 19-Jun-2013 HRS 421.7 LDG 188		E/C	406.5		
71EN2 NO. 2	ENGINE 9912710-1 FJ44-4A			73200-200 211090			E/C			
720001 E1	FAN ROTOR HW33162			110646 HW33162	MTH 01-Jun-2011 LDG 0		10000	0	(10000)10000	8299
720001 E2	FAN ROTOR HW33225			110646 HW33225	MTH 01-Jun-2011 LDG 3		10000	0	(10000)10003	8302
720002 E1	IP COMPRESSOR ROTOR UNK			221931 HW61024	MTH 12-Nov-2020 HRS 1694.9 LDG 1249		10000	1 0 0	(11232)11249	9548
720002 E2	IP COMPRESSOR ROTOR UNK			221931 HW61026	MTH 12-Nov-2020 HRS 1694.9 LDG 1249		10000	1 0 0	(11249)11249	9548
720003 E1	COMPLETE LP SHAFT ASSEMBLY RX10TY0086			111485 RX10TY0086	MTH 01-Jun-2011		O/C	0		
720003 E2	COMPLETE LP SHAFT ASSEMBLY RX10TY0076			111485 RX10TY0076	MTH 01-Jun-2011		O/C	0		
720004 E1	HIGH PRESSURE SHAFT RX10TG0105			72907 RX10TG0105	MTH 01-Jun-2011		O/C	0		
720004 E2	HIGH PRESSURE SHAFT RX10TG0085			72907 RX10TG0085	MTH 01-Jun-2011		O/C	0		
720005 E1	HP COMPRESSOR COVER AU20041			114826 AU20041	MTH 01-Jun-2011		O/C	0		
720005 E2	HP COMPRESSOR COVER AU20098			114826 AU20098	MTH 01-Jun-2011		O/C	0		
720006 E1	DIFFUSER CASE ASSEMBLY AU20089			115994 AU20089	MTH 01-Jun-2011		O/C	0		
720006 E2	DIFFUSER CASE ASSEMBLY AU20086			115994 AU20086	MTH 01-Jun-2011		O/C	0		
720007 E1	1ST STAGE LP TURBINE NOZZLE AU20204			118309 AU20204	MTH 01-Jun-2011		O/C	0		
720007 E2	1ST STAGE LP TURBINE NOZZLE AU20199			118309 AU20199	MTH 01-Jun-2011		O/C	0		
720008 E1	ACCESS DRIVE GEARBOX UNK			120757 MX20014	MTH 12-Jun-2013 HRS 421.7 LDG 188		O/C	406.5 173		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720008 E2	ACCESS DRIVE GEARBOX			115052 MX20015	MTH 01-Jun-2011		O/C	0		
725101 E1	HP COMPRESSOR ROTOR			114839 HW33328	MTH 01-Jun-2011 LDG 0		10000	0	(10000)10000	8299
725101 E2	HP COMPRESSOR ROTOR			114839 HW33323	MTH 01-Jun-2011 LDG 3		10000	0	(10000)10003	8302
725102 E1	HP TURBINE ROTOR			111126 HW33290	MTH 01-Jun-2011		O/C	0		
725102 E2	HP TURBINE ROTOR			111126 HW33294	MTH 01-Jun-2011		O/C	0		
725103 E1	HP TURBINE DISK			111125 HW33290	MTH 01-Jun-2011 LDG 0		10000	0	(10000)10000	8299
725103 E2	HP TURBINE DISK			111125 HW33294	MTH 01-Jun-2011 LDG 3		10000	0	(10000)10003	8302
725501 E1	1ST LP TURBINE DISK			77581 HW33259	MTH 01-Jun-2011 LDG 0		10000	0	(10000)10000	8299
725501 E2	1ST LP TURBINE DISK			77581 HW33258	MTH 01-Jun-2011 LDG 3		10000	0	(10000)10003	8302
725502 E1	2ND LP TURBINE DISK			73052 HW33197	MTH 01-Jun-2011 LDG 0		10000	0	(10000)10000	8299
725502 E2	2ND LP TURBINE DISK			73052 HW33196	MTH 01-Jun-2011 LDG 3		10000	0	(10000)10003	8302
732500 LEFT	LEFT FULL AUTHORITY DIGITAL ELECTRONIC CONTROL (FADEC)	KBCB		116662 CL10AW1728	MTH 21-Feb-2023 HRS 1960.3 LDG 1490		O/C			
732500 RIGHT	RIGHT FULL AUTHORITY DIGITAL ELECTRONIC CONTROL (FADEC)	KBCB		116662 CL10AW1691	MTH 21-Feb-2023 HRS 1960.3 LDG 1490		O/C			
730001 E1	PRESSURE SWITCH FUEL			1103P0448 9639	MTH 01-Jun-2011		O/C	0		
730001 E2	PRESSURE SWITCH FUEL			1103P0448 9616	MTH 01-Jun-2011		O/C	0		
730002 E1	FUEL NOZZLE ASSY	KBCB		111765 BCC-00009694	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
730002 E2	FUEL NOZZLE ASSY	KBCB		111765 BCC-00011034	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
730003 E1	SEAL AND FUEL SLINGER ASSEMBLY			115468 AU20089	MTH 01-Jun-2011		O/C	0		
730003 E2	SEAL AND FUEL SLINGER ASSEMBLY			115468 AU20074	MTH 01-Jun-2011		O/C	0		
731046 E1	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 01-Jun-2011		O/C	0		
731046 E2	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 01-Jun-2011		O/C	0		
732101 E1	FUEL DELIVERY UNIT	KEXX		122735 CL9ATY0029	MTH 14-Apr-2016 HRS 1138.2 LDG 710		5000	2486	(3637)3652.2	1478.5
732101 E2	FUEL DELIVERY UNIT	KBCB		122735 CL2ATY0253	MTH 03-Dec-2020 HRS 1706.4 LDG 1257		5000	516.2	(6190.2)6190.2	4016.5
732102 E1	PT2 SENSOR			113762 AXT0100273	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
732102 E2	PT2 SENSOR			113762 AXT0100276	MTH 01-Jun-2011		O/C	0		
732301 E1	ELEC FUEL FILTER INDICATOR			57847 GE4450	MTH 01-Jun-2011		O/C	0		
732301 E2	ELEC FUEL FILTER INDICATOR			57847 GE4499	MTH 01-Jun-2011		O/C	0		
733001 E1	FUEL FLOW TRANSMITTER 9912701-1			8TJ310AAA1 25645	MTH 01-Jun-2011		O/C	0		
733001 E2	FUEL FLOW TRANSMITTER 9912701-1			8TJ310AAA1 25654	MTH 01-Jun-2011		O/C	0		
741001 E1 INBOARD	IGNITION EXCITER			68145 CK1000365	MTH 01-Jun-2011		O/C	0		
741001 E1 OUTBOARD	IGNITION EXCITER			68145 CK1000377	MTH 01-Jun-2011		O/C	0		
741001 E2 INBOARD	IGNITION EXCITER *CF			73489 BL17763	MTH 26-May-2011		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER *CF			73489 BL17769	MTH 26-May-2011		O/C	0		
741002 E1	SHORT IGNITOR LEAD			70163 NSN	MTH 01-Jun-2011		O/C	0		
741002 E2	SHORT IGNITOR LEAD			70163 NSN	MTH 01-Jun-2011		O/C	0		
741003 E1	LONG IGNITOR LEAD			70163 NSN	MTH 01-Jun-2011		O/C	0		
741003 E2	LONG IGNITOR LEAD			70163 NSN	MTH 01-Jun-2011		O/C	0		
741004 E1 INBOARD	IGNITOR	KBCB		78214 CK-1700233	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
741004 E1 OUTBOARD	IGNITOR	KBCB		78214 CK-1201403	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
741004 E2 INBOARD	IGNITOR	KBCB		78214 CK-1904061	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
741004 E2 OUTBOARD	IGNITOR	KBCB		78214 CK-1500575	MTH 17-Aug-2023 HRS 2023.8 LDG 1543		O/C			
771001 E1	N1 DUAL MAGNETIC SPEED SENSOR			78231 MD156000	MTH 01-Jun-2011		O/C	0		
771001 E2	N1 DUAL MAGNETIC SPEED SENSOR			78231 MD0139233	MTH 01-Jun-2011		O/C	0		
771002 E1	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD0138564	MTH 01-Jun-2011		O/C	0		
771002 E2	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD0138462	MTH 01-Jun-2011		O/C	0		
771003 E1	TT2 SENSOR			114944 AXT0200446	MTH 01-Jun-2011		O/C	0		
771003 E2	TT2 SENSOR			114944 AXT0200444	MTH 01-Jun-2011		O/C	0		
772002 E1	ITT HARNESS ASSEMBLY			73151 YYF000117	MTH 01-Jun-2011		O/C	0		
772002 E2	ITT HARNESS ASSEMBLY			73151 YYF000114	MTH 01-Jun-2011		O/C	0		
790001 L/H	ENGINE OIL TEMPERTURE SENSOR			MS28034-3 163467	MTH 01-Jun-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
790001 R/H	ENGINE OIL TEMPURTURE SENSOR	MS28034-3 163497	MTH 01-Jun-2011		O/C	0		
792011 E1	OIL FILTER DIFFERENTIAL PRESSURE INDICATOR	115015 KM0099	MTH 01-Jun-2011		O/C	0		
792011 E2	OIL FILTER DIFFERENTIAL PRESSURE INDICATOR	115015 KM0110	MTH 01-Jun-2011		O/C	0		
792201 E1	LUBE OIL COOLER	110718 PP0624	MTH 01-Jun-2011		O/C	0		
792201 E2	LUBE OIL COOLER	110718 PP0627	MTH 01-Jun-2011		O/C	0		
792401 E1	LUBE AND SCAVENGE PUMP	114520 MX21000	MTH 01-Jun-2011 HRS 15.2		6000	0	(6000)6015.2	3841.5
792401 E2	LUBE AND SCAVENGE PUMP KLNN	114520 MX20914	MTH 19-Jul-2011 HRS 34.5 LDG 21		6000	0	(6034.5)6034.5	3860.8
793003 E1	OIL PRESSURE TRANSMITTER KJXN	APTE-304A-200G 8339-8-172	MTH 11-Jun-2016 HRS 1170.7 LDG 740		O/C	0		
793003 E2	OIL PRESSURE TRANSMITTER KGSO	APTE-304A-200G 9005-9-686	MTH 22-Dec-2023		O/C	0		
801102 LEFT	LEFT STARTER - GENERATOR 9912733-3 KMTV	MG94D-3 0295	MTH 22-Dec-2017 HRS 1408.7 LDG 939		H/T H/T H/T	0		
801102 RIGHT	RIGHT STARTER-GENERATOR 9912733-3 KSIF	MG94D-3 0728B	MTH 27-Feb-2023 HRS 1963.7 LDG 1492		H/T H/T H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525C-99-01 R01	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525C-99-02	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525C-99-03	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525C-99-05	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525C-05-01 R01	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM NON MSG-3 SCHEDULED MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM			INFORMATIONAL			-			
	MOC :									
SL 525C-05-01	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM NON MSG-3 SCHEDULED MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM			INFORMATIONAL			-			
	MOC :									
SL 525C-05-02	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE PROGRAM UPDATE AND FORMAT CHANGE			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000) CANCELLED				-			
	MOC :							
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)	INFORMATIONAL			-			
	MOC :							
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R06 E1	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1000 R06 E2	UNSERVICEABLE PARTS - NOTIFICATION	INFORMATIONAL			-			
	MOC :							
PSID WI-05-1003 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							
PSID WI-05-1003 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							
PSID WI-05-1003 R02 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							
PSID WI-05-1003 R02 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS				-			
	MOC :							
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1095-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED				-			
	MOC :							
SL WI-05-1095-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED				-			
	MOC :							
SL WI-05-1095 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1095 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1139-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE.) CANCELLED				-			
	MOC :							
SL WI-05-1139-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE.) CANCELLED				-			
	MOC :							
SL WI-05-1139 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1139 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL				-			
	MOC :							
SL WI-05-1184-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-05-1184-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELED									
MOC :										
SL WI-05-1192-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELED									
MOC :										
SL WI-05-1192-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELED									
MOC :										
SL WI-05-1194-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELED									
MOC :										
SL WI-05-1194-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELED									
MOC :										
SL 525C-08-01	LEVELING AND WEIGHING - AIRPLANE FLIGHT MANUAL WEIGHT AND BALANCE FORM UPDATES	ICT	MANDATORY	MTH 27-Feb-2013 HRS 376.9 LDG 149			-		Complete	
MOC : COMPLIED WITH										
SL 525C-08-02	AIRPLANE FLIGHT MANUAL WEIGHT AND BALANCE FORM UPDATE	KEXX	MANDATORY	DAYS 02-Mar-2015 HRS 866.1 LDG 503			-		Complete	
MOC : COMPLIED WITH										
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL				-			
MOC :										
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL				-			
MOC :										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL				-			
MOC :										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS		RECOMMENDED	MTH			-			
MOC :										
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL				-			
MOC :										
SL CIL-20-01 R03-CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		CANCELLED				-			
MOC :										
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL				-			
MOC :										
SL 525C-20-03	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL		INFORMATIONAL				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 525C-21-03	AIR CONDITIONING - PRE-PRESSURIZATION ACTIVATION IMPROVEMENT	KIWA	OPTIONAL	MTH 05-Nov-2011 HRS 101.6 LDG 49			A/R			Complete
	MOC : COMPLIED WITH									
SB 525C-21-04	AIR CONDITIONING - CONDITIONED AIR MUFFLER IMPROVEMENT	IWA	DISCRETIONARY	MTH 09-Apr-2012 HRS 242 LDG 98			-			Complete
	MOC : COMPLIED WITH									
SB 525C-21-06	AIR CONDITIONING - CONDITIONED AIR DUCT PLENUM INSTALLATION		DISCRETIONARY				-			
	MOC :									
SB 525C-21-08	AIR CONDITIONING - PRESSURIZATION WIRING MODIFICATION		RECOMMENDED	MTH			-			
	MOC :									
SL 525C-21-01 R01	AIR CONDITIONING - COMPRESSOR MOTOR FIRMWARE UPDATE		DISCRETIONARY				-			
	MOC :									
SL 525C-21-01	AIR CONDITIONING - COMPRESSOR MOTOR FIRMWARE UPDATE	KEXX	DISCRETIONARY	MTH 21-Aug-2013 HRS 477 LDG 228			-			Complete
	MOC : COMPLIED WITH									
SL 525C-21-02	COMPRESSOR MOTOR BUS BAR INSPECTION	KEXX	MANDATORY	DAYS 21-Aug-2013 HRS 477 LDG 228			-			Complete
	MOC : COMPLIED WITH									
SL 525C-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT		RECOMMENDED	MTH			-			
	MOC :									
SB 525C-23-01	COMMUNICATIONS - ENGINE EXCITER ELECTRO MAGNETIC INTERFERENCE (EMI) IMPROVEMENT		OPTIONAL				-			
	MOC :									
SB 525C-23-02	COMMUNICATIONS - AVIATOR 300 SATCOM ANTENNA REPLACEMENT		OPTIONAL				-			
	MOC :									
SB 525C-23-03 R01	COMMUNICATIONS - ATN-B1 CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION		OPTIONAL				-			
	MOC :									
SB 525C-23-03 R02	COMMUNICATIONS - ATN-B1 CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION		OPTIONAL				-			
	MOC :									
SB 525C-23-03	COMMUNICATIONS - ATN-B1 CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION		OPTIONAL				-			
	MOC :									
SL 525C-23-01	COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA		INFORMATIONAL				-			
	MOC :									
SL 525C-23-02	COMMUNICATIONS - ATG 4000 SOFTWARE UPGRADE		OPTIONAL				-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-23-03	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE TO VERSION 2.8 OPTIONAL						-			
MOC :										
SB 525C-24-02	ELECTRICAL POWER - AFT J-BOX WIRING MODIFICATION KIWA	RECOMMENDED	MTH HRS LDG	07-Feb-2012 186 78		A/R				Complete
MOC : COMPLIED WITH										
SB 525C-24-04 R01	ELECTRICAL POWER - DC TO DC CONVERTER INSTALLATION ICT	MANDATORY	MTH HRS LDG	08-Jun-2017 1375.2 897		A/R				Complete
MOC : COMPLIED WITH - SB525C-24-04 REV. 1; DC TO DC CONVERTER INSTALLATION. IS C/W DUE TO REV. 2 WAS ACCOMPLISHED.										
SB 525C-24-04 R02	ELECTRICAL POWER - DC TO DC CONVERTER INSTALLATION KIWA	MANDATORY	MTH HRS LDG	07-Feb-2012 186 78		A/R				N/A
MOC : NOT APPLICABLE - COMMENTS: THE INTENT OF ELECTRICAL POWER- DC TO DC CONVERTER INSTALLATION WAS PREVIOUSLY COMPLIED WITH ON NOVEMBER 5 2011 ON MTR# 1889139 BY PERFORMING THE ORIGINAL REVISION OF SB525C-24-04. PER REV 2 TRANSMITTAL SHEET INSTRUCTIONS AIRPLANES PREVIOUSLY MODIFIED BY OLDER REVISIONS OF THIS SERVICE BULLETIN ARE NOT EFFECTED. PLEASE CLEAR CESCOM OF SB525C-24-04 R2.										
SB 525C-24-04	ELECTRICAL POWER- DC TO DC CONVERTER INSTALLATION IWA	MANDATORY	MTH HRS LDG	05-Nov-2011 101.6 49		A/R				Complete
MOC : COMPLIED WITH										
SB 525C-24-05	ELECTRICAL POWER - NI-CAD OR LEAD ACID BATTERY INSTALLATION SDL	MANDATORY	DAYS HRS LDG	14-Oct-2011 84.1 40		A/R				Complete
MOC : COMPLIED WITH										
SB 525C-24-06	ELECTRICAL POWER - BATTERY TEMPERATURE SENSOR CONNECTOR REPLACEMENT KIWA	DISCRETIONARY	MTH HRS LDG	13-May-2012 274.2 108		-				Complete
MOC : COMPLIED WITH										
SB 525C-24-07 R01	EXTERNAL DRAIN HEATER WIRING MODIFICATION OPTIONAL						-			
MOC :										
SB 525C-24-07 R02	ELECTRICAL POWER - EXTERNAL DRAIN HEATER WIRING MODIFICATION OPTIONAL						-			
MOC :										
SB 525C-24-07	EXTERNAL DRAIN HEATER WIRING MODIFICATION OPTIONAL						-			
MOC :										
ASL 525C-24-02 R01	ELECTRICAL POWER - LITHIUM ION BATTERY STATUS INSPECTION KIWA	MANDATORY	MTH HRS LDG	07-Feb-2012 186 78		A/R				N/A
MOC : NOT APPLICABLE - THE EXTENT OF ASL525C-24-02-R1 DOES NOT APPLY TO THIS AIRCRAFT. LITHIUM ION BATTERY IS NOT INSTALLED. CLEAR CESCOM.										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 525C-24-02	ELECTRICAL POWER - LITHIUM ION BATTERY STATUS INSPECTION	ICT		MANDATORY	MTH 08-Jun-2017 HRS 1375.2 LDG 897		A/R			Complete
MOC : COMPLIED WITH - ASL525C-24-02; LITHIUM ION BATTERY STATUS INSPECTION. IS C/W DUE TO REV. 1 WAS ACCOMPLISHED.										
SL 525C-24-04	WING GROUND STUD TERMINAL REPLACEMENT	GSO		RECOMMENDED	MTH 27-Oct-2014 HRS 771.7 LDG 437		-			Complete
MOC : COMPLIED WITH										
SL 525C-24-07	ELECTRICAL POWER - ADHERE WING STUB GROUNDING WIRES TO PREVENT VIBRATION			DISCRETIONARY			-			
MOC :										
SB 525C-25-02	CABIN ENTRY STEP IMPROVEMENT	IWA		DISCRETIONARY	MTH 09-Apr-2012 HRS 242 LDG 98		-			Complete
MOC : COMPLIED WITH										
SB 525C-25-03	CABIN ENTRY STEP HARDWARE IMPROVEMENT	KIWA		RECOMMENDED	MTH 06-Apr-2013 HRS 379.4 LDG 151		-			Complete
MOC : COMPLIED WITH										
SB 525C-25-04 R01	EQUIPMENT/FURNISHINGS - POWERED HEADSET JACK MODIFICATION			RECOMMENDED	MTH		-			
MOC :										
SB 525C-25-04	EQUIPMENT/FURNISHINGS - POWERED HEADSET JACK MODIFICATION						-			
MOC :										
SB 525C-25-05	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK			OPTIONAL			-			
MOC :										
SB CIB-25-02	EQUIPMENT/FURNISHINGS - BELTED TOILET SEAT INERTIA REEL MODIFICATION	GSO		RECOMMENDED	MTH 27-May-2016 HRS 1165.7 LDG 735		-			Complete
MOC : COMPLIED WITH - C/W SB CIB-25-02 BELTED TOILET SEAT INERTIA REEL MODIFICATION.										
SL 525C-25-02 R01	CABIN SEAT CUSHION MODIFICATION	GSO		MANDATORY	MTH 13-Dec-2013 HRS 565.2 LDG 288		-			Complete
MOC : COMPLIED WITH										
SL 525C-25-02	CABIN SEAT CUSHION MODIFICATION	ICT		MANDATORY	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SL525C-25-02; CABIN SEAT CUSHION MODIFICATION. IS C/W DUE TO REV. 1 WAS ACCOMPLISHED.										
SL 525C-25-03	VENUE SYSTEM V4.2 SOFTWARE UPGRADE	KGSO		DISCRETIONARY	MTH 23-May-2015 HRS 922 LDG 538		-			Complete
MOC : COMPLIED WITH - SL525C-25-03 IS COMPLIED WITH, LOADED SYSTEM SOFTWARE VERSION 4.2. ALL WORK IAW SL525C-25-03.										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-25-04	EQUIPMENT/FURNISHINGS - VENUE SYSTEM SOFTWARE IMPROVEMENT	KGSO	RECOMMENDED	MTH 23-May-2015 HRS 922 LDG 538		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525C-25-04. ALL CHECKS GOOD.										
SL 525C-25-05	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION		OPTIONAL			-				
MOC :										
SB 525C-26-01 R01	FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT	GSO	MANDATORY	MTH 20-Dec-2023 HRS 2056.7 LDG 1577		-				Complete
MOC : COMPLIED WITH - C/W SB 525C-26-01 R01 FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT.										
SB 525C-26-01	FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT	KGYH	MANDATORY	MTH 18-Jul-2023 HRS 2006.2 LDG 1524		-				Complete
MOC : COMPLIED WITH - 3.1) PERFORMED SB525C-26-01 FIRE PROTECTION-FIRE LOOP WIRING IMPROVEMENTS, PER SB525C-26-01, DATED JULY 20, 2022. GUIDANCE AND FUNCTION CHECKED IAW MODEL 525C MAINTENANCE MANUAL 26-11-00. SYSTEM OPERATIONAL CHECK GOOD WITH NO DEFECTS FOUND.										
SB 525C-26-02	FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS		OPTIONAL			-				
MOC :										
SL 525C-26-01 R01	FIRE PROTECTION - INSPECTION OF THE FIRE EXTINGUISHER BOTTLE ELECTRICAL CONNECTORS AND CARTRIDGES FOR CORRECT IDENTIFICATION AND INSTALLATION		MANDATORY	DAYS		-				
MOC :										
SL 525C-26-01	FIRE PROTECTION - INSPECTION OF THE FIRE EXTINGUISHER BOTTLE ELECTRICAL CONNECTORS AND CARTRIDGES FOR CORRECT IDENTIFICATION AND INSTALLATION	KSIF	MANDATORY	DAYS 16-Sep-2024 HRS 2125.8 LDG 1656		-				Complete
MOC : COMPLIED WITH - CONNECTIONS IN CORRECT POSITIONS.										
SB 525C-27-03	FLIGHT CONTROLS - RUDDER BIAS VALVE REORIENTATION		OPTIONAL			-				
MOC :										
SL 525C-27-02	AFT ELEVATOR CONTROL CABLE REPLACEMENT	KIWA	MANDATORY	MTH 06-Apr-2013 HRS 379.4 LDG 151		-				Complete
MOC : COMPLIED WITH										
SB 525C-28-01	FUEL - SINGLE POINT REFUELING (SPR) INDICATOR LIGHT INSTALLATION	GSO	MANDATORY	MTH 19-Jun-2013 HRS 421.7 LDG 188			A/R			N/A
MOC : NOT APPLICABLE - CESCOM NOTE: SB525C-28-01 DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS		INFORMATIONAL			-				
MOC :										
SL 525C-28-03 R01	FUEL - FUEL FLOW TRANSMITTERS SOFTWARE CHECK	KEXX	MANDATORY	MTH 22-Jun-2016 HRS 1180.4 LDG 746		-				N/A
MOC : NOT APPLICABLE - SL525C-28-03 IS N/N DUE TO PART NUMBER & SERIAL NUMBER INSTALLED ON THIS AIRCRAFT.										
SL 525C-29-01 R01	HYDRAULIC POWER - DRAIN HOSE T-FITTING INSPECTION IN AFT FAIRING HYDRAULIC INSTALLATION		RECOMMENDED			-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-29-01	R02 HYDRAULIC POWER - DRAIN HOSE T-FITTING INSPECTION IN AFT FAIRING HYDRAULIC INSTALLATION									
				RECOMMENDED	MTH		-			
MOC :										
SL 525C-29-01	HYDRAULIC POWER - DRAIN HOSE T-FITTING INSPECTION IN AFT FAIRING HYDRAULIC INSTALLATION									
				RECOMMENDED	MTH		-			
MOC :										
SB 525C-30-02	TT2 HEATER WIRING MODIFICATION			MANDATORY	MTH 23-May-2015		-			Complete
	KGSO				HRS 922					
					LDG 538					
MOC : COMPLIED WITH - COMPLIED WITH SB525C-30-02 PER ACCOMPLISHMENT INSTRUCTIONS. ALL CHECKS GOOD.										
SL CIL-30-01	R01 ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
				INFORMATIONAL			-			
MOC :										
SB 525C-31-01	INDICATING/RECORDING SYSTEMS - MASTER CAUTION WIRING MODIFICATION									
	KIWA			DISCRETIONARY	MTH 13-May-2012		-			Complete
					HRS 274.2					
					LDG 108					
MOC : COMPLIED WITH										
SB 525C-31-03	INDICATING/RECORDING SYSTEMS - MDT-3110 (MAINTENANCE DATA TABLES) UPDATE									
				OPTIONAL			-			
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
				INFORMATIONAL			-			
MOC :										
SB 525C-32-04	R01 NOSE STRUT AIR VALVE REPLACEMENT									
				RECOMMENDED			-			
MOC :										
SB 525C-32-04	NOSE STRUT AIR VALVE REPLACEMENT				MTH 06-Apr-2013		-			Complete
	KIWA			RECOMMENDED	HRS 379.4					
					LDG 151					
MOC : COMPLIED WITH										
ASL 525C-32-01	LANDING GEAR - AFT MAIN LANDING GEAR TRUNNION PIN INSPECTION									
	KIWA			MANDATORY	MTH 16-Aug-2012		-			Complete
					HRS 321					
					LDG 124					
MOC : COMPLIED WITH										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
				INFORMATIONAL			-			
MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
				INFORMATIONAL			-			
MOC :										
SL 525C-32-02	R01 MAIN LANDING GEAR BRAKE INSPECTION				MTH 02-Apr-2014		-			Complete
LEFT	KEXX			MANDATORY	HRS 629.7					
					LDG 330					
MOC : COMPLIED WITH - C/W SL525C-32-02 MAIN LANDING GEAR BRAKE INSPECTION COMPLETED. NO FURTHER INSPECTION REQUIRED DUE TO LOT NUMBER.OF BRAKE ROTORS INSTALLED ON LEFT GEAR BRAKE ASSY. LH BRAKE ROTORSLOT NUMBERS: OB 10004 MOB10004 MIB10200 IB 10004										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-32-02 R01 MAIN LANDING GEAR BRAKE INSPECTION RIGHT	KEXX	MANDATORY	MTH 02-Apr-2014 HRS 629.7 LDG 330		-				Complete	
MOC : COMPLIED WITH - C/W SL525C-32-02 INSPECTION OF MAIN LANDING GEAR BRAKES COMPLETED. NO FURTHER INSPECTION REQUIRED DUE TO THE LOT NUMBER ROTORS INSTALLED ON RIGHT BRAKE . RH BRAKE ROTORS LOT NUMBERS:OB10004 MOB10004 MIB10003 IB 10003										
SL 525C-32-02 R02 MAIN LANDING GEAR BRAKE INSPECTION LEFT					-					
MOC :										
SL 525C-32-02 R02 MAIN LANDING GEAR BRAKE INSPECTION RIGHT					-					
MOC :										
SL 525C-32-02 LEFT	MAIN LANDING GEAR BRAKE INSPECTION KEXX	MANDATORY	MTH 25-Feb-2014 HRS 602.5 LDG 318		-				Complete	
MOC : COMPLIED WITH - C/W SL525C32-02 MAIN LANDING GEAR BRAKE VISUAL INSPECTION. NO DEFECTS NOTED. NEXT INSPECTION DUE IN 50 LANDINGS ACTL 368										
SL 525C-32-02 RIGHT	MAIN LANDING GEAR BRAKE INSPECTION KEXX	MANDATORY	MTH 25-Feb-2014 HRS 602.5 LDG 318		-				Complete	
MOC : COMPLIED WITH - C/W SL525C-32-02 MAIN LANDING GEAR BRAKE VISUAL INSPECTION. NO DEFECTS NOTED. NEXT INSPECTION DUE IN 50 LANDINGS ACTL368										
SL 525C-32-03	MAIN LANDING GEAR WHEEL DRIVE KEY INSPECTION KEXX	MANDATORY	MTH 29-Oct-2013 HRS 531.1 LDG 273		-				Complete	
MOC : COMPLIED WITH										
SL 525C-32-04 R01 NOSE LANDING GEAR WIRE ROUTING IMPROVEMENT GSO		RECOMMENDED	MTH 13-Dec-2013 HRS 565.2 LDG 288		-				Complete	
MOC : COMPLIED WITH										
SL 525C-32-04	NOSE LANDING GEAR WIRE IMPROVEMENT ICT	RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-				Complete	
MOC : COMPLIED WITH - SL525C-32-04; NOSE LANDING GEAR WIRE IMPROVEMENT. IS C/W DUE TO REV. 1 WAS ACCOMPLISHED.										
SL 525C-32-05	NOSE LANDING GEAR INSPECTION KGSO	MANDATORY	MTH 23-May-2015 HRS 922 LDG 538		-				Complete	
MOC : COMPLIED WITH - COMPLIED WITH CITATION SERVICE LETTER SL525C-32-05. NOSE GEAR EXTENSION MEASURED AT 8.75"										
SL 525C-32-06 R01 LANDING GEAR - MAIN LANDING GEAR TRUNNION PIN BEARING LUBRICATION KEXX		MANDATORY	MTH 18-Jul-2016 DAYS 1203.5 HRS 765 LDG		-				Complete	
MOC : COMPLIED WITH - VERIFIED ROYCO 64 WAS USED TO SERVICE THE MLG TRUNNIONS WHEN C/W INT. SERVICE LETTER 525C-32-06. C/W BY GREENSBORO CITATION SERVICE CENTER.CRS #CNQ7918C										
SL 525C-32-06	LANDING GEAR - MAIN LANDING GEAR TRUNNION PIN BEARING LUBRICATION GSO	MANDATORY	DAYS 27-May-2016 HRS 1165.7 LDG 735		-				Complete	
MOC : COMPLIED WITH - C/W SL 525C-32-06 MAIN LANDING GEAR TRUNNION PIN BEARING LUBRICATION.										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-32-10	LANDING GEAR - BRAKE CHECK VALVE VERIFICATION	MTH	27-Apr-2021	-				Complete		
	KSIF	RECOMMENDED	HRS 1737.9							
			LDG 1285							
MOC : COMPLIED WITH - C/W BY VISUAL INSPECTION AND NO DEFECTS WERE NOTED AT THIS TIME.										
SL 525C-32-12	LANDING GEAR - MAIN LANDING GEAR TRUNNION PIN INSPECTION	DAYS	13-Aug-2018	-				Complete		
	KBCB	MANDATORY	HRS 1472.3							
			LDG 1007							
MOC : COMPLIED WITH - INSPECTED AND FOUND SAFE FOR CONTINUED OPERATION AT THIS TIME.										
SL 525C-32-14 R01	LANDING GEAR - INSPECT THE MAIN LANDING GEAR FORWARD AND AFT TRUNNION MOUNTING PINS FOR CORRECT INSTALLATION			-						
	MANDATORY									
MOC : - COMPLIED WITH IN REV 0.										
SL 525C-32-14	LANDING GEAR - INSPECT THE MAIN LANDING GEAR FORWARD AND AFT TRUNNION MOUNTING PINS FOR CORRECT INSTALLATION	MTH	22-May-2022	-				Complete		
	KSIF	MANDATORY	HRS 1853							
			LDG 1390							
MOC : COMPLIED WITH - ALL MEASUREMENTS AND INSPECTIONS FOUND TO BE WITHIN MANUFACTURES SPECIFICATIONS AT THIS TIME. NO FURTHER ACTION IS REQUIRED.										
SB 525C-33-01 R01	EMERGENCY LIGHTING BATTERY PACK WIRING IMPROVEMENT	MTH	23-May-2015	-				Complete		
	KGSO	RECOMMENDED	HRS 922							
			LDG 538							
MOC : COMPLIED WITH - COMPLIED WITH SB525C-33-01 R1, EMERGENCY LIGHTING BATTERY PACK WIRING IMPROVEMENT, PER ACCOMPLISHMENT INSTRUCTIONS. ALL CHECKS GOOD.										
SB 525C-33-01 R02	EMERGENCY LIGHTING BATTERY PACK WIRING IMPROVEMENT			-						
	RECOMMENDED									
MOC :										
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			-						
	INFORMATIONAL									
MOC :										
SB 525C-34-02	NAVIGATION-ROCKWELL COLLINS IMPROVEMENTS	MTH	19-Jun-2013	A/R				N/A		
	GSO	MANDATORY	HRS 421.7							
			LDG 188							
MOC : NOT APPLICABLE - CESCOM NOTE: SB525C-34-02 DOES NOT APPLY PER AIRCRAFT SERIAL NUMBER										
SB 525C-34-03 R01	NAVIGATION - ROCKWELL COLLINS RADAR UPGRADE	MTH	08-Jun-2017	A/R				Complete		
	ICT	MANDATORY	HRS 1375.2							
			LDG 897							
MOC : COMPLIED WITH - SB525C-34-03 REV. 1; ROCKWELL COLLINS RADAR UPGRADE. WAS ACCOMPLISHED AT PRODUCTION.										
SB 525C-34-04	NAVIGATION- ROCKWELL COLLINS RADAR UPGRADE	MTH	05-Nov-2011	A/R				Complete		
	KIWA	RECOMMENDED	HRS 101.6							
			LDG 49							
MOC : COMPLIED WITH										
SB 525C-34-05 R01	NAVIGATION - TRAFFIC SURVEILLANCE SYSTEM (TSS-4100) TCAS II SOFTWARE 7.1 UPGRADE (SUPERSEDED BY SB 525C-34-12)			-						
	CANCELLED									
MOC :										
SB 525C-34-05	NAVIGATION - TRAFFIC SURVEILLANCE SYSTEM (TSS-4100) TCAS II SOFTWARE 7.1 UPGRADE			-						
	DISCRETIONARY									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-34-11	NAVIGATION - STORMSCOPE PROCESSOR MODIFICATION (MOD) LEVEL INSPECTION	KSIF	RECOMMENDED	MTH 22-Mar-2022 HRS 1847.5 LDG 1383		-				N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED AT THIS TIME.										
SB 525C-35-01	OXYGEN MASK WIRING MODIFICATION		DISCRETIONARY			-				
MOC :										
SL CIL-35-02	OXYGEN - TRANSMITTAL OF ZODIAC AEROTECHNICS SERVICE BULLETIN MC10-35-274	KEXX	MANDATORY	MTH 09-Jul-2015 HRS 961.5 LDG 569		-				N/A
MOC : NOT APPLICABLE - CIL-35-02 N/A DUE TO NOT OPERATING UNDER EASA REGULATIONS.										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KEXX	MANDATORY	MTH 20-Jan-2016 DAYS 1081.4 HRS 672 LDG		-				N/A
MOC : NOT APPLICABLE - PREVIOUSLY COMPLIED WITH ON MTR 2508633 DATED 12/08/2015.										
SB 525C-36-02	PNEUMATIC - PRECOOLER AND EXHAUST DUCT SEAL IMPROVEMENTS	GSO	RECOMMENDED	MTH 10-May-2013 HRS 406.5 LDG 173		-				Complete
MOC : COMPLIED WITH										
SB 525C-38-01	EXTERNALLY SERVICEABLE TOILET INSTALLATION		OPTIONAL			-				
MOC :										
SB 525C-52-01	CABIN DOOR HANDLE STOP INSTALLATION	GSO	DISCRETIONARY	MTH 27-May-2016 HRS 1165.7 LDG 735		-				Complete
MOC : COMPLIED WITH - C/W SB 525C-52-01 CABIN DOOR HANDLE STOP INSTALLATION.										
SB 525C-52-02	CABIN DOOR PIN SEQUENCER INSTALLATION		OPTIONAL			-				
MOC :										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	ICT	MANDATORY	MTH 27-Feb-2013 HRS 376.9 LDG 149		-				Complete
MOC : COMPLIED WITH										
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION		INFORMATIONAL			-				
MOC :										
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION	KSIF	MANDATORY	MTH 27-May-2021 HRS 1737.9 LDG 1285		-				Complete
MOC : COMPLIED WITH										
SL 525C-52-01	CABIN ENTRY DOOR INSPECTION	GSO	MANDATORY	MTH 19-Jun-2013 HRS 421.7 LDG 188		-				N/A
MOC : NOT APPLICABLE - CESCOM NOTE:SL525C-52-01 DOES NOT APPLY PER AIRCRAFT SERIAL NUMBER.										
SB 525C-53-03	FUSELAGE - NACA SCOOP COVER INSTALLATION		OPTIONAL			-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525C-53-03	FUSELAGE - TAILCONE SKIN VENTILATION HOLE INSPECTION/INSTALLATION	KGSO	MANDATORY	MTH 26-Jul-2024 HRS 2119.5 LDG 1648		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH SL 525C-53-03 IAW SL 525C-53-03.										
SL 525C-53-04	FUSELAGE - UPPER NOSE SKIN RIVETS INSPECTION/INSTALLATION		MANDATORY			-				
MOC :										
SB 525C-55-01 R01	BULLET FAIRING REPLACEMENT		OPTIONAL			-				
MOC :										
SB 525C-56-01 R01	WINDOWS - WINDSHIELD AND COCKPIT SIDE WINDOW FRAME MODIFICATION		RECOMMENDED			-				
MOC :										
SB 525C-56-01	WINDOWS - WINDSHIELD AND COCKPIT SIDE WINDOW FRAME MODIFICATION		RECOMMENDED	MTH		-				
MOC :										
SL 525C-56-01	WINDSHIELD RETAINER SCREWS TORQUE INSPECTION	KEXX	RECOMMENDED	MTH 10-Dec-2014 HRS 809.3 LDG 461		-				Complete
MOC : COMPLIED WITH										
SL 525C-57-02	FORWARD AND AFT SPAR VISUAL INSPECTION	KGSO	RECOMMENDED	MTH 23-May-2015 HRS 922 LDG 538		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525C-57-02, FORWARD AND AFT SPAR VISUAL INSPECTION PER ACCOMPLISHMENT INSTRUCTIONS. ALL CHECKS GOOD.										
SL 525C-57-03	SINGLE POINT REFUELING TUBES AND WING PROTECTION		OPTIONAL			-				
MOC :										
SL 525C-57-04	HYDRAULIC FITTINGS INSPECTION	KGSO	RECOMMENDED	MTH 23-May-2015 HRS 922 LDG 538		-				Complete
MOC : COMPLIED WITH - COMPLY WITH SL525C-57-04 HYDRAULIC FITTINGS INSPECTION PER ACCOMPLISHMENT INSTRUCTIONS. RESEALED AS REQUIRED. ALL CHECKS GOOD.										
SL WI-70-1006-CN E1	CANCELED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
CANCELLED										
MOC :										
SL WI-70-1006-CN E2	CANCELED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
CANCELLED										
MOC :										
SL WI-70-1006 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-70-1006 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-70-1010-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-70-1010-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-70-1010 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-70-1010 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-70-1011 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-70-1011 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL 525C-71-01	POWER PLANT - TRANSMITTAL OF WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-72-096 ENGINE – OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY – INSTALL			DISCRETIONARY			-			
	MOC :									
SL 525C-71-02 R01	POWER PLANT - SUPPORT CLAMP VERIFICATION			MTH			-			
	MOC :			MANDATORY						
SL 525C-71-02	POWER PLANT - SUPPORT CLAMP VERIFICATION (SUPERSEDED BY SL525C-71-02 R01)	KICT		MANDATORY	MTH 01-Aug-2017 HRS 1376.4 LDG 898		-			Complete
	MOC :									
SL 525C-71-03	POWER PLANT - HYDRAULIC PUMP DRAIN LINE REPLACEMENT			OPTIONAL			-			
	MOC :									
SL 525C-71-04	POWER PLANT - AFT ENGINE MOUNT ATTACH BOLT INSPECTION/REPLACEMENT	KSIF		RECOMMENDED	MTH 27-Feb-2023 HRS 1963.7 LDG 1492		-			Complete
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-71-1319-CN E1	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1319-CN E2	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1319 E1	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1319 E2	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1594 R01 -CN E1	CANCELED - INSPECT THE HP NOZZLE/HP TURBINE TRAILING EDGE AND 1ST LP TURBINE LEADING EDGE WITH A BORESCOPE - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1594 R01 -CN E2	CANCELED - INSPECT THE HP NOZZLE/HP TURBINE TRAILING EDGE AND 1ST LP TURBINE LEADING EDGE WITH A BORESCOPE - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1594 R01 E1	INSPECT THE HP NOZZLE/HP TURBINE TRAILING EDGE AND 1ST LP TURBINE LEADING EDGE WITH A BORESCOPE - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1594 R01 E2	INSPECT THE HP NOZZLE/HP TURBINE TRAILING EDGE AND 1ST LP TURBINE LEADING EDGE WITH A BORESCOPE - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1597-CN E1	CANCELED - POWER PLANT - FAULT ISOLATION - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1597-CN E2	CANCELED - POWER PLANT - FAULT ISOLATION - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1597 E1	POWER PLANT - FAULT ISOLATION - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1597 E2	POWER PLANT - FAULT ISOLATION - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1606 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1606 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION INFORMATIONAL				-			
MOC :								
SB FJ44-72-096 R01 E1	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-096 R02) ICT RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-				Complete
MOC : COMPLIED WITH - SB FJ44-72-096 REV. 1; OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY INSTALL. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB FJ44-72-096 R01 E2	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-096 R02) ICT RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-				Complete
MOC : COMPLIED WITH - SB FJ44-72-096 REV. 1; OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY INSTALL. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB FJ44-72-096 R02 E1	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL ICT RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 882		-				Complete
MOC : COMPLIED WITH - SB FJ44-72-096 REV. 2; OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY INSTALL. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB FJ44-72-096 R02 E2	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL ICT RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 900		-				Complete
MOC : COMPLIED WITH - SB FJ44-72-096 REV. 2; OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY INSTALL. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB FJ44-72-096 R03 E1	OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL RECOMMENDED			-				
MOC :								
SB FJ44-72-096 R03 E2	OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL RECOMMENDED			-				
MOC :								
SB FJ44-72-096 E1	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-096 R01) KIWA RECOMMENDED	MTH 13-May-2012 HRS 289.4 LDG 108		-				Complete
MOC : COMPLIED WITH								
SB FJ44-72-096 E2	ENGINE - OIL BREATHER TUBE ASSEMBLY & FRONT BYPASS DUCT RH BOSS ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-096 R01) KIWA RECOMMENDED	MTH 13-May-2012 HRS 274.2 LDG 111		-				Complete
MOC : COMPLIED WITH								
SB FJ44-72-102 R01 E1	ENGINE - BOLTS - REPLACE ICT RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-				Complete
MOC : COMPLIED WITH - SB FJ44-72-102 REV. 1; REPLACE ENGINE BOLTS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB FJ44-72-102 R01 E2	ENGINE - BOLTS - REPLACE RECOMMENDED	HRS		-			(5000)5000	2826.3
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-102 E1	ENGINE - BOLTS - REPLACE (SUPERSEDED BY FJ44-72-102 R01)	UNK		RECOMMENDED	MTH 12-Jun-2013 HRS 421.7 LDG 173		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-102 E2	ENGINE - BOLTS - REPLACE (SUPERSEDED BY FJ44-72-102 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-114 R01 E1	CASE AND INSERT ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5015.2	2841.5
MOC :										
SB FJ44-72-114 R01 E2	CASE AND INSERT ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	2826.3
MOC :										
SB FJ44-72-114 E1	ENGINE - CASE AND INSERT ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-114 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-114 E2	ENGINE - CASE AND INSERT ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-114 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-117 R01 E1	1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01) REPETITIVE INSPECTION	GSO		MANDATORY	MTH 03-Feb-2015 HRS 843.3 LDG 469		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 1 ENGINE FJ44-72-117 PARA (C)(1) REPETITIVE INSPECTION.										
SB FJ44-72-117 R01 E2	1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01) REPETITIVE INSPECTION	GSO		MANDATORY	MTH 03-Feb-2015 HRS 843.3 LDG 487		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 2 ENGINE FJ44-72-117 PARA (C)(1) REPETITIVE INSPECTION.										
SB FJ44-72-117 R01 E1	REPLACE 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01) THE 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY			MANDATORY	MTH 01-Jun-2011		-			
MOC :										
SB FJ44-72-117 R01 E2	REPLACE 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01) THE 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY			MANDATORY	MTH 01-Jun-2011		-			
MOC :										
SB FJ44-72-117 R04 E1	CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION REPETITIVE INSPECTION			CANCELLED			-			
MOC :										
SB FJ44-72-117 R04 E2	CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION REPETITIVE INSPECTION			CANCELLED			-			
MOC :										
SB FJ44-72-117 R04 E1	REPLACE CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-117 R04 PARA (C)(2) E2	REPLACE CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION 1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY			CANCELLED			-			
MOC :										
SB FJ44-72-117 R04 E1	CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION			CANCELLED			-			
MOC :										
SB FJ44-72-117 R04 E2	CANCELLED - 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY - REPETITIVE INSPECTION			CANCELLED			-			
MOC :										
SB FJ44-72-117 E1	1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01)	KEXX		MANDATORY	MTH 18-Mar-2014 HRS 615.5 LDG 324		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-117 E2	1ST LP TURBINE NOZZLE HOUSING AND HEATSHIELD ASSEMBLY - REPETITIVE INSPECTION (SUPERSEDED BY FJ44-72-117 R01)	KEXX		MANDATORY	MTH 18-Mar-2014 HRS 615.5 LDG 324		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-127 R01 E1	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R02)			MANDATORY			-			
MOC :										
SB FJ44-72-127 R01 E2	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R02)			MANDATORY			-			
MOC :										
SB FJ44-72-127 R02 E1	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R03)			MANDATORY			-			
MOC :										
SB FJ44-72-127 R02 E2	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R03)			MANDATORY			-			
MOC :										
SB FJ44-72-127 R03 E1	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY	GSO		MANDATORY	MTH 11-Aug-2018 HRS 1468.2 LDG 986		-			Complete
MOC : COMPLIED WITH - FJ44-72-127 R03 WAS COMPLIED WITH BY WILLIAMS INTERNATIONAL, CRS# WI5R335J UNDER W/O 1018853. ACCEPTANCE TESTS GOOD.										
SB FJ44-72-127 R03 E2	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY	GSO		MANDATORY	MTH 11-Aug-2018 HRS 1468.2 LDG 1006		-			Complete
MOC : COMPLIED WITH - FJ44-72-127 R03 WAS COMPLIED WITH BY WILLIAMS INTERNATIONAL, CRS# WI5R335J UNDER W/O 1018854. ACCEPTANCE TESTS GOOD.										
SB FJ44-72-127 E1	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R01)			MANDATORY			-			
MOC :										
SB FJ44-72-127 E2	REPLACE 1ST LP HEATSHIELD/NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY FJ44-72-127 R01)			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-136 R01 E1	IP FAIRING SUPPORT RING ASSEMBLY - REWORK OR REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-136 R01 E2	IP FAIRING SUPPORT RING ASSEMBLY - REWORK OR REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-136 R02 E1	IP FAIRING SUPPORT RING ASSEMBLY - REWORK OR REPLACE			RECOMMENDED	MTH		CSI	CSI		
MOC :										
SB FJ44-72-136 R02 E2	IP FAIRING SUPPORT RING ASSEMBLY - REWORK OR REPLACE			RECOMMENDED	MTH		CSI	CSI		
MOC :										
SB FJ44-72-136 E1	IP FAIRING SUPPORT RING ASSEMBLY - REPLACE	UNK		RECOMMENDED	MTH 12-Nov-2020 HRS 1694.9 LDG 1232		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-136 E2	IP FAIRING SUPPORT RING ASSEMBLY - REPLACE	UNK		RECOMMENDED	MTH 12-Nov-2020 HRS 1694.9 LDG 1252		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-137-CNCASE AND INSERT ASSEMBLY - INSPECTION E1				CANCELLED			-			
MOC :										
SB FJ44-72-137-CNCASE AND INSERT ASSEMBLY - INSPECTION E2				CANCELLED			-			
MOC :										
SB FJ44-72-137 E1	ENGINE - CASE AND INSERT ASSEMBLY - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-137 E2	ENGINE - CASE AND INSERT ASSEMBLY - INSPECTION			RECOMMENDED			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description				Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-138-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)											
E1				CANCELLED				-			

MOC :

SB FJ44-72-138-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)	
E2	CANCELLED

MOC :

SB FJ44-72-138	REPLACE - ACCESSORY DRIVE TOWERSHAFT (SUPERSEDED BY SB WISB-72-1037 R01)	
E1	RECOMMENDED	-

MOC :

SB FJ44-72-138	REPLACE - ACCESSORY DRIVE TOWERSHAFT (SUPERSEDED BY SB WISB-72-1037 R01)	
E2	RECOMMENDED	-

MOC :

SB FJ44-72-143	BLEED VALVE SHAFT - REPLACE	RECOMMENDED	-
R03			

E1

MOC :

SB FJ44-72-143	BLEED VALVE SHAFT - REPLACE	RECOMMENDED	-
R03			

E2

MOC :

SL 44-72-325 R06	ENGINE - 1ST LP TURBINE DISK - INSPECTION		-
E1			

MOC :

SL 44-72-325 R06	ENGINE - 1ST LP TURBINE DISK - INSPECTION		-
E2			

MOC :

SL 44-72-325 R07	1ST LP TURBINE DISK - INSPECTION		-
E1			

MOC :

SL 44-72-325 R07	1ST LP TURBINE DISK - INSPECTION		-
E2			

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R02		INFORMATIONAL	

E1

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R02		INFORMATIONAL	

E2

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R03		INFORMATIONAL	

E1

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R03		INFORMATIONAL	

E2

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R07		INFORMATIONAL	

E1

MOC :

PSID WI-05-1000	UNSERVICEABLE PARTS - NOTIFICATION		-
R07		INFORMATIONAL	

E2

MOC :



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS						-			
	MOC :									
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS						-			
	MOC :									
PSID WI-72-1050- CN E1	CANCELED - ENGINE - REAR HOUSING ASSEMBLY - REVISION TO ILLUSTRATED PARTS CATALOG (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE.)			CANCELLED			-			
	MOC :									
PSID WI-72-1050- CN E2	CANCELED - ENGINE - REAR HOUSING ASSEMBLY - REVISION TO ILLUSTRATED PARTS CATALOG (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE.)			CANCELLED			-			
	MOC :									
PSID WI-72-1050 E1	REAR HOUSING ASSEMBLY- REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
PSID WI-72-1050 E2	REAR HOUSING ASSEMBLY- REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
SB WI-72-1001 R01 E1	1.5 BEARING INNER RACE RETAINER - REPLACE			MTH			CSI			
	RECOMMENDED						CSI			
	MOC :									
SB WI-72-1001 R01 E2	1.5 BEARING INNER RACE RETAINER - REPLACE			MTH			CSI			
	RECOMMENDED						CSI			
	MOC :									
SB WI-72-1001 E1	1.5 BEARING INNER RACE RETAINER - REPLACE (SUPERSEDED BY WISB-72-1001 R01)						-			
	RECOMMENDED									
	MOC :									
SB WI-72-1001 E2	1.5 BEARING INNER RACE RETAINER - REPLACE (SUPERSEDED BY WISB-72-1001 R01)						-			
	RECOMMENDED									
	MOC :									
SB WI-72-1023 R01 E1	IP COMPRESSOR ROTOR - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1023 R01 E2	IP COMPRESSOR ROTOR - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1023 R02 E1	IP COMPRESSOR ROTOR - REPLACE	KGSO		RECOMMENDED	MTH 12-Nov-2020 HRS 1694.9 LDG 1232		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB WISB-72-1023 R02 NO. 1 ENGINE - IP COMPRESSOR ROTOR - REPLACE, SERVICE BULLETIN. SERVICE BULLETIN WAS PERFORMED BY WILLIAMS INTERNATIONAL CRS# WI5R335J ON WORK ORDER# 1103202 12/NOV/2020.									
SB WI-72-1023 R02 E2	IP COMPRESSOR ROTOR - REPLACE	KGSO		RECOMMENDED	MTH 12-Nov-2020 HRS 1694.9 LDG 1252		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB WISB-72-1023 R02 NO. 2 ENGINE - IP COMPRESSOR ROTOR - REPLACE, SERVICE BULLETIN. SERVICE BULLETIN WAS PERFORMED BY WILLIAMS INTERNATIONAL CRS# WI5R335J ON WORK ORDER# 1103202 12/NOV/2020.									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1023 R03 IP COMPRESSOR ROTOR - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R03 IP COMPRESSOR ROTOR - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R04 IP COMPRESSOR ROTOR - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R04 IP COMPRESSOR ROTOR - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R05 IP COMPRESSOR ROTOR - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R05 IP COMPRESSOR ROTOR - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R06 IP COMPRESSOR ROTOR - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R06 IP COMPRESSOR ROTOR - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R07 IP COMPRESSOR ROTOR - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 R07 IP COMPRESSOR ROTOR - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1023 E1	REPLACE - IP COMPRESSOR ROTOR (SUPERSEDED BY WISB-72-1023 R01)	RECOMMENDED			-			
	MOC :							
SB WI-72-1023 E2	REPLACE - IP COMPRESSOR ROTOR (SUPERSEDED BY WISB-72-1023 R01)	RECOMMENDED			-			
	MOC :							
SB WI-72-1027 R01 CASE AND INSERT ASSEMBLY - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1027 R01 CASE AND INSERT ASSEMBLY - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1027 R02 CASE AND INSERT ASSEMBLY - REPLACE E1		RECOMMENDED			-			
	MOC :							
SB WI-72-1027 R02 CASE AND INSERT ASSEMBLY - REPLACE E2		RECOMMENDED			-			
	MOC :							
SB WI-72-1027 R03 CASE AND INSERT ASSEMBLY - REPLACE E1		RECOMMENDED			CSI			
	MOC :							
SB WI-72-1027 R03 CASE AND INSERT ASSEMBLY - REPLACE E2		RECOMMENDED			CSI			
	MOC :							
SB WI-72-1027 R04 CASE AND INSERT ASSEMBLY - REPLACE E1		RECOMMENDED	MTH		CSI			
	MOC :				CSI			



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-72-1027 R04 CASE AND INSERT ASSEMBLY - REPLACE E2				RECOMMENDED	MTH		CSI CSI			
	MOC :									
SB WI-72-1027 E1	CASE AND INSERT ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1027 E2	CASE AND INSERT ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1031 R01 BALANCE PISTON - REPLACE E1					MTH		-			
	MOC :									
SB WI-72-1031 R01 BALANCE PISTON - REPLACE E2					MTH		-			
	MOC :									
SB WI-72-1031 R02 BALANCE PISTON - REPLACE E1				RECOMMENDED			CSI			
	MOC :									
SB WI-72-1031 R02 BALANCE PISTON - REPLACE E2				RECOMMENDED			CSI			
	MOC :									
SB WI-72-1031 E1	BALANCE PISTON - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1031 E2	BALANCE PISTON - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1				RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2				RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1					MTH		-			
	MOC :									
SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2					MTH		-			
	MOC :									
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1							-			
	MOC :									
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2							-			
	MOC :									
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1							-			
	MOC :									
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2							-			
	MOC :									
SB WI-72-1037 R05 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1				RECOMMENDED			CSI			
	MOC :									
SB WI-72-1037 R05 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2				RECOMMENDED			CSI			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			-			
	MOC :									
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			-			
	MOC :									
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1					MTH		-			
	MOC :									
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2					MTH		-			
	MOC :									
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1					MTH		-			
	MOC :									
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2					MTH		-			
	MOC :									
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			MPI			
	MOC :									
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			MPI			
	MOC :									
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1041 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1053 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1053 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1055 E1	NO. 1 CARBON SEAL - REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1055 E2	NO. 1 CARBON SEAL - REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1056 E1	1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1056 E2	1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1057 E1	LP TURBINE MODULE - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1057 E2	LP TURBINE MODULE - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1060 E1	GEARBOX ASSEMBLY - REPLACE			RECOMMENDED	MTH		CSI CSI			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-72-1060 E2	GEARBOX ASSEMBLY - REPLACE			RECOMMENDED	MTH		CSI CSI			
	MOC :									
SB WI-72-1061 R01 E1	1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED	MTH		MPI MPI			
	MOC :									
SB WI-72-1061 R01 E2	1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED	MTH		MPI MPI			
	MOC :									
SB WI-72-1061 E1	ENGINE - 1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1061 E2	ENGINE - 1ST LP TURBINE NOZZLE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1155 E1	NO. 1 CARBON SEAL - REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1155 E2	NO. 1 CARBON SEAL - REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1193-CN E1	CANCELED - ENGINE - REPAIR THE MIXER CASE LOBES - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1193-CN E2	CANCELED - ENGINE - REPAIR THE MIXER CASE LOBES - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1193 E1	REPAIR THE MIXER CASE LOBES - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1193 E2	REPAIR THE MIXER CASE LOBES - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WISL-72-1246-CN E1	CANCELED - ENGINE - MIXER CASE ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SB WISL-72-1246-CN E2	CANCELED - ENGINE - MIXER CASE ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1246 E1	MIXER CASE ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1246 E2	MIXER CASE ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1332-CN E1	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
	MOC :									
SL WI-72-1332-CN E2	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
	MOC :									
SL WI-72-1364-CN E1	CANCELED - REAR HOUSING ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1364-CN E2	CANCELED - REAR HOUSING ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1364 E1	REAR HOUSING ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1364 E2	REAR HOUSING ASSEMBLY - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB 525C-73-01	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) FIELD REPLACEMENT			OPTIONAL			-			
	MOC :									
SL 525C-73-01 R01	ENGINE FUEL AND CONTROL - MOTIVE FLOW FUEL LINE INSPECTION	KSIF	MANDATORY	MTH 27-Feb-2023 HRS 1963.7 LDG 1492			-			Complete
	MOC :			COMPLIED WITH - PROPER CLEARANCE AT THIS TIME.						
SL 525C-73-01	ENGINE FUEL AND CONTROL - MOTIVE FLOW FUEL LINE INSPECTION		RECOMMENDED	MTH			-			
	MOC :									
SB FJ44-73-045 R02 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE	KEXX	MANDATORY	MTH 14-Apr-2016 HRS 1138.2 LDG 710			-			Complete
	MOC :			COMPLIED WITH - COMPLIED WITH FJ44-73-045 R2. ALL WORK DONE I.A.W. WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-045 R2						
SB FJ44-73-045 R02 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE	KEXX	MANDATORY	MTH 14-Apr-2016 HRS 1138.2 LDG 710			-			Complete
	MOC :			COMPLIED WITH						



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-047 R01 E2	ENGINE FUEL AND CONTROL - FUEL MANIFOLD INLET FITTING - INSPECTION			MANDATORY	HRS		DUE DUE		(2500)2500	326.3
MOC :										
SB FJ44-73-047 E1	ENGINE FUEL AND CONTROL - FUEL MANIFOLD INLET FITTING - INSPECTION (SUPERSEDED BY FJ44-73-047 R01)	UNK		MANDATORY	MTH 12-Jun-2013 HRS 421.7 LDG 173		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-052 R02 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY FJ44-73-052 R03)	KEXX		MANDATORY	MTH 14-Apr-2016 HRS 1138.2 LDG 710		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-052 R03 E1	OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY FJ44-73-052 R04)	KEXX		MANDATORY	MTH 14-Apr-2016 HRS 1138.2 LDG 695		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN FJ44-73-052 R 3. ALL WORK DONE I.A.W. WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-73-052 R3										
SB FJ44-73-052 R03 E2	OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY FJ44-73-052 R04)	ICT		MANDATORY	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-73-052 REV. 3; OIL COOLER TO FDU FUEL TUBE ASSEMBLY & ATTACHING HARDWARE REPLACEMENT. IS C/W DUE TO REV. 2 WAS ACCOMPLISHED.										
SB FJ44-73-052 R04 E1	CANCELLED - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY SB WISB-73-1006 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-052 R04 E2	CANCELLED - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY SB WISB-73-1006 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-053 R04 E1	CANCELLED - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY SB WISB-73-1006 R06)			MANDATORY			-			
MOC :										
SB FJ44-73-053 R04 E2	CANCELLED - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE ASSEMBLY AND ATTACHING HARDWARE - REPLACE (SUPERSEDED BY SB WISB-73-1006 R06)			MANDATORY			-			
MOC :										
PSID WI-73-1008 R01 E1	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										
PSID WI-73-1008 R01 E2	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										
PSID WI-73-1012 E1	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										
PSID WI-73-1012 E2	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1005 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1005 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			MANDATORY			-			
	MOC :									
SB WI-73-1005 R03 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1005 R03 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1005 R04 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		(5000)5015.2	2841.5
	MOC :									
SB WI-73-1005 R04 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		(5000)5000	2826.3
	MOC :									
SB WI-73-1005 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1005 R01)			MANDATORY			-			
	MOC :									
SB WI-73-1005 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1005 R01)			MANDATORY			-			
	MOC :									
SB WI-73-1006 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES AND ATTACHING HARDWARE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1006 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES AND ATTACHING HARDWARE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1006 R06 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES AND ATTACHING HARDWARE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1006 R06 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES AND ATTACHING HARDWARE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1007 R01 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
	MOC :									
SB WI-73-1007 R01 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
	MOC :									
SB WI-73-1019-CN E1	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)			SUPERSEDED			-			
	MOC :									
SB WI-73-1019-CN E2	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)			SUPERSEDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1019 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)									
						-				
	MOC :									
SB WI-73-1019 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)									
						-				
	MOC :									
SB WI-73-1022 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
				NOT APPLICABLE		-				
	MOC :									
SB WI-73-1022 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
				NOT APPLICABLE		-				
	MOC :									
SB WI-73-1023 R01 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED		-				
	MOC :									
SB WI-73-1023 R01 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED		-				
	MOC :									
SB WI-73-1023 R02 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED		-				
	MOC :									
SB WI-73-1023 R02 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED		-				
	MOC :									
SB WI-73-1023 R03 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
					MTH	-				
	MOC :									
SB WI-73-1023 R03 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
					MTH	-				
	MOC :									
SB WI-73-1023 R04 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
					MTH	-				
	MOC :									
SB WI-73-1023 R04 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
					MTH	-				
	MOC :									
SB WI-73-1023 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED	MTH	-				
	MOC :									
SB WI-73-1023 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
				RECOMMENDED	MTH	-				
	MOC :									
SB WI-73-1031 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
						-				
	MOC :									
SB WI-73-1031 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
						-				
	MOC :									
SB WI-73-1032 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01									
						-				
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1032 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01									
	MOC :									
SB WI-73-1033 R01 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED MTH									
	MOC :									
SB WI-73-1033 R01 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED MTH									
	MOC :									
SB WI-73-1033 R02 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED									
	MOC :									
SB WI-73-1033 R02 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED									
	MOC :									
SB WI-73-1033 R03 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED									
	MOC :									
SB WI-73-1033 R03 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED									
	MOC :									
SB WI-73-1033 R04 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED HRS 630 (2691.5)2706.7 533									
	MOC :									
SB WI-73-1033 R04 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02									
	RECOMMENDED HRS 630 (2706.7)2706.7 533									
	MOC :									
SB WI-73-1042 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01									
	MOC :									
SB WI-73-1042 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01									
	MOC :									
SB WI-73-1043 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MOC :									
SB WI-73-1043 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MOC :									
SL WI-73-1026 E1	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-73-1026 E2	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-73-1037 E1	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-73-1037 E2	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-73-1073 E1	ENGINE FUEL AND CONTROL - FUEL DRAIN TUBE SEAL - REPLACE									
	MTH									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-73-1073 E2	ENGINE FUEL AND CONTROL - FUEL DRAIN TUBE SEAL - REPLACE			MTH			-			
MOC :										
SL WI-73-1084 E1	ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-73-1084 E2	ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SB WI-75-1001 E1	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1001 E2	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1001 E1	R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		CSI CSI CSI		(5000)5015.2	2841.5
MOC :										
SB WI-75-1001 E2	R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		CSI CSI CSI		(5000)5000	2826.3
MOC :										
SB WI-75-1001 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1001 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E1	R01 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E2	R01 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E1	R02 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E2	R02 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E1	R03 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E2	R03 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										
SB WI-75-1006 E1	R04 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED	MTH		-			
MOC :										
SB WI-75-1006 E2	R04 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED	MTH		-			
MOC :										
SB WI-75-1006 E1	R05 AIR - ACCELERATION BLEED LEVER - ADJUST			RECOMMENDED			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-75-1006 R05 AIR - ACCELERATION BLEED LEVER - ADJUST E2				RECOMMENDED			-			
MOC :										
SB WI-75-1006 R06 AIR - ACCELERATION BLEED LEVER - ADJUST E1		KBCB			MTH 02-Oct-2019 HRS 1591.6 LDG 1142		-			Complete
MOC : COMPLIED WITH										
SB WI-75-1006 R06 AIR - ACCELERATION BLEED LEVER - ADJUST E2		KBCB			MTH 02-Oct-2019 HRS 1591.6 LDG 1142		-			Complete
MOC : COMPLIED WITH										
SB WI-75-1006 R07 AIR - ACCELERATION BLEED LEVER - ADJUST E1					MTH		-			
MOC : - COMPLIED WITH IN REV 6										
SB WI-75-1006 R07 AIR - ACCELERATION BLEED LEVER - ADJUST E2					MTH		-			
MOC : - COMPLIED WITH IN REV 6										
SB WI-75-1006 R08 AIR - ACCELERATION BLEED LEVER - ADJUST E1				RECOMMENDED			-			
MOC :										
SB WI-75-1006 R08 AIR - ACCELERATION BLEED LEVER - ADJUST E2				RECOMMENDED			-			
MOC :										
SB WI-75-1006 R09 AIR - ACCELERATION BLEED LEVER - ADJUST E1				RECOMMENDED			-			
MOC :										
SB WI-75-1006 R09 AIR - ACCELERATION BLEED LEVER - ADJUST E2				RECOMMENDED			-			
MOC :										
SB WI-75-1006 AIR - ACCELERATION BLEED LEVER - ADJUST E1							-			
MOC :										
SB WI-75-1006 AIR - ACCELERATION BLEED LEVER - ADJUST E2							-			
MOC :										
SB 525C-76-01	ENGINE CONTROLS - UPDATED FJ44-4A FULL AUTHORITY ENGINE CONTROL (FADEC) FIELD REPLACEMENT OPTIONAL						-			
MOC :										
SB 525C-76-02	ENGINE CONTROLS - TRANSMITTAL OF WILLIAMS INTERNATIONAL SERVICE BULLETIN WISB-73-1033 REVISION 1, ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF APPLICATION SOFTWARE CP357.06.02 RECOMMENDED MTH						-			
MOC :										
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL									
MOC :										
SB FJ44-77-012 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R02)	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 1; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R02)	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 1; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 R02 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R03)	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 2; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 R02 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R03)	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 2; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 R03 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 3; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 R03 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE	ICT		RECOMMENDED	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-			Complete
MOC : COMPLIED WITH - SB FJ44-77-012 REV. 3; RE-ROUTE FADEC ENGINE HARNESS ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB FJ44-77-012 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R01)	GSO		RECOMMENDED	MTH 19-Jun-2013 HRS 421.7 LDG 173		-			Complete
MOC : COMPLIED WITH										
SB FJ44-77-012 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - RE-ROUTE (SUPERSEDED BY FJ44-77-012 R01)	GSO		RECOMMENDED	MTH 19-Jun-2013 HRS 421.7 LDG 191		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-013 R01 E1	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R01 E2	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R02 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED MTH			-			
MOC :										
SB FJ44-77-013 R02 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED MTH			-			
MOC :										
SB FJ44-77-013 R03 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R03 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R04 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R04 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R05 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R05 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R06 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R07 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 R09 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED MTH			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-77-013 R09 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED MTH			-			
MOC :										
SB FJ44-77-013 R10 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK						-			
MOC :										
SB FJ44-77-013 R10 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK						-			
MOC :										
SB FJ44-77-013 R11 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED MTH			MPI MPI			
MOC :										
SB FJ44-77-013 R11 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK			RECOMMENDED MTH			MPI MPI			
MOC :										
SB FJ44-77-013 E1	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-77-013 E2	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)			RECOMMENDED			-			
MOC :										
SB 525C-79-01 R01 E1	OIL - ENGINE OIL PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL			-			
MOC :										
SB 525C-79-01 E1	OIL - ENGINE OIL PRESSURE TRANSDUCER REPLACEMENT (SUPERSEDED BY 525C-79-01 R01)			OPTIONAL			-			
MOC :										
SB FJ44-79-011 R01 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)	UNK		MANDATORY	MTH 12-Jun-2013 HRS 421.7 LDG 188		-			Complete
MOC : COMPLIED WITH										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		MPI MPI MPI		(5000)5000	2826.3
MOC :										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5015.2	2841.5
MOC :										
SB FJ44-79-012 R01 E2	OIL - LUBE OIL COOLER - REWORK OR REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	2826.3
MOC :										
SB FJ44-79-012 E1	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-012 E2	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R01 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 R01 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 R02 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R02 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R03 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R03 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		-		(2500)2515.2	341.5
MOC :										
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		-		(2500)2500	326.3
MOC :										
SB FJ44-79-013 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-016 R05 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R05 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R06 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R06 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R07 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R07 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
	MOC :									
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
	MOC :									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
	MOC :									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2014-17-02	EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC	KEXX		MANDATORY	MTH 11-Sep-2014 HRS 730 LDG 408		-			N/A
MOC : NOT APPLICABLE - AD 2014-17-02 N/A BY EQUIPMENT INSTALLED . ARTEX 406 ELT CURRENTLY INSTALLED.										
FAA 2011-21-51-E	EMERGENCY AD - REPLACE THE LITHIUM-ION MAIN AIRCRAFT BATTERY, CESSNA P/N 9914788-1	KIWA		MANDATORY	DAYS 07-Feb-2012 HRS 186 LDG 78		-			N/A
MOC : NOT APPLICABLE - THE INTENT OF REPLACEMENT OF THE LITHIUM-ION MAIN AIRCRAFT BATTERY, CESSNA P/N 9914788-1, AD 2011-21-51-E WAS PERFORMED BY COMPLETION OF SB525C-24-05 ON MTR#1882620 DATED OCTOBER 01 2011. IAW AD 2011-21-51-E INSTRUCTIONS.										
FAA 2011-21-51	REPLACE THE LITHIUM-ION MAIN AIRCRAFT BATTERY, CESSNA P/N 9914788-1	KIWA		MANDATORY	DAYS 07-Feb-2012 HRS 186 LDG 78		-			Complete
MOC : COMPLIED WITH - THE INTENT OF REPLACEMENT OF THE LITHIUM-ION MAIN AIRCRAFT BATTERY, CESSNA P/N 9914788-1, AD 2011-21-51 WAS PERFORMED BY COMPLETION OF SB525C-24-05 ON MTR#1882620 DATED OCTOBER 01 2011. IAW AD 2011-21-51 INSTRUCTIONS.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KEXX		MANDATORY	MTH 13-Jul-2015 HRS 964.3 LDG 573		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER INSTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KEXX		MANDATORY	MTH 13-Jul-2015 HRS 964.3 LDG 573		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER INSTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KEXX		MANDATORY	MTH 13-Jul-2015 HRS 964.3 LDG 573		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER INSTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2015-10-02	EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KEXX		MANDATORY	MTH 13-Jul-2015 HRS 964.3 LDG 573		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER INSTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KBCB			MTH 27-Nov-2018 HRS 1497.5 LDG 1022		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KBCB		MANDATORY	MTH 27-Nov-2018 HRS 1497.5 LDG 1022		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS									
	KBCB	MANDATORY	MTH 27-Nov-2018			-				N/A
			HRS 1497.5							
			LDG 1022							
	MOC : NOT APPLICABLE									
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE									
		MANDATORY	MTH 27-Apr-2021			-				N/A
			HRS 1737.9							
			LDG 1285							
	MOC : NOT APPLICABLE									
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE									
		MANDATORY	MTH 27-Apr-2021			-				N/A
			HRS 1737.9							
			LDG 1285							
	MOC : NOT APPLICABLE									
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER									
		MANDATORY	MTH 27-Apr-2021			-				N/A
			HRS 1737.9							
			LDG 1285							
	MOC : NOT APPLICABLE									
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT									
	KSIF	MANDATORY	MTH 27-Apr-2021			-				N/A
			HRS 1737.9							
			LDG 1285							
	MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED. AMSAFE BUCKLES INSTALLED AT THIS TIME.									
FAA 2021-23-12	INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS									
	KSIF	MANDATORY	MTH 15-Dec-2021			-				Complete
			HRS 1806.4							
			LDG 1350							
	MOC : COMPLIED WITH - REVISED THE LIMITATIONS SECTION OF AFM AS REQUIRED.									
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)									
	KBCB	MANDATORY	MTH 15-Jun-2023			-				Complete
			HRS 1994.3							
			LDG 1512							
	MOC : COMPLIED WITH - REVISED THE LIMITATIONS SECTION OF AFM AS NEEDED.									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)									
	KBCB	MANDATORY	MTH 15-Jun-2023			-				Complete
			HRS 1994.3							
			LDG 1512							
	MOC : COMPLIED WITH - REVISED THE LIMITATIONS SECTION OF AFM AS NEEDED.									
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION									
	KBCB	MANDATORY	MTH 15-Jun-2023			-				Complete
			HRS 1994.3							
			LDG 1512							
	MOC : COMPLIED WITH - REVISED THE LIMITATIONS SECTION OF AFM AS NEEDED.									



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
 Aircraft Model: **525C - CJ4**
 Aircraft Serial: **525C-0039**
 Unit: Reg No: **N741MM**
 Airworthiness: **01-Jun-2011**
 Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KEXX	MANDATORY	MTH 03-Oct-2014 HRS 747.4 LDG 425		-				N/A
MOC : NOT APPLICABLE - N/A BY PART NUMBER INSTALLED										
FAA 2015-10-51-E	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KEXX	MANDATORY	MTH 17-Jun-2015 HRS 937.4 LDG 549		-				N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED.										
FAA 2015-10-51	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	ICT	MANDATORY	MTH 08-Jun-2017 HRS 1375.2 LDG 897		-				N/A
MOC : NOT APPLICABLE - AD2015-10-51; AVIDYNE FLIGHT DISPLAY INSPECTION. DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED. EFF. DATE IS 7-1-15.										
FAA 2017-22-14	NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS	KBCB	MANDATORY	MTH 29-Nov-2018 HRS 1497.5 LDG 1022		-				Complete
MOC : COMPLIED WITH - P/C/W AT UNIT OVERHAUL DATED 06/29/2017 BY ROCKWELL COLLINS UNDER FORM TRACKING NUMBER 105381259 BY INSTALLATION OF RCPN: 810-0052-102. NO FURTHER ACTION IS REQUIRED.										
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	KSIF	MANDATORY	MTH 01-Jan-2021 HRS 1713.1 LDG 1261		-				N/A
MOC : NOT APPLICABLE - C/W AD2020-10-05 AMENDMENT 39-21123, EFFECTIVE JUNE 24, 2020 PER PARAGRAPHS (1), (2) (D), (E) AND (F) AND NO "TEMP COMP" LINE FOUND PER ROCKWELL COLLINS SERVICE LETTER CSU-XX00-18-1. NO FURTHER ACTION IS REQUIRED.										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KEXX	MANDATORY	MTH 08-Jun-2015 HRS 937.4 LDG 549		-				N/A
MOC : NOT APPLICABLE										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KEXX	MANDATORY	MTH 08-Jun-2015 HRS 937.4 LDG 549		-				N/A
MOC : NOT APPLICABLE										
FAA 2015-08-07	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KEXX	MANDATORY	MTH 08-Jun-2015 HRS 937.4 LDG 549		-				N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KEXX		MANDATORY	MTH 08-Dec-2015 DAYS 1067.3 HRS 659 LDG		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KEXX		MANDATORY	MTH 08-Dec-2015 DAYS 1067.3 HRS 659 LDG		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KEXX		MANDATORY	MTH 08-Dec-2015 DAYS 1067.3 HRS 659 LDG		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KEXX		MANDATORY	MTH 08-Dec-2015 DAYS 1067.3 HRS 659 LDG		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KEXX		MANDATORY	MTH 08-Dec-2015 HRS 1067.3 LDG 659		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2015-23-09	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KEXX		MANDATORY	MTH 08-Dec-2015 HRS 1067.3 LDG 659		-			N/A
MOC : NOT APPLICABLE - N/A FOR P/N AND S/N INSTALLED IN THIS AIRCRAFT, PER ZODIAC S/B MCF-SBU-35-001.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KEXX		MANDATORY	MTH 11-Jul-2016 HRS 1196 LDG 760		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KEXX		MANDATORY	MTH 11-Jul-2016 HRS 1196 LDG 760		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KEXX		MANDATORY	MTH 11-Jul-2016 HRS 1196 LDG 760		-			N/A

MOC : NOT APPLICABLE



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12									
		KEXX		MANDATORY	MTH 11-Jul-2016 HRS 1196 LDG 760		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE, NO PBE INSTALLED IN THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
		KMTV		MANDATORY	MTH 26-Apr-2018 HRS 1434.1 LDG 959		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED AT THIS TIME.										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
		KMTV		MANDATORY	MTH 26-Apr-2018 HRS 1434.1 LDG 959		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED AT THIS TIME.										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.									
		KMTV		MANDATORY	MTH 26-Apr-2018 HRS 1434.1 LDG 959		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED AT THIS TIME.										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
		KMTV		MANDATORY	MTH 26-Apr-2018 HRS 1434.1 LDG 959		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY EQUIPMENT INSTALLED AT THIS TIME.										
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS									
		KSIF		MANDATORY	MTH 22-Mar-2022 HRS 1847.5 LDG 1383		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY DATE CODES OF HARNESSSES INSTALLED ON BOTH CREW MASKS.										
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD									
		KSIF		MANDATORY	MTH 22-Mar-2022 HRS 1847.5 LDG 1383		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY DATE CODES OF HARNESSSES INSTALLED ON BOTH CREW MASKS.										
FAA 2018-21-14	OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT									
		KSIF		MANDATORY	MTH 22-Mar-2022 HRS 1847.5 LDG 1383		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY BY DATE CODES OF HARNESSSES INSTALLED ON BOTH CREW MASKS.										



CESCOM 10 - Aircraft Status Report

Owner: **SHELOR INVESTMENTS LLC**
Aircraft Model: **525C - CJ4**
Aircraft Serial: **525C-0039**
Unit: Reg No: **N741MM**
Airworthiness: **01-Jun-2011**
Print Date: **24-Jan-2025 8:47AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2173.7	1701	06-Jan-2025	.38
ENG 1	2158.5	1701	06-Jan-2025	.38
ENG 2	2173.7	1698	06-Jan-2025	.38

Factory Installed

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
34FO632T	HF-9000 HIGH FREQUENCY COMMUNICATION TRANSCIVER FACTORY OPTION									
				632T FO	MTH 01-Jun-2011		O/C	0		
34FO675	COMMUNICATION MANAGEMENT FUNCT UNIT FACTORY OPTION									
				675Y FO	MTH 01-Jun-2011		O/C	0		
34FO686	SECOND FMS-3200 COLLINS FACTORY OPTION									
				686U FO	MTH 01-Jun-2011		O/C	0		