



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Maintenance Inspections

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                   | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains  |
|--------------------------------|-----------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------|----------------|----------------|----------------|----------------------------|---------------------|
| PPPP1                          | PAINT AIRCRAFT                                                                          |      |         |                               | MTH 06-Feb-2025                            |                | O/C            |                |                            |                     |
| 5-12-01                        | INSPECTION DOCUMENT 01                                                                  |      |         |                               | MTH 06-Feb-2025<br>HRS 0                   |                | 300            |                | 300                        | 232.2               |
| 5-12-02                        | INSPECTION DOCUMENT 02                                                                  |      |         |                               | MTH 06-Feb-2025                            |                | 12             |                | 28-Feb-2026                | 5 m 19 d            |
| B262201<br>CABIN               | FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 2            |      |         | C352TS<br>I-48488920          | MTH 06-Feb-2025                            |                | 12             |                | 28-Feb-2026                | 5 m 19 d            |
| Weight Check Date: 06-Feb-2025 |                                                                                         |      |         |                               |                                            |                |                |                |                            |                     |
| 5-12-03                        | INSPECTION DOCUMENT 03                                                                  |      |         |                               | MTH 06-Feb-2025<br>HRS 0<br>LDG 0<br>ACH 0 |                | 24             |                |                            |                     |
| 5-12-06                        | INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)              |      |         |                               | MTH 06-Feb-2025                            |                | 72             |                |                            |                     |
| A262201<br>CABIN               | DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 06                 |      |         | C352TS<br>I-48488920          | MTH 10-Jan-2025                            |                | 72             |                | 31-Jan-2031                | 64 m 22 d           |
| 5-12-08                        | INSPECTION DOCUMENT 08                                                                  |      |         |                               | MTH 06-Feb-2025<br>HRS 0                   |                | 24<br>300      |                | 28-Feb-2027<br>300         | 17 m 19 d<br>232.2  |
| 5-12-09                        | INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)              |      |         |                               | MTH 06-Feb-2025<br>HRS 0                   |                | 12<br>600      |                |                            |                     |
| 5-12-10                        | INSPECTION DOCUMENT 10                                                                  |      |         |                               | MTH 06-Feb-2025<br>HRS 0                   |                | 36<br>1200     |                | 29-Feb-2028<br>1200        | 29 m 20 d<br>1132.2 |
| 5-12-11                        | INSPECTION DOCUMENT 11                                                                  |      |         |                               | MTH 06-Feb-2025<br>HRS 0                   |                | 72<br>2400     |                | 28-Feb-2031<br>2400        | 65 m 19 d<br>2332.2 |
| 5-12-12                        | INSPECTION DOCUMENT 12 (14 CFR 91.207)                                                  |      |         |                               | MTH 06-Feb-2025                            |                | 12             |                | 28-Feb-2026                | 5 m 19 d            |
| A256201                        | DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER ARTEX (ELT): INSPECTION DOCUMENT 12   |      |         | 453-5060<br>25209132          | MTH 06-Feb-2025                            |                | 12             |                | 28-Feb-2026                | 5 m 19 d            |
| B256203                        | OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR TRANSMITTER: INSPECTION DOCUMENT 12    |      |         |                               | MTH 06-Feb-2025                            |                | 12             |                | 28-Feb-2026                | 5 m 19 d            |
| 5-12-13                        | INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)              |      |         |                               | MTH 06-Feb-2025                            |                | 24             |                |                            |                     |
| B341101<br>LEFT                | FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13                            |      |         |                               | MTH 06-Feb-2025                            |                | 24             |                | 28-Feb-2027                | 17 m 19 d           |
| B341101<br>NO. 1               | CALIBRATION TEST -- : INSPECTION DOCUMENT 13                                            |      |         | 011-02337-01<br>1U6105031     | MTH 06-Feb-2025                            |                | 24             |                | 28-Feb-2027                | 17 m 19 d           |
| Calibration Date: 06-Feb-2025  |                                                                                         |      |         |                               |                                            |                |                |                |                            |                     |
| B341101<br>NO. 2               | CALIBRATION TEST -- : INSPECTION DOCUMENT 13                                            |      |         | 011-02337-01<br>1U6105120     | MTH 06-Feb-2025                            |                | 24             |                | 28-Feb-2027                | 17 m 19 d           |
| Calibration Date: 06-Feb-2025  |                                                                                         |      |         |                               |                                            |                |                |                |                            |                     |
| B341101<br>RIGHT               | FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13                            |      |         |                               | MTH 06-Feb-2025                            |                | 24             |                | 28-Feb-2027                | 17 m 19 d           |
| B341101                        | CALIBRATION TEST ELECTRONIC STANDBY INDICATOR (4-IN-1) DISPLAY : INSPECTION DOCUMENT 13 |      |         | PN<br>SN-UNKNOWN              | MTH 06-Feb-2025                            |                | 24             |                | 28-Feb-2027                | 17 m 19 d           |
| Calibration Date: 06-Feb-2025  |                                                                                         |      |         |                               |                                            |                |                |                |                            |                     |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Maintenance Inspections

| Item Code<br>Position         | Description<br>Drawing # / Task #                                                             | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------|-----------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| B345701<br>LEFT               | CALIBRATION CHECK GTX 3000 MODE S TCAS II TRANSPONDER ATC SYSTEM: INSPECTION DOCUMENT 13      |      |         | 011-01997-00<br>20S014877     | MTH 06-Feb-2025          |                | 24             |                | 28-Feb-2027                | 17 m 19 d          |
| Calibration Date: 06-Feb-2025 |                                                                                               |      |         |                               |                          |                |                |                |                            |                    |
| B345701<br>RIGHT              | CALIBRATION CHECK GTX 3000 MODE S TCAS II TRANSPONDER ATC SYSTEM: INSPECTION DOCUMENT 13      |      |         | 011-01997-00<br>20S014904     | MTH 06-Feb-2025          |                | 24             |                | 28-Feb-2027                | 17 m 19 d          |
| Calibration Date: 06-Feb-2025 |                                                                                               |      |         |                               |                          |                |                |                |                            |                    |
| 5-12-14                       | INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                    |      |         |                               | MTH 06-Feb-2025          |                | T/C            |                |                            |                    |
| A324201<br>LEFT               | SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14                  |      |         | 3-1527-2<br>2079              | MTH 06-Feb-2025          |                | T/C            |                |                            |                    |
| A324201<br>NOSE               | SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI): INSPECTION DOCUMENT 14                  |      |         | 3-1418<br>D0604               | MTH 06-Feb-2025          |                | T/C            |                |                            |                    |
| A324201<br>RIGHT              | SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14                  |      |         | 3-1527-2<br>2013              | MTH 06-Feb-2025          |                | T/C            |                |                            |                    |
| 5-12-17                       | INSPECTION DOCUMENT 17 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                    |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 12<br>100      |                |                            |                    |
| B243601                       | FUNCTIONAL CHECK MAIN BATTERY NICKEL-CADMIUM BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 17 |      |         | 30978-002<br>12401627         | MTH 06-Feb-2025<br>HRS 0 |                | 12<br>100      |                | 28-Feb-2026<br>100         | 5 m 19 d<br>32.2   |
| 5-12-21                       | INSPECTION DOCUMENT 21                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 24<br>600      |                | 28-Feb-2027<br>600         | 17 m 19 d<br>532.2 |
| 5-12-29                       | INSPECTION DOCUMENT 29                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 7200           |                | 7200                       | 7132.2             |
| A530003                       | ZONAL INSPECTION COCKPIT AND CABIN ABOVE AND BELOW FLOORBOARD: INSPECTION DOCUMENT 29         |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 7200           |                | 7200                       | 7132.2             |
| 5-12-33                       | INSPECTION DOCUMENT 33                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 12<br>300      |                | 28-Feb-2026<br>300         | 5 m 19 d<br>232.2  |
| 5-12-36                       | INSPECTION DOCUMENT 36                                                                        |      |         |                               | MTH 06-Feb-2025          |                | 6              |                | 31-Aug-2025                | -9 d               |
| Over Due                      |                                                                                               |      |         |                               |                          |                |                |                |                            |                    |
| 5-12-37                       | INSPECTION DOCUMENT 37                                                                        |      |         |                               | MTH 06-Feb-2025<br>ACH 0 |                | 500            |                | 500                        | 500                |
| 5-12-MA                       | INSPECTION DOCUMENT MA                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 300            |                | 300                        | 232.2              |
| 5-12-MD                       | INSPECTION DOCUMENT MD                                                                        |      |         |                               | MTH 06-Feb-2025<br>LDG 0 |                | 5000           |                | 5000                       | 4941               |
| 5-12-MF                       | INSPECTION DOCUMENT MF                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 6000           |                | 6000                       | 5932.2             |
| 5-12-MG                       | INSPECTION DOCUMENT MG                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 6000           |                | 6000                       | 5932.2             |
| 5-12-MH                       | INSPECTION DOCUMENT MH                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 6000           |                | 6000                       | 5932.2             |
| 5-12-MI                       | INSPECTION DOCUMENT MI                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 7200           |                | 7200                       | 7132.2             |
| 5-12-MJ                       | INSPECTION DOCUMENT MJ                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 7200           |                | 7200                       | 7132.2             |
| 5-12-MK                       | INSPECTION DOCUMENT MK                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 7900           |                | 7900                       | 7832.2             |
| 5-12-MM                       | INSPECTION DOCUMENT MM                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 12000          |                | 12000                      | 11932.2            |
| 5-12-MN                       | INSPECTION DOCUMENT MN                                                                        |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 12000          |                | 12000                      | 11932.2            |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Maintenance Inspections

| Item Code<br>Position     | Description<br>Drawing # / Task # | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------|-----------------------------------|------|---------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 5-12-MO                   | INSPECTION DOCUMENT MO            |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 15200          |                | 15200                      | 15132.2            |
| 5-12-MP                   | INSPECTION DOCUMENT MP            |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 12<br>250      |                | 28-Feb-2026<br>250         | 5 m 19 d<br>182.2  |
| 5-12-MQ                   | INSPECTION DOCUMENT MQ            |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 14000          |                | 14000                      | 13932.2            |
| 05-50-00-870-803-01<br>E1 | POLISH FAN ROTOR                  |      |                                       | MTH 06-Feb-2025          |                | A/R            |                |                            |                    |
| 05-50-00-870-803-01<br>E2 | POLISH FAN ROTOR                  |      |                                       | MTH 06-Feb-2025          |                | A/R            |                |                            |                    |
| 052001<br>E1              | FJ44 CHECK 1                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 300            |                | (300)300                   | 232.2              |
| 052001<br>E2              | FJ44 CHECK 1                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 300            |                | (300)300                   | 232.2              |
| 052002<br>E1              | FJ44 CHECK 2                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 600            |                | (600)600                   | 532.2              |
| 052002<br>E2              | FJ44 CHECK 2                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 600            |                | (600)600                   | 532.2              |
| 052003<br>E1              | FJ44 CHECK 3                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 1750           |                | (1750)1750                 | 1682.2             |
| 052003<br>E2              | FJ44 CHECK 3                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 1750           |                | (1750)1750                 | 1682.2             |
| 052004<br>E1              | FJ44 CHECK 4                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 3500           |                | (3500)3500                 | 3432.2             |
| 052004<br>E2              | FJ44 CHECK 4                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 3500           |                | (3500)3500                 | 3432.2             |
| 052005<br>E1              | FJ44 CHECK 5                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 5250           |                | (5250)5250                 | 5182.2             |
| 052005<br>E2              | FJ44 CHECK 5                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 5250           |                | (5250)5250                 | 5182.2             |
| 052006<br>E1              | FJ44 CHECK 6                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 7000           |                | (7000)7000                 | 6932.2             |
| 052006<br>E2              | FJ44 CHECK 6                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 7000           |                | (7000)7000                 | 6932.2             |
| 052007<br>E1              | FJ44 CHECK 7                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 8750           |                | (8750)8750                 | 8682.2             |
| 052007<br>E2              | FJ44 CHECK 7                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 8750           |                | (8750)8750                 | 8682.2             |
| 052008<br>E1              | FJ44 CHECK 8                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 10500          |                | (10500)10500               | 10432.2            |
| 052008<br>E2              | FJ44 CHECK 8                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 10500          |                | (10500)10500               | 10432.2            |
| 052009<br>E1              | FJ44 CHECK 9                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 12250          |                | (12250)12250               | 12182.2            |
| 052009<br>E2              | FJ44 CHECK 9                      |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 12250          |                | (12250)12250               | 12182.2            |
| 052010<br>E1              | FJ44 CHECK 10                     |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 14000          |                | (14000)14000               | 13932.2            |
| 052010<br>E2              | FJ44 CHECK 10                     |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 14000          |                | (14000)14000               | 13932.2            |
| 052011<br>E1              | FJ44 CHECK 11                     |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 15750          |                | (15750)15750               | 15682.2            |
| 052011<br>E2              | FJ44 CHECK 11                     |      |                                       | MTH 06-Feb-2025<br>HRS 0 |                | 15750          |                | (15750)15750               | 15682.2            |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Maintenance Inspections

| Item Code                     | Description                                                                                        | Part Number   | C/W Time 1 | Adj.           | TBO 1       | TSO 1  | (ENG) DUE 1 | Remains |              |            |
|-------------------------------|----------------------------------------------------------------------------------------------------|---------------|------------|----------------|-------------|--------|-------------|---------|--------------|------------|
| Position                      | Drawing # / Task #                                                                                 | City          | Mod Lvl    | Part Serial No | C/W Time 2  | + or - | TBO 2       | TSO 2   | (ENG) DUE 2  | Remains    |
| 052012<br>E1                  | FJ44 CHECK 12                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 17500       |         | (17500)17500 | 17432.2    |
| 052012<br>E2                  | FJ44 CHECK 12                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 17500       |         | (17500)17500 | 17432.2    |
| 052013<br>E1                  | FJ44 CHECK 13                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 19250       |         | (19250)19250 | 19182.2    |
| 052013<br>E2                  | FJ44 CHECK 13                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 19250       |         | (19250)19250 | 19182.2    |
| 052014<br>E1                  | FJ44 CHECK 14                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 21000       |         | (21000)21000 | 20932.2    |
| 052014<br>E2                  | FJ44 CHECK 14                                                                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 21000       |         | (21000)21000 | 20932.2    |
| 12-28-05-600                  | 15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH                                                  |               |            | DAYS           | 06-Feb-2025 |        | O/C         |         |              |            |
| 12-28-05-601                  | 45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH                                                |               |            | DAYS           | 06-Feb-2025 |        | O/C         |         |              |            |
| 12-28-05-602                  | 90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH                                                   |               |            | DAYS           | 06-Feb-2025 |        | O/C         |         |              |            |
| 26-20-00-961                  | ENGINE FIRE EXTINGUISHER BOTTLES (HYDROSTATIC TEST) FUNCTIONAL CHECK                               |               |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | 30400048-1    |            | MTH            | 02-May-2024 |        | 60          |         | 31-May-2029  | 44 m 22 d  |
|                               |                                                                                                    | 89990B1       |            |                |             |        |             |         |              |            |
| Hydro Check Date: 02-May-2024 |                                                                                                    |               |            |                |             |        |             |         |              |            |
| 26-20-00-962<br>NO. 1         | NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (TOTAL LIFE)                                       |               |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | 13083-5       |            | MTH            | 01-Jan-2024 |        | 72          |         | 31-Jan-2030  | 52 m 22 d  |
|                               |                                                                                                    | ESD24A982-001 |            |                |             |        |             |         |              |            |
| 26-20-00-962<br>NO. 2         | NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (TOTAL LIFE)                                       |               |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | 3090-3824     |            | MTH            | 01-May-2024 |        | 72          |         | 31-May-2030  | 56 m 22 d  |
|                               |                                                                                                    | ESD24B200-001 |            |                |             |        |             |         |              |            |
| 26-22-00-961<br>CABIN         | CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK                               |               |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | C352TS        |            | MTH            | 10-Jan-2025 |        | 144         |         | 31-Jan-2037  | 136 m 22 d |
|                               |                                                                                                    | I-48488920    |            |                |             |        |             |         |              |            |
| Hydro Check Date: 10-Jan-2025 |                                                                                                    |               |            |                |             |        |             |         |              |            |
| 28-00-02-220                  | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT) |               |            | MTH            | 06-Feb-2025 |        | 3           |         | 31-May-2025  | -3 m 9 d   |
| Over Due                      |                                                                                                    |               |            |                |             |        |             |         |              |            |
| 28-00-02-221                  | MICROBIOLOGICAL CONTAMINATIONINSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)      |               |            | MTH            | 06-Feb-2025 |        | 12          |         | 28-Feb-2026  | 5 m 19 d   |
| 32-32-05-720                  | EMERGENCY PNEUMATIC STORAGE BOTTLE (HYDROSTATIC TEST) FUNCTIONAL CHECK                             |               |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | 40005320-2    |            | MTH            | 03-May-2025 |        | 36          |         | 29-Feb-2028  | 29 m 20 d  |
|                               |                                                                                                    | 8056          |            | HRS            | 46.3        |        |             |         |              |            |
|                               |                                                                                                    |               |            | LDG            | 43          |        |             |         |              |            |
| Hydro Check Date: 01-Feb-2025 |                                                                                                    |               |            |                |             |        |             |         |              |            |
| 35-00-00-780                  | OXYGEN BOTTLE RESTORATION (HYDROSTATIC TEST)                                                       |               |            | MTH            | 01-Feb-2024 |        | 60          |         | 28-Feb-2029  | 41 m 19 d  |
|                               |                                                                                                    | 176276-50     |            |                |             |        |             |         |              |            |
|                               |                                                                                                    | 1174053510    |            |                |             |        |             |         |              |            |
| Hydro Check Date: 01-Feb-2024 |                                                                                                    |               |            |                |             |        |             |         |              |            |
| 551010                        | EXAMINE HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS 4.78                                      |               |            | MTH            | 06-Feb-2025 |        |             |         |              |            |
|                               |                                                                                                    |               |            | HRS            | 0           |        | 14000       |         | 14000        | 13932.2    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 571010                | EXAMINE LOWER MAIN SPAR SPLICE AT WS 93.00                       |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 13200          |                | 13200                      | 13132.2            |
| 571015                | EXAMINE LOWER REAR SPAR SPLICE AT WS 93.00                       |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 15600          |                | 15600                      | 15532.2            |
| 571020                | EXAMINE MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 15000          |                | 15000                      | 14932.2            |
| 571025                | EXAMINE REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 15000          |                | 15000                      | 14932.2            |
| 571030                | EXAMINE MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00)     |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 15000          |                | 15000                      | 14932.2            |
| 710000<br>E1          | WATER RINSE                                                      |      |         |                               | MTH 06-Feb-2025          |                | ALF<br>ALF     |                |                            |                    |
| 710000<br>E2          | WATER RINSE                                                      |      |         |                               | MTH 06-Feb-2025          |                | ALF<br>ALF     |                |                            |                    |
| 710015<br>E1          | COMPRESSOR CLEANING                                              |      |         |                               | MTH 06-Feb-2025          |                | A/R            |                |                            |                    |
| 710015<br>E2          | COMPRESSOR CLEANING                                              |      |         |                               | MTH 06-Feb-2025          |                | A/R            |                |                            |                    |
| 731025<br>E1          | FUEL FILTER REPLACEMENT                                          |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 1200           |                | (1200)1200                 | 1132.2             |
| 731025<br>E2          | FUEL FILTER REPLACEMENT                                          |      |         |                               | MTH 06-Feb-2025<br>HRS 0 |                | 1200           |                | (1200)1200                 | 1132.2             |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code               | Description                             | Part Number                       | C/W Time 1               | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-------------------------|-----------------------------------------|-----------------------------------|--------------------------|--------|-------|-------|-------------|---------|
| Position                | Drawing # / Task # City Mod Lvl         | Part Serial No                    | C/W Time 2               | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 211003                  | HEAT PRESSURE EXCHANGER                 | 10840A<br>1637                    | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 211004                  | HEAT EXCHANGER SHUTOFF VALVE            | 27241287-24<br>5CA24              | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 211005                  | EMERGENCY PRESS SHUTOFF VALVE           | 2601-23<br>2010                   | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 211006<br>LEFT          | PRESSURE SHUTOFF VALVE                  | 5253-00-1<br>5985                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 211006<br>RIGHT         | PRESSURE SHUTOFF VALVE                  | 5253-00-1<br>5983                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 212001                  | UNDERFLOOR INLET AIR BLOWER             | 0113-12<br>3180                   | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 212003                  | TEMP PRESS COMPRESSION SWITCH           | 1173T42-3<br>4737                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 212011<br>AFT           | TEMPERATURE WINDSHIELD BLEED AIR SENSOR | 27221274<br>6CA78                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 212302                  | BLOWER - WINDSHIELD AIR MOTOR           | 7003-300<br>681                   | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 213003                  | PRESSURIZATION CONTROLLER               | 52811-1103<br>9912661-5<br>07633A | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 213004<br>LEFT          | KAPS II OUTFLOW VALVE                   | 52812-102<br>5809                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 213004<br>RIGHT         | KAPS II OUTFLOW VALVE                   | 52812-102<br>5813                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215001<br>FORWARD       | EVAPORATOR                              | 1134820-13<br>721A                | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215002<br>AFT           | EVAPORATOR                              | 1134820-14<br>837A                | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215004                  | COMPRESSOR CONDENSOR MODULE ASSEMBLY    | 9912459-8<br>1134400-31<br>796A   | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215006                  | DRIVE MOTOR ASSEMBLY                    | PN<br>SN-UNKNOWN                  | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215010                  | FREON A/C-BAROMETRIC SWITCH             | GBC300-82<br>2415402              | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 215014                  | COMPRESSOR ASSEMBLY                     | 1134160<br>11606                  | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 216002                  | TEMPERATURE CONTROLLER                  | 1E86-1<br>5CA733                  | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 216004                  | TEMPERATURE BLEED AIR INSTALL SENSOR    | 27221274<br>5CA65                 | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| A215004                 | COMPRESSOR DRIVE MOTOR BRUSHES          | PN<br>SN-UNKNOWN                  | MTH 06-Feb-2025<br>ACH 0 |        | 500   | 0     | 500         | 500     |
| 221003<br>AILERON       | SERVO                                   | 011-00877-20<br>19Z020700         | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 221004<br>RUDDER        | SERVO                                   | 011-00877-20<br>19Z020709         | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 221005<br>ELEVATOR TRIM | GSA 81 SERVO                            | 011-00878-20<br>1A1043982         | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 221009                  | GMC 710 AFCS MODE CONTROLLER            | 011-01020-10<br>22010687          | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 221010<br>ELEVATOR      | GSA 81 SERVO                            | 011-00878-20<br>1A1043973         | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |
| 221011<br>AILERON       | GSM 86 SERVO MOUNT                      | 011-02490-14<br>1GK047778         | MTH 06-Feb-2025          |        | O/C   | 0     |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code          | Description                        | Part Number               | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|--------------------|------------------------------------|---------------------------|-----------------|--------|-------|-------|-------------|---------|
| Position           | Drawing # / Task # City Mod Lvl    | Part Serial No            | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 221012<br>RUDDER   | GSM 86 SERVO MOUNT                 | 011-02490-15<br>1GK048442 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 221013<br>ELEVATOR | GSM 86 SERVO MOUNT                 | 011-02490-16<br>1GK048923 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 221014             | GSM 86 SERVO (ELEVATOR TRIM) MOUNT | 011-02490-22<br>1GK048295 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 231008             | GDR 66 VHF DATALINK RADIO          | 011-02303-00<br>222007196 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232008<br>BOTTOM   | COMM 2 ANTENNA                     | VHF10-829<br>4881         | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232008<br>LWR      | TCAS ANTENNA                       | S72-1735-26<br>874-3207   | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232008<br>TOP      | COMM 1 ANTENNA                     | VHF10-829<br>4883         | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232008<br>UPPER    | TCAS ANTENNA                       | S72-1735-26<br>874-3178   | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232014<br>LH       | GSD 41 DATA CONCENTRATOR           | 011-01457-01<br>2JH008798 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232014<br>RH       | GSD 41 DATA CONCENTRATOR           | 011-01457-01<br>2JH008882 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232021             | COMM 3 ANTENNA                     | VHF10-829<br>5154         | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232023<br>AFT      | WIFI ANTENNA                       | TRAB24/49003P<br>2232210  | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 232033<br>FWD      | WIFI ANTENNA                       | TRAB24/49003P<br>5092210  | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 235001<br>NO. 1    | GPS/XM ANTENNA                     | CI428-410<br>749779       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 235001<br>NO. 2    | GPS/XM ANTENNA                     | CI428-410<br>750179       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 235006<br>LEFT     | GMA 36 REMOTE AUDIO PROCESSOR      | 011-04093-00<br>4RK115437 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 235006<br>RIGHT    | GMA 36 REMOTE AUDIO PROCESSOR      | 011-04093-00<br>4RK115342 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 235009             | PA AMPLIFIER                       | 102025-1<br>10630724      | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 237003             | CVR MICROPHONE                     | S055-0067-00<br>100011838 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 344404             | GRAPHICAL WEATHER SYSTEM DATA LINK | 011-03177-15<br>5P0004601 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 242001<br>AUX      | AC CONVERTER                       | SS50<br>10418             | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 243002<br>LEFT     | GENERATOR CONTROL UNIT             | 51525-001F<br>P10469      | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 243002<br>RIGHT    | GENERATOR CONTROL UNIT             | 51525-001F<br>P10576      | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 243003             | MAIN BATTERY                       | 30978-002<br>12401627     | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 243007             | 14 AHR BATTERY ASSEMBLY            | RG24-15M<br>41380540      | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 243012             | STANDBY BATTERY                    | 501-1712-01<br>S00089     | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 245001             | PRESSURIZATION PCB ASSY            | 6318349-26<br>34149076-4  | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 245002<br>LEFT     | ASSEMBLY-FUEL CONTROL PCB          | 6318037-6<br>34367050-3   | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position        | Description<br>Drawing # / Task #                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|----------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 245002<br>RIGHT              | ASSEMBLY-FUEL CONTROL PCB                                |      |         | 6318037-6<br>34367050-4       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245003<br>LEFT               | ASSEMBLY-IGNITOR PCB                                     |      |         | 6318388-7<br>34339569-1       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245003<br>RIGHT              | ASSEMBLY-IGNITOR PCB                                     |      |         | 6318388-7<br>34231205-4       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245004<br>LEFT               | ANTI ICE PCB ASSY                                        |      |         | 6318390-1<br>34265201-3       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245004<br>RIGHT              | ANTI ICE PCB ASSY                                        |      |         | 6318390-1<br>34265201-2       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245005                       | PRINTED CIRCUIT BOARD (PCB) ASSEMBLY - DIAGNOSTICS NZ115 |      |         |                               |                          |                |                |                |                            |                    |
|                              |                                                          |      |         | 6318046-9<br>34170475-4       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245006                       | ENVIRONMENTAL PCB ASSY                                   |      |         | 6318358-20<br>34170513-1      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245007<br>LEFT               | PCB-START LOGIC ASSY                                     |      |         | 6318038-1<br>34529884-1       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245007<br>RIGHT              | PCB-START LOGIC ASSY                                     |      |         | 6318038-1<br>34529884-2       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245011                       | FUEL FLOW XMITTER PCB ASSY                               |      |         | 85-230-2<br>ONT00048          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245012                       | SPEEDBRAKE CONTROL PCB ASSY                              |      |         | 6318034-6<br>34085110-2       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245013                       | TAIL DEICE MONITOR PCB ASSY                              |      |         | 6318043-1<br>34170516-3       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245014                       | TAIL DEICE CONTROL PCB ASSY                              |      |         | 6318044-1<br>34268918-3       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245015                       | HYDRAULIC PCB ASSY                                       |      |         | 6318035-7<br>34268840-1       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245020                       | FADEC INTERFACE NZ116 ASSY                               |      |         | 6318387-11<br>34339568-4      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245022                       | FADEC INTERFACE NZ117 ASSY                               |      |         | 6318387-11<br>34339568-2      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245023                       | LANDING GEAR MONITOR PCB ASSY                            |      |         | 6318397-21<br>33851649-4      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245026<br>NO. 1              | LANDING GEAR PCB                                         |      |         | 6318398-6<br>34042291-1       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245027<br>NO. 2              | LANDING GEAR PCB                                         |      |         | 6318399-11<br>34042192-4      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 245200<br>CABIN              | ALT MODULE ASSY                                          |      |         | 7018119-1<br>34265392-3       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 25-62-00-960                 | ELT BEACON BATTERY PACK                                  |      |         | 452-0133<br>1010508-005       | MTH                      |                | DUE<br>DUE     |                | 01-Sep-2029                | 47 m 23 d          |
| Expiration Date: 01-Sep-2029 |                                                          |      |         |                               |                          |                |                |                |                            |                    |
| 256001                       | EMERGENCY LOCATOR TRANSMITTER                            |      |         | 453-5060<br>25209132          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 256004                       | ELT ANTENNA                                              |      |         | 110-340<br>746490             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 261002<br>LEFT               | FIRE DETECT SENSOR                                       |      |         | 3001-212-1004/455-9<br>220021 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 261002<br>RIGHT              | FIRE DETECT SENSOR                                       |      |         | 3001-212-1004/455-9<br>220105 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 262001                       | ENGINE FIRE EXTINGUISHER BOTTLE<br>9912048-7             |      |         | 30400048-1<br>89990B1         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 262002<br>NO. 1              | FIRE EXTINGUISHER CARTRIDGE                              |      |         | 13083-5<br>ESD24A982-001      | MTH 01-Jan-2024          |                | H/T<br>H/T     | 0              |                            |                    |
| 262002<br>NO. 2              | FIRE EXTINGUISHER CARTRIDGE                              |      |         | 3090-3824<br>ESD24B200-001    | MTH 01-May-2024          |                | H/T<br>H/T     | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 262003<br>CABIN       | PORTABLE FIRE EXTINGUISHER        |      |         | C352TS<br>I-48488920          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 271001<br>LH          | CONTROL WHEEL ASSY                |      |         | 6360115-1<br>20224-2          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 271001<br>RH          | CONTROL WHEEL ASSY                |      |         | 6360115-2<br>80524-12         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 273001<br>LEFT        | SHAKER CONTROL                    |      |         | 201<br>205877-02              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 275001                | SHUTOFF VALVE                     |      |         | 4083-1<br>1826                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 275002<br>LEFT        | FLAP HYD ACTUATOR                 |      |         | 1542000-9<br>3198             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 275002<br>RIGHT       | FLAP HYD ACTUATOR                 |      |         | 1542000-9<br>3203             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 275003<br>LEFT        | FLAP ASSEMBLY                     |      |         | 6325100-81<br>34349104        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 275004<br>RIGHT       | FLAP ASSEMBLY                     |      |         | 6325100-82<br>34136220        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 276001<br>LEFT        | SPEEDBRAKE ACTUATOR               |      |         | 1542100-5<br>3205A            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 276001<br>RIGHT       | SPEEDBRAKE ACTUATOR               |      |         | 1542100-5<br>3182A            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 281001<br>LEFT        | FUEL SURGE VALVE                  |      |         | 35C10D<br>7561                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 281001<br>RIGHT       | FUEL SURGE VALVE                  |      |         | 35C10D<br>7550                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282001<br>LEFT        | ELECTRIC FUEL PUMP                |      |         | 1C7-13<br>4CA16               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282001<br>RIGHT       | ELECTRIC FUEL PUMP                |      |         | 1C7-13<br>4CA15               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282002<br>LEFT        | FUEL TRANSFER PUMP                |      |         | RG45880<br>B6915              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282002<br>RIGHT       | FUEL TRANSFER PUMP                |      |         | RG45880<br>B6920              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282004<br>LEFT        | FUEL MOTOR ACTUATED VALVE         |      |         | AV24B1507<br>AA884168         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282004<br>RIGHT       | FUEL MOTOR ACTUATED VALVE         |      |         | AV24B1507<br>AA884164         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282005<br>LEFT        | FUEL TRANSFER EJECTOR             |      |         | RG45310<br>C5571              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282005<br>RIGHT       | FUEL TRANSFER EJECTOR             |      |         | RG45310<br>C5578              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 282006                | TRANSFER VALVE                    |      |         | ZSV57<br>2544634-11           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284001<br>LH          | NO.5 TRANSMITTER FUEL PROBE       |      |         | 10307T01Y00<br>MN59682        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284001<br>RH          | NO.5 TRANSMITTER FUEL PROBE       |      |         | 10307T01Y00<br>MN59093        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284003                | FUEL QUANTITY SIGNAL CONDITIONER  |      |         | 10310B01Y02<br>24071189       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284004<br>LH          | NO.3 TRANSMITTER FUEL PROBE       |      |         | 10305T01Y00<br>MN59306        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284004<br>RH          | NO.3 TRANSMITTER FUEL PROBE       |      |         | 10305T01Y00<br>MN59307        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284005<br>LH          | NO.4 TRANSMITTER FUEL PROBE       |      |         | 10306T01Y00<br>MN59642        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 284005<br>RH          | NO.4 TRANSMITTER FUEL PROBE       |      |         | 10306T01Y00<br>MN59638        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code       | Description                                | Part Number             | C/W Time 1                          | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-----------------|--------------------------------------------|-------------------------|-------------------------------------|--------|-------|-------------|-------------|---------|
| Position        | Drawing # / Task # City Mod Lvl            | Part Serial No          | C/W Time 2                          | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 284006<br>LH    | NO.2 TRANSMITTER FUEL PROBE                | 10304T01Y00<br>MN59299  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 284006<br>RH    | NO.2 TRANSMITTER FUEL PROBE                | 10304T01Y00<br>MN59008  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 284007<br>LH    | NO.1 TRANSMITTER FUEL PROBE                | 10303T01Y00<br>MN59292  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 284007<br>RH    | NO.1 TRANSMITTER FUEL PROBE                | 10303T01Y00<br>MN59297  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 284010<br>LH    | NO.6 TRANSMITTER FUEL PROBE                | 10309T03Y00<br>MN59520  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 284010<br>RH    | NO.6 TRANSMITTER FUEL PROBE                | 10309T03Y00<br>MN59316  | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291007          | PRESSURE SWITCH<br>9912373-6               | GPP1250-301<br>240610   | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291009<br>LEFT  | ENGINE DRIVEN HYDRAULIC PUMP               | 4120-046000<br>1689C    | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291009<br>RIGHT | ENGINE DRIVEN HYDRAULIC PUMP               | 4120-046000<br>1709C    | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291009A         | HYDRAULIC RELIEF VALVE                     | 2576-2<br>3012A         | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291010<br>LEFT  | HYDRAULIC SHUTOFF VALVE ASSY               | AV24B1388-2<br>AA883274 | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291010<br>RIGHT | HYDRAULIC SHUTOFF VALVE ASSY               | AV24B1388-2<br>AA870974 | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291011<br>LEFT  | FLOW SWITCH/CHECK HYD VALVE                | V10F-75<br>895          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291011<br>RIGHT | FLOW SWITCH/CHECK HYD VALVE                | V10F-75<br>872          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291012          | SPEED BRAKE DUMP VALVE SOLENOID            | 4082-6<br>1908          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291013          | LOADING VALVE SOLENOID<br>KICT             | 9912423-51<br>3251      | MTH 06-Feb-2025<br>HRS 8.1<br>LDG 6 |        | O/C   | 0<br>0<br>0 |             |         |
| 291014          | LANDING GEAR VALVE SOLENOID                | 4051-4<br>1868          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291016<br>LEFT  | SPEED BRAKE PORTION VALVE                  | 9505-1<br>3787          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291016<br>RIGHT | SPEED BRAKE PORTION VALVE                  | 9505-1<br>3788          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291017          | SPEED BRAKE PORTION VALVE                  | 2577-1<br>1921          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291018          | PNEUMATIC DUMP VALVE                       | 9503-2<br>1907          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291020          | SPEEDBRAKE VALVE SOLENOID                  | 4052-3<br>1940          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 291021          | FLAP VALVE SOLENOID                        | 4052-4<br>1981          | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 301001          | SHUTOFF ISOLATION VALVE                    | 2602-36<br>3003         | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 301002<br>LEFT  | PNEUMATIC DEICE SWITCH                     | 1106P55-1<br>14556A     | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 301002<br>RIGHT | PNEUMATIC DEICE SWITCH                     | 1106P55-1<br>14654A     | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |
| 301003<br>LEFT  | BLEED AIR PRESSURE REGULATOR SHUTOFF VALVE | 5285-00-3<br>5393       | MTH 06-Feb-2025                     |        | O/C   | 0           |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 301003<br>RIGHT       | BLEED AIR PRESSURE REGULATOR SHUTOFF VALVE |      |         | 5285-00-3<br>5392             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301004<br>LEFT        | TEMPERATURE DEICE SWITCH                   |      |         | 1173T42-4<br>6071             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301004<br>RIGHT       | TEMPERATURE DEICE SWITCH                   |      |         | 1173T42-4<br>6190             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301010<br>LEFT        | HORIZONTAL STABILIZER BOOT                 |      |         | 29S4D5244-11<br>NHF0620       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301010<br>RIGHT       | HORIZONTAL STABILIZER BOOT                 |      |         | 29S4D5244-12<br>NHD5570       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301012<br>LEFT        | WING SHUTOFF PRESSURE REGULATING VALVE     |      |         | 9912402-9<br>1H127-4<br>5CA49 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 301012<br>RIGHT       | WING SHUTOFF PRESSURE REGULATING VALVE     |      |         | 9912402-9<br>1H127-4<br>6CA55 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 303002<br>LEFT        | HEATED PITOT TUBE                          |      |         | PH502<br>AS10230304           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 303002<br>RIGHT       | HEATED PITOT TUBE                          |      |         | PH502<br>AS02240303           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304001<br>LH          | B/A TEMP MONITOR-                          |      |         | 1169-1<br>105392              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304002                | HEAT EXCHANGER                             |      |         | 10653A<br>2963                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304003                | WINDSHIELD S/O VALVE                       |      |         | 1H127-4<br>6CA52              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304004<br>AFT         | AFT PITOT STATIC CURRENT SENSOR            |      |         | 76250-6<br>18184              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304004<br>FORWARD     | FORWARD PITOT STATIC CURRENT SENSOR        |      |         | 76250-6<br>18183              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304005<br>AFT         | AFT SENSOR                                 |      |         | 76552-1<br>15524              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304005<br>FORWARD     | FORWARD SENSOR                             |      |         | 76552-1<br>15398              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304006                | TEMP BLEED AIR CONTROLLER                  |      |         | 1E58-1<br>2CA20               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304007                | TEMP CONTROL BLEED AIR VALVE               |      |         | 27241287<br>4CA43P            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304009<br>LEFT        | SOLENOID DEICE VALVE                       |      |         | 3D2353-06<br>N301335          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304009<br>RIGHT       | SOLENOID DEICE VALVE                       |      |         | 3D2353-06<br>N301340          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304012<br>LEFT        | WINDSHIELD BLEED AIR VALVE                 |      |         | 1403-25<br>7006               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304012<br>RIGHT       | WINDSHIELD BLEED AIR VALVE                 |      |         | 1403-25<br>7012               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304013                | PRESSURE WINDSHIELD SWITCH                 |      |         | 1115P25<br>5908AB             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 304014<br>AFT         | TEMPERATURE EVAPORATOR SENSOR              |      |         | 27221274<br>6CA106            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 313003                | ARES II 24-CH FLIGHT DATA RECORDER         |      |         | 6918236-20<br>2883            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code                     | Description                                                                                              | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains     |             |         |
|-------------------------------|----------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|-------------|-------------|---------|
| Position                      | Drawing # / Task #                                                                                       | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2       | (ENG) DUE 2 | Remains |
| 32-32-05-960                  | EMERGENCY PNEUMATIC STORAGE BOTTLE DISCARD                                                               |             | MTH        | 03-May-2025    |            | 288    | 144         | 31-May-2037 | 140 m 22 d  |         |
|                               | 9912368-2                                                                                                | 40005320-2  | HRS        | 46.3           |            |        |             |             |             |         |
|                               |                                                                                                          | 8056        | LDG        | 43             |            |        |             |             |             |         |
| Manufacture Date: 01-May-2013 |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 321001                        | NOSE LANDING GEAR STRUT ASSEMBLY (PART NUMBER 6342000-43, -45, -49), EXCEPT THE FORK AND PISTON ASSEMBLY |             |            |                |            |        |             |             |             |         |
| NOSE LANDING                  |                                                                                                          | 6342000-49  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
|                               |                                                                                                          | 34327575    | LDG        | 0              |            | 22500  | 0           | 22500       | 22441       |         |
| 321003                        | TRUNNION ASSEMBLY                                                                                        | 6341007-15  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| LEFT MAIN                     |                                                                                                          | 33732518C   | LDG        | 0              |            | 9310   | 0           | 9310        | 9251        |         |
| LANDING GEAR                  |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 321004                        | TRUNNION ASSEMBLY                                                                                        | 6341007-16  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| RIGHT MAIN                    |                                                                                                          | 33995605A   | LDG        | 0              |            | 9310   | 0           | 9310        | 9251        |         |
| LANDING GEAR                  |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 321005                        | TRAILING LINK AND AXLE ASSEMBLY                                                                          | 6341002-27  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| LEFT                          |                                                                                                          | 34100674    | LDG        | 0              |            | 21100  | 0           | 21100       | 21041       |         |
| 321006                        | TRAILING LINK AND AXLE ASSEMBLY                                                                          | 6341002-28  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| RIGHT                         |                                                                                                          | 34544551    | LDG        | 0              |            | 21100  | 0           | 21100       | 21041       |         |
| 321007                        | SHIMMY DAMPER ASSEMBLY                                                                                   | 6343001-10  | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
|                               |                                                                                                          | 34503182P   |            |                |            |        |             |             |             |         |
| 321008                        | OLEO ASSEMBLY                                                                                            | 6341130-12  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| LEFT                          |                                                                                                          | 34529737    | LDG        | 0              |            | 21100  | 0           | 21100       | 21041       |         |
| 321008                        | OLEO ASSEMBLY                                                                                            | 6341130-12  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| RIGHT                         |                                                                                                          | 34529727    | LDG        | 0              |            | 21100  | 0           | 21100       | 21041       |         |
| 321009                        | FORK AND PISTON ASSEMBLY                                                                                 | 6342000-39  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
|                               |                                                                                                          | 34478680    | LDG        | 0              |            | 12500  | 0           | 12500       | 12441       |         |
| 321013                        | LEFT MAIN LANDING GEAR ASSEMBLY                                                                          | PN          | MTH        | 06-Feb-2025    |            | H/T    | 0           |             |             |         |
| LEFT                          |                                                                                                          | SN-UNKNOWN  |            |                |            | H/T    |             |             |             |         |
| 321013                        | RIGHT MAIN LANDING GEAR ASSEMBLY                                                                         | PN          | MTH        | 06-Feb-2025    |            | H/T    | 0           |             |             |         |
| RIGHT                         |                                                                                                          | SN-UNKNOWN  |            |                |            | H/T    |             |             |             |         |
| 323000                        | ACTUATOR ASSEMBLY                                                                                        | 1541900-7   | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| NOSE LANDING                  | 9912370-5                                                                                                | 2742        | LDG        | 0              |            | 7500   | 0           | 7500        | 7441        |         |
| GEAR                          |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 323001                        | ACTUATOR ASSEMBLY                                                                                        | 1541800-13  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| LEFT MAIN                     | 9912397-8                                                                                                | 2277        | LDG        | 0              |            | 8952   | 0           | 8952        | 8893        |         |
| LANDING GEAR                  |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 323002                        | ACTUATOR ASSEMBLY                                                                                        | 1541800-13  | MTH        | 06-Feb-2025    |            | 0      |             |             |             |         |
| RIGHT MAIN                    | 9912397-8                                                                                                | 2278        | LDG        | 0              |            | 8952   | 0           | 8952        | 8893        |         |
| LANDING GEAR                  |                                                                                                          |             |            |                |            |        |             |             |             |         |
| 323003                        | NG UPLOCK ACTUATOR                                                                                       | 6327504-7   | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
|                               |                                                                                                          | 2455        |            |                |            |        |             |             |             |         |
| 323005                        | MLG UPLOCK ACTUATOR                                                                                      | 6327504-6   | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| LEFT                          |                                                                                                          | 5265        |            |                |            |        |             |             |             |         |
| 323005                        | MLG UPLOCK ACTUATOR                                                                                      | 6327504-6   | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| RIGHT                         |                                                                                                          | 5262        |            |                |            |        |             |             |             |         |
| 323006                        | HYD SHUTTLE VALVE                                                                                        | 95784       | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
|                               |                                                                                                          | 5404A       |            |                |            |        |             |             |             |         |
| 324001                        | MAIN LANDING GEAR WHEEL                                                                                  | 3-1527-2    | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| LEFT                          | 9912398-7                                                                                                | 2079        |            |                |            |        |             |             |             |         |
| 324001                        | MAIN LANDING GEAR WHEEL                                                                                  | 3-1527-2    | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| RIGHT                         | 9912398-7                                                                                                | 2013        |            |                |            |        |             |             |             |         |
| 324002                        | LANDING GEAR WHEEL ASSY                                                                                  | 3-1418      | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| NOSE                          |                                                                                                          | D0604       |            |                |            |        |             |             |             |         |
| 324005                        | MLG TIRE                                                                                                 | 277K08-1    | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| LEFT                          |                                                                                                          | 4020094     |            |                |            |        |             |             |             |         |
| 324005                        | MLG TIRE                                                                                                 | 277K08-1    | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| RIGHT                         |                                                                                                          | 40220251    |            |                |            |        |             |             |             |         |
| 324007                        | LANDING GEAR TIRE                                                                                        | 030-611-0   | MTH        | 06-Feb-2025    |            | O/C    | 0           |             |             |         |
| NOSE                          |                                                                                                          | 3048T00354  |            |                |            |        |             |             |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position                | Description<br>Drawing # / Task #             | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------|-----------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 324016<br>LEFT MAIN<br>LANDING GEAR  | BRAKE ASSY                                    |      |         | 2-1559-3<br>D0362             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324016<br>RIGHT MAIN<br>LANDING GEAR | BRAKE ASSY                                    |      |         | 2-1559-3<br>D0342             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324101                               | POWER BRAKE AND ANTISKID VALVE                |      |         | 9912374-7<br>1198             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324102<br>LEFT                       | ANTISKID TRANSDUCER ASSEMBLY                  |      |         | 40-955<br>12599               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324102<br>RIGHT                      | ANTISKID TRANSDUCER ASSEMBLY                  |      |         | 40-955<br>12521               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324103                               | BRAKE CONTROL BOX                             |      |         | 42-707-1<br>1927              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324106                               | HYDRAULIC PUMP MOTOR                          |      |         | MP50B1<br>6130                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324107                               | ANTISKID ACCUMULATOR                          |      |         | 9912644-2<br>2193             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324110                               | EMERGENCY BRAKE VALVE ASSY                    |      |         | 878208-05<br>V1182A           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 324112                               | PRESSURE ANTISKID SWITCH                      |      |         | 38-747502<br>1363             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 330001<br>CENTER                     | PANEL LIGHTS DIMMER                           |      |         | 273-1<br>1073                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 331003                               | INDIRECT LIGHTING CONTROL BOX                 |      |         | CLC500-01<br>202400000022767  | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334001                               | GROUND RECOGNITION LIGHT                      |      |         | 84003-3<br>1767               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334007                               | TAIL LIGHT ASSEMBLY                           |      |         | 01-0770966-00<br>890181       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334008<br>LEFT                       | PTA WINGTIP LIGHT                             |      |         | 87-03916-001<br>489           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334008<br>RIGHT                      | PTA WINGTIP LIGHT                             |      |         | 87-03917-001<br>504           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334009<br>LH                         | OVER WING LIGHT                               |      |         | OWL100-03<br>202400000034823  | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334009<br>RH                         | OVER WING LIGHT                               |      |         | OWL100-03<br>202400000029038  | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334010<br>LEFT                       | LED LANDING LIGHT                             |      |         | LDL100-02<br>202400000028135  | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 334010<br>RIGHT                      | LED LANDING LIGHT                             |      |         | LDL100-02<br>2024000000031494 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 341001                               | AOA COMPUTER                                  |      |         | C12406-5<br>203622-05         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 341009                               | AOA SENSOR                                    |      |         | C12417-2<br>206853-06         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 341010<br>AFT                        | RADIO ALTIMETER ANTENNA                       |      |         | S67-2002<br>543-17802         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 341010<br>FORWARD                    | RADIO ALTIMETER ANTENNA                       |      |         | S67-2002<br>543-118125        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 341601                               | ELECTRONIC FLIGHT DISPLAY EFD - 750 MOD UI013 |      |         | 9200-15754-0201<br>2012       | MTH 06-Feb-2025          |                | H/T<br>H/T     | 0              |                            |                    |
| 342015<br>LEFT                       | AHRS COMPUTER                                 |      |         | 011-03732-00<br>45T010185     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 342015<br>RIGHT                      | AHRS COMPUTER                                 |      |         | 011-03732-00<br>45T010348     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 342056                               | MULTI-FUNCTION MODULE                         |      |         | 9118009-4<br>34071115-3       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code           | Description                                                    | Part Number               | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|---------------------|----------------------------------------------------------------|---------------------------|-----------------|--------|-------|-------|-------------|---------|
| Position            | Drawing # / Task # City Mod Lvl                                | Part Serial No            | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 342062<br>LEFT      | GEA 71 ENGINE & AIRFRAME IO UNIT                               | 011-03682-04<br>4RE001738 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342062<br>RIGHT     | GEA 71 ENGINE & AIRFRAME IO UNIT                               | 011-03682-04<br>4RE001836 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342063<br>LEFT      | LEFT GTC 575 PORTRAIT-ORIENTED TOUCHSCREEN CONTROLLER          | 011-03759-01<br>4MT105719 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342063<br>RIGHT     | RIGHT GTC 575 PORTRAIT-ORIENTED TOUCHSCREEN CONTROLLER         | 011-03759-01<br>4MT105668 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342078<br>LEFT      | LEFT GIA 64E INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT  | 011-03711-41<br>5RV007108 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342078<br>RIGHT     | RIGHT GIA 64E INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT | 011-03711-41<br>5RV007164 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342085<br>NO. 1     | NO. 1 GDC 7400 RVSM AIR DATA COMPUTER                          | 011-02337-01<br>1U6105031 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342085<br>NO. 2     | NO. 2 GDC 7400 RVSM AIR DATA COMPUTER                          | 011-02337-01<br>1U6105120 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342086<br>CENTER    | CENTER GDU 1450W (MFD) MULTIFUNCTION FLIGHT DISPLAY            | 011-04187-00<br>4VS007955 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342086<br>COPILOT   | COPILOT GDU 1450W (PFD) PRIMARY FLIGHT DISPLAY                 | 011-04187-00<br>4VS007856 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342086<br>PILOT     | PILOT GDU 1450W (PFD) PRIMARY FLIGHT DISPLAY                   | 011-04187-00<br>4VS007951 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342090              | GWX70 ANTENNA                                                  | 117-00254-01<br>6630      | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342800<br>LEFT      | GMU 44 MAGNETOMETER                                            | 011-04201-00<br>4WT016595 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 342800<br>RIGHT     | GMU 44 MAGNETOMETER                                            | 011-04201-00<br>4WT016619 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 343010              | MARKER BEACON COUPLER                                          | DMB20-20<br>7238          | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 344001              | ANTENNA GLIDESLOPE COUPLER                                     | DGSC20-02<br>11586        | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 344008              | GWX 80 UN803 PROCESSOR                                         | 011-03997-00<br>4RR005255 | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 344024              | RADIO ALTIMETER INDICATOR                                      | 822-0615-206<br>5016L7    | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345001<br>LOWER AFT | DME #2 ANTENNA                                                 | L10-611-14<br>18967       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345004<br>L/H LOWER | TRANSPONDER ANTENNA                                            | L10-611-14<br>18911       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345004<br>L/H UPPER | TRANSPONDER ANTENNA                                            | L10-611-14<br>18674       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345004<br>R/H LOWER | TRANSPONDER ANTENNA                                            | L10-611-14<br>18929       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345004<br>R/H UPPER | TRANSPONDER ANTENNA                                            | L10-611-14<br>18939       | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345005              | MARKER BEACON ANTENNA                                          | MB10-754<br>3365          | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |
| 345006              | GLIDESLOPE ANTENNA                                             | RGS10-48<br>23916         | MTH 06-Feb-2025 |        | O/C   | 0     |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position         | Description<br>Drawing # / Task #         | City | Mod Lvl | Part Number<br>Part Serial No          | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains   |
|-------------------------------|-------------------------------------------|------|---------|----------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|----------------------|
| 345008<br>LEFT                | DME 1 RECEIVER                            |      |         | 822-1466-001<br>5012V5                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 345022<br>LEFT                | NAVIGATION(VOR/LOC/GS) ANTENNA            |      |         | S65-247-38<br>180-18223                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 345022<br>RIGHT               | NAVIGATION(VOR/LOC/GS) ANTENNA            |      |         | S65-247-38<br>180-18224                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 345070<br>LEFT                | GTX 3000 MODE S TCAS II TRANSPONDER       |      |         | 011-01997-00<br>20S014877              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 345070<br>RIGHT               | GTX 3000 MODE S TCAS II TRANSPONDER       |      |         | 011-01997-00<br>20S014904              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 346030                        | TCAS PROCESSOR                            |      |         | 011-02571-00<br>28P012216              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 346102<br>LH                  | GCU 275 PFD CONTROLLER                    |      |         | 011-01983-20<br>1U7202131              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 346102<br>RH                  | GCU 275 PFD CONTROLLER                    |      |         | 011-01983-20<br>1U7202134              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 35-00-00-960                  | OXYGEN BOTTLE                             |      |         | 176276-50<br>1174053510                | MTH 01-Apr-2024          |                | 180            | 0              | 30-Apr-2039                | 163 m 21 d           |
| Manufacture Date: 01-Apr-2024 |                                           |      |         |                                        |                          |                |                |                |                            |                      |
| 35-10-05-960<br>COPILOT       | COPILOT OXYGEN MASK OVERHAUL<br>9914771-1 |      |         | 174252-N6<br>1173057903                | MTH 24-Aug-2024          |                | O/C            | 0              |                            |                      |
| 35-10-05-960<br>PILOT         | PILOT OXYGEN MASK OVERHAUL<br>9914771-1   |      |         | 174252-N6<br>1173057904                | MTH 24-Aug-2024          |                | O/C            | 0              |                            |                      |
| 351008                        | OXYGEN 3 POSITION VALVE                   |      |         | P21007<br>R24040043                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 351010                        | OXYGEN PRESSURE TRANSDUCER                |      |         | APT-389-1000-<br>2400SG<br>8929-10-611 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 36-10-00-960<br>LEFT          | LEFT BLEED AIR PRECOOLER<br>9914402-4     |      |         | 8161-2<br>S4883HX-02652                | MTH 06-Feb-2025<br>HRS 0 |                | 108<br>3500    | 0<br>0         | 28-Feb-2034<br>3500        | 101 m 19 d<br>3432.2 |
| 36-10-00-960<br>RIGHT         | RIGHT BLEED AIR PRECOOLER<br>9914402-4    |      |         | 8161-2<br>S4883HX-02236                | MTH 06-Feb-2025<br>HRS 0 |                | 108<br>3500    | 0<br>0         | 28-Feb-2034<br>3500        | 101 m 19 d<br>3432.2 |
| 361001<br>LEFT                | TEMPERATURE SENSOR                        |      |         | 27431501-10<br>6CA69                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361001<br>RIGHT               | TEMPERATURE SENSOR                        |      |         | 27431501-10<br>6CA76                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361003                        | PNEUMATIC REGULATOR<br>9912510-1          |      |         | 1H75-25<br>7CA38                       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361004<br>LEFT                | PNEUMATIC SHUTOFF VALVE ASSY              |      |         | 2601-21<br>2428                        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361004<br>RIGHT               | PNEUMATIC SHUTOFF VALVE ASSY              |      |         | 2601-21<br>2448                        | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361007<br>LEFT                | OVER TEMP BLEED AIR SWITCH                |      |         | 1173T181-2<br>9469                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361007<br>RIGHT               | OVER TEMP BLEED AIR SWITCH                |      |         | 1173T181-2<br>9620                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361008<br>LEFT                | PRECOOLER DOOR VALVE                      |      |         | 5060-00-1<br>6619                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361008<br>RIGHT               | PRECOOLER DOOR VALVE                      |      |         | 5060-00-1<br>6552                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361010<br>LEFT                | CHECK VALVE                               |      |         | 1553-00-18<br>5439                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361010<br>RIGHT               | CHECK VALVE                               |      |         | 1553-00-18<br>5455                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |
| 361011<br>LEFT                | PRECOOLER ACTUATOR                        |      |         | 1H139-1<br>3CA13                       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                      |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position           | Description<br>Drawing # / Task #                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------|-----------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 361011<br>RIGHT                 | PRECOOLER ACTUATOR                                  |      |         | 1H139-2<br>4CA27              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 521000                          | CABIN ENTRY DOOR                                    |      |         | 6511690-816<br>1185           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 522004                          | PRESSURE SWITCH                                     |      |         | P18M30<br>7052                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 531000<br>LEFT                  | TRUNNION SUPPORT FITTING                            |      |         | 5513056-7<br>156472-8         | MTH 06-Feb-2025<br>LDG 0 |                | 22500          | 0              | 22500                      | 22441              |
| 531000<br>RIGHT                 | TRUNNION SUPPORT FITTING                            |      |         | 5513056-8<br>156473-9         | MTH 06-Feb-2025<br>LDG 0 |                | 22500          | 0              | 22500                      | 22441              |
| 531001                          | NOSE LANDING GEAR (NLG) ACTUATOR SUPPORT FITTING    |      |         | 6511105-1<br>33190313W        | MTH 06-Feb-2025<br>LDG 0 |                | 22500          | 0              | 22500                      | 22441              |
| 551015<br>LEFT UPPER            | LEFT UPPER HORIZONTAL STABILIZER SKIN BOND ASSEMBLY |      |         | 6332000-1<br>1185             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 553003<br>NO. 1                 | NO.1 VERTICAL STABILIZER WEB BOND ASSEMBLY          |      |         | 6331000-1<br>1185             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561001<br>LEFT                  | WINDSHIELD ASSY, (LH)                               |      |         | 93200-15<br>10910             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561001<br>RIGHT                 | WINDSHIELD ASSY, (LH)                               |      |         | 93200-16<br>10837             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>L1                    | CABIN DOOR WINDOW                                   |      |         | 6311123-16<br>10304           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>L2                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>16496         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>L3                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>16495         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>L4                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>16497         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>R1                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>15917         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>R2                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>16498         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>R3                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>16549         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561002<br>R4                    | CABIN WINDOW                                        |      |         | 6311123-11-1<br>15916         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561003<br>PILOT                 | SIDE WINDOW                                         |      |         | 6311263-1<br>10450            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 561004<br>COPILOT               | SIDE WINDOW                                         |      |         | 6311263-2<br>10403            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 571000<br>LEFT AFT              | TRUNNION ATTACH FITTING                             |      |         | 6322070-21<br>34318395A       | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 571000<br>RIGHT AFT             | TRUNNION ATTACH FITTING                             |      |         | 6322070-20<br>33763020K       | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 571001<br>LEFT FORWARD          | TRUNNION ATTACH FITTING                             |      |         | 6322060-19<br>33138329N       | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 571001<br>RIGHT FORWARD         | TRUNNION ATTACH FITTING                             |      |         | 6322060-20<br>3314772H        | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 571002<br>LEFT                  | SIDE BRACE FITTING                                  |      |         | 6322080-25<br>32805930F       | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 571002<br>RIGHT                 | SIDE BRACE FITTING                                  |      |         | 6322080-24<br>33561112P       | MTH 06-Feb-2025<br>LDG 0 |                | 21100          | 0              | 21100                      | 21041              |
| 71-20-00-960<br>LEFT ENGINE AFT | ISOLATOR MOUNT                                      |      |         | LM601SA4<br>LK5018            | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0              | 3500                       | 3432.2             |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position                             | Description<br>Drawing # / Task #    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------|--------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 71-20-00-960<br>LEFT ENGINE<br>FORWARD<br>BOTTOM  | ISOLATOR MOUNT                       |      |         | LM601SA5<br>6774              | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0<br>0         | 3500                       | 3432.2             |
| 71-20-00-960<br>LEFT ENGINE<br>FORWARD TOP        | ISOLATOR MOUNT                       |      |         | LM601SA5<br>6775              | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0<br>0         | 3500                       | 3432.2             |
| 71-20-00-960<br>RIGHT ENGINE<br>AFT               | ISOLATOR MOUNT                       |      |         | LM601SA4<br>LK4994            | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0<br>0         | 3500                       | 3432.2             |
| 71-20-00-960<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM | ISOLATOR MOUNT                       |      |         | LM601SA5<br>6834              | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0<br>0         | 3500                       | 3432.2             |
| 71-20-00-960<br>RIGHT ENGINE<br>FORWARD TOP       | ISOLATOR MOUNT                       |      |         | LM601SA5<br>6833              | MTH 06-Feb-2025<br>HRS 0 |                | 3500           | 0<br>0         | 3500                       | 3432.2             |
| 716000<br>LH                                      | TEMPERATURE SWITCH                   |      |         | 1173T0759<br>9597             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 716000<br>RH                                      | TEMPERATURE SWITCH                   |      |         | 1173T0759<br>9647             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 71EN1<br>NO. 1                                    | ENGINE                               |      |         | 72100-201<br>290779           | MTH 06-Feb-2025          |                | E/C            |                |                            |                    |
| 71EN2<br>NO. 2                                    | ENGINE                               |      |         | 72100-201<br>290780           | MTH 06-Feb-2025          |                | E/C            |                |                            |                    |
| 720007<br>E1                                      | 1ST LP TURBINE NOZZLE                |      |         | 232560<br>51157               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720007<br>E2                                      | 1ST LP TURBINE NOZZLE                |      |         | 126873<br>51196               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720010<br>E1                                      | BALL, DEEP GROOVE - 103 BEARING      |      |         | 78321<br>JT202677             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720010<br>E2                                      | BALL, DEEP GROOVE - 103 BEARING      |      |         | 78321<br>JT202690             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720015<br>E1                                      | BEARING, ROLLER - OUTER GDR ASSEMBLY |      |         | 78301<br>JT211032             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720015<br>E2                                      | BEARING, ROLLER - OUTER GDR ASSEMBLY |      |         | 78301<br>JT210979             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720025<br>E1                                      | BRG, 1ST RDCN RVL GEAR SUPPORT       |      |         | 221987<br>25091               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720025<br>E2                                      | BRG, 1ST RDCN RVL GEAR SUPPORT       |      |         | 221987<br>25049               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720030<br>E1                                      | COMBUSTOR ASSEMBLY                   |      |         | 119448<br>50492               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720030<br>E2                                      | COMBUSTOR ASSEMBLY                   |      |         | 119448<br>50490               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720035<br>E1                                      | DAMPED 1ST RDCN BEVEL GEAR           |      |         | 50349<br>BG7033               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720035<br>E2                                      | DAMPED 1ST RDCN BEVEL GEAR           |      |         | 50349<br>BG7132               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720040<br>E1                                      | HP SHAFT SEAL, FRONT RUNNER          |      |         | 123497<br>SBC-951C4           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720040<br>E2                                      | HP SHAFT SEAL, FRONT RUNNER          |      |         | 123497<br>SBC-955C2           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720045<br>E1                                      | LP TURBINE MODULE ASSY KIT           |      |         | 111748<br>45960               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720045<br>E2                                      | LP TURBINE MODULE ASSY KIT           |      |         | 111748<br>45926               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 720055<br>E1          | REAR, FUEL SLINGER, SEAL ASSEMBLY |      |         | 57882<br>50416                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720055<br>E2          | REAR, FUEL SLINGER, SEAL ASSEMBLY |      |         | 57882<br>50413                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720060<br>E1          | ACCESSORY DRIVE SHAFT             |      |         | 220690<br>ABK2866             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720060<br>E2          | ACCESSORY DRIVE SHAFT             |      |         | 220690<br>ABK2760             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720065<br>E1          | RETAINER, AXIAL CPRSR NUT         |      |         | 45785<br>21904                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720065<br>E2          | RETAINER, AXIAL CPRSR NUT         |      |         | 45785<br>21906                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720070<br>E1 NO. 1    | RING SEAL ASSEMBLY                |      |         | 45075<br>SBC-287D0            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720070<br>E2 NO. 1    | RING SEAL ASSEMBLY                |      |         | 45075<br>SBC-502D8            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720075<br>E1 NO. 2    | RING SEAL ASSEMBLY                |      |         | 45075<br>SBC-502D7            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720075<br>E2 NO. 2    | RING SEAL ASSEMBLY                |      |         | 45075<br>SBC-520D1            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720080<br>E1 NO. 3    | RING SEAL ASSEMBLY                |      |         | 64771<br>SBC-330D2            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720080<br>E2 NO. 3    | RING SEAL ASSEMBLY                |      |         | 64771<br>SBC-317D6            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720085<br>E1          | ROLLER, CYL - OD FLANGE BEARING   |      |         | 78302<br>JT207268             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720085<br>E2          | ROLLER, CYL - OD FLANGE BEARING   |      |         | 78302<br>JT207298             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720090<br>E1          | ROLLER, INNER GUIDED BEARING      |      |         | 79027<br>JT-201165            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720090<br>E2          | ROLLER, INNER GUIDED BEARING      |      |         | 79027<br>JT207785             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720095<br>E1          | STATOR, IP COMPRESSOR VANE        |      |         | 115576<br>50420               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720095<br>E2          | STATOR, IP COMPRESSOR VANE        |      |         | 115576<br>50424               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720100<br>E1          | VANE, FAN STATOR ASSEMBLY         |      |         | 229811<br>50183               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 720100<br>E2          | VANE, FAN STATOR ASSEMBLY         |      |         | 229811<br>50186               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723001<br>E1          | FAN ROTOR                         |      |         | 117810<br>HW77986             | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723001<br>E2          | FAN ROTOR                         |      |         | 117810<br>HW76898             | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723010<br>E1          | HP COMPRESSOR ROTOR               |      |         | 122723<br>HW79342             | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723010<br>E2          | HP COMPRESSOR ROTOR               |      |         | 122723<br>HW79275             | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723015<br>E1          | IP COMPRESSOR ROTOR               |      |         | 66032<br>HW80167              | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723015<br>E2          | IP COMPRESSOR ROTOR               |      |         | 66032<br>HW80168              | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 723022<br>E1          | DIFFUSER CASE ASSEMBLY            |      |         | 123872<br>52102               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723022<br>E2          | DIFFUSER CASE ASSEMBLY            |      |         | 123872<br>52096               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|--------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 723061<br>E1          | HIGH PRESSURE SHAFT                  |      |         | 118924<br>RX23RT4926          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723061<br>E2          | HIGH PRESSURE SHAFT                  |      |         | 118924<br>RX23RT4927          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723092<br>E1          | COMPLETE LP SHAFT ASSEMBLY           |      |         | 121728<br>RX22NG1220          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723092<br>E2          | COMPLETE LP SHAFT ASSEMBLY           |      |         | 121728<br>RX22NG1288          | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723149<br>E1          | HP COMPRESSOR COVER ASSY             |      |         | 69885<br>23577                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723149<br>E2          | HP COMPRESSOR COVER ASSY             |      |         | 69885<br>23394                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723205<br>E1          | CASE AND INSERT ASSEMBLY             |      |         | 235269<br>FRM5257             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723205<br>E2          | CASE AND INSERT ASSEMBLY             |      |         | 235269<br>FRM5418             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723510<br>E1 FRONT    | BRG HSG, BRG LP SHFT ASSEMBLY        |      |         | 50242<br>FL2539               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723510<br>E2 FRONT    | BRG HSG, BRG LP SHFT ASSEMBLY        |      |         | 50242<br>FL2548               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723515<br>E1          | CARBON RING SEAL & BRG RETNR HOUSING |      |         | 76881<br>51002                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723515<br>E2          | CARBON RING SEAL & BRG RETNR HOUSING |      |         | 76881<br>50975                | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723520<br>E1 NO. 1    | FACE,CARBON SEAL ASSEMBLY            |      |         | 57657<br>SBC-108D3            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723520<br>E2 NO. 1    | FACE,CARBON SEAL ASSEMBLY            |      |         | 57657<br>SBC-102D5            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723525<br>E1 NO. 2    | FACE,CARBON SEAL ASSEMBLY            |      |         | 68937<br>SBC-865D3            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723525<br>E2 NO. 2    | FACE,CARBON SEAL ASSEMBLY            |      |         | 68937<br>SBC-865D5            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723530<br>E1          | RUNNER, LP SHAFT, FRONT SEAL         |      |         | 79855<br>SERNO-0578           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723530<br>E2          | RUNNER, LP SHAFT, FRONT SEAL         |      |         | 79855<br>SERNO-0598           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723535<br>E1          | SPLIT INNER RING, BALL BEARING       |      |         | 126276<br>50276               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723535<br>E2          | SPLIT INNER RING, BALL BEARING       |      |         | 126276<br>50265               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723725<br>E1          | BEARING AND PINION ASSEMBLY          |      |         | 125105<br>21913               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 723725<br>E2          | BEARING AND PINION ASSEMBLY          |      |         | 125105<br>21928               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 724035<br>E1          | HP TURBINE ROTOR ASSEMBLY            |      |         | 111386<br>HW79871             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 724035<br>E2          | HP TURBINE ROTOR ASSEMBLY            |      |         | 111386<br>HW82565             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 724045<br>E1          | SEAL AND FUEL SLINGER ASSEMBLY       |      |         | 115471<br>202670              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 724045<br>E2          | SEAL AND FUEL SLINGER ASSEMBLY       |      |         | 115471<br>202652              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 725010<br>E1          | HP TURBINE DISK                      |      |         | 73853<br>HW79871              | MTH 06-Feb-2025<br>LDG 0 |                | 8000           | 0              | (8000)8000                 | 7941               |
| 725010<br>E2          | HP TURBINE DISK                      |      |         | 73853<br>HW82565              | MTH 06-Feb-2025<br>LDG 0 |                | 8000           | 0              | (8000)8000                 | 7941               |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-----------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 725020<br>E1           | 1ST LP TURBINE DISK<br>411        |      |         | 72704<br>HW82632              | MTH 06-Feb-2025<br>LDG 0 |                |                | 0              | (10000)10000               | 9941               |
| 725020<br>E2           | 1ST LP TURBINE DISK<br>411        |      |         | 72704<br>HW79855              | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 725030<br>E1           | 2ND LP TURBINE DISK               |      |         | 66993<br>HW81812              | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 725030<br>E2           | 2ND LP TURBINE DISK               |      |         | 66993<br>HW80017              | MTH 06-Feb-2025<br>LDG 0 |                | 10000          | 0              | (10000)10000               | 9941               |
| 726011<br>E1           | ACCESSORY DRIVE GEARBOX ASSEMBLY  |      |         | 120746<br>22564               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 726011<br>E2           | ACCESSORY DRIVE GEARBOX ASSEMBLY  |      |         | 120746<br>22567               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730001<br>LEFT ENGINE  | FUEL PRESSURE SWITCH              |      |         | 1103P0448<br>13520            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730001<br>RIGHT ENGINE | FUEL PRESSURE SWITCH              |      |         | 1103P0448<br>13524            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732301<br>NO. 1        | ELECTRIC IND-FUEL FILTER          |      |         | 57847<br>GE-12065             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732301<br>NO. 2        | ELECTRIC IND-FUEL FILTER          |      |         | 57847<br>GE-12056             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732500<br>LEFT ENGINE  | FADEC<br>9912680-5                |      |         | 221900<br>200350              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732500<br>RIGHT ENGINE | FADEC<br>9912680-5                |      |         | 221900<br>200306              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 733001<br>LEFT ENGINE  | FUEL FLOW TRANSMITTER             |      |         | 1573-4<br>623                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 733001<br>RIGHT ENGINE | FUEL FLOW TRANSMITTER             |      |         | 1573-4<br>642                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730001<br>E1           | FUEL PRESSURE SWITCH              |      |         | 1103P0448<br>13520            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730001<br>E2           | FUEL PRESSURE SWITCH              |      |         | 1103P0448<br>13524            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730002<br>E1           | FUEL NOZZLE ASSEMBLY<br>115       |      |         | 50817<br>BCC-00015503         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 730002<br>E2           | FUEL NOZZLE ASSEMBLY<br>115       |      |         | 50817<br>BCC-00015091         | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 731040<br>E1           | FUEL MANIFOLD ASSEMBLY            |      |         | 121784<br>23870               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 731040<br>E2           | FUEL MANIFOLD ASSEMBLY            |      |         | 121784<br>23869               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732001<br>E1           | FUEL CONTROL UNIT                 |      |         | 238772<br>71064               | MTH 06-Feb-2025<br>HRS 0 |                | 5000           | 0              | (5000)5000                 | 4932.2             |
| 732001<br>E2           | FUEL CONTROL UNIT                 |      |         | 238772<br>71073               | MTH 06-Feb-2025<br>HRS 0 |                | 5000           | 0              | (5000)5000                 | 4932.2             |
| 732301<br>E1           | ELEC FUEL FILTER INDICATOR        |      |         | 57847<br>GE-12065             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 732301<br>E2           | ELEC FUEL FILTER INDICATOR        |      |         | 57847<br>GE-12056             | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 733001<br>E1           | FUEL FLOW TRANSMITTER             |      |         | 1573-4<br>623                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 733001<br>E2           | FUEL FLOW TRANSMITTER             |      |         | 1573-4<br>642                 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 741010<br>E1 INBOARD   | IGNITION EXCITER                  |      |         | 68145<br>CK-2304773           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 741010<br>E2 INBOARD   | IGNITION EXCITER                  |      |         | 68145<br>CK-2303989           | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task #       | City | Mod Lvl | Part Number<br>Part Serial No          | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-----------------------------------------|------|---------|----------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 741020<br>E1 OUTBOARD  | IGNITION EXCITER                        |      |         | 68145<br>CK-2303014                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 741020<br>E2 OUTBOARD  | IGNITION EXCITER                        |      |         | 68145<br>CK-2304769                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 742201<br>E1 INBOARD   | IGNITOR                                 |      |         | 68032<br>CK-2302384                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 742201<br>E1 OUTBOARD  | IGNITOR                                 |      |         | 68032<br>CK-2301081                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 742201<br>E2 INBOARD   | IGNITOR                                 |      |         | 68032<br>CK-2302385                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 742201<br>E2 OUTBOARD  | IGNITOR                                 |      |         | 68032<br>CK2306526                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 762005<br>E1           | FRT BRG, HP SHAFT HOUSING ASSEMBLY      |      |         | 56195<br>JDM02078                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 762005<br>E2           | FRT BRG, HP SHAFT HOUSING ASSEMBLY      |      |         | 56195<br>JDM02055                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771005<br>E1           | N1 DUAL MAGNETIC SPEED SENSOR           |      |         | 57355<br>HCS2140528                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771005<br>E2           | N1 DUAL MAGNETIC SPEED SENSOR           |      |         | 57355<br>HCS2140524                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771005A<br>E1          | TT2 SENSOR                              |      |         | 114944<br>AXT0205738                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771005A<br>E2          | TT2 SENSOR                              |      |         | 114944<br>AXT0205753                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771015<br>E1           | N2 DUAL MAGNETIC SPEED SENSOR           |      |         | 54831<br>HCS2151174                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 771015<br>E2           | N2 DUAL MAGNETIC SPEED SENSOR           |      |         | 54831<br>HCS2151162                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 772002<br>E1           | ITT HARNESS                             |      |         | 75378<br>EMX005877                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 772002<br>E2           | ITT HARNESS                             |      |         | 75378<br>EMX005879                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 772205<br>E1           | PT2 PRESSURE DUAL SENSOR                |      |         | 113762<br>AXT0104587                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 772205<br>E2           | PT2 PRESSURE DUAL SENSOR                |      |         | 113762<br>AXT0104569                   | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 774405<br>E1           | HARNESS, ENGINE, DUEL CHAN ECU ASSEMBLY |      |         | 219784<br>WS00324                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 774405<br>E2           | HARNESS, ENGINE, DUEL CHAN ECU ASSEMBLY |      |         | 219784<br>WS00269                      | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793002<br>LEFT ENGINE  | OIL TEMPERATURE TRANSMITTER             |      |         | MS28034-3<br>304335                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793002<br>RIGHT ENGINE | OIL TEMPERATURE TRANSMITTER             |      |         | MS28034-3<br>302732                    | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793006<br>LEFT ENGINE  | OIL PRESSURE SWITCH                     |      |         | S1103P89-3<br>5194                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793006<br>RIGHT ENGINE | OIL PRESSURE SWITCH                     |      |         | S1103P89-3<br>5198                     | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793008<br>LEFT         | OIL TRANSDUCER                          |      |         | APTE-598A-1000-<br>200G<br>8987-11-397 | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793008<br>RIGHT        | OIL TRANSDUCER                          |      |         | APTE-598A-1000-<br>200G<br>9080-7-398  | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 792201<br>E1           | LUBE OIL COOLER                         |      |         | 121535<br>PP5291                       | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Components

| Item Code<br>Position        | Description<br>Drawing # / Task #          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|--------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 792201<br>E2                 | LUBE OIL COOLER                            |      |         | 121535<br>PP5298              | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 792401<br>E1                 | LUBE AND SCAVENGE PUMP                     |      |         | 236903<br>50126               | MTH 06-Feb-2025<br>HRS 0 |                | 6000           | 0              | (6000)6000                 | 5932.2             |
| 792401<br>E2                 | LUBE AND SCAVENGE PUMP                     |      |         | 236903<br>50122               | MTH 06-Feb-2025<br>HRS 0 |                | 6000           | 0              | (6000)6000                 | 5932.2             |
| 793006<br>E1                 | OIL PRESSURE SWITCH                        |      |         | S1103P89-3<br>5194            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793006<br>E2                 | OIL PRESSURE SWITCH                        |      |         | S1103P89-3<br>5198            | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793311<br>E1                 | INTERSTAGE HOUSING ASSEMBLY                |      |         | 117626<br>45123               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 793311<br>E2                 | INTERSTAGE HOUSING ASSEMBLY                |      |         | 117626<br>45125               | MTH 06-Feb-2025          |                | O/C            | 0              |                            |                    |
| 80-10-00-960<br>LEFT ENGINE  | LEFT ENGINE STARTER-GENERATOR RESTORATION  |      |         | MG94D-1<br>0633A              | MTH 06-Feb-2025<br>HRS 0 |                | 1000           | 0              | 1000                       | 932.2              |
| 80-10-00-960<br>RIGHT ENGINE | RIGHT ENGINE STARTER-GENERATOR RESTORATION |      |         | MG94D-1<br>0618A              | MTH 06-Feb-2025<br>HRS 0 |                | 1000           | 0              | 1000                       | 932.2              |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Service Bulletins

| Item Code<br>Position        | Description<br>Drawing # / Task #                                                                               | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|-----------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PSID WI-05-1003<br>R03<br>E1 | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>R03<br>E2 | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1173-CN<br>E1       | CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1173-CN<br>E2       | CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198 R01-CN<br>E1   | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL     |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198 R01-CN<br>E2   | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL     |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198 R01<br>E1      | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198 R01<br>E2      | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1198<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208 R01-CN<br>E1   | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL  |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208 R01-CN<br>E2   | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL  |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208 R01<br>E1      | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL             |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208 R01<br>E2      | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL             |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL             |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1208<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL             |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Service Bulletins

| Item Code<br>Position  | Description<br>Drawing # / Task #                                                                             | City | Part Number<br>Mod Lvl | Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|---------------------------------------------------------------------------------------------------------------|------|------------------------|----------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL WI-05-1209<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL           |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-05-1209<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL           |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SB 525-24-33           | ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) DIODE MODIFICATION<br>DISCRETIONARY                           |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| COM MC 525-007<br>R01  | GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES<br>INFORMATIONAL MTH                                        |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| COM MC M2-006<br>R01   | GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES<br>INFORMATIONAL MTH                                        |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SB 525-25-36           | EQUIPMENT/FURNISHINGS - CABIN ACOUSTIC NOISE IMPROVEMENT INSTALLATION<br>OPTIONAL                             |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL 525-27-07 R02       | FLIGHT CONTROLS - AFT ELEVATOR CABLE INSPECTION/REPLACEMENT<br>MANDATORY MTH                                  |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SB 525-34-111          | NAVIGATION - TOLD DATABASE UPDATE<br>RECOMMENDED MTH                                                          |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-70-1008-CN<br>E1 | CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-70-1008-CN<br>E2 | CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-70-1011-CN<br>E1 | CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED      |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-70-1011-CN<br>E2 | CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED      |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-71-1601-CN<br>E1 | CANCELED - POWER PLANT - VIBRATION SURVEY - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED                  |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-71-1601-CN<br>E2 | CANCELED - POWER PLANT - VIBRATION SURVEY - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED                  |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SB WI-72-1172<br>E1    | HIGH PRESSURE TURBINE BLADES - REPLACE<br>MTH                                                                 |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SB WI-72-1172<br>E2    | HIGH PRESSURE TURBINE BLADES - REPLACE<br>MTH                                                                 |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-72-1418-CN<br>E1 | CANCELED-ENGINE - REAR HOUSING ASSEMBLY - REVISION TO ENGINE MANUAL<br>CANCELLED                              |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |
| SL WI-72-1418-CN<br>E2 | CANCELED-ENGINE - REAR HOUSING ASSEMBLY - REVISION TO ENGINE MANUAL<br>CANCELLED                              |      |                        |                |                          |                |                |                |                            |                    |
|                        |                                                                                                               |      |                        |                |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                                                  |      |                        |                |                          |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Service Bulletins

| Item Code                    | Description                                                                                                              | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position                     | Drawing # / Task #                                                                                                       | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SB 525-73-05                 | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) ADAPTER REPLACEMENT                                                    |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            | OPTIONAL       | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB FJ44-73-044<br>R11<br>E1  | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB FJ44-73-044<br>R11<br>E2  | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R02<br>E1 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R02<br>E2 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R03<br>E1 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            | INFORMATIONAL  |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R03<br>E2 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            | INFORMATIONAL  |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R04<br>E1 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| PSID WI-73-1031<br>R04<br>E2 | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION                                             |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1032-CN<br>E1       | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01 (SUPERSEDED BY WISB-73-1042) |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            | SUPERSEDED     |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1032-CN<br>E2       | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01 (SUPERSEDED BY WISB-73-1042) |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            | SUPERSEDED     |            |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1040 R01<br>E1      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1040 R01<br>E2      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1040 R02<br>E1      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1040 R02<br>E2      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                   |             |            |                |            |        |             |         |             |         |
|                              |                                                                                                                          |             |            |                | MTH        |        | -           |         |             |         |
|                              | MOC :                                                                                                                    |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Service Bulletins

| Item Code                                                                                                                                                               | Description        | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                                                                                                                | Drawing # / Task # | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SB WI-73-1040 R03 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                                                |                    |             |            |                |            |        |             |         |             |         |
| E1                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1040 R03 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                                                                                |                    |             |            |                |            |        |             |         |             |         |
| E2                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1042 R01 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01                                                           |                    |             |            |                |            |        |             |         |             |         |
| E1                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SB WI-73-1042 R01 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01                                                           |                    |             |            |                |            |        |             |         |             |         |
| E2                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SL WI-73-1084-CN CANCELED - ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL |                    |             |            |                |            |        |             |         |             |         |
| E1                                                                                                                                                                      |                    |             |            | CANCELLED      |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SL WI-73-1084-CN CANCELED - ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL |                    |             |            |                |            |        |             |         |             |         |
| E2                                                                                                                                                                      |                    |             |            | CANCELLED      |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SL WI-73-1095 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REVISION TO LINE MAINTENANCE MANUAL                                                                        |                    |             |            |                |            |        |             |         |             |         |
| E1                                                                                                                                                                      |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SL WI-73-1095 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REVISION TO LINE MAINTENANCE MANUAL                                                                        |                    |             |            |                |            |        |             |         |             |         |
| E2                                                                                                                                                                      |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SB WI-74-1000 R01 IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT                                                                                           |                    |             |            |                |            |        |             |         |             |         |
| E1                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| SB WI-74-1000 R01 IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT                                                                                           |                    |             |            |                |            |        |             |         |             |         |
| E2                                                                                                                                                                      |                    |             |            | MTH            |            |        | -           |         |             |         |
| MOC :                                                                                                                                                                   |                    |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                    | Description<br>Drawing # / Task #                                                                                                                                                                                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2             | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1998-25-02                                                                                                                                                                                                           | APPLIANCE AD - INCORPORATING INFORMATION INTO THE AIRPLANE FLIGHT MANUAL (AFM) THAT SPECIFIES VERIFYING THE CORRECT ANTENNA CONFIGURATION EACH TIME AN AIRCRAFT EQUIPPED WITH A SKY497 INSTALLATION WITH A TOP-MOUNTED ANTENNA IS POWERED-UP |      |         |                               | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
|                                                                                                                                                                                                                          |                                                                                                                                                                                                                                              | KICT |         | MANDATORY                     |                                      |                |                |                |                            |                    |
| <b>MOC :</b> NOT APPLICABLE - FAA AD 1998-25-02, EFFECTIVE DATE DEC 22, 1998; BF GOODRICH AVIONICS SYSTEMS, INC. SKYWATCH SKY497 INSTALLATIONS WITH A TOP-MOUNTED ANTENNA. AD DOES NOT APPLY, PART NUMBER NOT INSTALLED. |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2006-16-18<br>R01 PARA (F)                                                                                                                                                                                           | INSTALL PLACARD                                                                                                                                                                                                                              | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO FAA 2006-16-18R1 SANDEL AVIONICS INC. - PLACARD INSTALLATION / AFM CHANGE / SOFTWARE UPDATE NOT INSTALLED ON THIS AIRCRAFT.                                          |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2006-16-18<br>R01 PARA (G)                                                                                                                                                                                           | REVISE AIRPLANE FLIGHT MANUAL (AFM)                                                                                                                                                                                                          | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO FAA 2006-16-18R1 SANDEL AVIONICS INC. - PLACARD INSTALLATION / AFM CHANGE / SOFTWARE UPDATE NOT INSTALLED ON THIS AIRCRAFT.                                          |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2006-16-18<br>R01 PARA (H)                                                                                                                                                                                           | UPDATE SOFTWARE                                                                                                                                                                                                                              | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO FAA 2006-16-18R1 SANDEL AVIONICS INC. - PLACARD INSTALLATION / AFM CHANGE / SOFTWARE UPDATE NOT INSTALLED ON THIS AIRCRAFT.                                          |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2006-16-18<br>R01                                                                                                                                                                                                    | APPLIANCE AD - INSTALL UPGRADED SOFTWARE IN THE TAWS/RMI                                                                                                                                                                                     | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO FAA 2006-16-18R1 SANDEL AVIONICS INC. - PLACARD INSTALLATION / AFM CHANGE / SOFTWARE UPDATE NOT INSTALLED ON THIS AIRCRAFT.                                          |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2013-08-05<br>PARA (G)                                                                                                                                                                                               | INSPECTION A/C COMPRESSOR HOUR METER                                                                                                                                                                                                         | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN RANGE LISTED ON FAA 2013-08-05 REPLACEMENT OF THE BRUSHES ON (P/N) 1134104-1 OR 1134104-5 AIR CONDITIONING (A/C) COMPRESSOR MOTOR.     |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2013-08-05<br>PARA (H)                                                                                                                                                                                               | REPLACE THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES                                                                                                                                                                       | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN RANGE LISTED ON FAA 2013-08-05 REPLACEMENT OF THE BRUSHES ON (P/N) 1134104-1 OR 1134104-5 AIR CONDITIONING (A/C) COMPRESSOR MOTOR.     |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2013-08-05<br>PARA (I)                                                                                                                                                                                               | DEACTIVATION OF THE AIR CONDITIONING                                                                                                                                                                                                         | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN RANGE LISTED ON FAA 2013-08-05 REPLACEMENT OF THE BRUSHES ON (P/N) 1134104-1 OR 1134104-5 AIR CONDITIONING (A/C) COMPRESSOR MOTOR.     |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2013-08-05<br>PARA (J)                                                                                                                                                                                               | RETURN OF REPLACED PARTS AND REPORTING REQUIREMENT                                                                                                                                                                                           | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN RANGE LISTED ON FAA 2013-08-05 REPLACEMENT OF THE BRUSHES ON (P/N) 1134104-1 OR 1134104-5 AIR CONDITIONING (A/C) COMPRESSOR MOTOR.     |                                                                                                                                                                                                                                              |      |         |                               |                                      |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Description<br>Drawing # / Task #                                                                                                                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2             | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2013-08-05                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM                                                                  | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN RANGE LISTED ON FAA 2013-08-05 REPLACEMENT OF THE BRUSHES ON (P/N) 1134104-1 OR 1134104-5 AIR CONDITIONING (A/C) COMPRESSOR MOTOR.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2001-02-13                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | ELECTRICAL POWER - REPLACE CERTAIN DIRECT CURRENT (DC) POWER BATTERY SWITCHES                                                                                                         | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE. THIS AMENDMENT ADOPTS A NEW AIRWORTHINESS DIRECTIVE (AD) THAT APPLIES TO CERTAIN THE CESSNA AIRCRAFT COMPANY (CESSNA) MODEL 525 (CITATION JET 1) AIRPLANES. THIS AD REQUIRES REPLACEMENT OF CERTAIN DIRECT CURRENT (DC) POWER BATTERY SWITCHES. THIS AD IS THE RESULT OF REPORTS OF THE POTENTIAL FOR A CERTAIN 8-POLE BATTERY SWITCH TO FAIL DURING FLIGHT. THE ACTIONS SPECIFIED BY THIS AD ARE INTENDED TO PREVENT THIS BATTERY SWITCH FROM FAILING WHILE THE AIRPLANE IS IN-FLIGHT, WHICH IS A LATENT FAILURE. THIS COULD RESULT IN THE PILOT'S INABILITY TO SELECT "EMER" POWER OR THE INABILITY TO DISCONNECT AN OVERHEATED MAIN SHIP'S BATTERY. NOT APPLICABLE DUE TO AIRCRAFT SERIAL EFFECTIVITY. |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2024-26-02<br>PARA (G)(1)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE                                                                      |      |         | MANDATORY                     | MTH                                  |                | 6              |                | 07-Sep-2025                | -2 d               |
| <b>MOC :</b> <b>Over Due</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2024-26-02<br>PARA (G)(2)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE |      |         | MANDATORY                     | MTH                                  |                | 12             |                | 07-Mar-2026                | 5 m 26 d           |
| <b>MOC :</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2024-26-02<br>PARA (G)(3)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER                             |      |         | MANDATORY                     | MTH                                  |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2024-26-02                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT                                                                 |      |         | MANDATORY                     | MTH                                  |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| LBA D-2021-127<br>R01                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | PACIFIC SCIENTIFIC COMPANY: ROTARY BUCKLE ASSEMBLIES - INSPECTION / REPLACEMENT                                                                                                       |      |         | MANDATORY                     | MTH                                  |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2005-17-11                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | FIRE PROTECTION - INSTALL IDENTIFICATION SLEEVES ON THE WIRING FOR BOTH ENGINE FIRE EXTINGUISHER BOTTLES                                                                              | KICT |         | MANDATORY                     | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD EFFECTIVE OCT 7, 2005; AD REQUIRES INSTALLATION OF ID SLEEVES ON ENGINE FIRE BOTTLES TO PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES. AD DOES NOT APPLY DUE TO AIRCRAFT MODEL AND SERIAL EFFECTIVITY.                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |
| FAA 2004-14-20                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | FLIGHT CONTROLS - REMOVE AND REPLACE AN OLD TRIM PCB ASSEMBLY WITH A NEW DESIGN ASSEMBLY OR MODIFY AN OLD TRIM PCB ASSEMBLY TO THE NEW DESIGN                                         | KICT |         | MANDATORY                     | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - THE FAA SUPERSEDES AIRWORTHINESS DIRECTIVE (AD) 2003-21-07, WHICH APPLIES TO CERTAIN THE CESSNA AIRCRAFT COMPANY (CESSNA) MODEL 525 AIRPLANES. AD 2003-21-07 CURRENTLY REQUIRES YOU TO DISENGAGE THE PITCH TRIM CIRCUIT BREAKER AND AP SERVO CIRCUIT BREAKER AND THEN TIE STRAP EACH OF THEM TO PREVENT THEM FROM BEING ENGAGED. THIS AD IS THE RESULT OF CESSNA HAVING NOW DEVELOPED AND MADE CHANGES IN THE DESIGN OF THE AFFECTED TRIM PRINTED CIRCUIT BOARD (PCB) ASSEMBLY TO ALLOW THE USE OF THE ASSEMBLY AND THE PREVENTION OF THE SINGLE-POINT FAILURE, AND IDENTIFICATION OF ADDITIONAL AIRPLANES THAT HAVE THE SAME UNSAFE CONDITION.                                                                           |                                                                                                                                                                                       |      |         |                               |                                      |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Airworthiness Directives

| Item Code                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Description                                                                                                                                                                                                                                                                                                                      | Part Number | C/W Time 1 | Adj.                                 | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|--------------------------------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Drawing # / Task #                                                                                                                                                                                                                                                                                                               | City        | Mod Lvl    | Part Serial No                       | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| FAA 2020-24-06                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM – DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT                                                                                                                                                                                        | KICT        | MANDATORY  | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - FAA 2020-24-06 EFFECTIVE DATE DECEMBER 28, 2020; THIS AD SUPERSEDES AD 2019-08-13. TEXTRON AVIATION, INC. MODELS 525, 525A AND 525B AIRPLANES,CERTIFICATED IN ANY CATEGORY, WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY.AD DOES NOT APPLY. PARTS NOT INSTALLED. NO FURTHER ACTION REQUIRED.                                                                                                              |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |
| FAA 2024-15-09                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE                                                                                                                                   | KICT        | MANDATORY  | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - FAA 2024-15-09, EFFECTIVE OCTOBER 22, 2024, REQUIRES INSTALLING PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) ANDREVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE. THE FAA IS ISSUING THIS AD TO ADDRESS THE UNSAFE CONDITION ON THESE PRODUCTS.AD NOT APPLICABLE DUE TO PARTS NOT INSTALLED ON AIRCRAFT.                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |
| FAA 1997-01-02                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | LANDING GEAR - REPETITIVELY INSPECTING THE MLG TRUNNION PINS FOR PROPER INSTALLATION, AND EITHER IMMEDIATELY OR EVENTUALLY REPLACING THE EXISTING DRY-FILM LUBRICATED MLG TRUNNION SLOT BEARINGS WITH SEALED AND SELF-LUBRICATING BEARINGS                                                                                       | KICT        | MANDATORY  | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - THIS AMENDMENT ADOPTS A NEW AIRWORTHINESS DIRECTIVE (AD) THAT APPLIES TO CERTAIN CESSNA AIRCRAFT COMPANY (CESSNA) MODEL 525 AIRPLANES. THIS ACTION REQUIRES REPETITIVELY INSPECTING THE MAIN LANDING GEAR (MLG) TRUNNION PINS FOR PROPER INSTALLATION, AND EITHER IMMEDIATELY OR EVENTUALLY REPLACING THE EXISTING DRY FILM LUBRICATED MLG TRUNNION SLOT BEARINGS WITH SEALED AND SELF-LUBRICATING BEARINGS.NOT APPLICABLE DUE TO AIRCRAFT SERIAL EFFECTIVITY.                                        |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |
| FAA 1997-05-03<br>R01                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | APPLIANCE AD - INSERTING A LIMITATION INTO THE OPERATIONS LIMITATION SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) OR FLIGHT MANUAL SUPPLEMENT FOR ALL OWNERS/OPERATORS OF AIRCRAFT EQUIPPED WITH AN ALLIEDSIGNAL AVIONICS, INC. (ALLIEDSIGNAL) MODELS GNS-XLS OR GNS-XL GLOBAL POSITIONING SYSTEMS (GPS) FLIGHT MANAGEMENT SYSTEM | KICT        | MANDATORY  | DAYS 06-Feb-2025<br>HRS 6.7<br>LDG 4 | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE, AD1997-05-03R1, EFFECTIVE APRIL 20, 1999, REQUIRES INSERTING A LIMITATION INTO THE OPERATIONS LIMITATION SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) OR FLIGHT MANUAL SUPPLEMENTFOR ALL OWNERS/OPERATORS OF AIRCRAFT EQUIPPED WITH AN ALLIEDSIGNAL AVIONICS, INC. (ALLIEDSIGNAL) MODELS GNS-XLS OR GNS-XL GLOBAL POSITIONING SYSTEMS (GPS) FLIGHT MANAGEMENT SYSTEM.NOT APPLICABLE- PARTS NOT INSTALLED                                                                               |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |
| FAA 2001-23-17                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | APPLIANCE AD - NAVIGATION - MODIFY THE UNIT TO INCORPORATE CIRCUITRY CHANGES TO THE GNS 430 UNIT'S DEVIATION AND FLAG OUTPUTS                                                                                                                                                                                                    | KICT        | MANDATORY  | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE. THIS AMENDMENT ADOPTS A NEW AIRWORTHINESS DIRECTIVE (AD) THAT APPLIES TO CERTAIN GARMIN INTERNATIONAL (GARMIN) GNS 430 UNITS THAT ARE INSTALLED ON AIRCRAFT.THIS AD REQUIRES YOU TO MODIFY THE UNIT TO INCORPORATE CIRCUITRY CHANGES TO THE GNS 430 UNIT'S DEVIATION AND FLAG OUTPUTS.THIS AD IS THE RESULT OF REPORTS OF INACCURATE COURSE DEVIATIONS CAUSED BY EXTERNAL ELECTRICAL NOISE TO THE GNS 430 UNIT'S COURSE DEVIATION INDICATOR (CDI)                                     |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |
| FAA 2002-20-09                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | APPLIANCE AD - NAVIGATION - INSPECT THE AFD-3010 UNIT TO DETERMINE IF IT CONTAINS AN MFP386 APPLICATION SPECIFIC INTEGRATED CIRCUIT (ASIC) DEVICE WITH A DATE CODE OF 0128                                                                                                                                                       | KICT        | MANDATORY  | MTH 06-Feb-2025<br>HRS 6.7<br>LDG 4  | -          |        |             |         |             | N/A     |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE. THIS AMENDMENT ADOPTS A NEW AIRWORTHINESS DIRECTIVE (AD) THAT APPLIES TO CERTAIN ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) AFD-3010 ADAPTIVE FLIGHT DISPLAYUNITS THAT ARE INSTALLED ON AIRCRAFT. THIS AD REQUIRES YOU TO INSPECT THE AFD-3010 UNIT TO DETERMINE IF IT CONTAINS AN MFP386 APPLICATION SPECIFIC INTEGRATED CIRCUIT (ASIC) DEVICewith a DATE CODE OF 0128. THIS AD ALSO REQUIRES YOU TO HAVE ANY AFD-3010 UNITS WITH AN MFP386 DEVICE WITH A DATE CODE OF 0128 MODIFIED. |                                                                                                                                                                                                                                                                                                                                  |             |            |                                      |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **UP AV LLC**  
Aircraft Model: **525-CITATION M2**  
Aircraft Serial: **525-1185**  
Unit: Reg No: **N4687K**  
Airworthiness: **06-Feb-2025**  
Print Date: **09-Sep-2025 11:14AM**

| Tracking Rate   | Hours       | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|-------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 1</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |
| <b>ENG 2</b>    | <b>67.8</b> | <b>59</b>           | <b>01-Sep-2025</b>  | <b>.15</b>                   |

### Airworthiness Directives

| Item Code                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | Description                                                                                                                                                                                                                                                                                                      | Part Number | C/W Time 1 | Adj.           | TBO 1       | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|-------------|--------|-------------|---------|-------------|---------|
| Position                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Drawing # / Task #                                                                                                                                                                                                                                                                                               | City        | Mod Lvl    | Part Serial No | C/W Time 2  | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| FAA 2004-08-15                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | APPLIANCE AD - NAVIGATION - INSPECT THE TAWS INSTALLATION AND REMOVE ANY TAWS WHERE BOTH THE TAWS AND ANY OTHER DEVICE ARE CONNECTED TO THE SAME BARO SET POTENTIOMETER                                                                                                                                          | KICT        | MANDATORY  | MTH            | 06-Feb-2025 | -      |             |         |             | N/A     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | HRS            | 6.7         |        |             |         |             |         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | LDG            | 4           |        |             |         |             |         |
| MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO FAA 2004-08-15 GOODRICH AVIONICS SYSTEMS, INC. - TERRAIN AWARENESS WARNING SYSTEM NOT INSTALLED ON THIS AIRCRAFT.                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                                                                                                                                                  |             |            |                |             |        |             |         |             |         |
| FAA 2014-18-01                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION                                                                                                                                                                                                               | KICT        | MANDATORY  | MTH            | 06-Feb-2025 | -      |             |         |             | N/A     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | HRS            | 6.7         |        |             |         |             |         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | LDG            | 4           |        |             |         |             |         |
| MOC : NOT APPLICABLE - NOT APPLICABLE. AD2014-18-01, EFFECTIVE OCTOBER 14, 2014, AD WAS PROMPTED BY INSTANCES WHERE THE TDR-94 AND TDR-94D MODE S TRANSPONDERS DID NOT PROPERLY RESPOND TO MODE S ONLY ALL-CALL INTERROGATIONS WHEN THE AIRPLANE TRANSITIONED FROM A GROUND TO AIRBORNE STATE. AD DOES NOT APPLY DUE TO AIRCRAFT SERIAL EFFECTIVITY.                                                                                                                                      |                                                                                                                                                                                                                                                                                                                  |             |            |                |             |        |             |         |             |         |
| FAA 2021-08-15                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE                                                                                                                                                                                       | KICT        | MANDATORY  | MTH            | 06-Feb-2025 | -      |             |         |             | N/A     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | HRS            | 6.7         |        |             |         |             |         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | LDG            | 4           |        |             |         |             |         |
| MOC : NOT APPLICABLE - FAA2021-08-15, ACCOMPLISHED AD2021-08-15, EFFECTIVE MAY 17, 2021, REQUIRES UPDATING SOFTWARE VERSION OF THE AFFECTED GTS PROCESSOR UNITS ( GTS825, GTS855, GTS800 ).GTS 800 PROCESSOR INSTALLED.GARMIN SOFTWARE VERSION 4.8.16 OR HIGHER HAS BEEN LOADED. NO FURTHER ACTION REQUIRED.                                                                                                                                                                              |                                                                                                                                                                                                                                                                                                                  |             |            |                |             |        |             |         |             |         |
| FAA 2008-03-10                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | FUSELAGE - INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE | KICT        | MANDATORY  | DAYS           | 06-Feb-2025 | -      |             |         |             | N/A     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | HRS            | 6.7         |        |             |         |             |         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | LDG            | 4           |        |             |         |             |         |
| MOC : NOT APPLICABLE - NOT APPLICABLE: FAA2008-03-10 FUSELAGE LOWER SKIN INSPECT DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER. EFFECTIVE MAR. 11, 2008 INSPECT LOWER WING SKIN FOR CORROSION.INSPECT THE LOWER WING SKIN, STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS AND EXTERNAL FAIRING FRAMES FOR CORROSION. REPAIR ANY DAMAGE FOUND.APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE RE INSTALLING; AND DISABLE THE COCKPIT MOUNTED RELIEF TUBE. |                                                                                                                                                                                                                                                                                                                  |             |            |                |             |        |             |         |             |         |
| FAA 2008-12-01                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | POWER PLANT - INSPECT FOR MISSING FIREWALL SEALANT BETWEEN THE AFT FIREWALL ASSEMBLY AND SEAL ASSEMBLY                                                                                                                                                                                                           | KICT        | MANDATORY  | DAYS           | 06-Feb-2025 | -      |             |         |             | N/A     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | HRS            | 6.7         |        |             |         |             |         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                  |             |            | LDG            | 4           |        |             |         |             |         |
| MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT IN THE EFFECTED RANGE OF FAA 2008-12-01 MISSING FIREWALL SEALANT.                                                                                                                                                                                                                                                                                                                                                 |                                                                                                                                                                                                                                                                                                                  |             |            |                |             |        |             |         |             |         |