



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052506B	INSPECT NOAA 406 MHZ ELT REGISTRATION KDTO				MTH 08-Jul-2024 HRS 2045.4 LDG 1544		24		31-Jul-2026	10 m 9 d
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (GTx345(D)R TEST) KICT				MTH 24-Jul-2024 HRS 2049.7 LDG 1547		24		31-Jul-2026	10 m 9 d
0534NXIV	VISUAL INSPECTION G1000 NXI EQUIPMENT/ACCESSORIES/WIRING HARNESS KICT				MTH 24-Jul-2024 HRS 2049.7 LDG 1547		1350		3399.7	1124
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK						A/R			
055002	ACCOMPLISH OVERSPEED CHECK						A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK						A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK						A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK						A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK						A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK						A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK						A/R			
5-12-01	INSPECTION DOCUMENT 01 KDTO				MTH 08-May-2024 HRS 2038.8 LDG 1541		450		2488.8	213.1
5-12-02	INSPECTION DOCUMENT 02 KDAL				MTH 21-May-2020 HRS 1618.7 LDG 1248		900		2518.7	243
5-12-03	INSPECTION DOCUMENT 03 KDAL				MTH 17-Jan-2018 HRS 1356.2 LDG 1059 ACH 506.2		1350		2706.2	430.5
5-12-04	INSPECTION DOCUMENT 04 KDAL				MTH 21-May-2020 HRS 1618.7 LDG 1248		1800		3418.7	1143
5-12-05	INSPECTION DOCUMENT 05				MTH 31-Jul-2012 HRS 0		3150		3150	874.3
5-12-06	INSPECTION DOCUMENT 06 KBJC				MTH 23-Jun-2025 HRS 2263.4 LDG 1665		12		30-Jun-2026	9 m 8 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK) KBJC			C352CS E-92812063	MTH 23-Jun-2025 HRS 2263.4 LDG 1665		12		30-Jun-2026	9 m 8 d
5-12-07	INSPECTION DOCUMENT 07 KDTO				MTH 08-May-2024 HRS 2038.8 LDG 1541		24		31-May-2026	8 m 9 d



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
					MTH 31-Jul-2012		60			
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)									
		KDAL		30401102-2	MTH 14-Jun-2022	-29	60		31-May-2027	20 m 9 d
				67573B1						
Hydro Check Date: 14-Jun-2022										
5-12-11	INSPECTION DOCUMENT 11									
		KDTO			MTH 08-May-2024		72		31-May-2030	56 m 9 d
					HRS 2038.8					
					LDG 1541					
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)									
		KDTO		C352CS	MTH 08-May-2024		72		31-May-2030	56 m 9 d
				E-92812063	HRS 2038.8					
					LDG 1541					
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
					MTH 31-Jul-2012		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)									
		KDAL		C352CS	MTH 21-May-2018		144		21-May-2030	55 m 29 d
				E-92812063						
Hydro Check Date: 21-May-2018										
5-12-13	INSPECTION DOCUMENT 13									
		KBJC			MTH 23-Jun-2025		12		30-Jun-2026	9 m 8 d
					HRS 2263.4		450		2713.4	437.7
					LDG 1665					
5-12-14	INSPECTION DOCUMENT 14									
		KBJC			MTH 23-Jun-2025		12		30-Jun-2026	9 m 8 d
					HRS 2263.4		900		3163.4	887.7
					LDG 1665					
5-12-15	INSPECTION DOCUMENT 15									
		KDTO			MTH 08-May-2024		24		31-May-2026	8 m 9 d
					HRS 2038.8		1350		3388.8	1113.1
					LDG 1541					
5-12-16	INSPECTION DOCUMENT 16									
		KDTO			MTH 08-May-2024		36		31-May-2027	20 m 9 d
					HRS 2038.8		1350		3388.8	1113.1
					LDG 1541					
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK 29-10-00-720									
		KDTO		9912652-2	MTH 08-May-2024		36		31-May-2027	20 m 9 d
				021B	HRS 2038.8		1350		3388.8	1113.1
					LDG 1541					
5-12-17	INSPECTION DOCUMENT 17									
		KDTO			MTH 08-May-2024		36		31-May-2027	20 m 9 d
					HRS 2038.8		1800		3838.8	1563.1
					LDG 1541					
5-12-18	INSPECTION DOCUMENT 18									
		KDTO			MTH 08-May-2024		36		31-May-2027	20 m 9 d
					HRS 2038.8		2250		4288.8	2013.1
					LDG 1541					
5-12-20	INSPECTION DOCUMENT 20									
		KDTO			MTH 08-May-2024		48		31-May-2028	32 m 9 d
					HRS 2038.8		2700		4738.8	2463.1
					LDG 1541					
5-12-21	INSPECTION DOCUMENT 21									
		KBJC			MTH 23-Jun-2025		12		30-Jun-2026	9 m 8 d
					HRS 2263.4					
					LDG 1665					
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
		KDTO			MTH 02-May-2024		24			
					HRS 2038.8					
					LDG 1541					
B341001	CALIBRATION TEST INDICATOR 14 CFR PART 91.411									
AIRSPEED		KBJC		261440-1143	MTH 13-Aug-2024		24		31-Aug-2026	11 m 9 d
				291097A						
Calibration Date: 13-Aug-2024										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 1	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KDTO		011-01110-01 1SW005597	MTH 02-May-2024		24		31-May-2026	8 m 9 d
Calibration Date: 02-May-2024										
B341001 NO. 2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KDTO		011-01110-01 1SW005596	MTH 02-May-2024		24		31-May-2026	8 m 9 d
Calibration Date: 02-May-2024										
B341001 STANDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	KDTO		162350-1161 181375C	MTH 02-May-2024		24		31-May-2026	8 m 9 d
Calibration Date: 02-May-2024										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	KDTO			MTH 02-May-2024		24		31-May-2026	8 m 9 d
B345000 LEFT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KDTO		011-00779-21 84810405	MTH 02-May-2024		24		31-May-2026	8 m 9 d
Calibration Date: 02-May-2024										
B345000 RIGHT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KICT		010-01776-03 51Y001742	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		24		31-Jul-2026	10 m 9 d
Calibration Date: 24-Jul-2024										
5-12-23	INSPECTION DOCUMENT 23 (NOT USED)				MTH 31-Jul-2012		N/R			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KDAL		3-1640 0974	MTH 20-May-2020 HRS 1618.7 LDG 1248		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	KICT		3-1642 0136	MTH		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KDAL		3-1640 0979	MTH 20-May-2020 HRS 1618.7 LDG 1248		A/R			
5-12-30	INSPECTION DOCUMENT 30	KDTO			MTH 08-May-2024 HRS 2038.8 LDG 1541		48 1800		31-May-2028 3838.8	32 m 9 d 1563.1
5-12-31	INSPECTION DOCUMENT 31	KDTO			MTH 12-Jun-2023 HRS 1979.9 LDG 1504		450		2429.9	154.2
5-12-32	INSPECTION DOCUMENT 32	KDTO			MTH 08-May-2024 HRS 2038.8 LDG 1541		72 1800		31-May-2030 3341	56 m 9 d 1670
5-12-34	INSPECTION DOCUMENT 34 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK			MTH 21-Jul-2025 HRS 2275.7 LDG 1671		6 450			
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK)	UNK		7639-30 G03202402	MTH 21-Jul-2025 HRS 2275.7 LDG 1671	-18	6 450		31-Jan-2026 2725.7	4 m 9 d 450
5-12-35	INSPECTION DOCUMENT 35	KBJC			MTH 23-Jun-2025 HRS 2263.4 LDG 1665		6		31-Dec-2025	3 m 9 d



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-37	INSPECTION DOCUMENT 37 KDAL			MTH HRS LDG	21-May-2018 1409.6 1102		7200		8609.6	6333.9
5-12-MA	INSPECTION DOCUMENT MA KDTO			MTH HRS LDG	12-Jun-2023 1979.9 1504		500		2479.9	204.2
5-12-MB	INSPECTION DOCUMENT MB KDAL			MTH HRS LDG	21-May-2020 1618.7 1248		950		2568.7	293
5-12-MC	INSPECTION DOCUMENT MC			MTH HRS	31-Jul-2012 0		4000		4000	1724.3
5-12-MD	INSPECTION DOCUMENT MD KBJC			MTH HRS LDG	23-Jun-2025 2263.4 1665		12		30-Jun-2026	9 m 8 d
5-12-ME	INSPECTION DOCUMENT ME KDTO			MTH HRS LDG	08-May-2024 2038.8 1541		36 1400		31-May-2027 3438.8	20 m 9 d 1163.1
5-12-MF	INSPECTION DOCUMENT MF			MTH HRS	31-Jul-2012 0		12000		12000	9724.3
A551001	INSPECT/SURFACE EDDY CURRENT HORIZONTAL STABILIZER FRONT SPAR UPPER FLANGE AND SPLICE STRAPS (BL 0.00 - BL 6.00)			MTH HRS	31-Jul-2012 0		12000		12000	9724.3
5-12-MG	INSPECTION DOCUMENT MG			MTH HRS	31-Jul-2012 0		5000		5000	2724.3
5-12-MH	INSPECTION DOCUMENT MH			MTH HRS	31-Jul-2012 0		8250		8250	5974.3
5-12-MI	INSPECTION DOCUMENT MI			MTH HRS	31-Jul-2012 0		12000		12000	9724.3
5-12-MJ	INSPECTION DOCUMENT MJ			MTH HRS	31-Jul-2012 0		10600		10600	8324.3
5-12-MK	INSPECTION DOCUMENT MK			MTH HRS	31-Jul-2012 0		10400		10400	8124.3
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE			MTH	31-Jul-2012		A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH KDAL			DAYS HRS LDG	06-May-2019 1540.1 1202		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH KDAL			DAYS HRS LDG	06-May-2019 1540.1 1202		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH KDAL			DAYS HRS LDG	06-May-2019 1540.1 1202		A/R			
0521009	ENVIRO SYSTEMS 500 HOUR INSPECTION KDAL			MTH HRS LDG ACH	21-May-2020 1618.7 1248 622.8		500		1122.8	307
0521009A	ENVIRO SYSTEMS 12 MONTH INSPECTION KBJC			MTH HRS LDG	23-Jun-2025 2263.4 1665		12		30-Jun-2026	9 m 8 d
262003A LEFT	REPLACE FIRE EXT CARTRIDGE KDAL			MTH HRS LDG	17-Jun-2022 1849.3 1417		72		30-Jun-2028	33 m 8 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003A RIGHT	REPLACE FIRE EXT CARTRIDGE KDAL			13083-5 09132027	MTH 17-Jun-2022 HRS 1849.3 LDG 1417		72		30-Jun-2028	33 m 8 d
32-30-40-960	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST) KDTO			40005369-2 9359	MTH 22-Dec-2022		36		31-Dec-2025	3 m 9 d
Hydro Check Date: 22-Dec-2022										
32-40-00-960	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST) KDTO			40005399-1 7285	MTH 22-Dec-2022		36		31-Dec-2025	3 m 9 d
Hydro Check Date: 22-Dec-2022										
35-00-00-960	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST KDAL			4441073-040 695979008	MTH 28-May-2021		60		31-May-2026	8 m 9 d
Hydro Check Date: 28-May-2021										
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION KBJC				MTH 23-Jun-2025 HRS 2263.4 LDG 1665		12 450		30-Jun-2026 (2663.2)2713.4	9 m 8 d 437.7
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION KBJC				MTH 23-Jun-2025 HRS 2263.4 LDG 1665		12 450		30-Jun-2026 (2663.2)2713.4	9 m 8 d 437.7
710010 E1	COMPRESSOR DESALINATION WASH ICT				MTH 12-Jun-2013 HRS 499.8 LDG 394		A/R			
710010 E2	COMPRESSOR DESALINATION WASH ICT				MTH 12-Jun-2013 HRS 499.8 LDG 394		A/R			
710010B E1	DESALINIZATION / FRESH WATER RINSE KICT				MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C			
710010B E2	DESALINIZATION / FRESH WATER RINSE KICT				MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 31-Jul-2012		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 31-Jul-2012		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR) KDTO				MTH 28-May-2024 HRS 2038.8 LDG 1541		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR) KDTO				MTH 28-May-2024 HRS 2038.8 LDG 1541		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 31-Jul-2012		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 31-Jul-2012		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-620-805-01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-805-01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-805-02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-805-02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-806-01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	31-Jul-2012		A/R			
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	31-Jul-2012		A/R			
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	31-Jul-2012		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	31-Jul-2012		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	31-Jul-2012		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	31-Jul-2012		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	31-Jul-2012		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	31-Jul-2012		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	31-Jul-2012		A/R			
720000 E1	PERFORM ENGINE OVERHAUL		MTH	31-Jul-2012					
			HRS	50.2		3500		(3500)3550.2	1274.5
720000 E2	PERFORM ENGINE OVERHAUL		MTH	31-Jul-2012					
			HRS	50.2		3500		(3500)3550.2	1274.5
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION		MTH	31-Jul-2021					
			HRS	1800.7	-.5	1750		(3500)3550.2	1274.5
			LDG	1387					
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION		MTH	31-Jul-2021					
			HRS	1800.7	-.5	1750		(3500)3550.2	1274.5
			LDG	1387					



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720003 E1	INSPECT LOW UTILIZATION ENGINE KDTO			MTH HRS LDG	04-May-2024 2038.8 1541		24		31-May-2026	8 m 9 d
720003 E2	INSPECT LOW UTILIZATION ENGINE KDTO			MTH HRS LDG	04-May-2024 2038.8 1541		24		31-May-2026	8 m 9 d
720020 E1	MONITORING OIL CONSUMPTION TREND			MTH	31-Jul-2012		A/R			
720020 E2	MONITORING OIL CONSUMPTION TREND			MTH	31-Jul-2012		A/R			
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS			1750		(3500)3550.2	1274.5
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS			1750		(3500)3550.2	1274.5
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER			MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER			MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT KBJC			MTH HRS LDG	23-Jun-2025 2263.4 1665		12 900		30-Jun-2026 (3113.2)3163.4	9 m 8 d 887.7
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT KBJC			MTH HRS LDG	23-Jun-2025 2263.4 1665		12 900		30-Jun-2026 (3113.2)3163.4	9 m 8 d 887.7
731055 E1	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAA67862 MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
731055 E2	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAA69830 MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN MTH HRS LDG	31-Jul-2021 1800.7 1387	-.5	1750		(3500)3550.2	1274.5
790010 E1	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY KDTO			MTH HRS LDG	04-May-2024 2038.8 1541		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Maintenance Inspections

Item Code	Description		Part Number		C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
790010 E2	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY	KDTO		MTH HRS LDG	04-May-2024 2038.8 1541		O/C			
790015 E1	REPLACE OIL FILTER ELEMENT	KDTO		MTH HRS LDG	04-May-2024 2038.8 1541		900		(2888.6)2938.8	663.1
790015 E2	REPLACE OIL FILTER ELEMENT	KDTO		MTH HRS LDG	04-May-2024 2038.8 1541		900		(2888.6)2938.8	663.1



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY. *CF			0113-12 2072	MTH 31-Jul-2012		O/C	0		
213001	KAPS II CONTROLLER 9912661-6 *CF			52811-102 1372	MTH 31-Jul-2012		O/C	0		
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 1575	MTH 31-Jul-2012		O/C	0		
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7 *CF			52812-102 1486	MTH 31-Jul-2012		O/C	0		
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14 UNK			1133610-4 593A	MTH 21-Jul-2025 HRS 2275.7 LDG 1671		O/C	0 0 0		
215002	CONDENSOR ASSEMBLY 9912660-3 *CF			1134620-5 627	MTH 31-Jul-2012		O/C	0		
215003	RECEIVER DRYER ASSY 9912660-18 *CF			1134275-13 117	MTH 31-Jul-2012		O/C	0		
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 963	MTH 31-Jul-2012		O/C	0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7 *CF			1133300-1 983	MTH 31-Jul-2012		O/C	0		
215005	VANE AXIAL BLOWER ASSY. *CF			1250435-10 673	MTH 31-Jul-2012		O/C	0		
215006A	COMPRESSOR DRIVE BELT KBJC			5MR535-25 N/A	MTH 11-Nov-2024 HRS 2125.5 LDG 1590		O/C	0 0 0		
215007	2.3 HP COMPRESSOR DRIVE MOTOR KDTN			1134146-6 1668A	MTH 01-Nov-2022 HRS 1898 LDG 1444		O/C	0 0 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD KDTN			1251171-12 N/A	MTH 01-Nov-2022 HRS 1898 LDG 1444 ACH 798.1			0 0 0 0	1598.1	782.3
215009	COMPRESSOR DRIVE PULLEY			PN SN-UNKNOWN			O/C			
221001 AILERON	GSA 80 TORQUE SERVO *CF			011-00877-00 66307465	MTH 31-Jul-2012		O/C	0		
221001 RUDDER	GSA 80 TORQUE SERVO *CF			011-00877-00 66307464	MTH 31-Jul-2012		O/C	0		
221002 ELEVATOR	GSA 81 TORQUE SERVO *CF			011-00878-10 71308486	MTH 31-Jul-2012		O/C	0		
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO *CF			011-00878-10 71308525	MTH 31-Jul-2012		O/C	0		
221003 AILERON	GSM 85A SERVO MOUNT *CF			011-01436-A2 10905383	MTH 31-Jul-2012		O/C	0		
221003 ELEVATOR	GSM 85A SERVO MOUNT *CF			011-01436-A0 11205391	MTH 31-Jul-2012		O/C	0		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT *CF			011-01436-A1 11305372	MTH 31-Jul-2012		O/C	0		
221003 RUDDER	GSM 85 SERVO MOUNT *CF			011-01436-A3 11005379	MTH 31-Jul-2012		O/C	0		
221004	GMC 710 AFCS CONTROLLER *CF			011-01020-10 22006290	MTH 31-Jul-2012		O/C	0		
231002 NO. 1	NO. 1 GMA 1360D AUDIO PANEL KICT			011-03568-20 4QF107023	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231002 NO. 2	NO. 2 GMA 1360D AUDIO PANEL KICT	011-03568-20 4QF106105	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
231003 NO. 1	VHF COMM ANTENNA *CF	VHF10-829 1229	MTH 31-Jul-2012		O/C	0		
231003 NO. 2	VHF COMM ANTENNA *CF	VHF10-829 1243	MTH 31-Jul-2012		O/C	0		
231011	SAT PHONE ANTENNA *CF	S67-1575-109 11908	MTH 31-Jul-2012		O/C	0		
231101	HIGH FREQUENCY CONTROLLER S3100-470 *CF	071-01605-0201 NSN	MTH 31-Jul-2012		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449 *CF	064-01073-0102 NSN	MTH 31-Jul-2012		O/C	0		
231103	HIGH FREQUENCY ANTENNA *CF	16390 NSN	MTH 31-Jul-2012		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFIER *CF	064-01072-0101 NSN	MTH 31-Jul-2012		O/C	0		
243001 LEFT	DIGITAL GCU 9912682-1 OR 9912682-3 *CF	51525-001F P5740	MTH 31-Jul-2012		O/C	0		
243001 RIGHT	DIGITAL GCU 9912682-3 OR 9912682-3 *CF	51525-001F P5792	MTH 31-Jul-2012		O/C	0		
243002	EMER INST BATTERY KDTO	B CBS24 00207M	MTH 14-Jun-2024 HRS 2038.8 LDG 1541		O/C			
243007	MAIN SHIP BATTERY KDAL	7639-30 G03202402	MTH 08-May-2024 HRS 2038.8 LDG 1541		O/C			
243015	RELAY DISCONNECT BATTERY S3155-1 *CF	A-931F CT-13075	MTH 31-Jul-2012		O/C	0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 1019	MTH 31-Jul-2012		O/C	0		
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 1010	MTH 31-Jul-2012		O/C	0		
245003	FLAP CONTROL MODULE KLIT	7018916-9 0652	MTH 28-Jul-2016 HRS 1146.8 LDG 897		O/C	0 0 0		
245005 LEFT	ICE PROTECTION CONTROL UNK	7018917-11 35337420-3	MTH 21-Jul-2025 HRS 2275.7 LDG 1671		O/C	0 0 0		
245005 RIGHT	ICE PROTECTION CONTROL KDTs	7018918-15 33733244-4	MTH 01-Apr-2024 HRS 2036.6 LDG 1540		O/C	0 0 0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL KICT	7018919-19 31973839-4	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF	7018919-13 0851	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245008	DOOR MONITOR-	*CF		7018921-8 0508	MTH 31-Jul-2012		O/C	0		
245009	LANDING GEAR MONITOR-	KDST		7018923-12 0591	MTH 10-Jul-2016 HRS 1108.8 LDG 884		O/C			
245010 LEFT	START CONTROL	KDTS		7018924-12 0351	MTH 17-Jul-2013 HRS 486.2 LDG 388		O/C	0 0 0		
245010 RIGHT	START CONTROL	KDAL		7018924-12 0658	MTH 19-May-2017 HRS 1262.3 LDG 971 ACH 462.1		O/C	0 0 0		
245011	FLAP MONITOR-	KLIT		7018925-13 0109	MTH 13-Mar-2019 HRS 1513.4 LDG 1180		O/C	0 0		
245013	DIAGNOSTIC UNIT	KLIT		7018927-7 0677	MTH 05-Jul-2020 HRS 1632.9 LDG 1262		O/C	0 0 0		
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	*CF		85-230-2 1045013M2	MTH 31-Jul-2012		O/C	0		
245015	MASTER INTERIOR SSR UNIT UZ100	*CF		10747P03E25 11078405	MTH 31-Jul-2012		O/C	0		
245016	AVN BUS #1 SENSOR UZ102	*CF		10747P03E25 11078408	MTH 31-Jul-2012		O/C	0		
245017 LEFT	AVN SENSOR	*CF		10747P03E25 11028107	MTH 31-Jul-2012		O/C	0		
245018 RIGHT	AVN BUS #2 SENSOR UZ104	*CF		10747P03E25 11068358	MTH 31-Jul-2012		O/C	0		
245019 LEFT	IGN #1 SENSOR UZ105	*CF		10747P03E10 10077917	MTH 31-Jul-2012		O/C	0		
245019 RIGHT	IGN #1 SENSOR UZ106	*CF		10747P03E10 10016821	MTH 31-Jul-2012		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107	*CF		10747P03E10 10016824	MTH 31-Jul-2012		O/C	0		
245020 RIGHT	IGN #2 SENSOR UZ108	*CF		10747P03E10 10016814	MTH 31-Jul-2012		O/C	0		
245021	COCKPIT FAN SENSOR UZ109	*CF		10747P03E25 11028092	MTH 31-Jul-2012		O/C	0		
245022	CABIN FAN SENSOR UZ110	*CF		10747P03E25 11078412	MTH 31-Jul-2012		O/C	0		
245023 LEFT	LH BOOST PUMP SENSOR UZ114	*CF		10747P03E25 11028099	MTH 31-Jul-2012		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR UZ111	*CF		10747P03E25 10067809	MTH 31-Jul-2012		O/C	0		
245024	CONDENSER FAN SENSOR UZ112	*CF		10747P03E25 10067876	MTH 31-Jul-2012		O/C	0		
245025	DC-DC CONVERTER UZ116	*CF		10747P03E10 10016762	MTH 31-Jul-2012		O/C	0		
245026	AVN EMERG SENSOR UZ200	*CF		10747P03E25 10067899	MTH 31-Jul-2012		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE	*CF		7018119-1 1093	MTH 31-Jul-2012		O/C	0		
245201 RIGHT	CABIN ALTITUDE MODULE	*CF		7018119-1 1099	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
246030 LEFT	MULTI FUNCTION DISPLAY			PN SN-UNKNOWN	MTH 31-Jul-2012		O/C	0		
246030 RIGHT	MULTI FUNCTION DISPLAY	KD TO		7018118-1 0116	MTH 14-Apr-2023 HRS 1966.1 LDG 1496		O/C	0 0 0		
251001	GLARESHIELD ASSEMBLY	*CF		4319027-17 213285-6	MTH 31-Jul-2012		O/C	0		
256001 NO. 1	LIFE VEST	KD TO		P01074-207 23020450144	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	0	30-Jun-2033	93 m 8 d
256001 NO. 2	LIFE VEST	KD TO		P01074-207 23020450141	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	0	30-Jun-2033	93 m 8 d
256001 NO. 3	LIFE VEST	KD TO		P01074-207 23020450142	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	0	30-Jun-2033	93 m 8 d
256001 NO. 4	LIFE VEST	KD TO		P01074-207 23020450143	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	0	30-Jun-2033	93 m 8 d
256001 NO. 5	LIFE VEST	KD TO		P01074-207 23020450144	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	3	31-Mar-2033	90 m 9 d
256001 NO. 6	LIFE VEST	KD TO		P01074-207 23020450145	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		120 O/C	0	30-Jun-2033	93 m 8 d
256002	ELT BATTERY	KDAL		452-0133 395756-036	MTH 17-Jun-2022 HRS 1849.3 LDG 1417	-50	60	0	30-Apr-2027	19 m 8 d
256004	ELT ANTENNA	*CF		110-340 383226	MTH 31-Jul-2012		O/C	0		
256007	ELT PROCESSOR C406N	*CF		453-5060 12923	MTH 31-Jul-2012		O/C	0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 212041	MTH 31-Jul-2012		O/C	0		
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 212343	MTH 31-Jul-2012		O/C	0		
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KDAL		30401102-2 67573B1	MTH 19-May-2017 HRS 1262.3 LDG 971 ACH 462.1		O/C	59 1262.3 971		
262003 LEFT	FIRE EXT CARTRIDGE	KDAL		13083-5 09132027	MTH 17-Jun-2022 HRS 1849.3 LDG 1417		72		31-Aug-2027	23 m 9 d
Manufacture Date: 31-Aug-2021										
262003 RIGHT	FIRE EXT CARTRIDGE	KDAL		13083-5 09132027	MTH 17-Jun-2022 HRS 1849.3 LDG 1417		72		31-Aug-2027	23 m 9 d
Manufacture Date: 31-Aug-2021										
262004	PORTABLE FIRE EXTINGUISHER KDAL			C352CS E-92812063	MTH 23-May-2018 HRS 1409.6 LDG 1102		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
271001 LEFT	CONTROL WHEEL ASSY *CF	4319065-3 1979	MTH 31-Jul-2012		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY *CF	4319065-4 1998	MTH 31-Jul-2012		O/C	0		
271002 --	ELEVATOR TRIM TAB ACTUATOR --	PN SN-UNKNOWN	MTH 31-Jul-2012		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0680	MTH 31-Jul-2012		O/C	0		
273002	AILERON TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0691	MTH 31-Jul-2012		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1 *CF	MP50Y-1 442AC	MTH 31-Jul-2012		O/C	0		
275002 LEFT	FLAP ACTUATOR 9912640-1 *CF	41013930-105 0918	MTH 31-Jul-2012		O/C	0		
275002 RIGHT	FLAP ACTUATOR 9912640-2 *CF	41013930-106 1030	MTH 31-Jul-2012		O/C	0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY KDAL	9914344-59 0971	MTH 21-May-2020 HRS 1618.7 LDG 1248		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY KDAL	9914344-59 059	MTH 21-May-2020 HRS 1618.7 LDG 1248		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR *CF	2R5211A 0048	MTH 31-Jul-2012		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR *CF	2R5212A 0045	MTH 31-Jul-2012		O/C	0		
282001 LEFT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C2124	MTH 31-Jul-2012		O/C	0		
282001 RIGHT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C2126	MTH 31-Jul-2012		O/C	0		
282002	TRANSFER VALVE 9914103-6 *CF	ZSV57 12-0124196	MTH 31-Jul-2012		O/C	0		
282003 LEFT	DC FUEL PUMP 9912553-1 *CF	1C7-23 4BH22	MTH 31-Jul-2012		O/C	0		
282003 RIGHT	DC FUEL PUMP 9912553-1 *CF	1C7-23 4BH18	MTH 31-Jul-2012		O/C	0		
282004 L1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 B9032	MTH 31-Jul-2012		O/C	0		
282004 L2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 B9031	MTH 31-Jul-2012		O/C	0		
282004 R1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 B9028	MTH 31-Jul-2012		O/C	0		
282004 R2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 B9027	MTH 31-Jul-2012		O/C	0		
282005 LEFT	VALVE-FUEL MOTOR 9912014-3 *CF	EM9014-3 AA340579	MTH 31-Jul-2012		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3 *CF	EM9014-3 AA336722	MTH 31-Jul-2012		O/C	0		
284001 L1	FUEL PROBE 9912664-1 *CF	020-251-001 0935	MTH 31-Jul-2012		O/C	0		
284001 L2	FUEL PROBE 9912664-2 *CF	020-251-002 1026	MTH 31-Jul-2012		O/C	0		
284001 L3	FUEL PROBE 9912664-3 *CF	020-251-003 0927	MTH 31-Jul-2012		O/C	0		
284001 L4	FUEL PROBE 9912664-4 *CF	020-251-004 0937	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284001 L5	FUEL PROBE 9912664-5	*CF		020-251-005 0884	MTH 31-Jul-2012		O/C	0		
284001 R1	FUEL PROBE 9912664-1	*CF		020-251-001 0927	MTH 31-Jul-2012		O/C	0		
284001 R2	FUEL PROBE 9912664-2	*CF		020-251-002 1024	MTH 31-Jul-2012		O/C	0		
284001 R3	FUEL PROBE 9912664-3	*CF		020-251-003 0939	MTH 31-Jul-2012		O/C	0		
284001 R4	FUEL PROBE 9912664-4	*CF		020-251-004 0928	MTH 31-Jul-2012		O/C	0		
284001 R5	FUEL PROBE 9912664-5	*CF		020-251-005 0892	MTH 31-Jul-2012		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6	*CF		367-350-001 1416	MTH 31-Jul-2012		O/C	0		
291001	HYDRAULIC POWER PACK ASSEMBLY KDTS			9912652-2 021B	MTH 06-Jul-2022 HRS 1856.8 LDG 1425		O/C	0 0 0		
291002	HYDRAULIC CHECK VALVE *CF			4001-20 6079A	MTH 31-Jul-2012		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE *CF			19940933-1 037842	MTH 31-Jul-2012		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	*CF		80665 0417	MTH 31-Jul-2012		O/C	0		
291007	HYDRAULIC MANIFOLD 9912657-14	*CF		8257-3 0406	MTH 31-Jul-2012		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2	*CF		2672 0407	MTH 31-Jul-2012		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3	*CF		80664 0406	MTH 31-Jul-2012		O/C	0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	*CF		4251 0406	MTH 31-Jul-2012		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	*CF		4252 0406	MTH 31-Jul-2012		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15	*CF		9625-1 0409	MTH 31-Jul-2012		O/C	0		
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	*CF		7550-2 1001	MTH 31-Jul-2012		O/C	0		
301001 LEFT	WING DE-ICE BOOT 9912662-17	KICT		P35-4D5317-17 NFT4570	MTH 26-Apr-2021 HRS 1750.5 LDG 1350		O/C	0 0 0		
301001 RIGHT	WING DE-ICE BOOT KDTS			9912662-18 NHB3350	MTH 01-Apr-2024 HRS 2036.6 LDG 1540		O/C	0 0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3	KICT		P29S4D5317-05 NFM7470	MTH 26-Apr-2021 HRS 1750.5 LDG 1350		O/C	0 0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4	KICT		P29S4D5317-06 NFM6230	MTH 26-Apr-2021 HRS 1750.5 LDG 1350		O/C	0 0 0		
301004 L1	DE-ICE PRESSURE SWITCH *CF			1106P55-1 8952A	MTH 31-Jul-2012		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH *CF			1106P55-1 9124A	MTH 31-Jul-2012		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
301004 L3	DE-ICE PRESSURE SWITCH *CF	1106P55-1 8912A	MTH 31-Jul-2012		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH *CF	1106P55-1 9142A	MTH 31-Jul-2012		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH *CF	1106P55-1 9121A	MTH 31-Jul-2012		O/C	0		
301004 R3	DE-ICE PRESSURE SWITCH *CF	1106P55-1 8577A	MTH 31-Jul-2012		O/C	0		
301004	VERT DE-ICE BOOT 9912662-13	KBJC P29S4D5317-13 NHH8360	MTH 11-Nov-2024 HRS 2125.5 LDG 1590		O/C	0 0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY KLIT	5285-00-3 2791	MTH 22-Aug-2021 HRS 1801.8 LDG 1388		O/C	109 1801.8 1388		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY KLIT	5285-00-3 2786	MTH 22-Aug-2021 HRS 1801.8 LDG 1388		O/C	109 1801.8 1388		
302002 LEFT	TEMP SWITCH *CF	1173T0759 6491	MTH 31-Jul-2012		O/C	0		
302002 RIGHT	TEMP SWITCH *CF	1173T0759 6516	MTH 31-Jul-2012		O/C	0		
304001 L1	DE-ICE VALVE *CF	3D2353-06 120606	MTH 31-Jul-2012		O/C	0		
304001 L2	DE-ICE VALVE *CF	3D2353-06 120607	MTH 31-Jul-2012		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER KDAL	7018108-30 0318	MTH 03-Apr-2019 HRS 1522.3 LDG 1188		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER KDAL	7018108-30 0413	MTH 03-Apr-2019 HRS 1522.3 LDG 1188		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF	7041020-5 414	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF	7041020-6 413	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
321001	NOSE LANDING GEAR TRUNNION *CF	7042020-1 417	MTH 31-Jul-2012		O/C	0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY *CF	7041050-5 159	MTH 31-Jul-2012 LDG 0		12000	0	12000	10329
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY *CF	7041050-5 157	MTH 31-Jul-2012 LDG 0		12000	0	12000	10329
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF	7041030-3 79	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF	7041030-4 79	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK *CF	6327504-6 3241	MTH 31-Jul-2012		O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK *CF	6327504-6 3235	MTH 31-Jul-2012		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
322002	NOSE GEAR FORK & PISTON ASSEMBLY *CF	7042040-6 34	MTH 31-Jul-2012		O/C	0		
322003	UPLOCK ACTUATOR *CF	6327504-7 1599	MTH 31-Jul-2012		O/C	0		
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1 *CF	FA100036-001 0436	MTH 31-Jul-2012 LDG 0		12000	0	12000	10329
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR LEFT FA100104-001 KDAL	9912653-5 FA100104-1-0418	MTH 25-Aug-2017 HRS 1302.5 LDG 1018 ACH 506.2		12000	947	12071	10400
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR RIGHT 9912653-6 *CF	FA100105-001 FA100105-1-0425	MTH 31-Jul-2012 LDG 0		12000	0	12000	10329
322011	NOSE LANDING GEAR ACTUATOR 9912654-2 *CF	FA100087-001 0425	MTH 31-Jul-2012 LDG 0		12000	0	12000	10329
322202	SHIMMY DAMPER *CF	7042030-2 MTM00272	MTH 31-Jul-2012		O/C	0		
322205	LANDING GEAR STRUT ASSEMBLY NOSE *CF	7042010-6 32	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
322206	LANDING GEAR DRAG BRACE ASSY NOSE CHP 4 *CF	7042120-5 165	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
323001	LANDING GEAR ASSEMBLY LEFT	PN SN-UNKNOWN	MTH 31-Jul-2012		O/C	0		
323001	LANDING GEAR ASSEMBLY RIGHT	PN SN-UNKNOWN	MTH 31-Jul-2012		O/C	0		
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE 9914678-3 KDTO	40005369-2 9359	MTH 27-Jan-2023 HRS 1941.5 LDG 1480		288	70	31-Mar-2041	186 m 9 d
Manufacture Date: 30-Mar-2017								
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE 9914678-4 KDTO	40005399-1 7285	MTH 27-Jan-2023 HRS 1941.5 LDG 1480		288	148	30-Sep-2034	108 m 8 d
Manufacture Date: 30-Sep-2010								
323003	EMER BLOW DOWN BTL PRESSURE GAUGE *CF	19940931-1 037829	MTH 31-Jul-2012		O/C	0		
324001	MAIN LANDING GEAR TIRE LEFT 9912646-1 KDTO	021-523-0 1218T00278	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		O/C	0 0 0		
324001	MAIN LANDING GEAR TIRE RIGHT 9912646-1 KDTO	021-523-0 1219T00304	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		O/C	0 0 0		
324002	NOSE LANDING GEAR TIRE 9912649-1 KDTO	079-606-0 2154T00179	MTH 12-Jun-2023 HRS 1979.9 LDG 1504		O/C	0 0 0		
324003	MAIN LANDING GEAR WHEEL LEFT 9912645-1 KICT	3-1640 0974	MTH 15-Jun-2014 HRS 711.6 LDG 566		O/C	23 711.6 566		
324003	MAIN LANDING GEAR WHEEL RIGHT 9912645-1 KDAL	3-1640 0979	MTH 23-May-2018 HRS 1409.6 LDG 1102		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324004 NOSE	NOSE LANDING GEAR WHEEL 9912648-1	KDAL		3-1642 0136	MTH 31-Mar-2021 HRS 1744.4 LDG 1346		O/C			
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KJXI		2-1706-1 0838A	MTH 26-Oct-2017 HRS 1330 LDG 1037		O/C	0 0 0		
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KDAL		2-1706-1 0080A	MTH 21-May-2020 HRS 1618.7 LDG 1248		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE 9914689-4	*CF		5145-1 0862	MTH 31-Jul-2012		O/C	0		
324006 RIGHT	SHUTTLE VALVE 9914689-4	*CF		5145-1 0859	MTH 31-Jul-2012		O/C	0		
324007	BRAKE METERING VALVE 9912650-9	*CF		84-75 0435	MTH 31-Jul-2012		O/C	0		
324101 LEFT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 0879	MTH 31-Jul-2012		O/C	0		
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 0889	MTH 31-Jul-2012		O/C	0		
324101	PARKING BRAKE VALVE 9912388-10	*CF		98433-1 0431	MTH 31-Jul-2012		O/C	0		
324102	ANTISKID CONTROL UNIT 9912650-1	*CF		556-3 302829540	MTH 31-Jul-2012		O/C	0		
324103	ANTISKID CONTROL VALVE 9912650-6	*CF		211-134-1 0436	MTH 31-Jul-2012		O/C	0		
324104	EMERGENCY BRAKE VALVE 9912651-1	*CF		72298 0456	MTH 31-Jul-2012		O/C	0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE *CF			19940931-1 038168	MTH 31-Jul-2012		O/C	0		
334001 LEFT	POWER SUPPLY 9912677-3	*CF		82004-1 000945	MTH 31-Jul-2012		O/C	0		
334001 RIGHT	POWER SUPPLY 9912677-3	*CF		82004-1 000947	MTH 31-Jul-2012		O/C	0		
334002	GROUND RECOGNITION LIGHT *CF			84003-4 0063	MTH 31-Jul-2012		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1	*CF		84005-1 000807	MTH 31-Jul-2012 HRS 0		8000	0	8000	5724.3
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2	*CF		84005-2 000788	MTH 31-Jul-2012 HRS 0		8000	0	8000	5724.3
335169 R/H	LANDING LIGHT ASSEMBLY KDTs			9912677-2 000880	MTH 06-Jan-2023 HRS 1925.1 LDG 1462		O/C	0 0 0		
341001	SWAAT UNIT 9912689-1	ICT		0863B2 258	MTH 11-Nov-2012 HRS 185.8 LDG 147		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM *CF			011-01110-01 1SW005597	MTH 31-Jul-2012		O/C	0		
341002 NO. 2	GDC 74B AIRDATA SYSTEM *CF			011-01110-01 1SW005596	MTH 31-Jul-2012		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM *CF			011-00978-00 47919930	MTH 31-Jul-2012		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM *CF			011-00978-00 47919922	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
341004 LEFT	PITOT PROBE 9912678-1	*CF	0851LN 291316	MTH 31-Jul-2012		O/C	0		
341004 RIGHT	PITOT PROBE 9912678-1	OXC	0851LN 297645	MTH 26-Oct-2012 HRS 166.4 LDG 126		O/C	0 0 0		
342001 STANDBY	ALTIMETER S3100-465	*CF	162350-1161 181375C	MTH 31-Jul-2012		O/C	0		
342002 AIRSPEED	INDICATOR	KBJC	261440-1143 291097A	MTH 06-Sep-2024 HRS 2078.4 LDG 1562		O/C	1 0 0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE KDAL		011-00831-00 46708346	MTH 09-Oct-2021 HRS 1810.3 LDG 1393		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE KDAL		011-00831-00 46709549	MTH 09-Oct-2021 HRS 1810.3 LDG 1393		O/C			
342003	MAGNETIC COMPASS *CF		S2800-821 NSN	MTH 31-Jul-2012		O/C	0		
342004 NO. 1	NO. 1 GDU 1050A DISPLAY KICT		010-01308-10 494108028	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
342004 NO. 2	NO. 2 GDU 1050A DISPLAY KICT		010-01308-10 494108031	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	KDTS	011-00868-10 42019921	MTH 08-Apr-2015 HRS 872.4 LDG 695		O/C	33 872.4 695		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	KDTS	011-00868-10 42019929	MTH 08-Apr-2015 HRS 872.4 LDG 695		O/C	33 872.4 695		
342006 NO. 1	GMU 44 MAGNETOMETER KDAL	MOD 1	011-00870-00 47521433	MTH 09-Oct-2017 HRS 1320 LDG 1031 ACH 506.2		O/C			
342006 NO. 2	GMU 44 MAGNETOMETER KDTS		011-00870-00 47507254	MTH 08-Apr-2015 HRS 872.4 LDG 695		O/C	0 0 0		
342007	GDU 1550 MFD UNIT KICT		010-01310-00 496002782	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513	*CF	4200-21 D12-11157	MTH 31-Jul-2012		O/C	0		
342010	AURAL WARNING UNIT KDTO		7018117-7 0111	MTH 11-Jul-2024 HRS 2045.4 LDG 1544		A/R	0 0 0		
344001	GARMIN GWX 75 WEATHER RADAR KICT		010-01590-00 4RR004760	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344001A	GARMIN GWX/GSX 12" RADAR ANTENNA ARRAY	KICT		117-00254-01 6178	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
344002	GARMIN GDL-69A DATA LINK	*CF		011-00987-00 47765405	MTH 31-Jul-2012		O/C	0		
344003	GARMIN GWX/GSX 10/12" RADARANTENNA W/O CONF MOD SUB ASSEMBLY	KICT		011-01769-00 NSN	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
345001	GPS/WAAS/XM ANTENNA	*CF		013-00245-00 9667	MTH 31-Jul-2012		O/C	0		
345002 RIGHT	RIGHT GARMIN GTX345(D)R TRANSPONDER	KICT	1	010-01776-03 51Y001742	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
345003 LEFT	TRANSPONDER	KDAL	1	011-00779-21 84810405	MTH 24-May-2018 HRS 1409.6 LDG 1102		O/C	3 0 0		
345004	GCU 475 FLIGHT MGMT CONTROL UNIT	KICT		010-01487-00 48V001526	MTH 24-Jul-2024 HRS 2049.7 LDG 1547		O/C	0 0 0		
345005	ADF RECEIVER	*CF		013-00166-00 NSN	MTH 31-Jul-2012		O/C	0		
345006	ADF ANTENNA	*CF		013-00165-00 NSN	MTH 31-Jul-2012		O/C	0		
345007	MARKER BEACON ANTENNA	*CF		MB10-754-2 0542	MTH 31-Jul-2012		O/C	0		
345008	GLIDE SLOPE ANTENNA	*CF		RGS10-48 16326	MTH 31-Jul-2012		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 3770	MTH 31-Jul-2012		O/C	0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 3860	MTH 31-Jul-2012		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 4321	MTH 31-Jul-2012		O/C	0		
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 3874	MTH 31-Jul-2012		O/C	0		
345010 LEFT	NAV ANTENNA	*CF		VT11-767-3 2569	MTH 31-Jul-2012		O/C	0		
345010 RIGHT	NAV ANTENNA			VT11-767-3 2574	MTH 31-Jul-2012		O/C	0		
345011	KN63 DME TRANSCEIVER	*CF		066-01070-0001 34591	MTH 31-Jul-2012		O/C	0		
345013	RMI CONVERTER	*CF		013-00167-00 NSN	MTH 31-Jul-2012		O/C	0		
345014	GPS/WAAS/ ANTENNA	*CF		013-00244-00 8990	MTH 31-Jul-2012		O/C	0		
345015	DME ANTENNA	*CF		L10-611-14 3975	MTH 31-Jul-2012		O/C	0		
346010	TAS PROCESSOR	*CF		066-01152-0101 KTA810-3672	MTH 31-Jul-2012		O/C	0		
346011 BOTTOM	TAS ANTENNA	*CF		L10-611-14 3859	MTH 31-Jul-2012		O/C	0		
346011 TOP	TAS ANTENNA	*CF		071-01599-0100 23767	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
346012	CONFIGURATION MODULE *CF	071-00112-0200 17422	MTH 31-Jul-2012		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT *CF	011-01105-20 1HQ005569	MTH 31-Jul-2012		O/C	0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT *CF	011-01105-20 1HQ005578	MTH 31-Jul-2012		O/C	0		
350001	OXYGEN BOTTLE	KDAL 4441073-040 695979008	MTH 01-Jul-2021 HRS 1784.9 LDG 1373		180	0	31-Aug-2029	47 m 9 d
Manufacture Date: 31-Aug-2014								
350002	OXYGEN PRESSURE GAUGE C668512-0101 *CF	MD97-1 A12-10783	MTH 31-Jul-2012		O/C	0		
351001 LEFT	CREW OXYGEN MASK 9914067-41 KDTS	LMNPTZ MC10-16-101 SE58194	MTH 01-Feb-2024 HRS 2026.8 LDG 1533		72	1	31-Jan-2030	52 m 9 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41 KDTS	LMNPTZ MC10-16-101 SE29548	MTH 01-Feb-2024 HRS 2026.8 LDG 1533		72	1	31-Jan-2030	52 m 9 d
361001 LEFT	PRECOOLER 9914402-7 *CF	8315-1 T0855	MTH 31-Jul-2012		O/C	0		
361001 RIGHT	PRECOOLER 9914402-7 *CF	8315-1 T0852	MTH 31-Jul-2012		O/C	0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY *CF	2601-34 0861A	MTH 31-Jul-2012		O/C	0		
361002 RIGHT	VARIABLE VENTURI VALVE ASSY *CF	2601-34 0859A	MTH 31-Jul-2012		O/C	0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2 *CF	1H75-23 5BF41	MTH 31-Jul-2012		O/C	0		
361004 LEFT	B/A SHUTOFF VALVE *CF	5253-00-3 3319	MTH 31-Jul-2012		O/C	0		
361004 RIGHT	B/A SHUTOFF VALVE *CF	5253-00-3 3320	MTH 31-Jul-2012		O/C	0		
361101 R1	DE-ICE VALVE *CF	3D2353-06 N120849	MTH 31-Jul-2012		O/C	0		
361101 R2	DE-ICE VALVE *CF	3D2353-06 N120843	MTH 31-Jul-2012		O/C	0		
522001	CABIN DOOR SEAL	KDAL 9912674-3 654	MTH 06-May-2019 HRS 1540.1 LDG 1202		O/C	0 0 0		
522002	ESCAPE HATCH SEAL 9912675-1 *CF	S-22561 268	MTH 31-Jul-2012		O/C	0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF	7013022-15 TSW0062	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF	7013022-16 TSW0048	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY CHP 4 *CF	7013022-17 TSW0066	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY CHP 4 *CF	7013022-18 TSW0021	MTH 31-Jul-2012 LDG 0		20000	0	20000	18329
533100	AFT PRESSURE BULKHEAD WEB BOND ASSEMBLY *CF	7011190-1-1 22523989	MTH 31-Jul-2012		O/C	0		
534101 FWD	ENGINE BEAM *CF	7012061-3 22553846	MTH 31-Jul-2012		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
552001 LEFT	ELEVATOR ASSEMBLY *CF			7034001-9 22668554	MTH 31-Jul-2012		O/C	0		
552001 RIGHT	ELEVATOR ASSEMBLY *CF			7034001-10 22668548	MTH 31-Jul-2012		O/C	0		
553001	VERTICAL STABILIZER ASSY *CF			7031001-1 22636462	MTH 31-Jul-2012		O/C	0		
561001 LEFT	WINDSHIELD ASSY, (LH) KDAL			9912745-13 18149H8495	MTH 06-May-2019 HRS 1540.1 LDG 1202		O/C	0 0		
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-10	*CF		NP-188601-4 12066H0429	MTH 31-Jul-2012		O/C	0		
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1	*CF		93310-1 1963	MTH 31-Jul-2012		O/C	0		
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2	*CF		93310-2 1958	MTH 31-Jul-2012		O/C	0		
562003 L1	CABIN WINDOW 9912747-13	*CF		93320-13 1503	MTH 31-Jul-2012		O/C	0		
562003 L2	CABIN WINDOW 9912747-13	*CF		93320-13 1535	MTH 31-Jul-2012		O/C	0		
562003 L3	CABIN WINDOW 9912747-13	*CF		93320-13 1517	MTH 31-Jul-2012		O/C	0		
562003 R1	CABIN WINDOW 9912747-13	*CF		93320-13 1511	MTH 31-Jul-2012		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-13	*CF		93320-13 1356	MTH 31-Jul-2012		O/C	0		
562003 R3	CABIN WINDOW 9912747-13	*CF		93320-13 1529	MTH 31-Jul-2012		O/C	0		
572001 LEFT WING	FWD SPAR *CF			7022022-1 90846	MTH 31-Jul-2012		O/C	0		
572001 RIGHT WING	FWD SPAR *CF			7022022-2 90222	MTH 31-Jul-2012		O/C	0		
572002 LEFT WING	REAR SPAR *CF			7022032-3 90135	MTH 31-Jul-2012		O/C	0		
572002 RIGHT WING	REAR SPAR *CF			7022032-4 90141	MTH 31-Jul-2012		O/C	0		
572003 LEFT WING	MAIN SPAR *CF			7022027-1 90384	MTH 31-Jul-2012		O/C	0		
572003 RIGHT WING	MAIN SPAR *CF			7022027-2 90308	MTH 31-Jul-2012		O/C	0		
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-5 403	MTH 31-Jul-2012 LDG 0			0 20000		18329
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-6 404	MTH 31-Jul-2012 LDG 0			0 20000	20000	18329
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-9 400	MTH 31-Jul-2012 LDG 0			0 20000	20000	18329
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-10 393	MTH 31-Jul-2012 LDG 0			0 20000	20000	18329
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-5 427	MTH 31-Jul-2012 LDG 0			0 20000	20000	18329
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-6 425	MTH 31-Jul-2012 LDG 0			0 20000	20000	18329
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1	*CF		7051001-1 00370	MTH 31-Jul-2012		O/C	0		
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA11 2073	MTH 31-Jul-2012 HRS 0			0 4000	4000	1724.3
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA11 2055	MTH 31-Jul-2012 HRS 0			0 4000	4000	1724.3



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF			7051001-2 00430	MTH 31-Jul-2012		O/C	0		
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA11 2054	MTH 31-Jul-2012 HRS 0		4000	0	4000	1724.3
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA11 2051	MTH 31-Jul-2012 HRS 0		4000	0	4000	1724.3
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK2554	MTH 31-Jul-2012 HRS 0		8000	0	8000	5724.3
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK2566	MTH 31-Jul-2012 HRS 0		8000	0	8000	5724.3
712003 AFT	ENGINE BEAM *CF			7012066-2 00416	MTH 31-Jul-2012		O/C	0		
712003 LEFT	AFT ENGINE MOUNT CHANNEL *CF			7051001-3 00379	MTH 31-Jul-2012		O/C	0		
712003 RIGHT	AFT ENGINE MOUNT CHANNEL *CF			7051001-4 00458	MTH 31-Jul-2012		O/C	0		
71EN1 NO. 1	ENGINE	KICT		35C0510-01 PCE-LB0853	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		E/C			
71EN2 NO. 2	ENGINE	KICT		35C0510-01 PCE-LB0852	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		E/C			
720010 E1	FAN ROTOR *CF			35C1940-01 FRAEPLUL8	MTH 31-Jul-2012 LDG 37 ACCC YC		10500	0 0	(10500)10537	8866 8866
720010 E2	FAN ROTOR *CF			35C1940-01 FRAEPLUW23	MTH 31-Jul-2012 LDG 37 ACCC YC		10500	0 0	(10500)10537	8866 8866
721010 E1	HP TURBINE DISK *CF			35C2311-01 CRAZAECJ406	MTH 31-Jul-2012 LDG 37 ACCC YC		5250	0 0	(5250)5287	3616 3616
721010 E2	HP TURBINE DISK *CF			35C2311-01 CRAZAECJ397	MTH 31-Jul-2012 LDG 37 ACCC YC		5250	0 0	(5250)5287	3616 3616
721020 E1	LP TURBINE DISK *CF			35C2372-01 CRAPZBW1027	MTH 31-Jul-2012 LDG 37 ACCC YC		10500	0 0	(10500)10537	8866 8866
721020 E2	LP TURBINE DISK *CF			35C2372-01 CRAPZBW1029	MTH 31-Jul-2012 LDG 37 ACCC YC		10500	0 0	(10500)10537	8866 8866
723010 E1	IMPELLER AND SHAFT ASSEMBLY UNK			35C5663-01 AAPPICGZ2069	MTH 19-Jul-2021 HRS 1800.7 LDG 1387 ACCC YC		10500	1350 1350	(11850)11887	10216 8866
723010 E2	IMPELLER AND SHAFT ASSEMBLY KBTV			35C5663-01 AAPPIAEX2029	MTH 01-Jun-2021 HRS 1800.7 LDG 1387 ACCC YC		10500	1350 1350	(11850)11887	10216 8866



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725010 E1	HP COMPRESSOR ROTOR UNK			35C3661-01 FRAEPNLC42	MTH 19-Jul-2021 HRS 1800.7 LDG 1387 ACCC YC		10500	1350 1350	(11850)11887	10216 8866
725010 E2	HP COMPRESSOR ROTOR *CF			35C3661-01 TXA1B5345	MTH 31-Jul-2012 LDG 37 ACCC YC		10500	0 0	(10500)10537	8866 8866
726010 E1	AGB STARTER MAGNETIC SEAL NSN			35C1022-01 NSN	MTH 31-Jul-2021 HRS 1800.7 LDG 1387	-5	1750	0 0 0	(3500)3550.2	1274.5
726010 E2	AGB STARTER MAGNETIC SEAL NSN			35C1022-01 NSN	MTH 31-Jul-2021 HRS 1800.7 LDG 1387	-5	1750	0 0 0	(3500)3550.2	1274.5
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 9879	MTH 31-Jul-2012		O/C	0		
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 9882	MTH 31-Jul-2012		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 *CF			TFF1573-4 AAD4983	MTH 31-Jul-2012		O/C	0		
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1 *CF			TFF1573-4 AAD7397	MTH 31-Jul-2012		O/C	0		
731050 E1	FUEL MANIFOLD UNK			35C6160-01 DEAAAA67862	MTH 19-Jul-2021 HRS 1800.7 LDG 1387		O/C	0 0 0		
731050 E2	FUEL MANIFOLD KBTv			35C6160-01 DEAAAA69830	MTH 01-Jun-2021 HRS 1800.7 LDG 1387		O/C	0 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.) *CF			35C0794-05 18116607	MTH 31-Jul-2012		H/T H/T	0		
732101 E2	FUEL METERING UNIT (F.M.U.) *CF			35C0794-05 18074323	MTH 31-Jul-2012		H/T H/T	0		
741001 E1	IGNITION EXCITER *CF			35C5472-01 WDA115484	MTH 31-Jul-2012		O/C	0		
741001 E2	IGNITION EXCITER *CF			35C5472-01 WDA115067	MTH 31-Jul-2012		O/C	0		
741002 E1 LEFT	IGNITER CABLE *CF			35C0844-01 NSN	MTH 31-Jul-2012		O/C	0		
741002 E2 LEFT	IGNITER CABLE *CF			35C0844-01 NSN	MTH 31-Jul-2012		O/C	0		
741003 E1 RIGHT	IGNITER CABLE *CF			35C0799-01 NSN	MTH 31-Jul-2012		O/C	0		
741003 E2 RIGHT	IGNITER CABLE *CF			35C0799-01 NSN	MTH 31-Jul-2012		O/C	0		
741004 E1 INBOARD	SPARK IGNITER KICT			35C2353-02 NSN	MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C	0 0 0		
741004 E2 INBOARD	SPARK IGNITER KICT			35C2353-02 NSN	MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C	0 0 0		
741005 E1 OUTBOARD	SPARK IGNITER KICT			35C2353-02 NSN	MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
741005 E2 OUTBOARD	SPARK IGNITER	KICT		35C2353-02 NSN	MTH 15-Jun-2014 HRS 761.8 LDG 592		O/C	0 0 0		
751003 E1	BLEED VALVE ACTUATOR	*CF		35C2851-02 18081047	MTH 31-Jul-2012		H/T H/T	0		
751003 E2	BLEED VALVE ACTUATOR	*CF		35C2851-02 18081043	MTH 31-Jul-2012		H/T H/T	0		
761001 E1	FADEC	KICT		35C4035-07 12-1040	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		O/C			
761001 E2	FADEC	KICT		35C4035-07 12-1045	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)	*CF		35C3778-04 WA44043	MTH 31-Jul-2012		H/T H/T	0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)	*CF		35C3778-04 WA43893	MTH 31-Jul-2012		H/T H/T	0		
793001 E1	OIL TEMP SENSOR	*CF		102-00083 07833	MTH 31-Jul-2012		O/C	0		
793001 E2	OIL TEMP SENSOR	*CF		102-00083 07822	MTH 31-Jul-2012		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER	KICT		APTE-598-1000-250G 8591-11-66	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		O/C	0 0 0		
793002 E2	OIL PRESSURE TRANSMITER	KICT		APTE-598-1000-250G 8591-11-369	MTH 30-Jul-2021 HRS 1800.7 LDG 1387		O/C	0 0 0		
801000 LEFT	STARTER GENERATOR	KDAL		MG-94E-1 0826D	MTH 21-May-2020 HRS 1618.7 LDG 1248		1500	0 0 0	3118.7	843
801000 RIGHT	STARTER GENERATOR	KDAL		MG94E-1 0984D	MTH 21-May-2020 HRS 1618.7 LDG 1248		1500	0 0 0	3118.7	843



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED			-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT			RECOMMENDED MTH			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT	KDTN	OPTIONAL	MTH 01-Nov-2022		-				Complete
				HRS 1898						
				LDG 1444						
	MOC : COMPLIED WITH - INSTALLED NEW FLAN BLADE ASSY. P/N K1134608-3 I/A/W SL510-21-05									
SL 510-23-01	LIGHTNING RELATED ANOMALIES OF THE GARMIN GMA 1347[D] AUDIO PANEL		INFORMATIONAL			A/R				
	MOC :									
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION	KDAL	MANDATORY	DAYS 19-May-2017		-				Complete
				HRS 1262.3						
				LDG 971						
				ACH 462.1						
	MOC : COMPLIED WITH									
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)		MANDATORY	DAYS		-				
	MOC :									
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS		OPTIONAL			-				
	MOC :									
SB 510-28-02	LOCKING FUEL CAP INSTALLATION		OPTIONAL			A/R				
	MOC :									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS		INFORMATIONAL			-				
	MOC :									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT	KDAL	RECOMMENDED	MTH 03-Apr-2019		-				Complete
				HRS 1522.3						
				LDG 1188						
	MOC : COMPLIED WITH - COMPLIED WITH SB510-30-06 R1. OPS CHECK GOOD IAW SB510-30-06 R1.									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)		RECOMMENDED	MTH		-				
	MOC :									
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-				
	MOC :									
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02)		INFORMATIONAL			A/R				
	MOC :									
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03)		INFORMATIONAL			A/R				
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)		INFORMATIONAL			A/R				
	MOC :									
SL 510-30-01 REV 04	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 05)		INFORMATIONAL			A/R				
	MOC :									
SL 510-30-01 REV 05	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 06)		INFORMATIONAL			A/R				
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01)									
	INFORMATIONAL									
	A/R									
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
	INFORMATIONAL									
	-									
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
	INFORMATIONAL									
	-									
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
	INFORMATIONAL									
	-									
	MOC :									
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION									
	KDAL	MANDATORY	DAYS 19-May-2017			-			Complete	
			HRS 1262.3							
			LDG 971							
			ACH 462.1							
	MOC : COMPLIED WITH - LEFT BRAKE S/N 0479, RIGHT BRAKE S/N 0244. NEITHER BRAKE IS S/N IS EFFECTED BY THIS SERVICE LETTER.									
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY									
	KDAL	MANDATORY	DAYS 22-May-2018			-			Complete	
			HRS 1409.6							
			LDG 1102							
	MOC : COMPLIED WITH									
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT									
	OPTIONAL									
	-									
	MOC :									
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION									
	OPTIONAL									
	A/R									
	MOC :									
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE									
	MCO	MANDATORY	MTH 29-Jun-2017			-			Complete	
			HRS 1279.8							
			LDG 1002							
	MOC : COMPLIED WITH									
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)									
	OPTIONAL									
	-									
	MOC :									
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)									
	UNK	OPTIONAL	MTH 24-May-2018			-			Complete	
			HRS 1409.6							
			LDG 1102							
	MOC : COMPLIED WITH - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE TO PREVIOUSLY INSTALLED DUAL GARMIN GTX-33D TRANSPONDER SYSTEMS.									
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE									
	OPTIONAL									
	-									
	MOC :									
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE									
	KDAL	RECOMMENDED	MTH 03-May-2019			-			Complete	
			HRS 1540.1							
			LDG 1202							
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
	MOC :									
SL 510-34-01	TRANSMITTAL OF GARMIN SERVICE ALERT 070424-00			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-05	GARMIN G1000 TRANSPONDER OPERATION CHANGE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-06	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0811, G1000 SERIES FLIGHT PLAN SEQUENCING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-07	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 0825 LPV AND LNAV/VNAV APPROACHES WITH THREE-CHARACTER AIRPORT IDENTIFIERS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-08	GPS/WAAS LOSS OF RECEPTION IN ALASKA, NORTHWEST CANADA, AND EASTERN RUSSIA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-10	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0915 REVISION A, G1000 SERIES NAVIGATION SUSPENDING DURING NON-PRECISION APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-12	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0933 REVISION A, SYSTEM MAY SELECT NAV 2 AS A NAVIGATION SOURCE DURING APPROACH			INFORMATIONAL			-			
	MOC :									
SL 510-34-13	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0922 REVISION A, VOR OR LOC/ILS APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL			-			
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL			-			
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	MCO		RECOMMENDED	MTH 29-Jun-2017 HRS 1279.8 LDG 1002		-			Complete
	MOC : COMPLIED WITH									
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL			-			
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL			-			
	MOC :									
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)	INFORMATIONAL			-			
	MOC :							
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 DAL MANDATORY	MTH			-			N/A
		DAYS 18-Jan-2016 HRS 1043.9 LDG 831						
	MOC : NOT APPLICABLE - C/W CIL-35-05. ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001 CRW OXYGEN MASKS N/A BY P/N & S/N							
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT KLIT MANDATORY	DAYS 06-Feb-2020 HRS 1585.9 LDG 1237			-			Complete
	MOC : COMPLIED WITH							
SL 510-52-05	DOORS - CABIN ENTRY DOOR HINGE SHIELD INSPECTION RECOMMENDED	MTH			-			Complete
	MOC : COMPLIED WITH - INCORPORATED AT PRODUCTION							
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT KLIT MANDATORY	DAYS 12-Dec-2019 HRS 1579.2 LDG 1231			-			Complete
	MOC : COMPLIED WITH							
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH 31-Jul-2012			-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7						-			
	MOC :									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7						-			
	MOC :									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63028 R01 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63037 R01 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63037 R01 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63043 R02 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER CATEGORY 6			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63043 R02 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER CATEGORY 6			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63051 R01 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63051 R01 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
MOC :										
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
MOC :										
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
MOC :										
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
MOC :										
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL				MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL				MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
MOC :										
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
MOC :										
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
MOC :										
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
MOC :										
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
MOC :										
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
MOC :										
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL ICT			CATEGORY 3	MTH 12-Jun-2013 HRS 499.8 LDG 394		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB PW600-72-63087 REV 2, ENGINE ELECTRONIC CONTROL - REPLACEMENT / MODIFICATION OF. ENGINE CURRENTLY HAS EEC P/N 35C4035-07 INSTALLED. NO ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	ICT		CATEGORY 3	MTH 12-Jun-2013 HRS 499.8 LDG 394		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB PW600-72-63087 REV 2, ENGINE ELECTRONIC CONTROL - REPLACEMENT / MODIFICATION OF. ENGINE CURRENTLY HAS EEC P/N 35C4035-07 INSTALLED. NO ACTION REQUIRED.										
SB PW600-72-63087 E1	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)			CATEGORY 3	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63087 E2	REPLACEMENT/MODIFICATION OF - ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R01)			CATEGORY 3	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
MOC :										
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
MOC :										
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6			-			
MOC :										
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6			-			
MOC :										
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6	MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6	MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
MOC :								
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7	MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7				-			
MOC :								
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)				-			
MOC :								
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3						-			
	MOC :									
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3						-			
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7						-			
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7						-			
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5						-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5						-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY RECOMMENDED				MTH 31-Jul-2021 HRS 1800.7 LDG 1387		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY RECOMMENDED				MTH 31-Jul-2021 HRS 1800.7 LDG 1387		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5			-			
	MOC :									
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7				-			
MOC :								
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7	MTH 31-Jul-2021 HRS 1800.7 LDG 1387			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH								
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
MOC :								
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5	MTH 31-Jul-2021 HRS 1800.7 LDG 1387			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH								
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5	MTH 31-Jul-2021 HRS 1800.7 LDG 1387			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH								
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5	MTH 31-Jul-2021 HRS 1800.7 LDG 1387			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH								
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5	MTH 31-Jul-2021 HRS 1800.7 LDG 1387			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH								
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING KDAL CATEGORY 3	MTH 07-Oct-2019 HRS 1618.6 LDG 1262			-			N/A
MOC : NOT APPLICABLE - THIS SB IS NOT APPLICABLE TO THIS AIRCRAFT LH FOHE SN WA44043 IS NOT ON LIST OF SN'S IN TABLE 1								
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING KDAL CATEGORY 3	MTH 07-Oct-2019 HRS 1618.6 LDG 1262			-			N/A
MOC : NOT APPLICABLE - THIS SB IS NOT APPLICABLE TO THIS AIRCRAFT. RH FOHE SN WA43893 IS NOT ON LIST OF SN'S IN TABLE 1								
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL KDTO CATEGORY 3	MTH 14-Jun-2023 HRS 1979.9 LDG 1504			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN NO. 63112 ON #1 ENGINE. WORK DONE IAW PRATT & WHITNEY 615F-A SERVICE BULLETIN PW600-72-63112 DATED 03/2021.								



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHING SEAL	KD TO		MTH 14-Jun-2023 HRS 1979.9 LDG 1504			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN NO. 63112 ON #2 ENGINE. WORK DONE IAW PRATT & WHITNEY 615F-A SERVICE BULLETIN PW600-72-63112 DATED 03/2021.										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)			CATEGORY 3	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)			CATEGORY 3	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7	MTH 31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MTH 31-Jul-2012			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MTH 31-Jul-2012			A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 8	MTH 31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	31-Jul-2012		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63115 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63115 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7			MTH			-			
MOC :										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7						-			
MOC :										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087 ICT			MANDATORY	MTH 12-Jun-2013 HRS 449.6 LDG 359		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB PW600-72-63087 REV 2, ENGINE ELECTRONIC CONTROL - REPLACEMENT / MODIFICATION OF. ENGINE CURRENTLY HAS EEC P/N 35C4035-07 INSTALLED. NO ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT RECOMMENDED MTH				-			
MOC :								
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8 MTH 31-Jul-2012				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8 MTH 31-Jul-2012				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT KICT OPTIONAL MTH 30-Jul-2021 HRS 1800.7 LDG 1387				-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-79-03; OIL - OIL PRESSURE TRANSDUCER REPLACEMENT, DATED AUGUST 09, 2017.								
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL				-			
MOC :								
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7 MTH 31-Jul-2012				-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01) CATEGORY 7			MTH	31-Jul-2012		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63008 R02 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63008 R02 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63047 R02 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) CATEGORY 3			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63047 R02 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) CATEGORY 3			MTH	31-Jul-2012		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SL 510-80-01	ENGINE STARTING			INFORMATIONAL			-			
MOC :										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM KDAL			RECOMMENDED	MTH 21-May-2020 HRS 1618.7 LDG 1248		-			Complete
MOC : COMPLIED WITH - REMOVED STARTER GENERATORS S/N 470C AND S/N 511C. INSTALLED OVERHAULED STARTER GENERATORS S/N 0826D AND S/N 0984D										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS CANCELLED						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
				CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
				CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
				CANCELLED			-			
	MOC :									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS									
				INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 (G) DATED JUNE 12, 2015 BY VISUAL INSPECTION ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT. AD 2015-10-02 (G) IS NOT APPLICABLE.								
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 (H) DATED JUNE 12, 2015 BY VISUAL INSPECTION ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT. AD 2015-10-02 (H) IS NOT APPLICABLE.								
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 (I) DATED JUNE 12, 2015 BY VISUAL INSPECTION ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT. AD 2015-10-02 (I) IS NOT APPLICABLE.								
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 DATED JUNE 12, 2015 BY VISUAL INSPECTION ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT. AD 2015-10-02 IS NOT APPLICABLE.								
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS KDAL		MTH 29-Aug-2018 HRS 1437.5 LDG 1128		-			N/A
MOC : NOT APPLICABLE - THIS AD 2017-16-01 IS NOT APPLICABLE, ELT IN QUESTION IS NOT INSTALLED. INSTALLED ELT IS AN ARTEX 453-5060.								
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT KDAL	MANDATORY	MTH 29-Aug-2018 HRS 1437.5 LDG 1128		-			Complete
MOC : COMPLIED WITH								
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS KDAL	MANDATORY	MTH 29-Aug-2018 HRS 1437.5 LDG 1128		-			Complete
MOC : COMPLIED WITH - INSTALLED ELT IS A ARTEX 453-5060.								
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE MANDATORY		MTH		-			
MOC :								
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE MANDATORY		MTH		-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	MANDATORY			-			
MOC :								
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MANDATORY			-			
MOC :								
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
MOC :								
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	MANDATORY	MTH		-			
MOC :								
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	MANDATORY			-			
MOC :								
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MANDATORY			-			
MOC :								
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	MANDATORY			-			
MOC :								
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	KDAL	MANDATORY	DAYS 22-May-2018 HRS 1409.6 LDG 1102	-			Complete
MOC : COMPLIED WITH - BOTH BRAKES ON THIS AIRCRAFT HAVE CORRECT PINS. LESS THAN 1.65 IN. IN TOTAL LENGTH								
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895	-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2014-18-01 DATED OCTOBER 14, 2014 BY VISUAL INSPECTION. APPLICABLE PN'S LISTED IN THIS AD IS NOT INSTALLED IN THIS ACFT. AD 2014-18-01 IS NOT APPLICABLE ON THIS ACFT.								
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895	-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-51- E DATED JULY 1, 2015 BY VISUAL INSPECTION. AVIDYNE IFD IS NOT INSTALLED IN THIS ACFT. AD 2015-10-51-E IS NOT APPLICABLE ON THIS ACFT.								
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895	-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-51 DATED JULY 1, 2015 BY VISUAL INSPECTION. AVIDYNE IFD IS NOT INSTALLED IN THIS ACFT. AD 2015-10-51-E IS NOT APPLICABLE ON THIS ACFT.								



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2015-08-07, (G), DATED DEC 28, 2015 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK PN AND SN INSTALLED IN THE AIRCRAFT IS NOT LISTED IN THE APPENDIX 1 OF THIS AD.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2015-08-07, (H) DATED DEC 28, 2015 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK PN AND SN INSTALLED IN THE AIRCRAFT IS NOT LISTED IN THE APPENDIX 1 OF THIS AD.									
FAA 2015-08-07	APLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KMCO	MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2015-08-07, DATED DEC 28, 2015 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK PN AND SN INSTALLED IN THE AIRCRAFT IS NOT LISTED IN THE APPENDIX 1 OF THIS AD.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	DAL	MANDATORY	MTH DAYS 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	DAL	MANDATORY	MTH DAYS 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	DAL	MANDATORY	MTH DAYS 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	DAL	MANDATORY	MTH DAYS 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	DAL	MANDATORY	MTH 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.									



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	DAL		MANDATORY	MTH 18-Jan-2016 HRS 1043.9 LDG 831		-			N/A
MOC : NOT APPLICABLE - DUE TO PART NUMBER & SERIAL NUMBER MC10-16-101 S/N'S SE70519 & SE70465.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2016-11-20 (G) DATED JULY 15, 2016 BY VISUAL INSPECTION, PBE IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2016-11-20 (H)(1) DATED JULY 15, 2016 BY VISUAL INSPECTION, PBE IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2016-11-20 (H)(2) DATED JULY 15, 2016 BY VISUAL INSPECTION, PBE IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 20-Jul-2016 HRS 1142.9 LDG 895		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2016-11-20 DATED JULY 15, 2016 BY VISUAL INSPECTION, PBE IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KDAL		MANDATORY	MTH 04-Apr-2018 HRS 1393.8 LDG 1088		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED, NOT APPLICABLE.										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KDAL		MANDATORY	MTH 04-Apr-2018 HRS 1393.8 LDG 1088		-			N/A
MOC : NOT APPLICABLE - NOT INSTALLED.										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KDAL		MANDATORY	MTH 04-Apr-2018 HRS 1393.8 LDG 1088		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE, PBE NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.										



CESCOM 10 - Aircraft Status Report

Owner: **WEST ELK CAPITAL LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0416**
Unit: **-0416** Reg No: **N86WH**
Airworthiness: **31-Jul-2012**
Print Date: **22-Sep-2025 2:40PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2275.7	1671	21-Jul-2025	.57
ENG 1	2225.5	1634	21-Jul-2025	.57
ENG 2	2225.5	1634	21-Jul-2025	.57
AIR COND	815.8		21-Jul-2025	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
	KDAL	MANDATORY	MTH	04-Apr-2018		-			N/A	
			HRS	1393.8						
			LDG	1088						
MOC : NOT APPLICABLE - NOT INSTALLED, NOT APPLICABLE.										
TCCA CF-2010-03	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
E1		MANDATORY	MTH	31-Jul-2012		-			N/A	
MOC : NOT APPLICABLE - DUE TO PART NUMBER OF THE FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE.										
TCCA CF-2010-03	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
E2		MANDATORY	MTH	31-Jul-2012		-			N/A	
MOC : NOT APPLICABLE - DUE TO THE PART NUMBER OF THE FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE.										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E1			MTH	31-Jul-2012		-			N/A	
MOC : NOT APPLICABLE - DUE TO PART NUMBER OF THE FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE.										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E2		MANDATORY	MTH	31-Jul-2012		-			N/A	
MOC : NOT APPLICABLE - DUE TO THE PART NUMBER OF THE FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE.										