

Maintenance Due List

N109TD

Make & Model (Serial)
CESSNA 560XLS (560-5589)Operator
ATM Aviation, LLCReported Date
24-May-2024Hours
3711.00Landings
3463

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	PW545B (PCE-DD0185)	3711.00	3463.00
Engine 2	PW545B (PCE-DD0190)	3711.00	3463.00
APU 0	RE100(XL) (P-541)	1957.30	3378.00

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 32-00-7202 Airframe INSPECTION INSP DOC 21 #6	42 AMP-HOUR CONCORDE LEAD ACID MAIN BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK Work Order Number: 000005 Man Hours: 0.00 Notes FLAT RATE	08-APR-2024 H: 3693.70 L: 3446	M: 3 H: 200.00	M: 1 H: 25.00		31-JUL-2024 H: 3893.70	M: 0 D: 30 H: 182.70
05 12-01 Airframe INSPECTION #14	INSPECTION DOCUMENT 1	11-OCT-2023 H: 3613.30 L: 3376	M: 12	M: 1		11-OCT-2024	M: 3 D: 10
25 60-10-7203 Airframe INSPECTION #261	ARTEX C406-N EMERGENCY LOCATORTRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL CHECK (AIRPLANES -5565 AND ON) (FAR 91.207) Notes EFFECTIVITY -5565 AND ON. NATIONAL REQUIREMENTS MAY EXIST WITH A DIFFERENT INTERVAL. MRBR 25-60-00-203, 25-60-00-204, 25-60-00-205, 25-60-00-206, 25-60-00-701, 25-60-00-702, 25-60-00-703, 25-60-00- 704	31-OCT-2023 H: 3613.30 L: 3376	M: 12	M: 1		31-OCT-2024	M: 3 D: 30
49 70-01-2200 APU INSPECTION #7	APU - REMOVE CHIP DETECTOR , CLEAN, EXAMINE AND INSTALL	27-OCT-2023 H: 1957.30 C: 3378	M: 12 H: 450.00	M: 1 H: 45.00		31-OCT-2024 H: 2407.30	M: 3 D: 30 H: 450.00
SB 30545 R4 Engine 1 SB - Recurring #82	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN Notes CATEGORY 3		H: 300.00			13-NOV-2024 H: 4500.00	M: 4 D: 12 H: 789.00

Maintenance Due List

N109TD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 70-00-9600 Airframe PART - Expiration #30	DK120 OR DK120/90 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD	04-DEC-2017 H: 2838.10 L: 2599		M: 1		01-DEC-2024	M: 5 D: 0
	Reference Number	Part Number	Serial Number				
	MRBR 23-70-00-901, 23-70-00-902	DK120/90	AT83480				
	Notes TRACKED BY COMPONENT EXPIRATION DATE. PER SUPPLIER RECOMMENDATION DUKANE SEACOM 03-TM-0037 (DK120) OR 03-TM-0063 (DK120/90) TECHNICAL MANUAL UNDERWATER ACOUSTIC BEACON.						
80 11-00-2200 APU INSPECTION #17	AUXILIARY POWER UNIT STARTER - GENERATOR DETAILED INSPECTION	15-APR-2020 H: 3273.10 L: 3004	H: 500.00	H: 25.00		H: 2125.80	H: 168.50
05 12-19 Airframe INSPECTION #200	INSPECTION DOCUMENT 19	12-OCT-2023 H: 3613.30 L: 3376	H: 300.00	H: 25.00		H: 3913.30	H: 202.30
26 22-00-2200 Airframe INSPECTION CABN FIRE EX #411	CABIN PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK	01-MAR-2024 H: 3654.80 L: 3413	M: 12	M: 1		31-MAR-2025	M: 8 D: 30
	Part Number	Serial Number					
	A352TS	C32533991					
26 22-00-2200 Airframe INSPECTION CKPT FIRE EX #597	COCKPIT PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK	01-MAR-2024 H: 3654.80 L: 3413	M: 12	M: 1		31-MAR-2025	M: 8 D: 30
	Part Number	Serial Number					
	A352TS	C32533990 0					
28 00-02-2201 Airframe INSPECTION #551	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)	08-APR-2024 H: 3693.70 L: 3446	M: 12			08-APR-2025	M: 9 D: 7
72 50-00-701 Engine 1 INSPECTION #32	PERFORMANCE CALIBRATION (5-POINT RUN) FUNCTIONAL CHECK: DO A PERFORMANCE CALIBRATION CHECK (REF. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) AND COMPARE WITH PREVIOUS 5-POINT PERFORMANCE CALIBRATION. ALTERNATIVELY, MONITOR THE ENGINE PERFORMANCE THROUGH ENGINE CONDITION TREND MONITORING (ECTM).	08-NOV-2019 H: 3203.30 L: 2953	H: 800.00	H: 25.00		H: 4003.30	H: 292.30
72 50-00-701 Engine 2 INSPECTION #2	PERFORMANCE CALIBRATION (5-POINT RUN) FUNCTIONAL CHECK: DO A PERFORMANCE CALIBRATION CHECK (REF. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) AND COMPARE WITH PREVIOUS 5-POINT PERFORMANCE CALIBRATION. ALTERNATIVELY, MONITOR THE ENGINE PERFORMANCE THROUGH ENGINE CONDITION TREND MONITORING (ECTM).	08-NOV-2019 H: 3203.30 L: 2953	H: 800.00	H: 25.00		H: 4003.30	H: 292.30

Maintenance Due List

N109TD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 10-00-901 Engine 1 INSPECTION #150	NO. 1 ENGINE - INSTALL FILTER NEW FUEL FILTER ELEMENT	04-DEC-2017 H: 2838.10 L: 2599	H: 1200.00	H: 25.00		H: 4038.10	H: 327.10
73 10-00-901 Engine 2 INSPECTION #110	NO. 2 ENGINE - INSTALL FILTER NEW FUEL FILTER ELEMENT	04-DEC-2017 H: 2838.10 L: 2599	H: 1200.00	H: 25.00		H: 4038.10	H: 327.10
79 10-00-901 Engine 1 INSPECTION #98	NO. 1 ENGINE - INSTALL FILTER NEW OIL FILTER ELEMENT	04-DEC-2017 H: 2838.10 L: 2599	H: 1200.00	H: 25.00		H: 4038.10	H: 327.10
79 10-00-901 Engine 2 INSPECTION #60	NO. 2 ENGINE - INSTALL FILTER NEW OIL FILTER ELEMENT	04-DEC-2017 H: 2838.10 L: 2599	H: 1200.00	H: 25.00		H: 4038.10	H: 327.10
05 12-11 Airframe INSPECTION #393	INSPECTION DOCUMENT 11	23-JUN-2023 H: 3565.50 L: 3321	M: 24	M: 1		23-JUN-2025	M: 11 D: 22
73 20-00-901 Engine 1 INSPECTION #36	NO. 1 ENGINE - FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT. Reference Number 73-20-02	15-APR-2020 H: 3273.10 L: 3004	H: 800.00	H: 25.00		H: 4073.10	H: 362.10
73 20-00-901 Engine 2 INSPECTION #13	NO. 2 ENGINE - FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT. Reference Number 73-20-02	15-APR-2020 H: 3273.10 L: 3004	H: 800.00	H: 25.00		H: 4073.10	H: 362.10
77 10-00-901 Engine 1 INSPECTION #37	NO. 1 ENGINE - ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION:DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARYENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	15-APR-2020 H: 3273.10 L: 3004	H: 800.00	H: 25.00		H: 4073.10	H: 362.10
77 10-00-901 Engine 2 INSPECTION #144	NO. 2 ENGINE - ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION:DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARYENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	15-APR-2020 H: 3273.10 L: 3004	H: 800.00	H: 25.00		H: 4073.10	H: 362.10

Maintenance Due List

N109TD

ATA / Type / Group	Description			Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-10-9600 Airframe PART - Expiration #624	EMERGENCY LOCATOR TRANSMITTER BATTERY DISCARD			15-APR-2020	M: 60	M: 1		30-JUN-2025	M: 11 D: 29
	Reference Number	Part Number	Serial Number	H: 3273.10					
	25-60-00-902	453-5060	385997-021	L: 3004					
	Notes TRACKED BY COMPONENT EXPIRATION DATE. TYPICAL BATTERY LIFE FOR ARTEX ELT 110-406, C406-2 AND C406-N IS 60 MONTHS. TYPICAL BATTERY LIFE FOR ARTEX 110-4 IS 24 MONTHS.								
49 30-00-9600 APU PART - Life Limited #23	APU - FUEL FILTER ELEMENT			12-OCT-2023	M: 24	M: 1	M: 4	30-JUN-2025	M: 11 D: 29
		Part Number	Serial Number	H: 1957.30	H: 900.00	H: 45.00	H: 0.00	H: 2857.30	H: 900.00
		3882440-1	SN -	C: 3378					
			UNKNOWN						